



## Appendix F: Action Log

---

**City of Denton**  
**ADA Self-Evaluation and Transition Plan**  
**Action Log**  
**1/4/2022**

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	5	American Legion Hall Senior Center	2	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ -	2	High		
Building	5	American Legion Hall Senior Center	5	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	2	High		
Building	5	American Legion Hall Senior Center	12	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	2	High		
Building	5	American Legion Hall Senior Center	13	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	2	High		
Building	5	American Legion Hall Senior Center	20	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	2	High		
Building	6	Monsignor King Outreach Center	2	The access aisle contains a built-up curb ramp with an 8.7 percent cross slope.	\$ 3,375	2	High		
Building	6	Monsignor King Outreach Center	3	The access aisle contains a built-up curb ramp with an 3 percent running slope.	\$ -	2	High		
Building	9	City Hall East (Municipal Complex)	1	There are not enough accessible stalls. There should be a minimum of 5 accessible parking stalls including a minimum of 1 van accessible stalls.	\$ 6,750	2	High		
Building	9	City Hall East (Municipal Complex)	8	There are no accessible parking stalls. There are a total of 79 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 4 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 6,750	2	High		
Building	10	City Hall West	1	The accessible parking space has a 6.3 percent running slope.	\$ 4,050	2	High		
Building	10	City Hall West	5	There is no accessible route of travel from the access aisle to the accessible building entrance.	\$ 4,050	2	High		
Building	10	City Hall West	7	The accessible parking space has a 4.6 percent running slope.	\$ 4,050	2	High		
Building	10	City Hall West	16	The maneuvering clearance at the accessible entrance has a 7.4 percent slope.	\$ 3,375	2	High		
Building	14	Denton Development Center	1	There are no accessible parking stalls. At the time of evaluations the parking lot was under construction and no parking had been striped.	\$ 6,750	2	High		
Building	16	Denton Senior Center	29	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	2	High		
Building	16	Denton Senior Center	59	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	2	High		
Building	29	Fire Station #5	3	The access aisle is not located on an accessible route of travel to the accessible building entrance.	\$ 2,025	2	High		
Building	29	Fire Station #5	5	The access aisle contains a built-up curb ramp.	\$ -	2	High		
Building	29	Fire Station #5	6	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ -	2	High		
Building	49	North Branch Library	13	The accessible route has running slopes greater than 5 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	2	High		
Building	49	North Branch Library	14	The accessible route has running slopes greater than 5 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	2	High		
Building	49	North Branch Library	17	The accessible route has running slopes greater than 5 percent across the width of the walk and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	2	High		
Building	50	North Lakes Annex	10	The building entrance is not located on an accessible route.	\$ 7,425	2	High		
Building	50	North Lakes Annex	11	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	2	High		
Building	50	North Lakes Annex	12	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	2	High		
Building	3	Airport Terminal and Admin Building	1	There are not enough accessible stalls. There are 2 accessible parking stalls including 0 designated for a van. There should be a minimum of 3 accessible parking stalls including a minimum of 1 van accessible stalls.	\$ 4,050	3	High		
Building	7	Center for Visual Arts	1	There are no van accessible parking stalls. There are a total of 84 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 4 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 4,050	3	High		
Building	9	City Hall East (Municipal Complex)	9	There are no van accessible parking stalls. There are a total of 46 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 2 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 4,050	3	High		
Building	15	Denton Energy Center	6	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	3	High		
Building	21	Emily Fowler Library	9	The access aisle is on the driver's side of the stall.	\$ 2,025	3	High		
Building	26	Fire Station #2	4	There are no accessible parking stalls.	\$ 4,050	3	High		
Building	28	Fire Station #4	6	There are no van accessible parking stalls.	\$ 2,025	3	High		
Building	29	Fire Station #5	1	There are no van accessible parking stalls.	\$ 4,050	3	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	32	Fire Station #8	4	There are no van accessible parking stalls. There are a total of 13 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 4,050	3	High		
Building	40	LL WTP - Operations Building	1	There are no accessible parking stalls. There are a total of 9 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 4,050	3	High		
Building	42	LRR WTP - Admin Building	3	There are not enough accessible stalls. There are 2 accessible parking stalls including 1 designated for a van. There should be a minimum of 3 accessible parking stalls including a minimum of 1 van accessible stalls.	\$ 4,050	3	High		
Building	44	Master Recycling Services - Building 101	1	There are no van accessible parking stalls. There are a total of 8 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 4,050	3	High		
Building	47	Natatorium	8	There are not enough accessible stalls. There are 4 accessible parking stalls including 0 designated for a van. There should be a minimum of 6 accessible parking stalls including a minimum of 1 van accessible stalls.	\$ 8,100	3	High		
Building	50	North Lakes Annex	1	There are no designated van accessible parking stalls.	\$ 2,025	3	High		
Building	52	PCRP - Administration	1	There are no accessible parking stalls. There are a total of 18 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 4,050	3	High		
Building	55	PCRP - Electronics Office	1	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	3	High		
Building	61	Quebec Hangars	9	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 4,050	3	High		
Building	61	Quebec Hangars	10	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	3	High		
Building	65	Solid Waste Services Building	8	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 4,725	3	High		
Building	69	Traffic Control	4	There are no van accessible parking stalls. There are a total of 10 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 1 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 4,050	3	High		
Building	3	Airport Terminal and Admin Building	2	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 2,025	4	High		
Building	3	Airport Terminal and Admin Building	11	The walking surface is obstructed.	\$ 1,013	4	High		
Building	3	Airport Terminal and Admin Building	13	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	4	High		
Building	3	Airport Terminal and Admin Building	14	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	4	High		
Building	3	Airport Terminal and Admin Building	22	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	4	High		
Building	3	Airport Terminal and Admin Building	23	The detectable warning is not the full width and depth of the curb ramp.	\$ 1,013	4	High		
Building	3	Airport Terminal and Admin Building	31	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Building	5	American Legion Hall Senior Center	1	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 4,050	4	High		
Building	5	American Legion Hall Senior Center	3	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	4	High		
Building	5	American Legion Hall Senior Center	4	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	4	High		
Building	5	American Legion Hall Senior Center	7	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	4	High		
Building	5	American Legion Hall Senior Center	9	The access aisle is not a minimum 8 feet to the centerline of the stripe. The accessible parking stall access aisle must be a minimum of 8 feet wide measured from centerline to centerline.	\$ 675	4	High		
Building	5	American Legion Hall Senior Center	11	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ -	4	High		
Building	5	American Legion Hall Senior Center	14	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Building	5	American Legion Hall Senior Center	19	The curb ramp side flares exceed maximum slope allowances.	\$ 3,375	4	High		
Building	5	American Legion Hall Senior Center	21	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		
Building	5	American Legion Hall Senior Center	22	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	5	American Legion Hall Senior Center	23	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Building	6	Monsignor King Outreach Center	1	The access aisle is only 59-1/2 inches where a minimum 8 feet is required.	\$ 675	4	High		
Building	6	Monsignor King Outreach Center	4	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Building	6	Monsignor King Outreach Center	6	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		
Building	6	Monsignor King Outreach Center	10	The accessible route of travel abruptly ends and contains a running slope of 7.3 percent.	\$ 3,375	4	High		
Building	6	Monsignor King Outreach Center	13	The ramps contains a 9 percent running slope.	\$ 4,725	4	High		
Building	6	Monsignor King Outreach Center	15	The landing at the change of direction does not meet minimum size requirements.	\$ 2,025	4	High		
Building	6	Monsignor King Outreach Center	16	The ramp does not have compliant handrails.	\$ 2,025	4	High		
Building	6	Monsignor King Outreach Center	17	The gripping surface of the handrail must be smooth.	\$ -	4	High		
Building	6	Monsignor King Outreach Center	18	The handrail does not extend past the end of the ramp.	\$ -	4	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	6	Monsignor King Outreach Center	19	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Building	6	Monsignor King Outreach Center	20	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Building	7	Center for Visual Arts	9	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	7	Center for Visual Arts	14	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	7	Center for Visual Arts	59	At least one accessible route (i.e. elevator ramp or platform lift) shall connect each story and mezzanine in multistory buildings and facilities.	\$ 6,750	4	High		
Building	7	Center for Visual Arts	86	At least one accessible route (i.e. elevator ramp or platform lift) shall connect each story and mezzanine in multistory buildings and facilities.	\$ 6,750	4	High		
Building	8	City Hall	1	The access aisle is on the driver's side of the stall.	\$ 675	4	High		
Building	8	City Hall	3	The access aisle is not located on an accessible route of travel to the accessible building entrance.	\$ 2,025	4	High		
Building	8	City Hall	31	The plaza contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 10,125	4	High		
Building	8	City Hall	45	The platform lift is not accessible because there is not adequate clear floor space within the lift.	\$ 6,750	4	High		
Building	8	City Hall	54	The platform lift is not accessible because there is not adequate clear floor space within the lift.	\$ 6,750	4	High		
Building	9	City Hall East (Municipal Complex)	4	The access aisle is on the driver's side of the stall.	\$ 2,025	4	High		
Building	9	City Hall East (Municipal Complex)	10	The access aisle is not a minimum 5 feet wide.	\$ 405	4	High		
Building	9	City Hall East (Municipal Complex)	11	The path of contains multiple issues and is not accessible. The entire back of the building is under construction.	\$ 6,750	4	High		
Building	9	City Hall East (Municipal Complex)	16	The transition from the curb ramp to the walk gutter or street is sloped greater than 5 percent.	\$ 2,025	4	High		
Building	9	City Hall East (Municipal Complex)	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	9	City Hall East (Municipal Complex)	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	9	City Hall East (Municipal Complex)	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	9	City Hall East (Municipal Complex)	32	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	9	City Hall East (Municipal Complex)	38	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	9	City Hall East (Municipal Complex)	39	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	9	City Hall East (Municipal Complex)	41	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	9	City Hall East (Municipal Complex)	43	There is no accessible route between the buildings.	\$ 3,375	4	High		
Building	10	City Hall West	2	The access aisle for the van accessible space is not wide enough at 94-1/2 inches.	\$ 675	4	High		
Building	10	City Hall West	3	The access aisle has a 3.2 percent running slope.	\$ 4,050	4	High		
Building	10	City Hall West	4	The accessible parking space has a 3.5 percent running slope.	\$ 4,050	4	High		
Building	10	City Hall West	6	The access aisle has a 2.5 percent running slope.	\$ 4,050	4	High		
Building	10	City Hall West	10	The stair risers are not uniform and minimum of 4 inches.	\$ 3,375	4	High		
Building	10	City Hall West	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	4	High		
Building	10	City Hall West	14	The accessible route of travel contains a cross slope of 4.5 percent.	\$ 3,375	4	High		
Building	10	City Hall West	15	The accessible route of travel contains a cross slope of 4.4 percent.	\$ 3,375	4	High		
Building	11	Civic Center	1	The accessible parking stall is not wide enough.	\$ 405	4	High		
Building	11	Civic Center	3	The access aisle is not a minimum 5 feet wide.	\$ 405	4	High		
Building	11	Civic Center	4	The accessible parking stall is not wide enough.	\$ 405	4	High		
Building	11	Civic Center	6	The access aisle is not a minimum 5 feet wide.	\$ 405	4	High		
Building	11	Civic Center	9	The accessible parking stall is not wide enough.	\$ 405	4	High		
Building	11	Civic Center	16	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 405	4	High		
Building	11	Civic Center	17	The accessible parking stall is not wide enough.	\$ 405	4	High		
Building	11	Civic Center	30	The entrance is not accessible and is missing signage.	\$ 338	4	High		
Building	11	Civic Center	33	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 4,725	4	High		
Building	12	Civic Center Pool	3	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 405	4	High		
Building	12	Civic Center Pool	32	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	12	Civic Center Pool	34	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	12	Civic Center Pool	36	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	12	Civic Center Pool	41	The curb ramp has no top landing and has flared sides greater than one unit vertical in 12 units horizontal (8.33-percent slope).	\$ 3,375	4	High		
Building	13	Denia Recreation Center	10	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	4	High		
Building	13	Denia Recreation Center	18	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	4	High		
Building	14	Denton Development Center	7	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	14	Denton Development Center	9	The ramp exceeds maximum rise requirements without an intermediate landing.	\$ 2,025	4	High		
Building	15	Denton Energy Center	1	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	4	High		
Building	15	Denton Energy Center	3	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ -	4	High		
Building	16	Denton Senior Center	2	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Building	16	Denton Senior Center	8	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Building	16	Denton Senior Center	10	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 2,700	4	High		
Building	16	Denton Senior Center	14	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Building	16	Denton Senior Center	16	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Building	16	Denton Senior Center	19	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	16	Denton Senior Center	20	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Building	16	Denton Senior Center	26	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	4	High		
Building	16	Denton Senior Center	34	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 4,050	4	High		
Building	16	Denton Senior Center	35	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 4,050	4	High		
Building	16	Denton Senior Center	36	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Building	16	Denton Senior Center	37	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 4,050	4	High		
Building	16	Denton Senior Center	39	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Building	16	Denton Senior Center	40	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 4,050	4	High		
Building	16	Denton Senior Center	41	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 4,050	4	High		
Building	16	Denton Senior Center	42	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Building	16	Denton Senior Center	48	The accessible parking stall is not wide enough.	\$ 675	4	High		
Building	16	Denton Senior Center	49	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 4,050	4	High		
Building	16	Denton Senior Center	66	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	16	Denton Senior Center	67	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	16	Denton Senior Center	73	The top of the curb ramp does not have a level landing that is a minimum of 36 inches in length.	\$ 2,025	4	High		
Building	16	Denton Senior Center	75	The top of the curb ramp does not have a level landing that is a minimum of 36 inches in length.	\$ 2,025	4	High		
Building	16	Denton Senior Center	77	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 743	4	High		
Building	16	Denton Senior Center	125	The ramp has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Building	16	Denton Senior Center	127	The top landing of the ramp does not meet minimum size requirements.	\$ -	4	High		
Building	20	Electric Administration Building	1	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 4,050	4	High		
Building	20	Electric Administration Building	8	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	4	High		
Building	20	Electric Administration Building	17	The grate openings are greater than 1/2 inch and are parallel to the direction of travel.	\$ 2,025	4	High		
Building	21	Emily Fowler Library	1	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	4	High		
Building	21	Emily Fowler Library	2	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 2,025	4	High		
Building	21	Emily Fowler Library	4	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Building	21	Emily Fowler Library	5	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 2,025	4	High		
Building	21	Emily Fowler Library	6	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	4	High		
Building	21	Emily Fowler Library	8	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 2,025	4	High		
Building	21	Emily Fowler Library	10	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	4	High		
Building	21	Emily Fowler Library	14	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	21	Emily Fowler Library	17	The accessible route contains loose gravel or surface materials that do not provide for a stable firm or slip-resistant surface.	\$ 2,025	4	High		
Building	21	Emily Fowler Library	22	The accessible route contains loose gravel that does not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Building	21	Emily Fowler Library	26	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	21	Emily Fowler Library	27	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 3,375	4	High		
Building	21	Emily Fowler Library	32	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Building	21	Emily Fowler Library	33	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Building	21	Emily Fowler Library	35	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	22	Engineering and Systems Operations	3	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	27	Fire Station #3	1	There are no accessible parking stalls.	\$ 4,050	4	High		
Building	28	Fire Station #4	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 338	4	High		
Building	28	Fire Station #4	9	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Building	28	Fire Station #4	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Building	28	Fire Station #4	12	The landing at the bottom of the ramp does not meet minimum length requirements.	\$ 3,375	4	High		
Building	28	Fire Station #4	14	The path of travel contains an expansion joint is spaced greater than 1/2 inch and a change in level.	\$ 2,025	4	High		
Building	29	Fire Station #5	4	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 338	4	High		
Building	29	Fire Station #5	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 338	4	High		
Building	29	Fire Station #5	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	4	High		
Building	29	Fire Station #5	51	The grate openings are greater than 1/2 inch and are parallel to the direction of travel.	\$ 6,075	4	High		
Building	30	Fire Station #6	8	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		
Building	30	Fire Station #6	11	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	32	Fire Station #8	2	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 405	4	High		
Building	33	Fire Station Annex (Old #4)	7	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	33	Fire Station Annex (Old #4)	10	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	34	Fleet Service Center	1	The accessible parking stall is not wide enough.	\$ 405	4	High		
Building	37	Linda McNatt Animal Care and Adoption Center	10	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	37	Linda McNatt Animal Care and Adoption Center	26	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	39	LL WTP - Maintenance Building	2	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Building	39	LL WTP - Maintenance Building	3	The curb ramp has no top landing and has flared sides greater than one unit vertical in 12 units horizontal (8.33-percent slope).	\$ -	4	High		
Building	39	LL WTP - Maintenance Building	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	42	LRR WTP - Admin Building	19	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	43	LRR WTP - Ozone Generation Building	2	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	4	High		
Building	46	MLK Jr Recreation Center	1	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	4	High		
Building	46	MLK Jr Recreation Center	3	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 405	4	High		
Building	46	MLK Jr Recreation Center	4	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	4	High		
Building	46	MLK Jr Recreation Center	5	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	4	High		
Building	46	MLK Jr Recreation Center	6	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	4	High		
Building	46	MLK Jr Recreation Center	7	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	4	High		
Building	46	MLK Jr Recreation Center	8	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	4	High		
Building	46	MLK Jr Recreation Center	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 3,375	4	High		
Building	46	MLK Jr Recreation Center	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	46	MLK Jr Recreation Center	25	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Building	46	MLK Jr Recreation Center	26	The transition from the curb ramp to the street is sloped greater than 5 percent.	\$ 2,025	4	High		
Building	46	MLK Jr Recreation Center	29	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	46	MLK Jr Recreation Center	33	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	4	High		
Building	46	MLK Jr Recreation Center	34	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Building	46	MLK Jr Recreation Center	46	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	46	MLK Jr Recreation Center	51	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	46	MLK Jr Recreation Center	53	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Building	47	Natatorium	17	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	48	New Central Fire Station	9	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	49	North Branch Library	15	There is no accessible route of travel from the public way.	\$ 3,375	4	High		
Building	49	North Branch Library	18	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	4	High		
Building	49	North Branch Library	26	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	50	North Lakes Annex	8	The building entrance is not located on an accessible route.	\$ 10,125	4	High		
Building	50	North Lakes Annex	15	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		
Building	50	North Lakes Annex	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	52	PCRP - Administration	8	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	4	High		
Building	52	PCRP - Administration	15	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	53	PCRP - Belt Press Building	2	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 4,725	4	High		
Building	55	PCRP - Electronics Office	9	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	4	High		
Building	55	PCRP - Electronics Office	10	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	4	High		
Building	56	PCRP - New Administration Building	1	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 2,025	4	High		
Building	56	PCRP - New Administration Building	3	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	4	High		
Building	58	PCRP - Operations Building	1	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	4	High		
Building	58	PCRP - Operations Building	3	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	58	PCRP - Operations Building	4	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	59	PCRP - Pretreatment Building	15	Gratings are spaced greater than 1/2 inch in the direction of travel.	\$ 1,013	4	High		
Building	61	Quebec Hangars	1	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 338	4	High		
Building	61	Quebec Hangars	11	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Building	61	Quebec Hangars	12	The grate openings are greater than 1/2 inch and are parallel to the direction of travel.	\$ 1,013	4	High		
Building	62	Service Center	20	The walking surface is obstructed.	\$ 1,013	4	High		
Building	65	Solid Waste Services Building	5	The access aisle is not a minimum 5 feet wide.	\$ 675	4	High		
Building	65	Solid Waste Services Building	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Building	65	Solid Waste Services Building	16	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	66	South Branch Library	1	The access aisle is not a minimum 5 feet wide.	\$ 675	4	High		
Building	66	South Branch Library	2	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 675	4	High		
Building	66	South Branch Library	4	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	4	High		
Building	66	South Branch Library	5	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 1,013	4	High		
Building	66	South Branch Library	8	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 1,013	4	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	66	South Branch Library	17	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Building	66	South Branch Library	19	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ -	4	High		
Building	66	South Branch Library	21	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ 2,025	4	High		
Building	69	Traffic Control	2	The access aisle is not a minimum 5 feet wide.	\$ 675	4	High		
Building	69	Traffic Control	3	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 4,050	4	High		
Building	69	Traffic Control	8	The accessible route has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	4	High		
Building	70	Transmission Engineering Department Building	1	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Building	70	Transmission Engineering Department Building	2	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	4	High		
Building	70	Transmission Engineering Department Building	4	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Park	1	Avondale Park	12	The accessible route of travel contains a cross slope of 15.8 percent and a grate with openings greater than 1/2 inch.	\$ 3,375	2	High		
Park	13	Fred Moore Park	33	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	2	High		
Park	13	Fred Moore Park	36	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	2	High		
Park	19	Jimmy Carter Park	1	There is no accessible route of travel from the public way.	\$ 4,725	2	High		
Park	19	Jimmy Carter Park	2	The accessible route of travel contains a running slope of 14.4 percent and a cross slope of 2.5 percent.	\$ 3,375	2	High		
Park	24	McKenna Park	1	The surfaces of the accessible parking spaces and access aisles are not firm stable and slip resistant.	\$ 4,050	2	High		
Park	1	Avondale Park	1	There are no van accessible parking stalls.	\$ 3,375	3	High		
Park	6	Clear Creek Natural Heritage Center	1	There are no van accessible parking stalls.	\$ 4,050	3	High		
Park	6	Clear Creek Natural Heritage Center	23	The surfaces of the accessible parking spaces and access aisles are not firm stable and slip resistant.	\$ 6,750	3	High		
Park	11	Denia Park	5	There are not enough accessible stalls. There should be a minimum of 2 accessible parking stalls including a minimum of 1 van accessible stalls.	\$ 4,050	3	High		
Park	12	Evers Park	24	There are no van accessible parking stalls.	\$ 8,100	3	High		
Park	12	Evers Park	26	There are no van accessible parking stalls.	\$ 4,050	3	High		
Park	19	Jimmy Carter Park	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 4,725	3	High		
Park	25	Milam Park	1	There are no van accessible parking stalls.	\$ 4,050	3	High		
Park	27	North Lakes Park	1	There are a total of 149 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 5 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 4,050	3	High		
Park	27	North Lakes Park	10	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	3	High		
Park	27	North Lakes Park	12	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	3	High		
Park	27	North Lakes Park	15	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	3	High		
Park	27	North Lakes Park	16	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	3	High		
Park	27	North Lakes Park	18	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	3	High		
Park	27	North Lakes Park	19	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	3	High		
Park	27	North Lakes Park	20	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	3	High		
Park	27	North Lakes Park	21	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	3	High		
Park	27	North Lakes Park	23	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	3	High		
Park	27	North Lakes Park	24	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	3	High		
Park	27	North Lakes Park	39	There are not enough accessible stalls. There are 3 accessible parking stalls including 0 designated for a van. There should be a minimum of 5 accessible parking stalls including a minimum of 1 van accessible stalls.	\$ 8,100	3	High		
Park	27	North Lakes Park	44	The surfaces of the accessible parking spaces and access aisles are not firm stable and slip resistant.	\$ 4,725	3	High		
Park	27	North Lakes Park	310	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	3	High		
Park	27	North Lakes Park	358	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 3,375	3	High		
Park	27	North Lakes Park	361	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 3,375	3	High		
Park	35	South Lakes Park	6	There are not enough accessible stalls. There are 108 accessible parking stalls including 0 designated for a van. There should be a minimum of 5 accessible parking stalls including a minimum of 1 van accessible stalls.	\$ 4,050	3	High		
Park	1	Avondale Park	3	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Park	1	Avondale Park	5	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Park	1	Avondale Park	10	The walkway contains abrupt vertical edges and variations over a 1/2 inch.	\$ 2,025	4	High		
Park	1	Avondale Park	21	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	4	High		
Park	1	Avondale Park	22	Compliance with ASTM F1951 and ASTM 1292 has not been determined.	\$ 4,725	4	High		
Park	2	Bowling Green Park	13	There is no accessible route to the trash can dog waste dispenser and community garden information box.	\$ 2,025	4	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	2	Bowling Green Park	17	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Park	2	Bowling Green Park	18	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	4	High		
Park	2	Bowling Green Park	19	Compliance with ASTM F1951 and ASTM 12 92 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 3,375	4	High		
Park	2	Bowling Green Park	20	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Park	3	Briercliff Park	11	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 2,025	4	High		
Park	3	Briercliff Park	12	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 2,025	4	High		
Park	4	Carl Young Sr. Park	19	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Park	4	Carl Young Sr. Park	21	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Park	4	Carl Young Sr. Park	22	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Park	4	Carl Young Sr. Park	24	Compliance with ASTM F1951 and ASTM 1292 has not been determined.	\$ 4,725	4	High		
Park	5	Carnegie Ridge Park	2	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	4	High		
Park	5	Carnegie Ridge Park	4	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	4	High		
Park	5	Carnegie Ridge Park	5	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	4	High		
Park	5	Carnegie Ridge Park	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	5	Carnegie Ridge Park	8	Compliance with ASTM F1951 and ASTM 1292 has not been determined.	\$ 4,725	4	High		
Park	6	Clear Creek Natural Heritage Center	2	The accessible parking stall is not wide enough.	\$ 2,025	4	High		
Park	6	Clear Creek Natural Heritage Center	3	The accessible parking stall is not wide enough.	\$ 2,025	4	High		
Park	9	Cross Timbers Park North	12	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 2,025	4	High		
Park	9	Cross Timbers Park North	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	4	High		
Park	10	Cross Timbers Park South	6	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 2,025	4	High		
Park	10	Cross Timbers Park South	7	There is no accessible route to the swings.	\$ 2,025	4	High		
Park	11	Denia Park	1	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Park	11	Denia Park	2	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ -	4	High		
Park	11	Denia Park	4	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Park	11	Denia Park	9	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 338	4	High		
Park	11	Denia Park	14	The access aisle is not a minimum 5 feet wide.	\$ 338	4	High		
Park	11	Denia Park	17	The access aisle is not a minimum 5 feet wide.	\$ 338	4	High		
Park	11	Denia Park	18	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	4	High		
Park	11	Denia Park	26	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Park	11	Denia Park	28	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Park	11	Denia Park	50	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	4	High		
Park	11	Denia Park	81	Compliance with ASTM F1951 and ASTM 1292 has not been determined.	\$ 4,725	4	High		
Park	11	Denia Park	82	Compliance with ASTM F1951 and ASTM 1292 has not been determined.	\$ 4,725	4	High		
Park	11	Denia Park	105	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	4	High		
Park	12	Evers Park	1	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Park	12	Evers Park	2	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ -	4	High		
Park	12	Evers Park	3	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	4	High		
Park	12	Evers Park	5	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Park	12	Evers Park	7	The access aisle is not a minimum 5 feet wide.	\$ 473	4	High		
Park	12	Evers Park	13	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 2,025	4	High		
Park	12	Evers Park	18	The accessible parking stall is not wide enough.	\$ 473	4	High		
Park	12	Evers Park	27	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Park	12	Evers Park	28	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	4	High		
Park	12	Evers Park	30	The accessible route contains surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Park	12	Evers Park	31	The accessible route contains surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	4	High		
Park	12	Evers Park	32	The accessible route contains surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	4	High		
Park	12	Evers Park	33	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		
Park	12	Evers Park	36	The landing of the ramp has a slope greater than 2 percent.	\$ -	4	High		
Park	12	Evers Park	40	There is no accessible route to the port-o-let.	\$ 2,025	4	High		
Park	12	Evers Park	41	The top of the curb ramp does not have a level landing that is a minimum of 36 inches in length.	\$ 2,025	4	High		
Park	12	Evers Park	43	The top of the curb ramp does not have a level landing that is a minimum of 36 inches in length.	\$ -	4	High		
Park	12	Evers Park	44	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	12	Evers Park	49	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	4	High		
Park	12	Evers Park	50	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	12	Evers Park	51	The walkway contains abrupt vertical edges and/or variations over 1/4 inch and expansion joints.	\$ 2,025	4	High		
Park	12	Evers Park	52	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	12	Evers Park	53	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	4	High		
Park	12	Evers Park	54	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	4	High		
Park	12	Evers Park	56	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	12	Evers Park	67	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Park	12	Evers Park	68	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	4	High		
Park	12	Evers Park	69	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	12	Evers Park	70	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	12	Evers Park	73	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Park	12	Evers Park	74	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	12	Evers Park	77	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	12	Evers Park	78	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	12	Evers Park	84	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	12	Evers Park	88	The accessible path of travel has cross slopes greater than 2 percent.	\$ 7,425	4	High		
Park	12	Evers Park	90	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	12	Evers Park	91	The accessible route contains surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	4	High		
Park	12	Evers Park	92	The accessible route contains surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	4	High		
Park	12	Evers Park	93	The accessible route contains surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	4	High		
Park	12	Evers Park	94	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 4,725	4	High		
Park	12	Evers Park	121	The accessible route of travel exceeds 5% running slope and therefore must be considered a ramp.	\$ 3,375	4	High		
Park	12	Evers Park	123	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces has not been determined.	\$ 4,725	4	High		
Park	12	Evers Park	126	The element extends down too close to the route of travel.	\$ 1,013	4	High		
Park	12	Evers Park	127	The baseball participation area is not on an accessible route.	\$ 1,013	4	High		
Park	12	Evers Park	130	The element extends down too close to the route of travel.	\$ 1,013	4	High		
Park	12	Evers Park	132	The element extends down too close to the route of travel.	\$ 1,013	4	High		
Park	12	Evers Park	134	The element extends down too close to the route of travel.	\$ 1,013	4	High		
Park	13	Fred Moore Park	1	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Park	13	Fred Moore Park	8	There is no accessible route to the playground.	\$ 2,025	4	High		
Park	13	Fred Moore Park	19	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	4	High		
Park	13	Fred Moore Park	22	There is no accessible route to the basketball court.	\$ 2,025	4	High		
Park	13	Fred Moore Park	31	The portable public restroom is not compliant.	\$ 1,013	4	High		
Park	13	Fred Moore Park	63	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	4	High		
Park	15	Goldfield Tennis Center	5	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		
Park	15	Goldfield Tennis Center	22	The accessible path of travel has cross slopes greater than 2 percent. Walkway with cross slope issues measures 10 panels each panel measures 42 inches wide by 50 inches long.	\$ 7,425	4	High		
Park	19	Jimmy Carter Park	3	The expansion joints are spaced greater than 1/2 inch.	\$ 4,725	4	High		
Park	19	Jimmy Carter Park	6	The accessible route contains a build-up of mud and debris that does not provide a stable firm slip-resistant surface.	\$ 2,025	4	High		
Park	19	Jimmy Carter Park	10	The accessible route contains a build-up of mud and debris that does not provide a stable firm slip-resistant surface.	\$ 2,025	4	High		
Park	19	Jimmy Carter Park	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Park	19	Jimmy Carter Park	14	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Park	19	Jimmy Carter Park	17	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Park	19	Jimmy Carter Park	18	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	4	High		
Park	20	Joe Skiles Park	6	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Park	21	Lake Forest Park	60	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 2,025	4	High		
Park	21	Lake Forest Park	61	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 2,025	4	High		
Park	22	Mack Park	40	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 4,725	4	High		
Park	22	Mack Park	59	Compliance with ASTM F1951 and ASTM 1292 has not been determined.	\$ 4,725	4	High		
Park	22	Mack Park	60	Compliance with ASTM F1951 and ASTM 1292 has not been determined.	\$ 4,725	4	High		
Park	23	Martin Luther King Jr. Park	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	23	Martin Luther King Jr. Park	8	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 2,025	4	High		
Park	23	Martin Luther King Jr. Park	9	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 2,025	4	High		
Park	24	McKenna Park	20	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 6,750	4	High		
Park	24	McKenna Park	21	There is no accessible route to the portable restrooms.	\$ 2,025	4	High		
Park	24	McKenna Park	24	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Park	24	McKenna Park	32	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	24	McKenna Park	39	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Park	24	McKenna Park	40	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Park	24	McKenna Park	51	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	4	High		
Park	24	McKenna Park	58	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a compliant ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	24	McKenna Park	60	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	4	High		
Park	24	McKenna Park	61	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	4	High		
Park	25	Milam Park	4	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	4	High		
Park	25	Milam Park	12	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		
Park	25	Milam Park	15	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	4	High		
Park	25	Milam Park	16	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Park	25	Milam Park	18	The transfer space is sloped greater than 2 percent.	\$ 2,025	4	High		
Park	25	Milam Park	21	The transfer space is sloped greater than 2 percent.	\$ 2,025	4	High		
Park	26	Nette Shultz Park	1	The landing of the ramp has a slope greater than 2 percent.	\$ 3,375	4	High		
Park	26	Nette Shultz Park	3	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 3,375	4	High		
Park	26	Nette Shultz Park	6	The accessible route contains surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Park	26	Nette Shultz Park	15	The walkway contains abrupt vertical edges over 1/4 inch.	\$ 2,025	4	High		
Park	26	Nette Shultz Park	25	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	4	High		
Park	26	Nette Shultz Park	26	There is no accessible route to the playground.	\$ 2,025	4	High		
Park	27	North Lakes Park	17	The access aisle is not a minimum 5 feet wide.	\$ 338	4	High		
Park	27	North Lakes Park	22	The access aisle is not a minimum 5 feet wide.	\$ 338	4	High		
Park	27	North Lakes Park	30	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 338	4	High		
Park	27	North Lakes Park	35	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 338	4	High		
Park	27	North Lakes Park	37	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 338	4	High		
Park	27	North Lakes Park	41	The access aisle is not a minimum 5 feet wide.	\$ 338	4	High		
Park	27	North Lakes Park	42	The access aisle is not a minimum 5 feet wide.	\$ 338	4	High		
Park	27	North Lakes Park	61	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ -	4	High		
Park	27	North Lakes Park	65	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 338	4	High		
Park	27	North Lakes Park	70	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	4	High		
Park	27	North Lakes Park	72	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	4	High		
Park	27	North Lakes Park	74	The access aisle is not located on an accessible route of travel.	\$ 2,025	4	High		
Park	27	North Lakes Park	77	The accessible parking space is not located on the shortest accessible route.	\$ 2,025	4	High		
Park	27	North Lakes Park	80	The access aisle is not located on an accessible route of travel.	\$ 2,025	4	High		
Park	27	North Lakes Park	82	The accessible parking space is not located on the shortest accessible route.	\$ 2,025	4	High		
Park	27	North Lakes Park	84	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	4	High		
Park	27	North Lakes Park	91	The surfaces of the accessible parking spaces and access aisles are not firm stable and slip resistant.	\$ 4,725	4	High		
Park	27	North Lakes Park	105	The path of travel contains cross slopes expansion joints and changes in level.	\$ 2,700	4	High		
Park	27	North Lakes Park	108	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	27	North Lakes Park	110	The accessible path of travel has cross slopes greater than 2 percent (6 panels).	\$ 3,375	4	High		
Park	27	North Lakes Park	120	The required edge protection is missing.	\$ 3,375	4	High		
Park	27	North Lakes Park	141	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Park	27	North Lakes Park	142	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Park	27	North Lakes Park	151	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Park	27	North Lakes Park	154	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Park	27	North Lakes Park	155	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip resistant surface.	\$ 10,125	4	High		
Park	27	North Lakes Park	159	The accessible path of travel has cross slopes greater than 2 percent (7 panels measuring 95 inches wide by 48 inches long).	\$ 3,375	4	High		
Park	27	North Lakes Park	171	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Park	27	North Lakes Park	172	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Park	27	North Lakes Park	173	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Park	27	North Lakes Park	174	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent and is obstructed by gravel.	\$ 3,375	4	High		
Park	27	North Lakes Park	176	There is no accessible route from the parking lot to the dog park.	\$ 4,725	4	High		
Park	27	North Lakes Park	178	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 10,125	4	High		
Park	27	North Lakes Park	183	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Park	27	North Lakes Park	187	The accessible route contains loose gravel and surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	27	North Lakes Park	190	The accessible route contains loose gravel and surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Park	27	North Lakes Park	192	The accessible route contains loose gravel and surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Park	27	North Lakes Park	285	The walking surface is obstructed.	\$ 1,013	4	High		
Park	27	North Lakes Park	290	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	4	High		
Park	27	North Lakes Park	291	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	4	High		
Park	27	North Lakes Park	363	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	4	High		
Park	27	North Lakes Park	364	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	4	High		
Park	27	North Lakes Park	369	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	4	High		
Park	27	North Lakes Park	384	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	4	High		
Park	28	North Pointe Park	6	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Park	28	North Pointe Park	7	Compliance with ASTM F1951 and ASTM 1292 has not been determined.	\$ 4,725	4	High		
Park	30	Owsley Park	8	The accessible route of travel exceeds 5 percent running slope and therefore must be considered a ramp.	\$ 2,025	4	High		
Park	31	Quakertown Park	32	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ 4,725	4	High		
Park	32	Sequoia Park	1	There is no accessible route of travel from the public way.	\$ 4,725	4	High		
Park	32	Sequoia Park	2	The treads are not the minimum required depth.	\$ 4,725	4	High		
Park	34	Skate Works	1	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 1,013	4	High		
Park	35	South Lakes Park	5	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	4	High		
Park	35	South Lakes Park	35	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	35	South Lakes Park	36	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	35	South Lakes Park	74	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	35	South Lakes Park	75	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Park	35	South Lakes Park	76	The curb ramp does not have a compliant top landing and the side flares are too steep.	\$ -	4	High		
Park	35	South Lakes Park	102	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	21	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	4	High		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	22	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	4	High		
Park	37	Water Works Park	2	The access aisle is not a minimum 5 feet wide.	\$ 338	4	High		
Park	37	Water Works Park	4	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	4	High		
Park	37	Water Works Park	17	The curb ramp side flares exceed maximum slope allowances.	\$ -	4	High		
Park	37	Water Works Park	18	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Park	37	Water Works Park	20	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	4	High		
Park	37	Water Works Park	21	The curb ramp side flares exceed maximum slope allowances.	\$ -	4	High		
Park	37	Water Works Park	56	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	37	Water Works Park	59	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Park	37	Water Works Park	93	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	4	High		
Park	37	Water Works Park	102	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	4	High		
Park	38	Wheeler Ridge Park	3	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	12	Nette Shultz Trail	1	The required edge protection is missing.	\$ 10,125	2	High		
Paved Trail	12	Nette Shultz Trail	24	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	2	High		
Paved Trail	-999	Preserve at Pecan Creek	5	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ 2,025	4	High		
Paved Trail	-999	Preserve at Pecan Creek	6	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	-999	Preserve at Pecan Creek	7	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	-999	Preserve at Pecan Creek	16	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	-999	Preserve at Pecan Creek	21	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	-999	Preserve at Pecan Creek	22	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	1	Avondale Trail	2	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Paved Trail	1	Avondale Trail	11	The transition from the curb ramp to the walk gutter or street is sloped greater than 5 percent.	\$ 3,375	4	High		
Paved Trail	2	Bowling Green Trail	8	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Paved Trail	3	Carl Young Park Trail	3	The accessible route has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.). Cross slopes are greater than 2 percent across the width of the walk.	\$ 2,700	4	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	4	Cooper Creek Trail	1	The accessible route of travel contains a running slope of 8.7 percent and changes in level.	\$ 2,025	4	High		
Paved Trail	4	Cooper Creek Trail	22	The path of contains multiple issues and is not accessible.	\$ 4,725	4	High		
Paved Trail	4	Cooper Creek Trail	29	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	4	Cooper Creek Trail	43	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	4	Cooper Creek Trail	47	The accessible route of travel contains a cross slope of 8 percent and a running slope of 7.5 percent.	\$ 2,025	4	High		
Paved Trail	4	Cooper Creek Trail	58	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Paved Trail	4	Cooper Creek Trail	62	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Paved Trail	4	Cooper Creek Trail	64	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Paved Trail	5	Cross Timbers Trail	7	There is no accessible route to the trail head.	\$ 4,725	4	High		
Paved Trail	5	Cross Timbers Trail	8	There is no accessible route to the trail head located at the pond off of monticito drive.	\$ 4,725	4	High		
Paved Trail	5	Cross Timbers Trail	11	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	5	Cross Timbers Trail	20	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	4	High		
Paved Trail	6	Denia Trail	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	7	Evers Park Trail	2	The required edge protection is missing.	\$ 1,013	4	High		
Paved Trail	7	Evers Park Trail	14	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	7	Evers Park Trail	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	7	Evers Park Trail	23	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ 2,025	4	High		
Paved Trail	7	Evers Park Trail	25	The curb ramp side flares exceed maximum slope allowances.	\$ 3,375	4	High		
Paved Trail	7	Evers Park Trail	28	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	4	High		
Paved Trail	7	Evers Park Trail	42	The accessible path of travel has cross slopes greater than 2 percent and changes in level.	\$ 2,025	4	High		
Paved Trail	7	Evers Park Trail	53	The accessible route of travel contains a cross slope of 3.2 to 5.1 percent and changes in elevation. 5 panels of sidewalk with slope and elevation issues.	\$ 3,375	4	High		
Paved Trail	7	Evers Park Trail	55	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	7	Evers Park Trail	60	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	8	Fred Moore Trail	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	8	Fred Moore Trail	20	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	8	Fred Moore Trail	23	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	8	Fred Moore Trail	24	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	8	Fred Moore Trail	25	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	8	Fred Moore Trail	26	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	4	High		
Paved Trail	8	Fred Moore Trail	28	The curb ramp has no top landing and has flared sides greater than one unit vertical in 12 units horizontal (8.33-percent slope).	\$ -	4	High		
Paved Trail	8	Fred Moore Trail	29	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	8	Fred Moore Trail	32	The curb ramp has no top landing and has flared sides greater than one unit vertical in 12 units horizontal (8.33-percent slope).	\$ -	4	High		
Paved Trail	8	Fred Moore Trail	34	There is no accessible route to the walkway.	\$ 3,375	4	High		
Paved Trail	8	Fred Moore Trail	60	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	9	Frontier Park Trail	1	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		
Paved Trail	9	Frontier Park Trail	2	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 3,375	4	High		
Paved Trail	9	Frontier Park Trail	5	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	4	High		
Paved Trail	10	Katy Trail (Denton Rail Trail)	102	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	10	Katy Trail (Denton Rail Trail)	104	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	10	Katy Trail (Denton Rail Trail)	155	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	11	Lake Forest Trail	7	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	11	Lake Forest Trail	20	The accessible route contains loose gravel and surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Paved Trail	12	Nette Shultz Trail	2	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	12	Nette Shultz Trail	25	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Paved Trail	12	Nette Shultz Trail	33	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	12	Nette Shultz Trail	34	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	13	North Lakes Trail	3	There is no accessible route to the trail head.	\$ 4,725	4	High		
Paved Trail	13	North Lakes Trail	4	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Paved Trail	13	North Lakes Trail	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	13	North Lakes Trail	42	The accessible path of travel has cross slopes greater than 2 percent and changes in level.	\$ 2,025	4	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	13	North Lakes Trail	44	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	13	North Lakes Trail	47	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	13	North Lakes Trail	48	The accessible path of travel has cross slopes greater than 2 percent and changes in level.	\$ 2,025	4	High		
Paved Trail	13	North Lakes Trail	64	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 6,750	4	High		
Paved Trail	13	North Lakes Trail	65	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 3,375	4	High		
Paved Trail	14	North Pointe Trail	1	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Paved Trail	14	North Pointe Trail	3	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Paved Trail	14	North Pointe Trail	5	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	4	High		
Paved Trail	14	North Pointe Trail	11	The required edge protection is missing.	\$ 1,013	4	High		
Paved Trail	14	North Pointe Trail	13	The required edge protection is missing.	\$ 1,013	4	High		
Paved Trail	17	Quakertown Trail	23	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Paved Trail	17	Quakertown Trail	28	The required edge protection is missing from the ramp run and/or ramp landing.	\$ 1,013	4	High		
Paved Trail	17	Quakertown Trail	37	The accessible route of travel contains a running slope of 9.7 percent and expansion joints.	\$ 2,025	4	High		
Paved Trail	17	Quakertown Trail	45	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	17	Quakertown Trail	46	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	17	Quakertown Trail	47	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Paved Trail	17	Quakertown Trail	48	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	17	Quakertown Trail	62	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	4	High		
Paved Trail	17	Quakertown Trail	65	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	18	Sequoia Trail	15	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	19	South Lakes Trail	22	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	19	South Lakes Trail	41	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	19	South Lakes Trail	76	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	19	South Lakes Trail	104	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Paved Trail	19	South Lakes Trail	116	There is no accessible route to the nature trail head.	\$ 2,025	4	High		
Paved Trail	22	Wheeler Ridge Trail	8	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	4	High		
Paved Trail	22	Wheeler Ridge Trail	10	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	4	High		
Paved Trail	22	Wheeler Ridge Trail	24	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	4	High		
Signalized Intersection	1	Intersection of Teasley Ln and Old Alton Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Old Alton Rd	\$ 37,400	2	High		
Signalized Intersection	10	Intersection of Teasley Ln and Nobson Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Nobson Ln	\$ 39,000	2	High		
Signalized Intersection	23	Intersection of Londonderry Ln and Jason Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Londonderry Ln and Jason Dr	\$ 44,300	2	High		
Signalized Intersection	45	Intersection of Eagle Dr and Bernard St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Eagle Dr and Bernard St	\$ 31,900	2	High		
Signalized Intersection	48	Intersection of Eagle Dr and Ave C	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Eagle Dr and Ave C	\$ 54,300	2	High		
Signalized Intersection	49	Intersection of E McKinney St and Billy Ryan High School (Lat. 33.2088; Long. -97.0778)	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E McKinney St and Billy Ryan High School (Lat. 33.2088; Long. -97.0778)	\$ 59,600	2	High		
Signalized Intersection	50	Intersection of S Welch St and W Highland St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Welch St and W Highland St	\$ 66,900	2	High		
Signalized Intersection	53	Intersection of S Welch St and W Prairie St / Union Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Welch St and W Prairie St / Union Cir	\$ 83,800	2	High		
Signalized Intersection	54	Intersection of S Bell Ave and E Prairie St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bell Ave and E Prairie St	\$ 52,300	2	High		
Signalized Intersection	55	Intersection of S Welch St and W Chestnut St / Union Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Welch St and W Chestnut St / Union Cir	\$ 87,700	2	High		
Signalized Intersection	59	Intersection of Loop 288 and E McKinney St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loop 288 and E McKinney St	\$ 37,200	2	High		
Signalized Intersection	60	Intersection of S Carroll Blvd and W Mulberry St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Carroll Blvd and W Mulberry St	\$ 59,900	2	High		
Signalized Intersection	66	Intersection of N Welch St and W Hickory St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Welch St and W Hickory St	\$ 73,600	2	High		
Signalized Intersection	67	Intersection of W Hickory St and Fry St / Ave A	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hickory St and Fry St / Ave A	\$ 39,800	2	High		
Signalized Intersection	68	Intersection of W Hickory St and Ave B	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hickory St and Ave B	\$ 76,500	2	High		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Signalized Intersection	71	Intersection of S Elm St and W Oak St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Elm St and W Oak St	\$ 34,900	2	High		
Signalized Intersection	73	Intersection of W Oak St and Fry St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Oak St and Fry St	\$ 39,100	2	High		
Signalized Intersection	74	Intersection of W Oak St and Jagoe St / Ave C	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Oak St and Jagoe St / Ave C	\$ 79,300	2	High		
Signalized Intersection	80	Intersection of S Elm St and W McKinney St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Elm St and W McKinney St	\$ 38,200	2	High		
Signalized Intersection	89	Intersection of N Bell Ave and Chapel Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bell Ave and Chapel Dr	\$ 38,100	2	High		
Signalized Intersection	90	Intersection of W University Dr and Malone St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and Malone St	\$ 9,900	2	High		
Signalized Intersection	94	Intersection of W University Dr and I-35 Frontage Rd NB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and I-35 Frontage Rd NB	\$ 21,700	2	High		
Signalized Intersection	96	Intersection of E University Dr and N Bell Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E University Dr and N Bell Ave	\$ 34,600	2	High		
Signalized Intersection	97	Intersection of E University Dr and N Locust St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E University Dr and N Locust St	\$ 55,300	2	High		
Signalized Intersection	98	Intersection of W University Dr and N Elm St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and N Elm St	\$ 44,900	2	High		
Signalized Intersection	101	Intersection of Mingo Rd and Nottingham Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mingo Rd and Nottingham Dr	\$ 18,600	2	High		
Signalized Intersection	108	Intersection of N Bell Ave and E Sherman Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bell Ave and E Sherman Dr	\$ 53,900	2	High		
Signalized Intersection	110	Intersection of E University Dr and Nottingham Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E University Dr and Nottingham Dr	\$ 31,200	2	High		
Signalized Intersection	113	Intersection of N Elm St and W Windsor Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Elm St and W Windsor Dr	\$ 31,400	2	High		
Signalized Intersection	114	Intersection of N Locust St and Windsor Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Locust St and Windsor Dr	\$ 100,800	2	High		
Signalized Intersection	124	Intersection of W University Dr and I-35 Frontage Rd SB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and I-35 Frontage Rd SB	\$ 36,600	2	High		
Signalized Intersection	6	Intersection of Teasley Ln and Ryan Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Ryan Rd	\$ 13,400	3	High		
Signalized Intersection	39	Intersection of Loop 288 and Shady Oaks Dr / Morse St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loop 288 and Shady Oaks Dr / Morse St	\$ 34,400	3	High		
Signalized Intersection	2	Intersection of Teasley Ln and Montecito Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Montecito Dr	\$ 36,200	4	High		
Signalized Intersection	75	Intersection of N Woodrow Ln and E McKinney St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Woodrow Ln and E McKinney St	\$ 42,700	4	High		
Unpaved Trail	1	Clear Creek Trail	1	The trail contains loose gravel that does not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Unpaved Trail	1	Clear Creek Trail	2	The trail contains loose gravel that does not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Unpaved Trail	1	Clear Creek Trail	3	The trail contains loose gravel that does not provide for a stable firm slip-resistant surface.	\$ 2,025	4	High		
Unpaved Trail	3	IIOF Cemetery Trail	1	The accessible route contains loose gravel that does not provide for a stable firm slip-resistant surface.	\$ 13,500	4	High		
Unpaved Trail	3	IIOF Cemetery Trail	2	The accessible route contains loose gravel that does not provide for a stable firm slip-resistant surface.	\$ 4,050	4	High		
Unpaved Trail	4	Oakwood Cemetery Trail	1	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	4	High		
Unpaved Trail	4	Oakwood Cemetery Trail	2	The accessible route contains loose gravel that does not provide for a stable firm slip-resistant surface.	\$ 6,750	4	High		
Unpaved Trail	4	Oakwood Cemetery Trail	3	The accessible route contains loose gravel that does not provide for a stable firm slip-resistant surface.	\$ 6,750	4	High		
Unpaved Trail	4	Oakwood Cemetery Trail	4	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	4	High		
Unpaved Trail	4	Oakwood Cemetery Trail	5	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	4	High		
PROW Sidewalk	1	Abbot's Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,480	1	Very Poor		
PROW Sidewalk	50	N North Texas Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	1	Very Poor		
PROW Sidewalk	59	Ave H	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,600	1	Very Poor		
PROW Sidewalk	78	N Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,350	1	Very Poor		
PROW Sidewalk	87	Bernard St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,710	1	Very Poor		
PROW Sidewalk	204	Coit St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,980	1	Very Poor		
PROW Sidewalk	263	Denton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,370	1	Very Poor		
PROW Sidewalk	297	Egan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,570	1	Very Poor		
PROW Sidewalk	328	Forest St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,070	1	Very Poor		
PROW Sidewalk	337	Foxcroft Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,370	1	Very Poor		
PROW Sidewalk	344	Fulton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,920	1	Very Poor		
PROW Sidewalk	376	Grove St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,130	1	Very Poor		
PROW Sidewalk	390	Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,850	1	Very Poor		
PROW Sidewalk	391	Heritage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,000	1	Very Poor		
PROW Sidewalk	394	W Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,820	1	Very Poor		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	402	W Highland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 28,410	1	Very Poor		
PROW Sidewalk	417	Hinkle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,030	1	Very Poor		
PROW Sidewalk	487	Kings Row	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,830	1	Very Poor		
PROW Sidewalk	544	Malone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,150	1	Very Poor		
PROW Sidewalk	549	Maple St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,700	1	Very Poor		
PROW Sidewalk	605	Miller St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	1	Very Poor		
PROW Sidewalk	631	Mounts Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,530	1	Very Poor		
PROW Sidewalk	668	Oakland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 480	1	Very Poor		
PROW Sidewalk	692	Pace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,470	1	Very Poor		
PROW Sidewalk	712	Pear Tree Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,260	1	Very Poor		
PROW Sidewalk	715	W Pecan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,800	1	Very Poor		
PROW Sidewalk	718	Pennsylvania Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,480	1	Very Poor		
PROW Sidewalk	739	Ponder Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	1	Very Poor		
PROW Sidewalk	742	E Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,210	1	Very Poor		
PROW Sidewalk	764	Redstone Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,420	1	Very Poor		
PROW Sidewalk	775	Roberts St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,800	1	Very Poor		
PROW Sidewalk	789	N Ruddell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	1	Very Poor		
PROW Sidewalk	798	Sagewood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,860	1	Very Poor		
PROW Sidewalk	817	Scripture St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,370	1	Very Poor		
PROW Sidewalk	830	Sheraton Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,090	1	Very Poor		
PROW Sidewalk	831	E Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,950	1	Very Poor		
PROW Sidewalk	833	W Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,550	1	Very Poor		
PROW Sidewalk	838	Simmons St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 340	1	Very Poor		
PROW Sidewalk	860	Stuart Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,590	1	Very Poor		
PROW Sidewalk	864	Sunnydale Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 37,480	1	Very Poor		
PROW Sidewalk	867	Swisher Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,520	1	Very Poor		
PROW Sidewalk	878	Tanglewood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,650	1	Very Poor		
PROW Sidewalk	891	Thunderbird Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,330	1	Very Poor		
PROW Sidewalk	895	Titan Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,690	1	Very Poor		
PROW Sidewalk	927	Wainwright St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,050	1	Very Poor		
PROW Sidewalk	928	E Walnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,990	1	Very Poor		
PROW Sidewalk	933	N Welch St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,940	1	Very Poor		
PROW Sidewalk	935	S Welch St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,040	1	Very Poor		
PROW Sidewalk	963	Willow Stone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,340	1	Very Poor		
PROW Sidewalk	975	E Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,850	1	Very Poor		
PROW Sidewalk	987	S Wood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,060	1	Very Poor		
PROW Sidewalk	993	Woodland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,520	1	Very Poor		
PROW Sidewalk	1002	Yellowstone Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,020	1	Very Poor		
PROW Sidewalk	1051	Shenandoah Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	1	Very Poor		
PROW Sidewalk	1052	Charleston Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,360	1	Very Poor		
PROW Sidewalk	1202	Sunrise Cove	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,800	1	Very Poor		
PROW Sidewalk	1420	Bent Oaks Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 490	1	Very Poor		
PROW Sidewalk	1743	Fairway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,740	1	Very Poor		
PROW Sidewalk	1878	Union Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 340	1	Very Poor		
PROW Sidewalk	9	Alegre Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,080	1	Poor		
PROW Sidewalk	16	Amarillo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,040	1	Poor		
PROW Sidewalk	17	Amherst Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,740	1	Poor		
PROW Sidewalk	20	Anna St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,220	1	Poor		
PROW Sidewalk	28	Atlas Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,240	1	Poor		
PROW Sidewalk	30	Audra Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,170	1	Poor		
PROW Sidewalk	32	N Austin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,080	1	Poor		
PROW Sidewalk	36	Ave A	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,240	1	Poor		
PROW Sidewalk	40	N Ave B	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	1	Poor		
PROW Sidewalk	44	S Ave C	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,920	1	Poor		
PROW Sidewalk	50	N North Texas Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,680	1	Poor		
PROW Sidewalk	65	Bandera St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,910	1	Poor		
PROW Sidewalk	78	N Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,240	1	Poor		
PROW Sidewalk	79	S Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 970	1	Poor		
PROW Sidewalk	81	Bellaire Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 34,720	1	Poor		
PROW Sidewalk	87	Bernard St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,260	1	Poor		
PROW Sidewalk	107	N Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 32,880	1	Poor		
PROW Sidewalk	110	S Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,820	1	Poor		
PROW Sidewalk	122	S Bradshaw St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,260	1	Poor		
PROW Sidewalk	134	Broadway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,440	1	Poor		
PROW Sidewalk	139	Brooke St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,190	1	Poor		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	152	Burning Tree Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,960	1	Poor		
PROW Sidewalk	171	N Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,460	1	Poor		
PROW Sidewalk	173	Casie Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,250	1	Poor		
PROW Sidewalk	177	Cedar Hill St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,580	1	Poor		
PROW Sidewalk	183	Chapel Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,340	1	Poor		
PROW Sidewalk	185	Charlotte St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 900	1	Poor		
PROW Sidewalk	211	Colonial Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,680	1	Poor		
PROW Sidewalk	216	W Congress St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	1	Poor		
PROW Sidewalk	226	Corbin Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 720	1	Poor		
PROW Sidewalk	263	Denton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,510	1	Poor		
PROW Sidewalk	276	Dunes Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,030	1	Poor		
PROW Sidewalk	277	Dunes St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,930	1	Poor		
PROW Sidewalk	297	Egan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,210	1	Poor		
PROW Sidewalk	317	Ferguson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,360	1	Poor		
PROW Sidewalk	318	First St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,880	1	Poor		
PROW Sidewalk	328	Forest St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,970	1	Poor		
PROW Sidewalk	334	Fowler Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,220	1	Poor		
PROW Sidewalk	337	Foxcroft Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,670	1	Poor		
PROW Sidewalk	339	Frame St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,680	1	Poor		
PROW Sidewalk	344	Fulton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,860	1	Poor		
PROW Sidewalk	357	Georgetown Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 820	1	Poor		
PROW Sidewalk	361	Glenwood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,990	1	Poor		
PROW Sidewalk	367	Grant Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,890	1	Poor		
PROW Sidewalk	370	Greenlee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,380	1	Poor		
PROW Sidewalk	374	Gregg St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,770	1	Poor		
PROW Sidewalk	390	Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	1	Poor		
PROW Sidewalk	394	W Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 48,760	1	Poor		
PROW Sidewalk	413	Hillcrest St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,380	1	Poor		
PROW Sidewalk	417	Hinkle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,060	1	Poor		
PROW Sidewalk	421	Hollycreek St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,710	1	Poor		
PROW Sidewalk	446	Industrial St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,320	1	Poor		
PROW Sidewalk	449	Inglewood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,610	1	Poor		
PROW Sidewalk	453	Jacqueline Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,350	1	Poor		
PROW Sidewalk	482	Kimberly Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	1	Poor		
PROW Sidewalk	487	Kings Row	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,760	1	Poor		
PROW Sidewalk	495	Lakey St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,300	1	Poor		
PROW Sidewalk	509	Lillian B Miller Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,090	1	Poor		
PROW Sidewalk	512	Linden Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	1	Poor		
PROW Sidewalk	527	Londonderry Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,140	1	Poor		
PROW Sidewalk	530	Longmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,270	1	Poor		
PROW Sidewalk	531	Longridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,440	1	Poor		
PROW Sidewalk	544	Malone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,430	1	Poor		
PROW Sidewalk	549	Maple St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,340	1	Poor		
PROW Sidewalk	558	Marietta St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,520	1	Poor		
PROW Sidewalk	581	E McKinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,950	1	Poor		
PROW Sidewalk	586	Meadow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,180	1	Poor		
PROW Sidewalk	599	Metro St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,020	1	Poor		
PROW Sidewalk	602	Mill St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,180	1	Poor		
PROW Sidewalk	631	Mounts Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,860	1	Poor		
PROW Sidewalk	635	W Mulberry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,610	1	Poor		
PROW Sidewalk	655	Nottingham Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 790	1	Poor		
PROW Sidewalk	660	W Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,840	1	Poor		
PROW Sidewalk	672	Oakshire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 27,500	1	Poor		
PROW Sidewalk	676	Old Alton Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,800	1	Poor		
PROW Sidewalk	682	Old North Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	1	Poor		
PROW Sidewalk	683	Old Orchard Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,290	1	Poor		
PROW Sidewalk	699	Panhandle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,880	1	Poor		
PROW Sidewalk	704	W Parkway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,990	1	Poor		
PROW Sidewalk	705	Parvin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,780	1	Poor		
PROW Sidewalk	712	Pear Tree Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,450	1	Poor		
PROW Sidewalk	722	Pheasant Hollow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,770	1	Poor		
PROW Sidewalk	739	Ponder Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,280	1	Poor		
PROW Sidewalk	742	E Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,350	1	Poor		
PROW Sidewalk	744	W Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,610	1	Poor		
PROW Sidewalk	767	Regal Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 910	1	Poor		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	774	Robbie-O St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,830	1	Poor		
PROW Sidewalk	775	Roberts St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,980	1	Poor		
PROW Sidewalk	789	N Ruddell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,120	1	Poor		
PROW Sidewalk	796	Sadaw Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,700	1	Poor		
PROW Sidewalk	798	Sagewood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,880	1	Poor		
PROW Sidewalk	815	Schuyler St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,720	1	Poor		
PROW Sidewalk	817	Scripture St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,310	1	Poor		
PROW Sidewalk	821	Seminole Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,980	1	Poor		
PROW Sidewalk	824	Shadow Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,750	1	Poor		
PROW Sidewalk	845	Sombre Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,140	1	Poor		
PROW Sidewalk	847	Southridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,860	1	Poor		
PROW Sidewalk	848	Spencer Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,070	1	Poor		
PROW Sidewalk	860	Stuart Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,060	1	Poor		
PROW Sidewalk	871	W Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,780	1	Poor		
PROW Sidewalk	891	Thunderbird Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,730	1	Poor		
PROW Sidewalk	895	Titan Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,840	1	Poor		
PROW Sidewalk	910	Twilight Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 900	1	Poor		
PROW Sidewalk	925	Vine St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,040	1	Poor		
PROW Sidewalk	927	Wainwright St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,380	1	Poor		
PROW Sidewalk	929	W Walnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,560	1	Poor		
PROW Sidewalk	930	Warren Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	1	Poor		
PROW Sidewalk	956	Whitney Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,600	1	Poor		
PROW Sidewalk	963	Willow Stone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,770	1	Poor		
PROW Sidewalk	975	E Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,860	1	Poor		
PROW Sidewalk	976	W Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,860	1	Poor		
PROW Sidewalk	986	N Wood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,240	1	Poor		
PROW Sidewalk	993	Woodland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,280	1	Poor		
PROW Sidewalk	997	S Woodrow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,840	1	Poor		
PROW Sidewalk	1000	Worthington Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,070	1	Poor		
PROW Sidewalk	1002	Yellowstone Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,990	1	Poor		
PROW Sidewalk	1021	Deerwood Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,350	1	Poor		
PROW Sidewalk	1030	Royal Oaks Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,300	1	Poor		
PROW Sidewalk	1033	Wellington Oaks Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,140	1	Poor		
PROW Sidewalk	1046	Saints Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,300	1	Poor		
PROW Sidewalk	1050	Cumberland Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,510	1	Poor		
PROW Sidewalk	1051	Shenandoah Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,660	1	Poor		
PROW Sidewalk	1052	Charleston Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	1	Poor		
PROW Sidewalk	1054	Richmond Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,760	1	Poor		
PROW Sidewalk	1055	Natchez Trace	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,440	1	Poor		
PROW Sidewalk	1131	Brinker Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,020	1	Poor		
PROW Sidewalk	1177	Balboa Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,820	1	Poor		
PROW Sidewalk	1178	Lido Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,740	1	Poor		
PROW Sidewalk	1180	Stone Mountain Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,300	1	Poor		
PROW Sidewalk	1194	Remington St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,370	1	Poor		
PROW Sidewalk	1201	Chateau Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,720	1	Poor		
PROW Sidewalk	1209	Huron Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,490	1	Poor		
PROW Sidewalk	1210	Wind River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,380	1	Poor		
PROW Sidewalk	1315	Bent Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,340	1	Poor		
PROW Sidewalk	1316	Springcreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,440	1	Poor		
PROW Sidewalk	1317	Creekbend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 820	1	Poor		
PROW Sidewalk	1318	Beechwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 28,210	1	Poor		
PROW Sidewalk	1321	Monte Carlo Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,620	1	Poor		
PROW Sidewalk	1333	Cape Hatteras Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,050	1	Poor		
PROW Sidewalk	1334	W El Paseo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,180	1	Poor		
PROW Sidewalk	1335	Le Sage Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,310	1	Poor		
PROW Sidewalk	1343	Heights Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,160	1	Poor		
PROW Sidewalk	1347	San Felipe Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,110	1	Poor		
PROW Sidewalk	1352	Greenbend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,150	1	Poor		
PROW Sidewalk	1353	Wintercreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,190	1	Poor		
PROW Sidewalk	1361	Great Bear Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,920	1	Poor		
PROW Sidewalk	1363	Ottawa Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,190	1	Poor		
PROW Sidewalk	1367	Champlain Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,300	1	Poor		
PROW Sidewalk	1368	St. Johns Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,240	1	Poor		
PROW Sidewalk	1375	Stanford Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,830	1	Poor		
PROW Sidewalk	1376	Centenary Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,970	1	Poor		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1377	Harvard Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,430	1	Poor		
PROW Sidewalk	1399	White Dove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,740	1	Poor		
PROW Sidewalk	1405	Cherry Tree Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,330	1	Poor		
PROW Sidewalk	1409	Serenity Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,720	1	Poor		
PROW Sidewalk	1411	Glen Falls Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,950	1	Poor		
PROW Sidewalk	1420	Bent Oaks Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	1	Poor		
PROW Sidewalk	1421	Briary Trace Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,700	1	Poor		
PROW Sidewalk	1426	Lakeview Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 750	1	Poor		
PROW Sidewalk	1441	Crenshaw Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,970	1	Poor		
PROW Sidewalk	1443	Palmetto Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,330	1	Poor		
PROW Sidewalk	1508	Savage Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,770	1	Poor		
PROW Sidewalk	1509	Cruise St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,270	1	Poor		
PROW Sidewalk	1510	Dixon Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,370	1	Poor		
PROW Sidewalk	1522	Dayspring Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,540	1	Poor		
PROW Sidewalk	1591	Constantina Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,880	1	Poor		
PROW Sidewalk	1593	Briar Forest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,370	1	Poor		
PROW Sidewalk	1613	Nautical Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,160	1	Poor		
PROW Sidewalk	1618	Provence Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,180	1	Poor		
PROW Sidewalk	1622	Alsace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,750	1	Poor		
PROW Sidewalk	1623	Napa Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,510	1	Poor		
PROW Sidewalk	1671	Hudsonwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 310	1	Poor		
PROW Sidewalk	1711	Waters Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 970	1	Poor		
PROW Sidewalk	1748	Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,180	1	Poor		
PROW Sidewalk	1749	Friesian Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,470	1	Poor		
PROW Sidewalk	1753	Tennessee Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,130	1	Poor		
PROW Sidewalk	1766	Tristan Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,210	1	Poor		
PROW Sidewalk	1804	Thoroughbred Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,330	1	Poor		
PROW Sidewalk	1878	Union Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,300	1	Poor		
PROW Sidewalk	1880	Shelby Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,270	1	Poor		
PROW Sidewalk	1888	Saddle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	1	Poor		
PROW Sidewalk	1915	Eagle Mountain Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,060	1	Poor		
Building	1	Airport Control Tower	1	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Building	2	Airport LESA	1	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 405	5	Medium		
Building	2	Airport LESA	7	The door is equipped with both a closer and a latch and there is no latch side clearance.	\$ 473	5	Medium		
Building	3	Airport Terminal and Admin Building	9	There are no accessible tables.	\$ 1,013	5	Medium		
Building	3	Airport Terminal and Admin Building	10	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Building	3	Airport Terminal and Admin Building	17	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 743	5	Medium		
Building	3	Airport Terminal and Admin Building	18	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 743	5	Medium		
Building	3	Airport Terminal and Admin Building	32	There are no accessible tables.	\$ 1,013	5	Medium		
Building	3	Airport Terminal and Admin Building	34	There is no assistive listening system in the assembly area.	\$ 3,375	5	Medium		
Building	3	Airport Terminal and Admin Building	38	The door does not have a compliant maneuvering clearance.	\$ 3,375	5	Medium		
Building	3	Airport Terminal and Admin Building	41	The door does not have a compliant maneuvering clearance.	\$ 3,375	5	Medium		
Building	5	American Legion Hall Senior Center	15	The threshold is greater than 1/2 inch high. The threshold at a doorway shall be no higher than 1/2 inch. Changes in level between 1/4 inch and 1/2 inch must be beveled at 1:2 or less. 1/4 inch is the maximum vertical rise.	\$ 675	5	Medium		
Building	5	American Legion Hall Senior Center	24	The landing at the entrance doors exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	5	American Legion Hall Senior Center	25	The landing at the entrance doors exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	5	American Legion Hall Senior Center	33	The vision light panels (glazing/window) exceed height requirements.	\$ 4,050	5	Medium		
Building	5	American Legion Hall Senior Center	34	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	5	American Legion Hall Senior Center	35	The door contains horizontal and/or vertical joints on the first 10 inches of the bottom of the door that are greater than 1/16 inches.	\$ 2,025	5	Medium		
Building	5	American Legion Hall Senior Center	36	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	5	American Legion Hall Senior Center	37	The door contains horizontal and/or vertical joints on the first 10 inches of the bottom of the door that are greater than 1/16 inches.	\$ 1,013	5	Medium		
Building	5	American Legion Hall Senior Center	38	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	5	American Legion Hall Senior Center	40	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	5	American Legion Hall Senior Center	49	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	5	American Legion Hall Senior Center	58	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	6	Monsignor King Outreach Center	11	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	6	Monsignor King Outreach Center	24	The maneuvering clearance at the entrance door has a 6.5 percent slope.	\$ 3,375	5	Medium		
Building	6	Monsignor King Outreach Center	27	The transaction counter is too high at 42-1/4 inches.	\$ 2,700	5	Medium		
Building	6	Monsignor King Outreach Center	28	The door is equipped with both a closer and a latch and there is no latch side clearance.	\$ 2,025	5	Medium		
Building	6	Monsignor King Outreach Center	29	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	6	Monsignor King Outreach Center	34	The door is equipped with knob style door hardware requiring grasping and twisting to operate.	\$ 506	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	6	Monsignor King Outreach Center	35	The door operating hardware to the laundry room is not accessible.	\$ 506	5	Medium		
Building	6	Monsignor King Outreach Center	36	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	6	Monsignor King Outreach Center	45	The threshold has a vertical change greater than 1/4 inch.	\$ 675	5	Medium		
Building	6	Monsignor King Outreach Center	46	The threshold has a vertical change greater than 1/4 inch.	\$ 675	5	Medium		
Building	6	Monsignor King Outreach Center	47	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	6	Monsignor King Outreach Center	48	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	6	Monsignor King Outreach Center	49	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	6	Monsignor King Outreach Center	60	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	7	Center for Visual Arts	2	The striping and markings for the accessible parking stalls access aisle are dilapidated and in need of repair.	\$ 405	5	Medium		
Building	7	Center for Visual Arts	19	The landing at the entrance doors exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	7	Center for Visual Arts	26	The landing at the entrance doors exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	7	Center for Visual Arts	27	The threshold is greater than 1/2 inch high.	\$ 1,013	5	Medium		
Building	7	Center for Visual Arts	31	There is no accessible route to the stage.	\$ 3,375	5	Medium		
Building	7	Center for Visual Arts	34	There is no assistive listening system in the assembly area.	\$ 3,375	5	Medium		
Building	7	Center for Visual Arts	35	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	7	Center for Visual Arts	41	The door closer is less than 78 inches off the finished floor.	\$ 743	5	Medium		
Building	7	Center for Visual Arts	42	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	7	Center for Visual Arts	43	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	7	Center for Visual Arts	49	The door closer is less than 78 inches off the finished floor.	\$ 743	5	Medium		
Building	7	Center for Visual Arts	50	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	7	Center for Visual Arts	51	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	7	Center for Visual Arts	55	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	7	Center for Visual Arts	56	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	7	Center for Visual Arts	57	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	7	Center for Visual Arts	63	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	7	Center for Visual Arts	67	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	7	Center for Visual Arts	78	The door operating hardware is not accessible.	\$ 1,013	5	Medium		
Building	7	Center for Visual Arts	79	The door operating hardware exceeds maximum height requirements.	\$ 506	5	Medium		
Building	7	Center for Visual Arts	80	The door operating hardware exceeds maximum height requirements.	\$ 506	5	Medium		
Building	7	Center for Visual Arts	81	The door closer is less than 78 inches off the finished floor.	\$ 743	5	Medium		
Building	7	Center for Visual Arts	82	The door closer is less than 78 inches off the finished floor.	\$ 743	5	Medium		
Building	7	Center for Visual Arts	83	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	7	Center for Visual Arts	84	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	7	Center for Visual Arts	85	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	7	Center for Visual Arts	87	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	7	Center for Visual Arts	96	The door operating hardware exceeds maximum height requirements.	\$ 506	5	Medium		
Building	7	Center for Visual Arts	99	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	7	Center for Visual Arts	103	The door operating hardware is not accessible.	\$ 1,519	5	Medium		
Building	8	City Hall	4	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 405	5	Medium		
Building	8	City Hall	26	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	8	City Hall	27	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	8	City Hall	44	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	8	City Hall	53	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	8	City Hall	56	The counter is too high.	\$ 2,700	5	Medium		
Building	8	City Hall	57	There are no accessible work surfaces.	\$ 1,013	5	Medium		
Building	8	City Hall	58	The door operating hardware is not accessible.	\$ 2,025	5	Medium		
Building	8	City Hall	59	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	8	City Hall	63	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	8	City Hall	65	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	8	City Hall	77	The door does not open at least 90 degrees.	\$ 2,025	5	Medium		
Building	8	City Hall	79	The maneuvering clearance on the pull side of the door is obstructed.	\$ 3,375	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	9	City Hall East (Municipal Complex)	22	<p>The utility payment kiosk does not comply with current Federal or State standards for one or more of the following:</p> <p>Unless a clear or correct key is provided each operable part shall be able to be differentiated by sound or touch without activation. Machines shall be speech enabled. Operating instructions and orientation visible transaction prompts user input verification error messages and all displayed information for full use shall be accessible to and independently usable by individuals with vision impairments. Speech shall be delivered through a mechanism that is readily available to all users including but not limited to an industry standard connector or a telephone handset. Speech shall be recorded or digitized human or synthesized. Speech shall be capable of being repeated or interrupted. Volume control shall be provided for the speech function.</p> <p>At least one tactilely discernible input control shall be provided for each function. Where provided key surfaces not on active areas of display screens shall be raised above surrounding surfaces. Where membrane keys are the only method of input each shall be tactilely discernible from surrounding surfaces and adjacent keys.</p> <p>Numeric keys shall be arranged in a 12-key ascending or descending telephone keypad layout. The number five key shall be tactilely distinct from the other keys.</p> <p>Function keys shall contrast visually from background surfaces Characters and symbols on key surfaces shall contrast visually from key surfaces. Visual contrast shall be either light-on-dark or dark-on-light.</p> <p>Function key surfaces shall have tactile symbols as follows: Enter or Proceed key: raised circle; Clear or Correct key: raised left arrow; Cancel key: raised letter ex; Add Value key: raised plus sign; Decrease Value key: raised minus sign.</p>	\$ 10,800	5	Medium		
Building	9	City Hall East (Municipal Complex)	51	The counter is too high.	\$ 2,700	5	Medium		
Building	9	City Hall East (Municipal Complex)	56	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	9	City Hall East (Municipal Complex)	65	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	9	City Hall East (Municipal Complex)	66	The door operating hardware exceeds maximum height requirements.	\$ 506	5	Medium		
Building	9	City Hall East (Municipal Complex)	67	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	9	City Hall East (Municipal Complex)	83	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	9	City Hall East (Municipal Complex)	84	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 1,013	5	Medium		
Building	9	City Hall East (Municipal Complex)	94	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	9	City Hall East (Municipal Complex)	95	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	9	City Hall East (Municipal Complex)	100	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	9	City Hall East (Municipal Complex)	105	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	9	City Hall East (Municipal Complex)	108	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	9	City Hall East (Municipal Complex)	114	There is a step up required to access the jury box.	\$ 1,080	5	Medium		
Building	9	City Hall East (Municipal Complex)	116	There are 2 steps required for access to the witness stand.	\$ 1,080	5	Medium		
Building	9	City Hall East (Municipal Complex)	118	There is no assistive listening system in the court room.	\$ 3,375	5	Medium		
Building	9	City Hall East (Municipal Complex)	119	There are no wheelchair seating spaces provided.	\$ 2,025	5	Medium		
Building	9	City Hall East (Municipal Complex)	120	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	9	City Hall East (Municipal Complex)	125	The top rim of the lavatory is too high.	\$ 2,700	5	Medium		
Building	9	City Hall East (Municipal Complex)	128	The top rim of the lavatory is too high.	\$ 2,700	5	Medium		
Building	9	City Hall East (Municipal Complex)	132	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	5	Medium		
Building	9	City Hall East (Municipal Complex)	141	There is no assistive listening system in the assembly area.	\$ 2,025	5	Medium		
Building	9	City Hall East (Municipal Complex)	142	There is no assistive listening system in the assembly area.	\$ 2,025	5	Medium		
Building	9	City Hall East (Municipal Complex)	143	There is no assistive listening system in the assembly area.	\$ 2,025	5	Medium		
Building	9	City Hall East (Municipal Complex)	144	There is no assistive listening system in the assembly area.	\$ 2,025	5	Medium		
Building	9	City Hall East (Municipal Complex)	147	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	9	City Hall East (Municipal Complex)	150	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	11	Civic Center	14	The access aisle is not a minimum 5 feet wide.	\$ 405	5	Medium		
Building	11	Civic Center	15	The accessible parking stall is not wide enough.	\$ 405	5	Medium		
Building	11	Civic Center	29	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	11	Civic Center	35	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	11	Civic Center	41	The maneuvering clearance at the door is less than 42 inches perpendicular to the door.	\$ 4,725	5	Medium		
Building	11	Civic Center	42	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	11	Civic Center	43	There is no assistive listening system in the assembly area.	\$ 3,375	5	Medium		
Building	11	Civic Center	47	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375	5	Medium		
Building	11	Civic Center	49	The doors have a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	11	Civic Center	72	The door does not open at least 90 degrees.	\$ 675	5	Medium		
Building	11	Civic Center	73	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	11	Civic Center	74	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	11	Civic Center	75	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	11	Civic Center	76	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	11	Civic Center	80	The maneuvering clearance on the pull side of the door is obstructed.	\$ 338	5	Medium		
Building	11	Civic Center	82	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	11	Civic Center	85	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	12	Civic Center Pool	8	At the time of the evaluation the lift had no power and could not be operated or tested.	\$ 2,025	5	Medium		
Building	12	Civic Center Pool	19	There is no accessible route to the tables.	\$ 2,025	5	Medium		
Building	12	Civic Center Pool	20	There is no accessible route to the table.	\$ 2,025	5	Medium		
Building	12	Civic Center Pool	33	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Building	12	Civic Center Pool	37	The door does not have a compliant maneuvering clearance.	\$ 2,025	5	Medium		
Building	12	Civic Center Pool	47	The bench is not deep enough.	\$ 1,013	5	Medium		
Building	12	Civic Center Pool	57	The bench in the changing stalls are not deep enough.	\$ 1,013	5	Medium		
Building	12	Civic Center Pool	61	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	12	Civic Center Pool	67	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	12	Civic Center Pool	68	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	12	Civic Center Pool	69	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	12	Civic Center Pool	75	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	13	Denia Recreation Center	1	The accessible parking stall is not wide enough.	\$ 675	5	Medium		
Building	13	Denia Recreation Center	15	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	13	Denia Recreation Center	16	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	13	Denia Recreation Center	27	The doors have a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	13	Denia Recreation Center	29	The vision light panels exceed height requirements.	\$ 3,038	5	Medium		
Building	13	Denia Recreation Center	31	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	13	Denia Recreation Center	38	The maneuvering clearance at the door is obstructed.	\$ 473	5	Medium		
Building	13	Denia Recreation Center	47	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	13	Denia Recreation Center	48	The doors have a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	13	Denia Recreation Center	49	The vision light panels exceed height requirements.	\$ 2,025	5	Medium		
Building	13	Denia Recreation Center	50	The exercise machine or equipment does not provide compliant clear floor space for transfer.	\$ 3,375	5	Medium		
Building	13	Denia Recreation Center	55	The vision light panels exceed height requirements.	\$ 1,013	5	Medium		
Building	13	Denia Recreation Center	56	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 5,130	5	Medium		
Building	13	Denia Recreation Center	57	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	13	Denia Recreation Center	58	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	13	Denia Recreation Center	59	The doors have a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	13	Denia Recreation Center	61	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	13	Denia Recreation Center	62	The vision light panels exceed height requirements.	\$ 1,013	5	Medium		
Building	14	Denton Development Center	4	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,013	5	Medium		
Building	14	Denton Development Center	5	The stair risers are not the correct height.	\$ 2,025	5	Medium		
Building	14	Denton Development Center	6	The stair risers are not uniform in height.	\$ -	5	Medium		
Building	14	Denton Development Center	36	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	15	Denton Energy Center	7	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	15	Denton Energy Center	8	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	15	Denton Energy Center	15	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	15	Denton Energy Center	18	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	15	Denton Energy Center	20	The threshold has a vertical change greater than 1/4 inch.	\$ 675	5	Medium		
Building	15	Denton Energy Center	21	The threshold has a vertical change greater than 1/4 inch.	\$ 675	5	Medium		
Building	16	Denton Senior Center	9	The access aisle is not a minimum 5 feet wide.	\$ 675	5	Medium		
Building	16	Denton Senior Center	17	The access aisle is not a minimum 5 feet wide.	\$ 675	5	Medium		
Building	16	Denton Senior Center	46	The access aisle is not a minimum 5 feet wide.	\$ 675	5	Medium		
Building	16	Denton Senior Center	47	The striping and markings for the accessible parking stalls loading/unloading access aisle are dilapidated and in need of repair and/or maintenance.	\$ 675	5	Medium		
Building	16	Denton Senior Center	54	The handrails do not meet minimum height requirements.	\$ 2,025	5	Medium		
Building	16	Denton Senior Center	57	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	16	Denton Senior Center	58	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	16	Denton Senior Center	62	There is no accessible route to the putting green.	\$ 2,025	5	Medium		
Building	16	Denton Senior Center	68	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 743	5	Medium		
Building	16	Denton Senior Center	85	There are no accessible tables.	\$ 1,013	5	Medium		
Building	16	Denton Senior Center	86	There are no accessible tables.	\$ 1,013	5	Medium		
Building	16	Denton Senior Center	107	The maneuvering clearance at the door is obstructed by the bench.	\$ 338	5	Medium		
Building	16	Denton Senior Center	108	The exercise machine or equipment does not provide compliant clear floor space for transfer. Exercise machines and equipment shall have a clear floor space positioned for transfer or for use by an individual seated in a wheelchair. Clear floor or ground spaces required at exercise machines and equipment is be permitted to overlap.	\$ 2,025	5	Medium		
Building	16	Denton Senior Center	111	There are no accessible work surfaces.	\$ 1,013	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	16	Denton Senior Center	112	The door operating hardware is not accessible.	\$ 1,013	5	Medium		
Building	16	Denton Senior Center	115	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	16	Denton Senior Center	120	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	16	Denton Senior Center	138	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 1,013	5	Medium		
Building	16	Denton Senior Center	139	The door operating hardware is not accessible.	\$ 1,519	5	Medium		
Building	16	Denton Senior Center	147	The door operating hardware is not accessible.	\$ 2,025	5	Medium		
Building	16	Denton Senior Center	148	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	16	Denton Senior Center	150	The maneuvering clearance at the door is obstructed.	\$ 1,013	5	Medium		
Building	16	Denton Senior Center	151	There are no accessible work surfaces.	\$ 1,013	5	Medium		
Building	20	Electric Administration Building	3	The threshold is greater than 1/2 inch high.	\$ 2,025	5	Medium		
Building	20	Electric Administration Building	5	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	20	Electric Administration Building	6	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	20	Electric Administration Building	9	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	20	Electric Administration Building	13	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	20	Electric Administration Building	14	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	20	Electric Administration Building	27	The maneuvering clearance on the pull side of the door is obstructed.	\$ 1,013	5	Medium		
Building	20	Electric Administration Building	28	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	20	Electric Administration Building	32	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 1,013	5	Medium		
Building	21	Emily Fowler Library	13	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	21	Emily Fowler Library	20	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	21	Emily Fowler Library	21	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	21	Emily Fowler Library	38	The AED device projects into the headroom clearance in the circulation path.	\$ 473	5	Medium		
Building	21	Emily Fowler Library	46	There is no assistive listening system in the assembly area.	\$ 3,375	5	Medium		
Building	22	Engineering and Systems Operations	1	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 675	5	Medium		
Building	22	Engineering and Systems Operations	4	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	23	Facilities Management	13	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	23	Facilities Management	14	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	23	Facilities Management	15	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	23	Facilities Management	18	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	23	Facilities Management	22	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	23	Facilities Management	35	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	23	Facilities Management	36	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	23	Facilities Management	37	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	23	Facilities Management	42	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	23	Facilities Management	43	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	26	Fire Station #2	18	The maneuvering clearance on the pull side of the door is obstructed.	\$ 2,025	5	Medium		
Building	26	Fire Station #2	20	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	27	Fire Station #3	3	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 405	5	Medium		
Building	27	Fire Station #3	8	The door bell is positioned too high for either a side or front approach.	\$ 338	5	Medium		
Building	28	Fire Station #4	15	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	28	Fire Station #4	22	The door exceeds the maximum pressure to open the door.	\$ 338	5	Medium		
Building	28	Fire Station #4	23	The maneuvering clearance on the pull side of the door is obstructed.	\$ 2,025	5	Medium		
Building	29	Fire Station #5	7	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	29	Fire Station #5	13	The maneuvering clearance at the door exceeds a 2 percent slope.	\$ 2,025	5	Medium		
Building	29	Fire Station #5	14	The door operating hardware exceeds maximum height requirements.	\$ 1,013	5	Medium		
Building	29	Fire Station #5	16	The door operating hardware is not accessible.	\$ 1,013	5	Medium		
Building	29	Fire Station #5	17	The door closer is less than 78 inches off the finished floor.	\$ 675	5	Medium		
Building	29	Fire Station #5	18	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	29	Fire Station #5	24	The door closer is less than 78 inches off the finished floor.	\$ 675	5	Medium		
Building	29	Fire Station #5	28	The door is equipped with knob style door hardware requiring grasping and twisting to operate.	\$ 506	5	Medium		
Building	29	Fire Station #5	30	The threshold has a vertical change greater than 1/4 inch.	\$ 675	5	Medium		
Building	29	Fire Station #5	37	The door is equipped with knob style door hardware requiring grasping and twisting to operate.	\$ 506	5	Medium		
Building	29	Fire Station #5	39	The door closer is less than 78 inches off the finished floor.	\$ 743	5	Medium		
Building	29	Fire Station #5	41	The threshold has a vertical change greater than 1/4 inch.	\$ 675	5	Medium		
Building	29	Fire Station #5	42	The door is equipped with knob style door hardware requiring grasping and twisting to operate.	\$ 506	5	Medium		
Building	29	Fire Station #5	44	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	29	Fire Station #5	45	The door is equipped with knob style door hardware requiring grasping and twisting to operate.	\$ 506	5	Medium		
Building	29	Fire Station #5	46	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	29	Fire Station #5	48	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	29	Fire Station #5	49	The maneuvering clearance at the door exceeds 2 percent slope.	\$ -	5	Medium		
Building	29	Fire Station #5	52	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	29	Fire Station #5	53	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	29	Fire Station #5	54	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	29	Fire Station #5	55	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	30	Fire Station #6	4	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	30	Fire Station #6	20	The door closer is less than 78 inches off the finished floor.	\$ 743	5	Medium		
Building	30	Fire Station #6	21	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	30	Fire Station #6	23	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	30	Fire Station #6	25	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	30	Fire Station #6	26	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	30	Fire Station #6	27	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	30	Fire Station #6	28	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	30	Fire Station #6	30	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	30	Fire Station #6	33	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	30	Fire Station #6	35	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	30	Fire Station #6	36	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	30	Fire Station #6	38	The maneuvering clearance on the pull side of the door extends less than 18 inches on the latch side.	\$ 3,375	5	Medium		
Building	30	Fire Station #6	42	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	30	Fire Station #6	46	The maneuvering clearance on the pull side of the door extends less than 18 inches on the latch side.	\$ 3,375	5	Medium		
Building	30	Fire Station #6	47	The maneuvering clearance on the pull side of the door extends less than 18 inches on the latch side.	\$ 3,375	5	Medium		
Building	30	Fire Station #6	48	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	31	Fire Station #7	2	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	31	Fire Station #7	3	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	31	Fire Station #7	10	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	31	Fire Station #7	19	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	31	Fire Station #7	20	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	31	Fire Station #7	21	The maneuvering clearance at the door is obstructed.	\$ 675	5	Medium		
Building	32	Fire Station #8	12	The maneuvering clearance at the door is obstructed.	\$ 1,013	5	Medium		
Building	32	Fire Station #8	13	The maneuvering clearance at the door is obstructed.	\$ 1,013	5	Medium		
Building	32	Fire Station #8	14	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 1,013	5	Medium		
Building	33	Fire Station Annex (Old #4)	3	The striping for the access aisle is dilapidated.	\$ 405	5	Medium		
Building	33	Fire Station Annex (Old #4)	6	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	33	Fire Station Annex (Old #4)	8	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	33	Fire Station Annex (Old #4)	11	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	34	Fleet Service Center	4	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	34	Fleet Service Center	8	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 1,350	5	Medium		
Building	34	Fleet Service Center	9	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	34	Fleet Service Center	15	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	34	Fleet Service Center	17	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	34	Fleet Service Center	19	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	34	Fleet Service Center	25	The counter is too high.	\$ 2,700	5	Medium		
Building	35	Household Hazardous Waste Building	3	The work surface is not within the allowable range.	\$ 1,013	5	Medium		
Building	35	Household Hazardous Waste Building	7	The maneuvering clearance at the door is obstructed.	\$ 675	5	Medium		
Building	36	Landfill Weigh Station	1	The transaction counter is too high.	\$ 3,375	5	Medium		
Building	36	Landfill Weigh Station	3	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	36	Landfill Weigh Station	7	The maneuvering clearance on the pull side of the door is obstructed.	\$ 2,025	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	2	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 405	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	5	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	6	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	7	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	11	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	14	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	18	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	19	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	20	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	21	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	31	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	32	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	39	The maneuvering clearance perpendicular to the door is less than 42 inches.	\$ -	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	44	The maneuvering clearance perpendicular to the door is less than 42 inches.	\$ 5,130	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	45	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 2,025	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	49	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	52	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	38	LL WTP - Blower Building	1	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	39	LL WTP - Maintenance Building	4	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	40	LL WTP - Operations Building	2	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	40	LL WTP - Operations Building	8	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	40	LL WTP - Operations Building	10	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	40	LL WTP - Operations Building	11	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	40	LL WTP - Operations Building	12	The maneuvering space between the two doors in the vestibule is noncompliant.	\$ 3,375	5	Medium		
Building	40	LL WTP - Operations Building	13	The vision light panels (glazing/window) exceed height requirements.	\$ 11,138	5	Medium		
Building	40	LL WTP - Operations Building	23	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,013	5	Medium		
Building	40	LL WTP - Operations Building	32	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	41	LL WTP - Ozone Generator Building	1	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	41	LL WTP - Ozone Generator Building	3	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	42	LRR WTP - Admin Building	1	The accessible parking stall is not wide enough.	\$ 405	5	Medium		
Building	42	LRR WTP - Admin Building	10	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	42	LRR WTP - Admin Building	11	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	42	LRR WTP - Admin Building	20	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	42	LRR WTP - Admin Building	50	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	42	LRR WTP - Admin Building	57	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 2,025	5	Medium		
Building	43	LRR WTP - Ozone Generation Building	1	The threshold is greater than 1/2 inch high.	\$ 2,025	5	Medium		
Building	43	LRR WTP - Ozone Generation Building	6	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	43	LRR WTP - Ozone Generation Building	7	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	44	Master Recycling Services - Building 101	2	The striping and markings for the accessible parking stalls loading/unloading access aisle are dilapidated and in need of repair or maintenance.	\$ 405	5	Medium		
Building	44	Master Recycling Services - Building 101	4	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	45	Metering Pit	1	The door is equipped with knob style door hardware requiring grasping and twisting to operate.	\$ 1,013	5	Medium		
Building	46	MLK Jr Recreation Center	10	There are no accessible tables.	\$ 1,013	5	Medium		
Building	46	MLK Jr Recreation Center	11	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	46	MLK Jr Recreation Center	12	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	46	MLK Jr Recreation Center	15	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	46	MLK Jr Recreation Center	31	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	46	MLK Jr Recreation Center	35	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	46	MLK Jr Recreation Center	43	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	46	MLK Jr Recreation Center	47	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	46	MLK Jr Recreation Center	48	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	46	MLK Jr Recreation Center	49	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	46	MLK Jr Recreation Center	50	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	46	MLK Jr Recreation Center	54	The transaction counter is too high.	\$ 3,375	5	Medium		
Building	46	MLK Jr Recreation Center	58	The doors have a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	46	MLK Jr Recreation Center	59	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	46	MLK Jr Recreation Center	64	The bench is not deep enough.	\$ 1,013	5	Medium		
Building	46	MLK Jr Recreation Center	65	Accessible lockers are not provided.	\$ 2,025	5	Medium		
Building	46	MLK Jr Recreation Center	74	The bench is not deep enough.	\$ 1,013	5	Medium		
Building	46	MLK Jr Recreation Center	75	Accessible lockers are not provided.	\$ 2,025	5	Medium		
Building	46	MLK Jr Recreation Center	89	The maneuvering clearance on the pull side of the door is obstructed.	\$ 3,375	5	Medium		
Building	46	MLK Jr Recreation Center	96	The maneuvering clearance on the pull side of the door is obstructed.	\$ 3,375	5	Medium		
Building	46	MLK Jr Recreation Center	97	The counter is too high.	\$ 2,700	5	Medium		
Building	46	MLK Jr Recreation Center	99	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	46	MLK Jr Recreation Center	102	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	46	MLK Jr Recreation Center	105	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	46	MLK Jr Recreation Center	107	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	46	MLK Jr Recreation Center	108	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	46	MLK Jr Recreation Center	109	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	46	MLK Jr Recreation Center	113	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	46	MLK Jr Recreation Center	114	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	46	MLK Jr Recreation Center	116	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	46	MLK Jr Recreation Center	117	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	46	MLK Jr Recreation Center	120	The counter is too high.	\$ 270	5	Medium		
Building	46	MLK Jr Recreation Center	122	The exercise machine or equipment does not provide compliant clear floor space for transfer.	\$ 3,375	5	Medium		
Building	46	MLK Jr Recreation Center	127	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375	5	Medium		
Building	46	MLK Jr Recreation Center	131	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	47	Natatorium	3	The access aisle is not a minimum 5 feet wide.	\$ 405	5	Medium		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	47	Natorium	6	The access aisle is not a minimum 5 feet wide.	\$ 405	5	Medium		
Building	47	Natorium	23	The power assist button was not operational at the time of evaluation.	\$ 2,025	5	Medium		
Building	47	Natorium	24	The transaction counter is too high.	\$ 1,013	5	Medium		
Building	47	Natorium	32	The swimming pool/spa lift cannot be operated unassisted.	\$ 4,050	5	Medium		
Building	47	Natorium	34	At the time of the evaluation the lift had no power and could not be operated or tested.	\$ 2,025	5	Medium		
Building	47	Natorium	35	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	47	Natorium	36	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	47	Natorium	37	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	47	Natorium	38	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	47	Natorium	49	Accessible lockers are not provided.	\$ 2,025	5	Medium		
Building	47	Natorium	53	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	47	Natorium	55	Accessible lockers are not provided.	\$ 2,025	5	Medium		
Building	47	Natorium	58	Accessible lockers are not provided.	\$ 2,025	5	Medium		
Building	47	Natorium	62	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	47	Natorium	64	Accessible lockers are not provided.	\$ 2,025	5	Medium		
Building	47	Natorium	71	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	47	Natorium	72	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	47	Natorium	73	The door does not open at least 90 degrees.	\$ 675	5	Medium		
Building	47	Natorium	74	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	47	Natorium	80	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	48	New Central Fire Station	8	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	48	New Central Fire Station	11	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	48	New Central Fire Station	35	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	48	New Central Fire Station	37	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	48	New Central Fire Station	48	The door does not open at least 90 degrees.	\$ 338	5	Medium		
Building	48	New Central Fire Station	87	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	48	New Central Fire Station	92	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	49	North Branch Library	6	The striping and markings for the access aisle is dilapidated and in need of repair.	\$ 405	5	Medium		
Building	49	North Branch Library	32	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	49	North Branch Library	47	The work surface is not within the allowable range.	\$ 1,013	5	Medium		
Building	49	North Branch Library	48	The work surface is not within the allowable range.	\$ 1,013	5	Medium		
Building	49	North Branch Library	49	The work surface is not within the allowable range.	\$ 1,013	5	Medium		
Building	49	North Branch Library	49	The library staff has designated this as the accessible catalog search station.					
Building	49	North Branch Library	56	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	49	North Branch Library	58	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	49	North Branch Library	59	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	49	North Branch Library	61	There is no assistive listening system in the assembly area.	\$ 3,375	5	Medium		
Building	49	North Branch Library	63	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	49	North Branch Library	64	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	49	North Branch Library	65	There is no assistive listening system in the assembly area.	\$ 3,375	5	Medium		
Building	49	North Branch Library	76	The maneuvering clearance at the door is obstructed by the trash can.	\$ 338	5	Medium		
Building	49	North Branch Library	83	The maneuvering clearance at the door is obstructed by the trash can.	\$ 338	5	Medium		
Building	49	North Branch Library	86	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	49	North Branch Library	89	The vision light panels (glazing/window) exceed height requirements.	\$ 10,125	5	Medium		
Building	50	North Lakes Annex	20	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	50	North Lakes Annex	21	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	50	North Lakes Annex	22	The landing at the entrance doors exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	50	North Lakes Annex	26	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	50	North Lakes Annex	27	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	50	North Lakes Annex	38	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	50	North Lakes Annex	40	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	50	North Lakes Annex	42	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	51	North Lakes Recreation Center	1	The access aisle is not a minimum 5 feet wide.	\$ 405	5	Medium		
Building	51	North Lakes Recreation Center	15	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	51	North Lakes Recreation Center	23	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	51	North Lakes Recreation Center	24	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	51	North Lakes Recreation Center	30	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	51	North Lakes Recreation Center	32	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	51	North Lakes Recreation Center	34	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	51	North Lakes Recreation Center	35	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	51	North Lakes Recreation Center	37	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	51	North Lakes Recreation Center	41	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	51	North Lakes Recreation Center	44	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	51	North Lakes Recreation Center	47	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	51	North Lakes Recreation Center	51	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	51	North Lakes Recreation Center	52	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 5,130	5	Medium		
Building	51	North Lakes Recreation Center	53	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	51	North Lakes Recreation Center	54	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	51	North Lakes Recreation Center	55	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	51	North Lakes Recreation Center	60	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	51	North Lakes Recreation Center	65	The bench is not deep enough.	\$ 1,013	5	Medium		
Building	51	North Lakes Recreation Center	66	Accessible lockers are not provided.	\$ 2,025	5	Medium		
Building	51	North Lakes Recreation Center	70	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 338	5	Medium		
Building	51	North Lakes Recreation Center	71	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	51	North Lakes Recreation Center	74	The bench is not deep enough.	\$ 1,013	5	Medium		
Building	51	North Lakes Recreation Center	75	Accessible lockers are not provided.	\$ 2,025	5	Medium		
Building	51	North Lakes Recreation Center	81	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	51	North Lakes Recreation Center	82	The required clear floor space is not wide enough.	\$ 1,013	5	Medium		
Building	51	North Lakes Recreation Center	86	There are no accessible tables.	\$ 1,013	5	Medium		
Building	51	North Lakes Recreation Center	88	The counter is too high.	\$ 2,700	5	Medium		
Building	51	North Lakes Recreation Center	89	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 338	5	Medium		
Building	52	PCRP - Administration	16	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	52	PCRP - Administration	17	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	52	PCRP - Administration	25	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375	5	Medium		
Building	52	PCRP - Administration	33	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375	5	Medium		
Building	52	PCRP - Administration	34	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	52	PCRP - Administration	35	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	52	PCRP - Administration	40	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	52	PCRP - Administration	41	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	52	PCRP - Administration	42	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	52	PCRP - Administration	43	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	52	PCRP - Administration	44	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	52	PCRP - Administration	45	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	52	PCRP - Administration	49	The door operating hardware is not accessible.	\$ 9,113	5	Medium		
Building	52	PCRP - Administration	52	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	52	PCRP - Administration	59	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375	5	Medium		
Building	52	PCRP - Administration	71	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	52	PCRP - Administration	72	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375	5	Medium		
Building	52	PCRP - Administration	74	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	52	PCRP - Administration	75	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	53	PCRP - Belt Press Building	4	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	54	PCRP - Beneficial Reuse Building	2	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	55	PCRP - Electronics Office	4	The threshold is greater than 1/2 inch high.	\$ 2,025	5	Medium		
Building	55	PCRP - Electronics Office	7	The threshold is greater than 1/2 inch high.	\$ 2,025	5	Medium		
Building	55	PCRP - Electronics Office	11	The door operating hardware is not accessible (3 doors).	\$ 1,519	5	Medium		
Building	55	PCRP - Electronics Office	13	The vision light panels (glazing/window) exceed height requirements (2 doors).	\$ 2,025	5	Medium		
Building	55	PCRP - Electronics Office	14	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	56	PCRP - New Administration Building	2	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 270	5	Medium		
Building	56	PCRP - New Administration Building	8	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	56	PCRP - New Administration Building	9	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	57	PCRP - Old Blower Building	2	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	57	PCRP - Old Blower Building	4	The maneuvering clearance at the door is obstructed.	\$ 3,375	5	Medium		
Building	58	PCRP - Operations Building	5	The door operating hardware is not accessible (2 doors).	\$ 1,013	5	Medium		
Building	58	PCRP - Operations Building	9	The vision light panels (glazing/window) exceed height requirements (2 doors).	\$ 2,025	5	Medium		
Building	58	PCRP - Operations Building	10	The vision light panels (glazing/window) exceed height requirements (2 doors).	\$ 2,025	5	Medium		
Building	58	PCRP - Operations Building	12	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 3,375	5	Medium		
Building	58	PCRP - Operations Building	13	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	59	PCRP - Pretreatment Building	12	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	59	PCRP - Pretreatment Building	13	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	59	PCRP - Pretreatment Building	14	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	61	Quebec Hangars	7	The striping and markings for the accessible parking stalls loading/unloading access aisle are dilapidated and in need of repair or maintenance.	\$ 338	5	Medium		
Building	61	Quebec Hangars	8	The access aisle is not a minimum 5 feet wide.	\$ -	5	Medium		
Building	61	Quebec Hangars	13	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Building	61	Quebec Hangars	14	The door does not have a compliant maneuvering clearance.	\$ 2,025	5	Medium		
Building	61	Quebec Hangars	15	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Building	61	Quebec Hangars	16	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Building	61	Quebec Hangars	17	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Building	61	Quebec Hangars	18	The door does not have a compliant maneuvering clearance.	\$ 2,025	5	Medium		
Building	61	Quebec Hangars	19	The door does not have a compliant maneuvering clearance.	\$ 2,025	5	Medium		
Building	61	Quebec Hangars	20	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Building	61	Quebec Hangars	24	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Building	61	Quebec Hangars	25	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Building	61	Quebec Hangars	26	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Building	61	Quebec Hangars	27	The door does not have a compliant maneuvering clearance.	\$ 2,025	5	Medium		
Building	61	Quebec Hangars	28	The door does not have a compliant maneuvering clearance.	\$ 2,025	5	Medium		
Building	62	Service Center	12	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	62	Service Center	13	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	62	Service Center	14	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	62	Service Center	15	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	62	Service Center	32	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	62	Service Center	50	The door operating hardware is not accessible.	\$ 1,013	5	Medium		
Building	62	Service Center	55	The door operating hardware is not accessible.	\$ 1,519	5	Medium		
Building	62	Service Center	59	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	62	Service Center	68	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	62	Service Center	69	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	62	Service Center	79	The door operating hardware is not accessible.	\$ 1,519	5	Medium		
Building	62	Service Center	84	The door operating hardware is not accessible.	\$ 3,038	5	Medium		
Building	62	Service Center	86	The door operating hardware is not accessible.	\$ 1,519	5	Medium		
Building	62	Service Center	87	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	62	Service Center	89	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	62	Service Center	90	The door operating hardware is not accessible.	\$ 1,013	5	Medium		
Building	62	Service Center	96	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Building	62	Service Center	101	The door operating hardware is not accessible.	\$ 3,038	5	Medium		
Building	62	Service Center	105	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	62	Service Center	111	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	62	Service Center	112	The door operating hardware is not accessible.	\$ 3,038	5	Medium		
Building	62	Service Center	121	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	62	Service Center	126	The door operating hardware is not accessible.	\$ 3,038	5	Medium		
Building	62	Service Center	127	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	5	Medium		
Building	62	Service Center	130	The door operating hardware is not accessible.	\$ 1,013	5	Medium		
Building	62	Service Center	131	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	5	Medium		
Building	62	Service Center	132	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	62	Service Center	133	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	64	Solid Waste Maintenance Building	1	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Building	65	Solid Waste Services Building	6	The maneuvering clearance on the pull side of the exterior door is obstructed.	\$ 2,025	5	Medium		
Building	65	Solid Waste Services Building	9	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Building	65	Solid Waste Services Building	17	There are no accessible tables.	\$ 1,013	5	Medium		
Building	65	Solid Waste Services Building	20	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	65	Solid Waste Services Building	22	The transaction counter is too high.	\$ 2,700	5	Medium		
Building	65	Solid Waste Services Building	28	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	65	Solid Waste Services Building	30	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	65	Solid Waste Services Building	32	The vision light panels (glazing/window) exceed height requirements (14 doors).	\$ 14,175	5	Medium		
Building	65	Solid Waste Services Building	33	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	65	Solid Waste Services Building	36	The vision light panels (glazing/window) exceed height requirements (2 doors).	\$ 2,025	5	Medium		
Building	65	Solid Waste Services Building	37	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	65	Solid Waste Services Building	39	The vision light panels (glazing/window) exceed height requirements (3 doors).	\$ 3,038	5	Medium		
Building	65	Solid Waste Services Building	48	The maneuvering clearance at the door is obstructed.	\$ 338	5	Medium		
Building	65	Solid Waste Services Building	55	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	66	South Branch Library	24	There are no accessible work surfaces.	\$ 1,013	5	Medium		
Building	66	South Branch Library	26	There is no accessible route to the puppet theater.	\$ 1,013	5	Medium		
Building	66	South Branch Library	27	The maneuvering clearance at the door is less than 42 inches perpendicular to the door.	\$ 5,130	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	66	South Branch Library	31	There is no assistive listening system in the assembly area.	\$ 3,375	5	Medium		
Building	66	South Branch Library	35	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	66	South Branch Library	39	The door exceeds the maximum allowable opening force.	\$ 338	5	Medium		
Building	66	South Branch Library	48	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 1,013	5	Medium		
Building	67	SW Triple Wide	1	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	67	SW Triple Wide	9	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	67	SW Triple Wide	10	The door operating hardware is not accessible.	\$ 3,038	5	Medium		
Building	67	SW Triple Wide	15	The maneuvering clearance perpendicular to the door is not 54 inches minimum.	\$ 3,375	5	Medium		
Building	67	SW Triple Wide	18	The maneuvering clearance at the door does not meet the minimum required dimensions.	\$ 3,375	5	Medium		
Building	69	Traffic Control	5	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Building	69	Traffic Control	7	The door operating hardware is not accessible (6 doors).	\$ 3,038	5	Medium		
Building	69	Traffic Control	18	Clear floor space is not provide at the tactile door sign.	\$ 338	5	Medium		
Building	70	Transmission Engineering Department Building	7	The handrails are not at the correct height.	\$ 1,013	5	Medium		
Building	70	Transmission Engineering Department Building	11	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	70	Transmission Engineering Department Building	15	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	72	Utility Office/Field Operations	1	The threshold is greater than 1/2 inch high.	\$ 2,025	5	Medium		
Building	72	Utility Office/Field Operations	2	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	72	Utility Office/Field Operations	3	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	72	Utility Office/Field Operations	4	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	72	Utility Office/Field Operations	5	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	72	Utility Office/Field Operations	6	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Building	72	Utility Office/Field Operations	24	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Building	72	Utility Office/Field Operations	25	The door closer is less than 78 inches off the finished floor.	\$ 743	5	Medium		
Building	72	Utility Office/Field Operations	31	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	72	Utility Office/Field Operations	34	The door operating hardware is not accessible.	\$ 506	5	Medium		
Building	72	Utility Office/Field Operations	39	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Building	2	Airport LESA	2	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	2	Airport LESA	3	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	2	Airport LESA	4	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	2	Airport LESA	6	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	3	Airport Terminal and Admin Building	3	The required edge protection is missing from the ramp run and/or ramp landing.	\$ 1,013	6	Medium		
Building	3	Airport Terminal and Admin Building	4	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	3	Airport Terminal and Admin Building	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	3	Airport Terminal and Admin Building	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	12	The walking surface is obstructed.	\$ 1,013	6	Medium		
Building	3	Airport Terminal and Admin Building	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	3	Airport Terminal and Admin Building	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	3	Airport Terminal and Admin Building	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	3	Airport Terminal and Admin Building	21	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	3	Airport Terminal and Admin Building	24	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	25	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	26	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	27	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	28	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	29	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	30	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	3	Airport Terminal and Admin Building	36	The restroom does not include accessible fixtures or elements. The door is not self-closing and is missing a loop handle on the inside the rear and side grab bars are mounted too high the rear grab bar does not extend 24 inches on the open side of the stall the toilet paper dispenser is not the correct distance from the front of the toilet and the floor drain is too low resulting in a change in level.	\$ 4,050	6	Medium		
Building	3	Airport Terminal and Admin Building	37	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 3,375	6	Medium		
Building	3	Airport Terminal and Admin Building	39	The restroom does not include accessible fixtures or elements. The door is not self-closing and is missing a loop handle on the inside the rear and side grab bars are mounted too high the rear grab bar does not extend 24 inches on the open side of the stall the toilet centerline is incorrect and the toilet paper dispenser is not the correct distance from the front of the toilet.	\$ 4,050	6	Medium		
Building	5	American Legion Hall Senior Center	6	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	5	American Legion Hall Senior Center	8	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Building	5	American Legion Hall Senior Center	10	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Building	5	American Legion Hall Senior Center	16	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	5	American Legion Hall Senior Center	17	Parked vehicles reduce the required width of the accessible route.	\$ 2,025	6	Medium		
Building	5	American Legion Hall Senior Center	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	5	American Legion Hall Senior Center	31	The top of the sink is above the allowable height requirement.	\$ 5,400	6	Medium		
Building	5	American Legion Hall Senior Center	32	The kitchen counter top is too high. The kitchen work surface shall be 34 inches maximum above the finish floor or ground.	\$ 2,025	6	Medium		
Building	5	American Legion Hall Senior Center	39	The television projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	5	American Legion Hall Senior Center	41	The television projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	5	American Legion Hall Senior Center	43	The force required to operate the door hardware exceeds 5 pounds.	\$ 675	6	Medium		
Building	5	American Legion Hall Senior Center	44	The toilet compartment is not wide enough.	\$ 675	6	Medium		
Building	5	American Legion Hall Senior Center	45	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	5	American Legion Hall Senior Center	50	The compartment door is located too far from the partition or wall.	\$ 675	6	Medium		
Building	5	American Legion Hall Senior Center	52	The toilet compartment is not wide enough.	\$ 675	6	Medium		
Building	5	American Legion Hall Senior Center	54	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	6	Monsignor King Outreach Center	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	6	Monsignor King Outreach Center	7	The accessible route of travel contains a cross slope of 2.8 percent and an expansion joint.	\$ 2,025	6	Medium		
Building	6	Monsignor King Outreach Center	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	6	Monsignor King Outreach Center	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	6	Monsignor King Outreach Center	12	The valve projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	6	Monsignor King Outreach Center	14	The ramp run contains changes in level greater than 1/4 inch.	\$ 675	6	Medium		
Building	6	Monsignor King Outreach Center	25	The accessible route of travel contains a cross slope of 2.4 percent.	\$ 2,025	6	Medium		
Building	6	Monsignor King Outreach Center	26	The AED box projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	6	Monsignor King Outreach Center	30	The top of the sink is above the allowable height requirement at 36 inches.	\$ 3,375	6	Medium		
Building	6	Monsignor King Outreach Center	37	The AED box projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	6	Monsignor King Outreach Center	38	The drinking fountain projects from the wall into the pedestrian way with its leading edge above 27 inches from the floor.	\$ 2,025	6	Medium		
Building	6	Monsignor King Outreach Center	42	The floor drain is set too low in the floor which causes a slope of 3.6 and 5.3 percent.	\$ 3,375	6	Medium		
Building	6	Monsignor King Outreach Center	43	Gratings are spaced greater than 1/2 inch in the direction of travel.	\$ 1,350	6	Medium		
Building	6	Monsignor King Outreach Center	52	The transfer shower stalls dimensions are greater than 36 by 36 inches. There are 7 showers stalls provided and none are accessible.	\$ 5,400	6	Medium		
Building	6	Monsignor King Outreach Center	56	The restroom is missing accessible fixtures or elements.	\$ 3,375	6	Medium		
Building	6	Monsignor King Outreach Center	57	The restroom does not include accessible fixtures or elements.	\$ 8,100	6	Medium		
Building	6	Monsignor King Outreach Center	58	The restroom does not include accessible fixtures or elements.	\$ 6,750	6	Medium		
Building	6	Monsignor King Outreach Center	59	The restroom does not include accessible fixtures or elements.	\$ 13,500	6	Medium		
Building	6	Monsignor King Outreach Center	61	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	3	Parked vehicles reduce the required width of the accessible route.	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	7	Center for Visual Arts	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	7	Center for Visual Arts	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	7	Center for Visual Arts	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	7	Center for Visual Arts	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	7	Center for Visual Arts	13	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	15	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	18	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Building	7	Center for Visual Arts	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	7	Center for Visual Arts	24		\$ -	6	Medium		
Building	7	Center for Visual Arts	25	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	28	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	7	Center for Visual Arts	29	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	7	Center for Visual Arts	30	There is a change in level greater than 1/4 inch.	\$ 3,375	6	Medium		
Building	7	Center for Visual Arts	32	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,013	6	Medium		
Building	7	Center for Visual Arts	33	The stairway contains open risers.	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	36	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	37	The handrail projects less than 12 inches beyond the landing at the top and bottom of the stairs parallel to the floor or ground.	\$ 1,013	6	Medium		
Building	7	Center for Visual Arts	38	The element extends down too close to the route of travel.	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	39	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	40	The wall sign is mounted too high.	\$ 338	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	7	Center for Visual Arts	44	There are not enough accessible toilet compartments. The room contains 2 toilet compartments. A minimum of one must be wheelchair accessible .	\$ 4,050	6	Medium		
Building	7	Center for Visual Arts	48	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	52	There are not enough accessible toilet compartments.	\$ 4,050	6	Medium		
Building	7	Center for Visual Arts	54	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	58	The handrail does not extend for the correct distance and/or direction at the bottom of the stairway.	\$ 1,013	6	Medium		
Building	7	Center for Visual Arts	60	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	61	The ramp does not have compliant handrails.	\$ 1,013	6	Medium		
Building	7	Center for Visual Arts	62	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	64	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	7	Center for Visual Arts	65	The handrail exceeds maximum height requirements.	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	66	The stairway only has a handrail on one side.	\$ 2,025	6	Medium		
Building	7	Center for Visual Arts	69	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	71	The top of the sink is above the allowable height requirement.	\$ 2,700	6	Medium		
Building	7	Center for Visual Arts	72	The top of the sink is above the allowable height requirement.	\$ 2,700	6	Medium		
Building	7	Center for Visual Arts	74	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	75	The restroom is missing accessible fixtures or elements. The urinal chairs and divider are in the toilet clear floor space the flush control is on the wrong side the rear grab bar does not extend the correct distance on the open side of the toilet the side grab bar does not extend the correct distance the toilet seat is too high the lavatory rim is too high mirror is too high the lavatory clear floor space is obstructed by the door swing paper towel dispenser is too high the coat hook is too high and the door maneuvering clearance is not 18 inches on the pull side.	\$ 4,050	6	Medium		
Building	7	Center for Visual Arts	76	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	77	The restroom is missing accessible fixtures or elements. The flush control is on the wrong side the waste basket is in the toilet clear floor space the rear grab bar does not extend the correct distance on the open side of the toilet the side grab bar does not extend the correct distance the toilet paper dispenser is located too far in front of the toilet the lavatory rim is too high mirror is too high paper towel dispenser is too high the coat hook is too high and the door maneuvering clearance is not 18 inches on the pull side.	\$ 4,050	6	Medium		
Building	7	Center for Visual Arts	88	Knee and toe clearance has not been provided at the sink.	\$ 3,375	6	Medium		
Building	7	Center for Visual Arts	89	The top of the sink is above the allowable height requirement.	\$ -	6	Medium		
Building	7	Center for Visual Arts	90	The top of the sink is above the allowable height requirement.	\$ 2,700	6	Medium		
Building	7	Center for Visual Arts	95	The kitchen counter top is too high.	\$ 3,375	6	Medium		
Building	7	Center for Visual Arts	98	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	100	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	7	Center for Visual Arts	101	The wall sign is incorrectly located.	\$ 1,350	6	Medium		
Building	8	City Hall	2	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	8	City Hall	5	The required parking signage is missing.	\$ 338	6	Medium		
Building	8	City Hall	6	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	8	City Hall	7	There is no accessible route to the flag pole.	\$ 2,025	6	Medium		
Building	8	City Hall	8	The walking surface is obstructed.	\$ 1,013	6	Medium		
Building	8	City Hall	9	The ramp run has not been provided with edge protection.	\$ 1,013	6	Medium		
Building	8	City Hall	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Building	8	City Hall	12	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Building	8	City Hall	13	The handrail does not extend for the correct distance at the bottom of the stairway.	\$ 1,013	6	Medium		
Building	8	City Hall	14	The tree limb extends down too close to the route of travel.	\$ 1,013	6	Medium		
Building	8	City Hall	17	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Building	8	City Hall	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	8	City Hall	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	8	City Hall	20	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		
Building	8	City Hall	21	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		
Building	8	City Hall	22	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	8	City Hall	23	The light fixtures projects more than 4 inches into the circulation path.	\$ 2,025	6	Medium		
Building	8	City Hall	24	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	8	City Hall	25	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	8	City Hall	28	Stairways must have handrails on both sides.	\$ 2,025	6	Medium		
Building	8	City Hall	29	Stairways must have handrails on both sides.	\$ 2,025	6	Medium		
Building	8	City Hall	30	Stairways must have handrails on both sides.	\$ 2,025	6	Medium		
Building	8	City Hall	32	The ramp run has not been provided with edge protection.	\$ 2,025	6	Medium		
Building	8	City Hall	33	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	8	City Hall	34	The handrail does not extend past the ramp at the top.	\$ 743	6	Medium		
Building	8	City Hall	35	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	8	City Hall	36	The AED device projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	8	City Hall	37	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Building	8	City Hall	38	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Building	8	City Hall	39	Stairways must have handrails on both sides.	\$ 1,013	6	Medium		
Building	8	City Hall	40	Stairways must have handrails on both sides.	\$ 1,013	6	Medium		
Building	8	City Hall	41	The handrails are not at the correct height.	\$ 1,013	6	Medium		
Building	8	City Hall	42	The handrails are not at the correct height.	\$ 1,013	6	Medium		
Building	8	City Hall	43	The handrail does not extend for the correct distance at the bottom of the stairway.	\$ -	6	Medium		
Building	8	City Hall	46	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	8	City Hall	49	The restroom is missing accessible fixtures or elements. The rear grab bar is not long enough and is mounted too high the side grab bar is too high the flush control is on the incorrect side the toilet paper dispenser is not the correct distance from the front of the toilet the mirror is too high the coat hook is too high and the self-closing faucet does not remain open a minimum of 10 seconds.	\$ 3,375	6	Medium		
Building	8	City Hall	50	The restroom is missing accessible fixtures or elements. The rear grab bar is not mounted the correct distance or height the side grab bar is too high the lavatory is in the toilets clear floor space the toilet paper dispenser is not the correct distance from the front of the toilet the mirror is too high the coat hook is too high restroom signage is missing and the self-closing faucet does not remain open a minimum of 10 seconds.	\$ 3,375	6	Medium		
Building	8	City Hall	60	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,013	6	Medium		
Building	8	City Hall	61	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	8	City Hall	62	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	8	City Hall	64	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	8	City Hall	66	The handrails are not at the correct height.	\$ 1,013	6	Medium		
Building	8	City Hall	67	The handrail does not extend for the correct distance and/or direction at the bottom of the stairway.	\$ 1,013	6	Medium		
Building	8	City Hall	69	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	8	City Hall	72	The water fountain projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	8	City Hall	73	The drop box projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	8	City Hall	89	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	8	City Hall	91	The urinal is located in an area that does not provide the required clear floor space for a front approach.	\$ 2,025	6	Medium		
Building	8	City Hall	92	There are not enough accessible toilet compartments.	\$ 4,050	6	Medium		
Building	8	City Hall	96	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	8	City Hall	97	There are not enough accessible toilet compartments.	\$ 4,050	6	Medium		
Building	8	City Hall	100	The shelf projects more than 4 inches into the circulation path.	\$ 338	6	Medium		
Building	8	City Hall	103	The restroom is missing accessible fixtures or elements. The flush control is on the wrong side the toilet paper dispenser is not the correct distance from the front of the toilet the toilet seat cover dispenser obstructs the side grab bar the lavatory is in the toilet clear floor space and the paper towel dispenser is too high.	\$ 4,050	6	Medium		
Building	8	City Hall	104	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	8	City Hall	106	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	9	City Hall East (Municipal Complex)	2	The parking sign is mounted too low.	\$ 338	6	Medium		
Building	9	City Hall East (Municipal Complex)	3	The parking sign is mounted too low.	\$ 338	6	Medium		
Building	9	City Hall East (Municipal Complex)	6	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	6	Medium		
Building	9	City Hall East (Municipal Complex)	7	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	9	City Hall East (Municipal Complex)	12	Stairways must have handrails on both sides.	\$ 1,013	6	Medium		
Building	9	City Hall East (Municipal Complex)	13	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	14	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	15	The landing allows the accumulation of water.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	20	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	9	City Hall East (Municipal Complex)	21	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	23	The clear floor space required at the utility payment kiosk is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	24	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	27	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	28	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	9	City Hall East (Municipal Complex)	29	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	9	City Hall East (Municipal Complex)	30	The handrail does not extend past the ramp.	\$ 1,013	6	Medium		
Building	9	City Hall East (Municipal Complex)	31	The accessible route contains loose gravel and surface materials that do not provide for a stable firm slip-resistant surface.	\$ 675	6	Medium		
Building	9	City Hall East (Municipal Complex)	33	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	34	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	9	City Hall East (Municipal Complex)	35	The stairway handrails are not compliant. The handrails have the following issues: Installed at the incorrect height and the bottom handrail extensions are missing or extend incorrectly.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	36	Stairways must have handrails on both sides.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	37	The stairway treads are sloped greater than 2 percent in any direction and are not uniform heights.	\$ 3,375	6	Medium		
Building	9	City Hall East (Municipal Complex)	40	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	9	City Hall East (Municipal Complex)	42	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	45	The counter is too high. There are two detective counters and non are accessible height.	\$ 2,700	6	Medium		
Building	9	City Hall East (Municipal Complex)	46	The counter is too high. There are four customer service counters and non are accessible height.	\$ 2,700	6	Medium		
Building	9	City Hall East (Municipal Complex)	48	The counter is too high. There are two counters for police records one accessible and one is not. The non-accessible counter is the one used.	\$ 2,700	6	Medium		
Building	9	City Hall East (Municipal Complex)	50	The stairway handrails are not compliant. The handrails have the following issues: Installed at the incorrect height the bottom handrail extensions are missing or extend incorrectly the handrail gripping surface is not the correct size.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	52	The drop box projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	9	City Hall East (Municipal Complex)	58	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the coat hook is too high and the toilet paper dispenser is not located the correct distance in front of the toilet.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	61	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the coat hook is too high the toilet seat cover dispenser is out of reach range and obstructs the rear grab bar and the toilet paper dispenser is not located the correct distance in front of the toilet.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	68	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	9	City Hall East (Municipal Complex)	69	The restroom is missing accessible fixtures or elements. The door is missing an outside loop handle the rear and side grab bar are too high the rear grab bar does not extend the correct distance on the open side of the toilet and the toilet paper dispenser is not mounted the correct distance in front of the toilet.	\$ 2,025	6	Medium		
Building	9	City Hall East (Municipal Complex)	70	The wall shelf projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	9	City Hall East (Municipal Complex)	71	The urinal is confined on three sides (alcove).	\$ 945	6	Medium		
Building	9	City Hall East (Municipal Complex)	75	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	9	City Hall East (Municipal Complex)	76	The restroom is missing accessible fixtures or elements. The toilet stall is not deep enough the door is not self-closing and missing an inside loop handle the rear grab bar does not extend the correct distance on the open side of the toilet the toilet seat cover dispenser and toilet operations obstruct the rear grab bar and the toilet paper dispenser is not mounted the correct distance in front of the toilet.	\$ 4,050	6	Medium		
Building	9	City Hall East (Municipal Complex)	93	The wall sign is mounted too high.	\$ 1,013	6	Medium		
Building	9	City Hall East (Municipal Complex)	104	The television projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	9	City Hall East (Municipal Complex)	107	The first aid kit and AED device projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	9	City Hall East (Municipal Complex)	115	The television projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	9	City Hall East (Municipal Complex)	123	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	9	City Hall East (Municipal Complex)	124	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the toilet paper dispenser is not located the correct distance in front of the toilet.	\$ 1,013	6	Medium		
Building	9	City Hall East (Municipal Complex)	129	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	9	City Hall East (Municipal Complex)	130	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the rear grab bar does not extend the correct distance on the closed side of the toilet the flush control is on the wrong side the coat hook is too high the stall is not deep enough and the toilet paper dispenser is not located the correct distance in front of the toilet.	\$ 4,050	6	Medium		
Building	9	City Hall East (Municipal Complex)	145	The restroom is missing accessible fixtures or elements. The door is not self-closing the toilet centerline is incorrect the rear and side grab bars are too high and the toilet paper dispenser is not the correct distance in front of the toilet.	\$ 3,375	6	Medium		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	9	City Hall East (Municipal Complex)	148	The restroom is missing accessible fixtures or elements. The door is not self-closing the rear and side grab bars are too high and the toilet paper dispenser is not the correct distance in front of the toilet.	\$ 2,025	6	Medium		
Building	10	City Hall West	8	The required parking signage is missing at the accessible parking space.	\$ 338	6	Medium		
Building	10	City Hall West	9	The directional signage to the accessible entrance is dilapidated and needs to be replaced.	\$ 338	6	Medium		
Building	10	City Hall West	11	The stairway is missing a handrail for the bottom set of stairs.	\$ 2,025	6	Medium		
Building	10	City Hall West	12	The handrail extension is not long enough of the top set of stairs.	\$ 1,013	6	Medium		
Building	11	Civic Center	2	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Building	11	Civic Center	5	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Building	11	Civic Center	7	The accessible parking stall is not wide enough.	\$ 405	6	Medium		
Building	11	Civic Center	8	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Building	11	Civic Center	10	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Building	11	Civic Center	11	The accessible parking stall is not wide enough.	\$ 405	6	Medium		
Building	11	Civic Center	12	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Building	11	Civic Center	13	The accessible parking stall is not wide enough.	\$ 405	6	Medium		
Building	11	Civic Center	18	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Building	11	Civic Center	20	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	11	Civic Center	21	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	11	Civic Center	22	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Building	11	Civic Center	23	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	11	Civic Center	24	The accessible route has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.). Cross slopes are greater than 2 percent across the width of the walk.	\$ 3,375	6	Medium		
Building	11	Civic Center	25	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	6	Medium		
Building	11	Civic Center	26	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	11	Civic Center	27	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	11	Civic Center	28	The walking surface is obstructed.	\$ 2,025	6	Medium		
Building	11	Civic Center	31	The walking surface is obstructed.	\$ 2,025	6	Medium		
Building	11	Civic Center	32	The walking surface is obstructed.	\$ 2,025	6	Medium		
Building	11	Civic Center	34	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	6	Medium		
Building	11	Civic Center	36	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	11	Civic Center	37	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	6	Medium		
Building	11	Civic Center	44	The television projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	11	Civic Center	48	The accessible route has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	11	Civic Center	50	The room contains 6 or more fixtures and therefore must have a minimum of one ambulatory toilet stall.	\$ 3,375	6	Medium		
Building	11	Civic Center	58	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend the correct distance on the closed side of the toilet the toilet paper dispenser is not the correct distance from the front of the toilet and obstructs the side grab bar and the door is not self-closing and is missing a loop handle on the inside.	\$ 2,025	6	Medium		
Building	11	Civic Center	60	The toilet compartment is missing accessible fixtures or elements. The flush handle is located on the wrong side of the toilet the door is missing an inside loop handle and the trash can is in the toilets clear floor space.	\$ 2,025	6	Medium		
Building	11	Civic Center	62	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 3,375	6	Medium		
Building	11	Civic Center	67	The room contains 6 or more fixtures and therefore must have a minimum of one ambulatory toilet stall (6 stalls total).	\$ 3,375	6	Medium		
Building	11	Civic Center	68	The kitchen counter top is too high.	\$ 3,375	6	Medium		
Building	11	Civic Center	86	The drinking fountain projects into the clearance in the circulation path.	\$ 675	6	Medium		
Building	12	Civic Center Pool	1	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	12	Civic Center Pool	2	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Building	12	Civic Center Pool	4	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Building	12	Civic Center Pool	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	10	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	12	Civic Center Pool	15	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	16	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	17	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	12	Civic Center Pool	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	22	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	12	Civic Center Pool	23	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	12	Civic Center Pool	24	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	12	Civic Center Pool	25	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	12	Civic Center Pool	26	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	12	Civic Center Pool	27	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	12	Civic Center Pool	28	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	12	Civic Center Pool	29	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Building	12	Civic Center Pool	30	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	12	Civic Center Pool	31	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	12	Civic Center Pool	35	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 743	6	Medium		
Building	12	Civic Center Pool	38	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	12	Civic Center Pool	39	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 743	6	Medium		
Building	12	Civic Center Pool	40	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ 1,013	6	Medium		
Building	12	Civic Center Pool	42	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 743	6	Medium		
Building	12	Civic Center Pool	46	There are no accessible bathing and shower facilities.	\$ 2,025	6	Medium		
Building	12	Civic Center Pool	51	The accessible route has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	12	Civic Center Pool	54	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 338	6	Medium		
Building	12	Civic Center Pool	56	The restroom is missing accessible fixtures or elements.  The flush control is on the incorrect side the door is not self-closing and is missing an inside loop handle.	\$ 2,025	6	Medium		
Building	12	Civic Center Pool	59	There are no accessible bathing and shower facilities.	\$ 2,025	6	Medium		
Building	13	Denia Recreation Center	2	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	13	Denia Recreation Center	3	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	13	Denia Recreation Center	4	The required parking signage is missing.	\$ 338	6	Medium		
Building	13	Denia Recreation Center	5	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	13	Denia Recreation Center	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	13	Denia Recreation Center	7	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	13	Denia Recreation Center	8	The concrete expansion joints are spaced greater than 1/2 inch.	\$ 743	6	Medium		
Building	13	Denia Recreation Center	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	13	Denia Recreation Center	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	13	Denia Recreation Center	12	The ramp contains a change of direction and the landing does not meet slope requirements.	\$ 3,375	6	Medium		
Building	13	Denia Recreation Center	13	The landing at the change of direction does not meet minimum size requirements.	\$ -	6	Medium		
Building	13	Denia Recreation Center	14	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Building	13	Denia Recreation Center	19	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	13	Denia Recreation Center	23	The water fountains project into the circulation path.	\$ 1,013	6	Medium		
Building	13	Denia Recreation Center	30	The restroom does not include accessible fixtures or elements.	\$ 4,725	6	Medium		
Building	13	Denia Recreation Center	33	The shower has not been provided with a hand-held spray unit with a 60 inch hose.	\$ 540	6	Medium		
Building	13	Denia Recreation Center	37	The hand dryer and paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	13	Denia Recreation Center	41	The shower has not been provided with a hand-held spray unit with a 60 inch hose.	\$ 540	6	Medium		
Building	13	Denia Recreation Center	42	The accessible route of travel contains cross slopes greater than 2 percent.	\$ 4,725	6	Medium		
Building	13	Denia Recreation Center	53	Knee and toe space has not been provided at the sink.	\$ 750	6	Medium		
Building	14	Denton Development Center	2	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	14	Denton Development Center	3	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	6	Medium		
Building	14	Denton Development Center	8	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	14	Denton Development Center	10	The handrails do not meet minimum height requirements.	\$ 1,013	6	Medium		
Building	14	Denton Development Center	11	The handrail does not extend past the ramp.	\$ 743	6	Medium		
Building	14	Denton Development Center	25	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	14	Denton Development Center	26	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	14	Denton Development Center	27	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	14	Denton Development Center	28	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	14	Denton Development Center	29	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	14	Denton Development Center	30	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	14	Denton Development Center	32	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 945	6	Medium		
Building	14	Denton Development Center	33	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 3,375	6	Medium		
Building	14	Denton Development Center	35	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 945	6	Medium		
Building	15	Denton Energy Center	2	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Building	15	Denton Energy Center	4	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Building	15	Denton Energy Center	5	The ramp run and landing has not been provided with edge protection.	\$ 1,013	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	15	Denton Energy Center	22	Stairways must have handrails on both sides.	\$ 1,013	6	Medium		
Building	16	Denton Senior Center	1	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	3	The access aisle contains abrupt edges surface irregularities and loose gravel.	\$ 3,375	6	Medium		
Building	16	Denton Senior Center	4	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	5	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	6	Medium		
Building	16	Denton Senior Center	6	The parking stall contains abrupt edges surface irregularities and loose gravel.	\$ -	6	Medium		
Building	16	Denton Senior Center	7	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	11	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ -	6	Medium		
Building	16	Denton Senior Center	12	The required parking signage is missing.	\$ 338	6	Medium		
Building	16	Denton Senior Center	13	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	15	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	18	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	21	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ -	6	Medium		
Building	16	Denton Senior Center	22	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	6	Medium		
Building	16	Denton Senior Center	23	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	24	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	6	Medium		
Building	16	Denton Senior Center	25	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Building	16	Denton Senior Center	27	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	6	Medium		
Building	16	Denton Senior Center	28	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	30	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	31	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Building	16	Denton Senior Center	32	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Building	16	Denton Senior Center	33	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	6	Medium		
Building	16	Denton Senior Center	38	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	43	The access aisle is not a minimum 5 feet wide.	\$ 675	6	Medium		
Building	16	Denton Senior Center	45	The required parking signage is missing.	\$ 338	6	Medium		
Building	16	Denton Senior Center	50	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	51	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	6	Medium		
Building	16	Denton Senior Center	52	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Building	16	Denton Senior Center	55	The entrance is not accessible and is missing signage. An identification sign identifying that this entrance is not accessible and directional signage pointing to the accessible entrance is required.	\$ 338	6	Medium		
Building	16	Denton Senior Center	56	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	16	Denton Senior Center	60	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	16	Denton Senior Center	61	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	16	Denton Senior Center	64	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	65	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	69	The walking surface is obstructed.	\$ 473	6	Medium		
Building	16	Denton Senior Center	70	The tree limbs extends down too close to the route of travel.	\$ 1,013	6	Medium		
Building	16	Denton Senior Center	72	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	74	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	76	The building entrance is not located on an accessible route.	\$ 338	6	Medium		
Building	16	Denton Senior Center	78	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	79	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	16	Denton Senior Center	80	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	16	Denton Senior Center	81	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	82	Parked vehicles reduce the required width of the accessible route.	\$ 3,375	6	Medium		
Building	16	Denton Senior Center	89	There are no wheelchair accessible toilet compartments. The room contains 2 toilet compartments. A minimum of one must be wheelchair accessible .	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	90	The urinal is confined on three sides and does not have the required clearance for a front approach.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	94	There are no wheelchair accessible toilet compartments. The room contains 3 toilet compartments. A minimum of one must be wheelchair accessible .	\$ 4,050	6	Medium		
Building	16	Denton Senior Center	100	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 473	6	Medium		
Building	16	Denton Senior Center	104	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 473	6	Medium		
Building	16	Denton Senior Center	113	The top of the sink is above the allowable height requirement.	\$ 2,700	6	Medium		
Building	16	Denton Senior Center	116	The top of the sink is above the allowable height requirement.	\$ 2,700	6	Medium		
Building	16	Denton Senior Center	121	The hand sanitizer dispensers projects into the headroom clearance in the circulation path.	\$ 1,013	6	Medium		
Building	16	Denton Senior Center	124	The stairway only has a handrail on one side.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	126	The landing at the bottom of the ramp does not meet minimum length requirements.	\$ 1,013	6	Medium		
Building	16	Denton Senior Center	128	The ramp does not have compliant handrails and handrail extensions.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	137	The fire extinguisher projects into the headroom clearance in the circulation path.	\$ 473	6	Medium		
Building	16	Denton Senior Center	140	The hand sanitizer dispenser projects into the headroom clearance in the circulation path.	\$ 473	6	Medium		
Building	16	Denton Senior Center	141	The hand sanitizer dispenser projects into the headroom clearance in the circulation path.	\$ 473	6	Medium		
Building	16	Denton Senior Center	143	The fire extinguisher projects into the headroom clearance in the circulation path.	\$ 473	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	16	Denton Senior Center	144	The ramps exceeds the maximum running slope allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	16	Denton Senior Center	145	The ramps exceeds the maximum running slope allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	16	Denton Senior Center	146	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Building	16	Denton Senior Center	149	The top of the sink is above the allowable height requirement.	\$ 2,700	6	Medium		
Building	20	Electric Administration Building	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	20	Electric Administration Building	7	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	20	Electric Administration Building	10	The walking surface is obstructed.	\$ 743	6	Medium		
Building	20	Electric Administration Building	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Building	20	Electric Administration Building	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	20	Electric Administration Building	15	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	20	Electric Administration Building	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Building	20	Electric Administration Building	18	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	20	Electric Administration Building	20	The toilet compartment does not include accessible fixtures or elements.	\$ 3,375	6	Medium		
Building	20	Electric Administration Building	29	The toilet compartment is missing accessible fixtures or elements.	\$ 1,013	6	Medium		
Building	20	Electric Administration Building	34	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	20	Electric Administration Building	35	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	20	Electric Administration Building	43	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	21	Emily Fowler Library	3	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	21	Emily Fowler Library	7	The parking sign is mounted too low.	\$ 338	6	Medium		
Building	21	Emily Fowler Library	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	21	Emily Fowler Library	15	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	21	Emily Fowler Library	16	The entrance is not accessible and is missing signage.	\$ 473	6	Medium		
Building	21	Emily Fowler Library	18	The accessible route contains loose gravel that does not provide for a stable firm or slip-resistant surface.	\$ 2,025	6	Medium		
Building	21	Emily Fowler Library	19	There is a change in level greater than 1/4 inch.	\$ 1,013	6	Medium		
Building	21	Emily Fowler Library	23	The accessible route contains loose gravel that does not provide for a stable firm slip-resistant surface.	\$ 4,725	6	Medium		
Building	21	Emily Fowler Library	24	There is no accessible route to the art installation.	\$ 1,013	6	Medium		
Building	21	Emily Fowler Library	28	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 743	6	Medium		
Building	21	Emily Fowler Library	29	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Building	21	Emily Fowler Library	30	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	21	Emily Fowler Library	31	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	21	Emily Fowler Library	34	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	21	Emily Fowler Library	39	The route of travel does not meet minimum width requirements around the book stacks.	\$ 3,375	6	Medium		
Building	21	Emily Fowler Library	40	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	21	Emily Fowler Library	41	The handrail extension is not a minimum 12 inches.	\$ 1,013	6	Medium		
Building	21	Emily Fowler Library	42	The route of travel does not meet minimum width requirements around the book stacks.	\$ 3,375	6	Medium		
Building	21	Emily Fowler Library	43	The route of travel does not meet minimum width requirements around the book stacks.	\$ 3,375	6	Medium		
Building	21	Emily Fowler Library	44	The route of travel does not meet minimum width requirements around the book stacks.	\$ 3,375	6	Medium		
Building	21	Emily Fowler Library	45	The telephone and fire alarm projects into the headroom clearance in the circulation path.	\$ 945	6	Medium		
Building	21	Emily Fowler Library	47	The wall sign is mounted too high.	\$ 675	6	Medium		
Building	21	Emily Fowler Library	48	The toilet compartment is missing accessible fixtures or elements	\$ 1,283	6	Medium		
Building	21	Emily Fowler Library	52	The toilet compartment is missing accessible fixtures or elements.	\$ 1,283	6	Medium		
Building	21	Emily Fowler Library	54	The restroom is missing accessible fixtures or elements.	\$ 4,725	6	Medium		
Building	22	Engineering and Systems Operations	2	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	22	Engineering and Systems Operations	7	The required edge protection is missing from the ramp run.	\$ 2,025	6	Medium		
Building	22	Engineering and Systems Operations	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	22	Engineering and Systems Operations	9	The water fountains projects into the circulation path.	\$ 5,130	6	Medium		
Building	22	Engineering and Systems Operations	14	The AED projects into the circulation path.	\$ 473	6	Medium		
Building	23	Facilities Management	1	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	23	Facilities Management	2	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	23	Facilities Management	3	The required edge protection is missing.	\$ 1,013	6	Medium		
Building	23	Facilities Management	4	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	23	Facilities Management	5	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	23	Facilities Management	6	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Building	23	Facilities Management	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	23	Facilities Management	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	23	Facilities Management	9	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	23	Facilities Management	11	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	6	Medium		
Building	23	Facilities Management	12	The tree limbs extends down too close to the route of travel.	\$ 1,013	6	Medium		
Building	23	Facilities Management	16	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Building	23	Facilities Management	17	Stairways must have handrails on both sides.	\$ 1,013	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	23	Facilities Management	19	The restroom is missing accessible fixtures or elements. The door is missing an inside loop handle and is not self-closing the rear and side grab bars are too high the toilet seat covers are obstructing the side grab bar and the toilet paper dispenser is not located the correct distance in front of the toilet.	\$ 3,375	6	Medium		
Building	23	Facilities Management	25	The restroom is missing accessible fixtures or elements. The door is missing an inside loop handle and is not self-closing the rear and side grab bars are too high the toilet seat covers are obstructing the side grab bar and the toilet paper dispenser is not located the correct distance in front of the toilet.	\$ 3,375	6	Medium		
Building	23	Facilities Management	26	The restroom is missing accessible fixtures or elements. The rear and side grab bar are to high the lavatory is in the toilets clear floor space the paper towel dispenser soap dispenser and mirror are mounted too high the toilet seat covers are obstructing the side grab bar and the toilet paper dispenser is not the correct distance in front of the toilet.	\$ 4,050	6	Medium		
Building	23	Facilities Management	27	The restroom is missing accessible fixtures or elements. The rear and side grab bar are to high the lavatory is in the toilets clear floor space the paper towel dispenser is mounted too high the self closing faucet does not remain open for a minimum of 10 seconds the toilet seat covers are obstructing the side grab bar the coat hook is too high the door threshold is to high and the toilet paper dispenser is not the correct distance in front of the toilet.	\$ 4,725	6	Medium		
Building	23	Facilities Management	28	The restroom is missing accessible fixtures or elements. The rear and side grab bar are to high the lavatory is in the toilets clear floor space the paper towel dispenser is mounted too high the self closing faucet does not remain open for a minimum of 10 seconds the toilet seat covers are obstructing the side grab bar the coat hook is too high the door threshold is to high and the toilet paper dispenser is not the correct distance in front of the toilet.	\$ 4,050	6	Medium		
Building	23	Facilities Management	38	The television projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	24	Fire Drill Tower (Fire Station #7)	1	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	24	Fire Drill Tower (Fire Station #7)	2	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	25	Fire Outdoor Classroom (Fire Station #7)	1	The grate openings are greater than 1/2 inch and are parallel to the direction of travel.	\$ 1,013	6	Medium		
Building	25	Fire Outdoor Classroom (Fire Station #7)	2	The walking surface is obstructed by the hose reel.	\$ 675	6	Medium		
Building	26	Fire Station #2	1	The van stall is missing a sign identifying it as a van accessible stall.	\$ 338	6	Medium		
Building	26	Fire Station #2	2	The access aisle is not a minimum 8 feet to the centerline of the stripe.	\$ 270	6	Medium		
Building	26	Fire Station #2	3	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	26	Fire Station #2	6	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	6	Medium		
Building	26	Fire Station #2	7	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	6	Medium		
Building	26	Fire Station #2	8	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	26	Fire Station #2	9	The entrance is not accessible and is missing signage.	\$ 338	6	Medium		
Building	26	Fire Station #2	12	The television projects into the headroom clearance in the circulation path.	\$ 338	6	Medium		
Building	26	Fire Station #2	21	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	26	Fire Station #2	28	The stairway contains open risers.	\$ 3,375	6	Medium		
Building	26	Fire Station #2	29	The element extends down too close to the route of travel.	\$ 2,025	6	Medium		
Building	27	Fire Station #3	4	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Building	27	Fire Station #3	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	27	Fire Station #3	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	27	Fire Station #3	7	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	27	Fire Station #3	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	27	Fire Station #3	10	Parked vehicles reduce the required width of the accessible route.	\$ 2,025	6	Medium		
Building	27	Fire Station #3	14	The television projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	28	Fire Station #4	1	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 4,050	6	Medium		
Building	28	Fire Station #4	2	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	28	Fire Station #4	3	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 4,050	6	Medium		
Building	28	Fire Station #4	4	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	6	Medium		
Building	28	Fire Station #4	5	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	28	Fire Station #4	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	28	Fire Station #4	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	28	Fire Station #4	13	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	6	Medium		
Building	28	Fire Station #4	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	29	Fire Station #5	2	The required parking signage is missing.	\$ -	6	Medium		
Building	29	Fire Station #5	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	29	Fire Station #5	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Building	29	Fire Station #5	23	The restroom does not include accessible fixtures or accessories.	\$ 4,050	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	30	Fire Station #6	1	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Building	30	Fire Station #6	2	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	30	Fire Station #6	5	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 3,375	6	Medium		
Building	30	Fire Station #6	7	Parked vehicles reduce the required width of the accessible route.	\$ 2,025	6	Medium		
Building	30	Fire Station #6	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	30	Fire Station #6	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	30	Fire Station #6	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	30	Fire Station #6	14	The restroom is missing accessible fixtures or elements.  The door contains knob style hardware the toilet flush control is on the wrong side the rear grab bar is not long enough the lavatory does not provide knee clearance the lavatory controls require tight grasping the lavatory pipes are not insulated the lavatory is in the toilet clear floor space the paper towel dispenser is an obstruction and requires tight grasping the door swings into the maneuvering clearance and the door maneuvering clearance is obstructed by the cabinet and trash can.	\$ 4,050	6	Medium		
Building	30	Fire Station #6	34	The grate openings are greater than 1/2 inch and are parallel to the direction of travel.	\$ 2,025	6	Medium		
Building	30	Fire Station #6	41	The drinking fountain projects from the wall into the pedestrian way with its leading edge above 27 inches from the floor.	\$ 675	6	Medium		
Building	30	Fire Station #6	43	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	6	Medium		
Building	31	Fire Station #7	4	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 3,375	6	Medium		
Building	31	Fire Station #7	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	31	Fire Station #7	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	31	Fire Station #7	7	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	31	Fire Station #7	11	Knee clearance has not been provided underneath the sink.	\$ 2,700	6	Medium		
Building	31	Fire Station #7	12	The restroom is missing accessible fixtures or elements.  The rear grab bar does not extend the correct distance the lavatory is in the toilet clear floor space the toilet paper dispenser is located at an incorrect distance in front of the toilet and the paper towel dispenser is mounted too high and obstructs the door maneuvering clearance.	\$ 4,050	6	Medium		
Building	31	Fire Station #7	13	The restroom is missing accessible fixtures or elements.  The rear grab bar does not extend the correct distance the lavatory is in the toilet clear floor space the toilet paper dispenser is located at an incorrect distance in front of the toilet and the paper towel dispenser is mounted too high and obstructs the door maneuvering clearance.	\$ 4,050	6	Medium		
Building	31	Fire Station #7	14	The television projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	32	Fire Station #8	1	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	32	Fire Station #8	3	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	32	Fire Station #8	5	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	32	Fire Station #8	9	Parked vehicles reduce the required width of the accessible route.	\$ 2,025	6	Medium		
Building	33	Fire Station Annex (Old #4)	1	The required parking signage is missing.	\$ 338	6	Medium		
Building	33	Fire Station Annex (Old #4)	2	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	33	Fire Station Annex (Old #4)	4	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	33	Fire Station Annex (Old #4)	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	33	Fire Station Annex (Old #4)	9	The telephone projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	33	Fire Station Annex (Old #4)	12	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	34	Fleet Service Center	2	The required parking signage is missing.	\$ 338	6	Medium		
Building	34	Fleet Service Center	5	The lockbox projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	34	Fleet Service Center	6	The wall sign is mounted too high.	\$ 1,350	6	Medium		
Building	34	Fleet Service Center	10	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	34	Fleet Service Center	18	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	35	Household Hazardous Waste Building	1	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	35	Household Hazardous Waste Building	2	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	35	Household Hazardous Waste Building	4	Compliant room identification signs are missing.	\$ 338	6	Medium		
Building	35	Household Hazardous Waste Building	8	The lavatory's clear floor space obstructed by the trash can.	\$ 338	6	Medium		
Building	35	Household Hazardous Waste Building	9	The television projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	1	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.  Parking spaces and access aisles serving them shall be stable firm and slip resistant. Access aisles shall be at the same level as the parking spaces they serve. Changes in level are not permitted and shall not be sloped steeper than 2% in any direction.	\$ 2,025	6	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	3	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	4	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	13	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	17	Knee and toe clearance has not been provided at the sink.	\$ 2,700	6	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	22	The room identification sign is noncompliant.	\$ 1,350	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	37	Linda McNatt Animal Care and Adoption Center	30	The floor mat or carpet pile height is too high.	\$ 4,725	6	Medium		
Building	39	LL WTP - Maintenance Building	10	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Building	39	LL WTP - Maintenance Building	11	The floor drain is set too low in the floor which causes a steep slope and/or vertical changes of elevation greater than 1/4 inch.	\$ 12,150	6	Medium		
Building	40	LL WTP - Operations Building	3	Parked vehicles reduce the required width of the accessible route.	\$ 2,025	6	Medium		
Building	40	LL WTP - Operations Building	4	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	40	LL WTP - Operations Building	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	40	LL WTP - Operations Building	6	Stairways must have handrails on both sides.	\$ 1,013	6	Medium		
Building	40	LL WTP - Operations Building	9	The entrance is not accessible and is missing signage.	\$ 338	6	Medium		
Building	40	LL WTP - Operations Building	14	The total number of drinking fountains are not equally divided between those that are accessible to wheelchair users and those that are available to standing persons.  Where more than two are provided 50 percent of the total number of drinking fountains provided shall be accessible to wheelchair users and 50 percent available to standing persons.	\$ 5,130	6	Medium		
Building	40	LL WTP - Operations Building	21	Gratings are spaced greater than 1/2 inch in the direction of travel.	\$ 2,025	6	Medium		
Building	40	LL WTP - Operations Building	22	The stairway contains open risers.	\$ 3,375	6	Medium		
Building	40	LL WTP - Operations Building	24	There are not enough accessible toilet compartments.	\$ 4,050	6	Medium		
Building	40	LL WTP - Operations Building	31	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 338	6	Medium		
Building	40	LL WTP - Operations Building	33	The restroom is missing accessible fixtures or elements.  There is no accessible toilet compartment the lavatory is too high the lavatory pipes are not insulated there is not an accessible shower the toilet seat cover dispenser is mounted too high the toilet paper dispenser is not the correct distance from the front of the toilet the mirror is too high the paper towel dispenser is too high there are no accessible lockers.	\$ 4,050	6	Medium		
Building	41	LL WTP - Ozone Generator Building	4	The threshold is greater than 1/2 inch high.	\$ 675	6	Medium		
Building	41	LL WTP - Ozone Generator Building	7	Gratings are spaced greater than 1/2 inch in the direction of travel.	\$ 4,725	6	Medium		
Building	42	LRR WTP - Admin Building	2	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 2,025	6	Medium		
Building	42	LRR WTP - Admin Building	4	The parking sign is mounted too low.	\$ 338	6	Medium		
Building	42	LRR WTP - Admin Building	5	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	42	LRR WTP - Admin Building	6	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ -	6	Medium		
Building	42	LRR WTP - Admin Building	7	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	42	LRR WTP - Admin Building	8	The walking surface is obstructed.	\$ 2,025	6	Medium		
Building	42	LRR WTP - Admin Building	9	The stairs extends down too close to the route of travel.	\$ 1,013	6	Medium		
Building	42	LRR WTP - Admin Building	12	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	42	LRR WTP - Admin Building	13	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	42	LRR WTP - Admin Building	15	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	42	LRR WTP - Admin Building	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	42	LRR WTP - Admin Building	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	42	LRR WTP - Admin Building	23	Knee clearance has not been provided underneath the sink.	\$ 3,375	6	Medium		
Building	42	LRR WTP - Admin Building	26	The AED device projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	42	LRR WTP - Admin Building	27	The drinking fountain projects from the wall into the pedestrian way with its leading edge above 27 inches from the floor.	\$ 675	6	Medium		
Building	42	LRR WTP - Admin Building	28	The elevator does not have a star on both jambs at the main entry level.	\$ 2,025	6	Medium		
Building	42	LRR WTP - Admin Building	29	The equipment extends down too close to the route of travel.	\$ 2,025	6	Medium		
Building	42	LRR WTP - Admin Building	38	The lavatory is confined on three sides and is considered to be installed in an alcove.	\$ 2,025	6	Medium		
Building	44	Master Recycling Services - Building 101	3	The ramp run and landing has not been provided with edge protection.	\$ 1,013	6	Medium		
Building	44	Master Recycling Services - Building 101	6	The stairway handrails are not compliant. The handrails have the following issues:  - Missing on one side - The bottom handrail extensions are missing - The top handrail extensions are missing or extend incorrectly	\$ 1,013	6	Medium		
Building	44	Master Recycling Services - Building 101	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	44	Master Recycling Services - Building 101	12	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	44	Master Recycling Services - Building 101	14	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	2	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Building	46	MLK Jr Recreation Center	13	The accessible path of travel has cross slopes greater than 2 percent and expansion joint.	\$ 2,025	6	Medium		
Building	46	MLK Jr Recreation Center	14	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		
Building	46	MLK Jr Recreation Center	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	46	MLK Jr Recreation Center	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	46	MLK Jr Recreation Center	19	Parked vehicles reduce the required width of the accessible route.	\$ 4,725	6	Medium		
Building	46	MLK Jr Recreation Center	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	22	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	23	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	46	MLK Jr Recreation Center	24	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Building	46	MLK Jr Recreation Center	27	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	28	The accessible path of travel has cross slopes greater than 2 percent and an expansion joint.	\$ 2,025	6	Medium		
Building	46	MLK Jr Recreation Center	30	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	46	MLK Jr Recreation Center	32	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	37	The entrance is not accessible and is missing signage.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	38	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	46	MLK Jr Recreation Center	39	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Building	46	MLK Jr Recreation Center	40	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	41	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	42	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	44	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Building	46	MLK Jr Recreation Center	45	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	46	MLK Jr Recreation Center	52	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	61	There are not enough accessible toilet compartments. The room contains 3 toilet compartments. A minimum of one must be wheelchair accessible .	\$ 4,725	6	Medium		
Building	46	MLK Jr Recreation Center	62	There are no accessible bathing and shower facilities.	\$ 4,725	6	Medium		
Building	46	MLK Jr Recreation Center	69	The route of travel does not provide a minimum width of 36 inches.	\$ 2,025	6	Medium		
Building	46	MLK Jr Recreation Center	71	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	72	There are no accessible bathing and shower facilities.	\$ 4,725	6	Medium		
Building	46	MLK Jr Recreation Center	77	The route of travel does not provide a minimum width of 36 inches.	\$ 2,025	6	Medium		
Building	46	MLK Jr Recreation Center	78	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	79	There are not enough accessible toilet compartments. The room contains 3 toilet compartments. A minimum of one must be wheelchair accessible .	\$ 4,725	6	Medium		
Building	46	MLK Jr Recreation Center	82	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	83	There are not enough accessible toilet compartments. The room contains 2 toilet compartments. A minimum of one must be wheelchair accessible .	\$ 4,725	6	Medium		
Building	46	MLK Jr Recreation Center	90	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	91	There are not enough accessible toilet compartments. The room contains 3 toilet compartments. A minimum of one must be wheelchair accessible .	\$ 4,725	6	Medium		
Building	46	MLK Jr Recreation Center	98	The room identification sign is noncompliant.	\$ 675	6	Medium		
Building	46	MLK Jr Recreation Center	100	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	104	The restroom is missing accessible fixtures or elements. The flush handle is located on the incorrect side the lavatory is in the toilets clear floor space rear and side grab bars are missing the sink is too high and does not provide knee and toe clearance the sink controls require tight grasping to operate and the toilet paper dispenser is located the incorrect distance in front of the toilet.	\$ 4,050	6	Medium		
Building	46	MLK Jr Recreation Center	106	The counter is too high.	\$ 2,700	6	Medium		
Building	46	MLK Jr Recreation Center	110	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	111	The top of the sink is above the allowable height requirement.	\$ 2,700	6	Medium		
Building	46	MLK Jr Recreation Center	112	The kitchen counter top is too high.	\$ -	6	Medium		
Building	46	MLK Jr Recreation Center	115	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	118	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	124	There is a change in level greater than 1/4 inch.	\$ 2,025	6	Medium		
Building	46	MLK Jr Recreation Center	125	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	46	MLK Jr Recreation Center	126	The kitchen counter top is too high.	\$ 3,375	6	Medium		
Building	46	MLK Jr Recreation Center	130	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	47	Natatorium	1	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	47	Natatorium	2	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	6	Medium		
Building	47	Natatorium	7	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	47	Natatorium	9	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	47	Natatorium	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	47	Natatorium	11	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	47	Natatorium	12	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	47	Natatorium	13	The walking surface is obstructed.	\$ 1,013	6	Medium		
Building	47	Natatorium	14	The tree limb extends down too close to the route of travel.	\$ 1,013	6	Medium		
Building	47	Natatorium	15	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	47	Natorium	16	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	47	Natorium	18	The walkway contains abrupt vertical edges and/or variations over 1/4 inch and a cross slope of 3.3 percent.	\$ 2,025	6	Medium		
Building	47	Natorium	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	47	Natorium	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	47	Natorium	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	47	Natorium	22	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	47	Natorium	27	The accessible route of travel contains cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	47	Natorium	28	The stairway handrails are not compliant. The handrails have the following issues:  The handrails are Installed at the incorrect height and the bottom handrail extensions are missing or extend incorrectly.	\$ 3,375	6	Medium		
Building	47	Natorium	29	The stairs extends down too close to the route of travel.	\$ 675	6	Medium		
Building	47	Natorium	30	The accessible route of travel contains cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	47	Natorium	31	There is a change in level greater than 1/4 inch.	\$ 1,013	6	Medium		
Building	47	Natorium	51	There are no accessible bathing and shower facilities.  The grab bars are not installed correctly the shower unit is missing and the transfer space is not provided.	\$ 5,400	6	Medium		
Building	47	Natorium	60	There are no accessible bathing and shower facilities.  The grab bars are not installed correctly the shower unit is missing and the transfer space is not provided.	\$ 5,400	6	Medium		
Building	47	Natorium	66	The restroom is missing accessible fixtures or elements.  The rear grab bar does not extend the correct distance on the open side of the toilet the lavatory is in the toilet clear floor space and the paper towel and soap dispenser are too high.	\$ 4,050	6	Medium		
Building	47	Natorium	67	The transfer shower compartment is not the minimum required size.  The grab bars are not installed correctly and the shower unit is missing.	\$ 5,400	6	Medium		
Building	47	Natorium	69	The restroom is missing accessible fixtures or elements.  The side grab bar is more than 12 inches off the back wall the door is not self-closing and the door is missing an inside loop handle.	\$ 1,485	6	Medium		
Building	48	New Central Fire Station	1	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	48	New Central Fire Station	2	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Building	48	New Central Fire Station	3	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	4	The stairway tread contains a change in elevation.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	6	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Building	48	New Central Fire Station	7	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Building	48	New Central Fire Station	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	12	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	48	New Central Fire Station	13	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	48	New Central Fire Station	14	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	15	The handrails do not meet minimum height requirements.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	16	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	17	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	18	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	19	The stairway tread contains a change in elevation.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	20	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	24	The drinking fountain projects from the wall into the pedestrian way with its leading edge above 27 inches from the floor.	\$ 675	6	Medium		
Building	48	New Central Fire Station	25	The emergency control buttons are not grouped together.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	26	The mail box projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	48	New Central Fire Station	27	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	48	New Central Fire Station	28	The restroom is missing accessible fixtures or elements.  The side grab bar does not extend the correct distance from the back wall the toilet paper dispenser is not installed the correct distance in front of the toilet and the door is missing an inside loop handle.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	31	The wall sign is incorrectly located.	\$ 338	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	48	New Central Fire Station	32	The restroom is missing accessible fixtures or elements. The side grab bar does not extend the correct distance from the back wall the toilet paper dispenser is not installed the correct distance in front of the toilet the door is obstructed by the chair and the door is missing an inside loop handle.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	36	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	48	New Central Fire Station	38	The room identification sign is noncompliant.	\$ 2,363	6	Medium		
Building	48	New Central Fire Station	41	The drinking fountain projects from the wall into the pedestrian way with its leading edge above 27 inches from the floor.	\$ 675	6	Medium		
Building	48	New Central Fire Station	51	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the rear grab bar does not extend the correct distance on the open side of the toilet and the toilet paper dispenser is not installed the correct distance in front of the toilet.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	55	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the rear grab bar does not extend the correct distance on the open side of the toilet the side grab bar does not extend the correct distance from the back wall and the toilet paper dispenser is not installed the correct distance in front of the toilet.	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	62	The drinking fountain projects from the wall into the pedestrian way with its leading edge above 27 inches from the floor.	\$ 675	6	Medium		
Building	48	New Central Fire Station	65	The television projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	48	New Central Fire Station	70	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	48	New Central Fire Station	72	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	48	New Central Fire Station	74	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	48	New Central Fire Station	86	The grate openings are greater than 1/2 inch and are parallel to the direction of travel. There are 2 grates per bay and 5 bays total	\$ 2,025	6	Medium		
Building	48	New Central Fire Station	90	There is a change in level greater than 1/4 inch.	\$ 1,013	6	Medium		
Building	49	North Branch Library	1	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 2,025	6	Medium		
Building	49	North Branch Library	2	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 2,025	6	Medium		
Building	49	North Branch Library	3	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 2,025	6	Medium		
Building	49	North Branch Library	4	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	49	North Branch Library	5	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Building	49	North Branch Library	7	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	49	North Branch Library	8	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ -	6	Medium		
Building	49	North Branch Library	9	The parking sign is mounted too low.	\$ 338	6	Medium		
Building	49	North Branch Library	10	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 2,025	6	Medium		
Building	49	North Branch Library	11	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 2,025	6	Medium		
Building	49	North Branch Library	12	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 2,025	6	Medium		
Building	49	North Branch Library	16	The entrance is not accessible and is missing signage.	\$ 338	6	Medium		
Building	49	North Branch Library	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	49	North Branch Library	23	The concrete expansion joints are spaced greater than 1/2 inch. All expansion joints on this path contain spacing greater than 1/2 inch.	\$ 203	6	Medium		
Building	49	North Branch Library	24	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	49	North Branch Library	25	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	49	North Branch Library	27	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	49	North Branch Library	28	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	49	North Branch Library	29	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	49	North Branch Library	30	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	49	North Branch Library	31	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 4,725	6	Medium		
Building	49	North Branch Library	33	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	49	North Branch Library	34	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	49	North Branch Library	35	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	49	North Branch Library	36	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Building	49	North Branch Library	37	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	49	North Branch Library	38	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	6	Medium		
Building	49	North Branch Library	39	The television projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	49	North Branch Library	43	Compliant room identification signs are missing.	\$ 338	6	Medium		
Building	49	North Branch Library	50	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	49	North Branch Library	51	The magazine rack projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	49	North Branch Library	52	The route of travel does not meet minimum width requirements around the book stacks.	\$ 3,375	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	49	North Branch Library	54	Compliant room identification signs are missing.	\$ 338	6	Medium		
Building	49	North Branch Library	55	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	49	North Branch Library	57	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	49	North Branch Library	60	Knee and toe space has not been provided at the sink.	\$ 2,700	6	Medium		
Building	49	North Branch Library	62	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	49	North Branch Library	66	Compliant room identification signs are missing.	\$ 338	6	Medium		
Building	49	North Branch Library	67	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	49	North Branch Library	68	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	49	North Branch Library	69	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	49	North Branch Library	84	The restroom is missing accessible fixtures or elements.  The rear and side grab bars are too high the side grab bar does not extend the correct distance the soap dispenser obstructs the rear grab bar and is in the toilet clear floor space the feminine product dispenser requires tight grasping to operate the lavatory is in the toilet clear floor space the lavatory does not provide the required knee and toe clearance the self-closing faucets do not remain open a minimum of 10 seconds the baby changing table is mounted too high the trash can obstructs the door maneuvering clearance and the coat hook is too high.	\$ 4,050	6	Medium		
Building	49	North Branch Library	85	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	49	North Branch Library	87	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	49	North Branch Library	88	The wall sign is mounted too high.	\$ 1,350	6	Medium		
Building	49	North Branch Library	91	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	50	North Lakes Annex	2	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	50	North Lakes Annex	3	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Building	50	North Lakes Annex	4	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 2,025	6	Medium		
Building	50	North Lakes Annex	5	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 2,025	6	Medium		
Building	50	North Lakes Annex	6	The required parking signage is missing.	\$ 338	6	Medium		
Building	50	North Lakes Annex	7	The required parking signage is missing.	\$ 338	6	Medium		
Building	50	North Lakes Annex	9	The water fountains project into the circulation path.	\$ 743	6	Medium		
Building	50	North Lakes Annex	13	The tree limbs extends down too close to the route of travel.	\$ 675	6	Medium		
Building	50	North Lakes Annex	14	The walking surface is obstructed by the landscaping.	\$ 743	6	Medium		
Building	50	North Lakes Annex	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Building	50	North Lakes Annex	18	The walking surface is obstructed by the landscaping.	\$ 743	6	Medium		
Building	50	North Lakes Annex	19	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	50	North Lakes Annex	25	The AED device projects into the headroom clearance in the circulation path.	\$ 338	6	Medium		
Building	50	North Lakes Annex	28	The top of the sink is above the allowable height requirement.	\$ 2,025	6	Medium		
Building	50	North Lakes Annex	29	The kitchen counter top is too high.	\$ 3,375	6	Medium		
Building	50	North Lakes Annex	30	The transfer shower compartment is not the minimum required size.	\$ 4,725	6	Medium		
Building	50	North Lakes Annex	34	The transfer shower compartment is not the minimum required size.	\$ 4,725	6	Medium		
Building	51	North Lakes Recreation Center	2	The ramp run has not been provided with edge protection.	\$ 1,013	6	Medium		
Building	51	North Lakes Recreation Center	3	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	51	North Lakes Recreation Center	4	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	51	North Lakes Recreation Center	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	51	North Lakes Recreation Center	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	51	North Lakes Recreation Center	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	51	North Lakes Recreation Center	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	51	North Lakes Recreation Center	9	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	51	North Lakes Recreation Center	10	Parked vehicles reduce the required width of the accessible route.	\$ 3,375	6	Medium		
Building	51	North Lakes Recreation Center	11	The accessible route contains surface materials that do not provide for a stable firm slip-resistant surface.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	16	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	51	North Lakes Recreation Center	17	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	21	The tree limbs extends down too close to the route of travel.	\$ 1,013	6	Medium		
Building	51	North Lakes Recreation Center	22	There is a change in level greater than 1/4 inch.	\$ 2,025	6	Medium		
Building	51	North Lakes Recreation Center	26	The water fountain projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	29	The element extends down too close to the route of travel.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	33	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	51	North Lakes Recreation Center	38	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	51	North Lakes Recreation Center	43	The tactile sign is incorrectly located.	\$ 338	6	Medium		
Building	51	North Lakes Recreation Center	48	Clear floor space is not provide at the tactile door sign.	\$ 675	6	Medium		
Building	51	North Lakes Recreation Center	57	Clear floor space is not provide at the tactile door sign.	\$ 338	6	Medium		
Building	51	North Lakes Recreation Center	61	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle rear grab bar does not extend the correct distance on the open side of the toilet stall the baby changing table is mounted too high.	\$ 1,350	6	Medium		
Building	51	North Lakes Recreation Center	63	There are no accessible bathing and shower facilities.	\$ 5,400	6	Medium		
Building	51	North Lakes Recreation Center	72	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the toilet center line is too far off the wall and the waste disposal is in the toilet clear floor space.	\$ 4,050	6	Medium		
Building	51	North Lakes Recreation Center	80	There are no accessible bathing and shower facilities.	\$ 5,400	6	Medium		
Building	51	North Lakes Recreation Center	83	The floor mat or carpet pile height is too high.	\$ 10,125	6	Medium		
Building	51	North Lakes Recreation Center	84	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 10,125	6	Medium		
Building	51	North Lakes Recreation Center	85	The floor mat or carpet pile height is too high.	\$ 10,125	6	Medium		
Building	51	North Lakes Recreation Center	87	The grate openings are greater than 1/2 inch and are parallel to the direction of travel.	\$ 338	6	Medium		
Building	51	North Lakes Recreation Center	90	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Building	51	North Lakes Recreation Center	91	The restroom is missing accessible fixtures or elements. The side grab bar is greater than 12 inches off the back wall the coat hook is too high and the paper towel dispenser is too high.	\$ 1,350	6	Medium		
Building	52	PCRP - Administration	2	The accessible route of travel contains a cross slope of 2.3 percent and a change in level.	\$ 2,025	6	Medium		
Building	52	PCRP - Administration	3	Stairways must have handrails on both sides.	\$ 1,013	6	Medium		
Building	52	PCRP - Administration	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	52	PCRP - Administration	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	52	PCRP - Administration	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	52	PCRP - Administration	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	52	PCRP - Administration	9	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	6	Medium		
Building	52	PCRP - Administration	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	52	PCRP - Administration	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	52	PCRP - Administration	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	52	PCRP - Administration	13	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Building	52	PCRP - Administration	14	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	52	PCRP - Administration	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	52	PCRP - Administration	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	52	PCRP - Administration	20	The walking surface is obstructed.	\$ 675	6	Medium		
Building	52	PCRP - Administration	21	The stairway handrails are not compliant. The bottom handrail extensions are missing or extend incorrectly and handrail is missing on one side.	\$ 1,013	6	Medium		
Building	52	PCRP - Administration	22	The stair nosing is not one of the compliant configurations.	\$ 2,025	6	Medium		
Building	52	PCRP - Administration	23	The stair nosing is not one of the compliant configurations.	\$ 2,025	6	Medium		
Building	52	PCRP - Administration	24	Non-accessible entrance/s signage missing.	\$ 338	6	Medium		
Building	52	PCRP - Administration	30	The cabinet projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	52	PCRP - Administration	31	The shelf projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	52	PCRP - Administration	53	A turning space is not provided within the room.	\$ 4,050	6	Medium		
Building	52	PCRP - Administration	54	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	52	PCRP - Administration	56	There are not enough accessible toilet compartments.	\$ 4,050	6	Medium		
Building	52	PCRP - Administration	63	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	52	PCRP - Administration	66	There are not enough accessible toilet compartments.	\$ 4,050	6	Medium		
Building	53	PCRP - Belt Press Building	3	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	6	Medium		
Building	53	PCRP - Belt Press Building	7	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	55	PCRP - Electronics Office	2	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	55	PCRP - Electronics Office	3	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	55	PCRP - Electronics Office	5	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	55	PCRP - Electronics Office	6	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	55	PCRP - Electronics Office	8	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	55	PCRP - Electronics Office	12	The stairway handrails are not compliant. The handrails have the following issues: - Missing on one side - The bottom handrail extensions are missing or extend incorrectly - The top handrail extensions are missing or extend incorrectly	\$ 2,025	6	Medium		
Building	56	PCRP - New Administration Building	4	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Building	56	PCRP - New Administration Building	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	56	PCRP - New Administration Building	6	The ramp landing has not been provided with edge protection.	\$ 1,013	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	58	PCRP - Operations Building	2	The walking surface is obstructed. A 36 inch wide minimum walking surface is required.	\$ 1,013	6	Medium		
Building	58	PCRP - Operations Building	11	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	59	PCRP - Pretreatment Building	1	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 4,725	6	Medium		
Building	59	PCRP - Pretreatment Building	2	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Building	59	PCRP - Pretreatment Building	16	The stairway contains open risers.	\$ 2,025	6	Medium		
Building	59	PCRP - Pretreatment Building	17	The stairway handrails are not nearly compliant. The handrails have the following issues: - Installed at the incorrect height - The bottom handrail extensions are missing or extend incorrectly - The top handrail extensions are missing or extend incorrectly - The handrail gripping surface is not the correct size	\$ 2,025	6	Medium		
Building	61	Quebec Hangars	2	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 4,050	6	Medium		
Building	61	Quebec Hangars	3	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	61	Quebec Hangars	4	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 4,050	6	Medium		
Building	61	Quebec Hangars	5	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	61	Quebec Hangars	6	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 4,050	6	Medium		
Building	61	Quebec Hangars	21	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	61	Quebec Hangars	22	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	61	Quebec Hangars	23	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Building	61	Quebec Hangars	30	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	62	Service Center	1	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	62	Service Center	2	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	62	Service Center	3	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	62	Service Center	4	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	62	Service Center	5	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	62	Service Center	6	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	62	Service Center	7	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	62	Service Center	8	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Building	62	Service Center	9	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ -	6	Medium		
Building	62	Service Center	10	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	62	Service Center	11	Non-accessible entrance/s signage missing.	\$ 2,025	6	Medium		
Building	62	Service Center	16	The stairway handrails are not compliant. Installed at the incorrect height and the bottom handrail extensions are missing.	\$ 2,025	6	Medium		
Building	62	Service Center	17	The stairway only has a handrail on one side.	\$ 2,025	6	Medium		
Building	62	Service Center	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	62	Service Center	19	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Building	62	Service Center	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	62	Service Center	22	There are not enough accessible toilet compartments. The room contains 7 toilet compartments. A minimum of one must be wheelchair accessible .	\$ 4,050	6	Medium		
Building	62	Service Center	23	The room contains 6 or more fixtures and therefore must have a minimum of one ambulatory toilet stall.	\$ 2,025	6	Medium		
Building	62	Service Center	24	There are no accessible shower facilities.	\$ 5,400	6	Medium		
Building	62	Service Center	33	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	62	Service Center	34	There are not enough accessible toilet compartments. The room contains 3 toilet compartments. A minimum of one must be wheelchair accessible.	\$ 4,050	6	Medium		
Building	62	Service Center	35	There are no accessible shower facilities.	\$ 5,400	6	Medium		
Building	62	Service Center	41	The restroom is missing accessible fixtures or elements. Door is not self-closing and is missing loop handles on the inside and outside of the door the side grab bar does not extend the correct distance from the back wall the sanitizer obstructs the rear grab bar and the toilet paper dispenser is not installed the correct distance in front of the toilet.	\$ 2,025	6	Medium		
Building	62	Service Center	42	The urinal is confined on three sides (alcove).	\$ 945	6	Medium		
Building	62	Service Center	44	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075	6	Medium		
Building	62	Service Center	45	The paper towel dispenser projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	62	Service Center	47	The restroom is missing accessible fixtures or elements. Door is not self-closing and is missing loop handles on the inside and outside of the door the side grab bar does not extend the correct distance from the back wall the sanitizer obstructs the rear grab bar the storage cabinet is in the door/toilet clear floor space and the toilet paper dispenser is not installed the correct distance in front of the toilet.	\$ 2,025	6	Medium		
Building	62	Service Center	51	The stairway contains open risers.	\$ 2,025	6	Medium		
Building	62	Service Center	52	The handrail does not extend for the correct distance at the bottom of the stairway.	\$ 1,013	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	62	Service Center	54	The fountain projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	62	Service Center	56	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	62	Service Center	58	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	62	Service Center	60	The top of the sink is above the allowable height requirement.	\$ 2,700	6	Medium		
Building	62	Service Center	61	Knee clearance has not been provided underneath the sink.	\$ -	6	Medium		
Building	62	Service Center	80	The grate openings are greater than 1/2 inch and are parallel to the direction of travel.	\$ 1,013	6	Medium		
Building	62	Service Center	81	The wall sign is mounted too high.	\$ 675	6	Medium		
Building	62	Service Center	88	The handrails do not meet minimum height requirements.	\$ 1,013	6	Medium		
Building	62	Service Center	97	The AED device projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	62	Service Center	104	The television projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	62	Service Center	117	The first aid box projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Building	62	Service Center	118	The wall sign is mounted too high.	\$ 338	6	Medium		
Building	62	Service Center	122	The room identification sign is noncompliant.	\$ 675	6	Medium		
Building	63	Solid Waste Fleet/Maintenance Shop	1	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	63	Solid Waste Fleet/Maintenance Shop	9	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	65	Solid Waste Services Building	1	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Building	65	Solid Waste Services Building	2	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	6	Medium		
Building	65	Solid Waste Services Building	3	The required parking signage is missing.	\$ 338	6	Medium		
Building	65	Solid Waste Services Building	4	The required parking signage is missing.	\$ 338	6	Medium		
Building	65	Solid Waste Services Building	10	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 1,013	6	Medium		
Building	65	Solid Waste Services Building	11	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	65	Solid Waste Services Building	12	The stairway contains open risers.	\$ 4,725	6	Medium		
Building	65	Solid Waste Services Building	13	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Building	65	Solid Waste Services Building	14	The top landing of the ramp does not meet minimum size requirements.	\$ 2,025	6	Medium		
Building	65	Solid Waste Services Building	15	The handrail does not extend past the ramp.	\$ 1,013	6	Medium		
Building	65	Solid Waste Services Building	18	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Building	65	Solid Waste Services Building	19	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 1,013	6	Medium		
Building	65	Solid Waste Services Building	21	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	65	Solid Waste Services Building	25	The water fountain projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	65	Solid Waste Services Building	26	The restroom does not include accessible fixtures or elements. The rear grab bar does not extend the correct distance on the open side of the toilet the urinal is in the toilets clear floor space the paper towel dispenser is mounted too high and the hand dryer is in the lavatory clear floor space.	\$ 4,050	6	Medium		
Building	65	Solid Waste Services Building	27	The restroom does not include accessible fixtures or elements. The cabinet is in the toilets clear floor space the toilet paper dispenser is not the correct distance from the front of the toilet the paper towel dispenser and toilet seat cover dispenser are mounted too high the trash can is in the door maneuvering space and the hand dryer is in the lavatory clear floor space.	\$ 4,050	6	Medium		
Building	65	Solid Waste Services Building	29	The first aid cabinet projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	65	Solid Waste Services Building	31	The room identification sign is noncompliant (20 rooms).	\$ 6,750	6	Medium		
Building	65	Solid Waste Services Building	35	The first aid cabinet projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	65	Solid Waste Services Building	38	The AED device projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	65	Solid Waste Services Building	40	The hand dryers project into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	65	Solid Waste Services Building	47	The hand dryer projects into the headroom clearance in the circulation path.	\$ 675	6	Medium		
Building	65	Solid Waste Services Building	53	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075	6	Medium		
Building	65	Solid Waste Services Building	54	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075	6	Medium		
Building	66	South Branch Library	3	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Building	66	South Branch Library	6	The curb ramp side flares exceed maximum slope allowances.	\$ 2,025	6	Medium		
Building	66	South Branch Library	7	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Building	66	South Branch Library	9	The curb ramp side flares exceed maximum slope allowances.	\$ 2,025	6	Medium		
Building	66	South Branch Library	10	The clear floor space required at the material return is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	6	Medium		
Building	66	South Branch Library	11	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	66	South Branch Library	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	66	South Branch Library	13	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	66	South Branch Library	14	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	66	South Branch Library	15	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Building	66	South Branch Library	18	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Building	66	South Branch Library	20	The ramp does not have compliant handrails.	\$ 1,013	6	Medium		
Building	66	South Branch Library	22	The route of travel does not meet minimum width requirements around the book stacks.	\$ 3,375	6	Medium		
Building	66	South Branch Library	23	The route of travel does not meet minimum width requirements around the book stacks.	\$ 3,375	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	66	South Branch Library	25	The route of travel does not provide a minimum width of 36 inches.	\$ 2,025	6	Medium		
Building	66	South Branch Library	28	The water fountains projects into the circulation path.	\$ 743	6	Medium		
Building	66	South Branch Library	30	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	66	South Branch Library	32	The urinal is confined on three sides and does not have the required clear floor space.	\$ 1,013	6	Medium		
Building	66	South Branch Library	34	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 3,375	6	Medium		
Building	66	South Branch Library	36	The restroom is missing accessible fixtures or elements.	\$ 1,283	6	Medium		
Building	66	South Branch Library	38	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 3,375	6	Medium		
Building	66	South Branch Library	40	The restroom is missing accessible fixtures or elements.	\$ 1,283	6	Medium		
Building	66	South Branch Library	43	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 3,375	6	Medium		
Building	66	South Branch Library	46	The restroom is missing accessible fixtures or elements.	\$ 2,025	6	Medium		
Building	66	South Branch Library	47	The AED device projects into the circulation path.	\$ 473	6	Medium		
Building	67	SW Triple Wide	2	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Building	67	SW Triple Wide	3	There is a change in level greater than 1/4 inch.	\$ 1,013	6	Medium		
Building	67	SW Triple Wide	4	The accessible route contains surface materials that does not provide for a slip resistant surface.	\$ 2,025	6	Medium		
Building	67	SW Triple Wide	5	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Building	67	SW Triple Wide	6	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	67	SW Triple Wide	7	The accessible route contains surface materials that does not provide for a slip resistant surface.	\$ 2,025	6	Medium		
Building	67	SW Triple Wide	8	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Building	67	SW Triple Wide	13	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	67	SW Triple Wide	16	The room identification sign is noncompliant.	\$ 338	6	Medium		
Building	69	Traffic Control	1	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 4,050	6	Medium		
Building	70	Transmission Engineering Department Building	3	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Building	70	Transmission Engineering Department Building	5	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Building	70	Transmission Engineering Department Building	6	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Building	70	Transmission Engineering Department Building	10	The defibrillator projects into the headroom clearance in the circulation path.	\$ 338	6	Medium		
Building	72	Utility Office/Field Operations	7	Stairways must have handrails on both sides.	\$ 1,013	6	Medium		
Building	72	Utility Office/Field Operations	8	The entrance is not accessible and is missing signage. An identification sign identifying that this entrance is not accessible and directional signage pointing to the accessible entrance is required.	\$ 338	6	Medium		
Building	72	Utility Office/Field Operations	9	The entrance is not accessible and is missing signage. An identification sign identifying that this entrance is not accessible and directional signage pointing to the accessible entrance is required.	\$ 338	6	Medium		
Building	72	Utility Office/Field Operations	10	Stairways must have handrails on both sides.	\$ 1,013	6	Medium		
Building	72	Utility Office/Field Operations	12	The AED device first aid kit and data sheets projects into the circulation path.	\$ 743	6	Medium		
Building	72	Utility Office/Field Operations	15	The television projects into the headroom clearance in the circulation path.	\$ 743	6	Medium		
Building	72	Utility Office/Field Operations	26	The restroom is missing accessible fixtures or elements. The side grab bar does not extend the correct distance the rear and side grab bar are mounted too high the toilet paper dispenser is not mounted the correct distance in front of the toilet and obstructs the side grab bar.	\$ 3,375	6	Medium		
Building	72	Utility Office/Field Operations	32	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	72	Utility Office/Field Operations	35	The restroom is missing accessible fixtures or elements. The door is missing an inside loop handle and is not self-closing rear grab bar is too high and does not extend the correct distance on either side of the toilet the side grab bar is mounted too high and does not extend the correct distance the toilet paper dispenser is not mounted on the correct side of the toilet compartment nor the correct distance in front of the toilet and the toilet seat cover obstructs the rear grab bar.	\$ 3,375	6	Medium		
Building	72	Utility Office/Field Operations	40	The wall sign is incorrectly located.	\$ 338	6	Medium		
Building	3	Airport Terminal and Admin Building	16	The drop box is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	3	Airport Terminal and Admin Building	33	There is no knee clearance under the drinking fountain.	\$ 3,375	7	Medium		
Building	5	American Legion Hall Senior Center	26	The total number of drinking fountains are not equally divided between those that are accessible to wheelchair users and those that are available to standing persons.	\$ 5,130	7	Medium		
Building	5	American Legion Hall Senior Center	27	The required clear floor space is not deep enough.	\$ 3,375	7	Medium		
Building	5	American Legion Hall Senior Center	28	The clear floor space required at accessible drinking fountains is not positioned for a forward approach.	\$ -	7	Medium		
Building	5	American Legion Hall Senior Center	29	The angle of the water stream is not compliant. The angle of the water stream shall be measured horizontally relative to the front face of the unit. Where spouts are located less than 3 inches of the front of the unit the angle of the water stream shall be 30 degrees maximum. Where spouts are located between 3 inches and 5 inches maximum from the front of the unit the angle of the water stream shall be 15 degrees maximum.	\$ 2,025	7	Medium		
Building	5	American Legion Hall Senior Center	30	The drinking fountain projects from the wall into the pedestrian way with its leading edge above 27 inches from the floor.	\$ 675	7	Medium		
Building	5	American Legion Hall Senior Center	46	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 945	7	Medium		
Building	5	American Legion Hall Senior Center	53	The toilet is not located within the range allowed from the side wall or partition.	\$ 3,105	7	Medium		
Building	5	American Legion Hall Senior Center	55	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 945	7	Medium		
Building	6	Monsignor King Outreach Center	32	One drinking fountain is provided and it is for standing persons.	\$ 5,130	7	Medium		
Building	6	Monsignor King Outreach Center	33	There are 10 lockers provided and none are accessible.	\$ 2,025	7	Medium		
Building	6	Monsignor King Outreach Center	39	Unable to determine the water flow of the fountain as fountain was not operational at the time of evaluation.	\$ 3,375	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	6	Monsignor King Outreach Center	40	There are 28 lockers and none are accessible.	\$ 2,025	7	Medium		
Building	6	Monsignor King Outreach Center	41	There are 16 lockers and none are accessible.	\$ 2,025	7	Medium		
Building	6	Monsignor King Outreach Center	44	There are 16 lockers provided and none are accessible.	\$ 2,025	7	Medium		
Building	6	Monsignor King Outreach Center	51	A bench is provided and it does not meet the depth requirements at 14 inches.	\$ 1,013	7	Medium		
Building	6	Monsignor King Outreach Center	53	The hand held sprayer unit is not equipped with a non-positive on/off control.	\$ 506	7	Medium		
Building	6	Monsignor King Outreach Center	54	The top rim of the lavatory is too high at 34-1/2 inches.	\$ 2,700	7	Medium		
Building	6	Monsignor King Outreach Center	55	The top rim of the lavatory is too high at 34-3/4 inches.	\$ 2,700	7	Medium		
Building	7	Center for Visual Arts	7	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Building	7	Center for Visual Arts	17	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	7	Center for Visual Arts	20	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Building	7	Center for Visual Arts	22	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Building	7	Center for Visual Arts	23	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Building	7	Center for Visual Arts	68	The faucet controls required force greater than 5 pounds to activate controls.	\$ 506	7	Medium		
Building	7	Center for Visual Arts	70	There are not enough drinking fountains.	\$ 5,130	7	Medium		
Building	7	Center for Visual Arts	92	The faucet controls require twisting of the wrist.	\$ 506	7	Medium		
Building	7	Center for Visual Arts	93	The controls are located such that operation require reaching across burners.	\$ 2,363	7	Medium		
Building	7	Center for Visual Arts	94	The microwave and oven controls are positioned too high for either a side or front approach.	\$ 2,025	7	Medium		
Building	7	Center for Visual Arts	97	The first aid kit is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	8	City Hall	10	The badge reader is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	8	City Hall	15	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Building	8	City Hall	16	The clear floor space required at the trash can is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Building	8	City Hall	68	The drinking fountain is not accessible. Knee clearance is not provided the water flow is less than 4 inches high clear floor space is not provided and the water fountain is an obstruction.	\$ 5,130	7	Medium		
Building	8	City Hall	70	The fire alarm is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	8	City Hall	71	The drop box is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	8	City Hall	82	Knee clearance at 27 inches off the floor is not 8 inches minimum deep.	\$ 1,013	7	Medium		
Building	8	City Hall	83	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Building	8	City Hall	87	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Building	8	City Hall	88	Knee clearance at 27 inches off the floor is not 8 inches minimum deep.	\$ 1,013	7	Medium		
Building	8	City Hall	98	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	9	City Hall East (Municipal Complex)	25	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	26	The drop box is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	44	There is no accessible route to the trash can.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	47	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	49	The utility payment box is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	53	The water flow from the spout does not meet minimum height requirements.	\$ 2,025	7	Medium		
Building	9	City Hall East (Municipal Complex)	54	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	55	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	59	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675	7	Medium		
Building	9	City Hall East (Municipal Complex)	60	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	62	The top rim of the lavatory is too high. There are three lavatories. The one with wrapped pipes too high. other 2 without the wrapped pipes are at the compliant height.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	63	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675	7	Medium		
Building	9	City Hall East (Municipal Complex)	64	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	72	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	73	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 2,025	7	Medium		
Building	9	City Hall East (Municipal Complex)	74	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Building	9	City Hall East (Municipal Complex)	77	Compliant knee space has not been provided under the lavatory.	\$ 2,700	7	Medium		
Building	9	City Hall East (Municipal Complex)	78	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	79	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 2,025	7	Medium		
Building	9	City Hall East (Municipal Complex)	81	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	85	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	92	The drinking fountain has multiple violations. Knee clearance is not provided the water flow is less than 4 inches and the fountain is a protruding object.	\$ 2,025	7	Medium		
Building	9	City Hall East (Municipal Complex)	109	The camera/intercom is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	110	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	111	The water flow from the spout does not meet minimum height requirements.	\$ 2,025	7	Medium		
Building	9	City Hall East (Municipal Complex)	113	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	126	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675	7	Medium		
Building	9	City Hall East (Municipal Complex)	127	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	9	City Hall East (Municipal Complex)	131	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675	7	Medium		
Building	9	City Hall East (Municipal Complex)	135	The drop box is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	136	The water flow from the spout does not meet minimum height requirements.	\$ 2,025	7	Medium		
Building	9	City Hall East (Municipal Complex)	137	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	138	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	139	The microwaves are positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	140	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	7	Medium		
Building	9	City Hall East (Municipal Complex)	146	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	149	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	9	City Hall East (Municipal Complex)	151	Accessible lockers are not provided. Locker room contains 60 total lockers and 3 need to be accessible.	\$ 2,025	7	Medium		
Building	9	City Hall East (Municipal Complex)	152	The hand held sprayer unit is mounted above the required maximum height.	\$ 473	7	Medium		
Building	9	City Hall East (Municipal Complex)	153	Accessible lockers are not provided. The locker room contains 52 lockers and 3 need to be accessible.	\$ 2,025	7	Medium		
Building	9	City Hall East (Municipal Complex)	154	The hand held sprayer unit is mounted above the required maximum height.	\$ 473	7	Medium		
Building	11	Civic Center	38	The elevator audible signal is missing.	\$ 3,375	7	Medium		
Building	11	Civic Center	39	The elevator visible signal is missing and/or non complaint.	\$ 3,375	7	Medium		
Building	11	Civic Center	40	The elevator does not have the correct doorjamb marking.	\$ 2,025	7	Medium		
Building	11	Civic Center	46	The vending machines are positioned too high for either a side or front approach.	\$ 3,375	7	Medium		
Building	11	Civic Center	51	The door to the toilet room swings into the required clear floor space required at the urinal.	\$ 2,025	7	Medium		
Building	11	Civic Center	52	Compliant knee space has not been provided under the lavatory (sink on the left side of the restroom).	\$ 2,025	7	Medium		
Building	11	Civic Center	53	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep (2 sinks on the right).	\$ 2,025	7	Medium		
Building	11	Civic Center	56	The water and drain pipes under the lavatory are not adequately insulated (2 on the left).	\$ 675	7	Medium		
Building	11	Civic Center	57	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,350	7	Medium		
Building	11	Civic Center	65	The water and drain pipes under the lavatory are not adequately insulated (4 total).	\$ 675	7	Medium		
Building	11	Civic Center	66	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,620	7	Medium		
Building	11	Civic Center	77	The urinal flush handle is located higher than 44 inches off the floor.	\$ 2,025	7	Medium		
Building	11	Civic Center	78	The restroom is missing accessible fixtures or elements. The inside loop handle is missing and the toilet paper dispenser is located the incorrect distance in front of the toilet.	\$ 1,013	7	Medium		
Building	11	Civic Center	81	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Building	11	Civic Center	83	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend the correct distance on the open side of the toilet the toilet paper dispenser is not the correct distance from the front of the toilet and the door is not self-closing and is missing a loop handle on the inside.	\$ 2,025	7	Medium		
Building	11	Civic Center	84	The coat hook is positioned too high for either a side or front approach.	\$ 473	7	Medium		
Building	12	Civic Center Pool	5	There are not enough drinking fountains.	\$ 5,130	7	Medium		
Building	12	Civic Center Pool	6	The clear floor space required at the fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Building	12	Civic Center Pool	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	7	Medium		
Building	12	Civic Center Pool	50	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,485	7	Medium		
Building	12	Civic Center Pool	52	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Building	12	Civic Center Pool	53	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Building	13	Denia Recreation Center	17	The clear floor space required at the trash cans is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Building	13	Denia Recreation Center	20	The handrail does not have the required extension at the top of the stair flight.	\$ 1,013	7	Medium		
Building	13	Denia Recreation Center	21	The handrails are not at the correct height.	\$ 1,013	7	Medium		
Building	13	Denia Recreation Center	22	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	13	Denia Recreation Center	24	The total number of drinking fountains are not equally divided between those that are accessible to wheelchair users and those that are available to standing persons.	\$ 5,130	7	Medium		
Building	13	Denia Recreation Center	25	The spout for the drinking fountain is too high.	\$ -	7	Medium		
Building	13	Denia Recreation Center	34	The bench is not deep enough.	\$ 878	7	Medium		
Building	13	Denia Recreation Center	35	The top rim of the lavatory is too high.	\$ 2,025	7	Medium		
Building	13	Denia Recreation Center	36	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	13	Denia Recreation Center	43	The bench is not deep enough.	\$ 878	7	Medium		
Building	13	Denia Recreation Center	44	The top rim of the lavatory is too high.	\$ 2,025	7	Medium		
Building	13	Denia Recreation Center	45	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	13	Denia Recreation Center	51	The coat rack is positioned too high for either a side or front approach.	\$ 743	7	Medium		
Building	16	Denton Senior Center	53	The element is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Building	16	Denton Senior Center	63	There is no accessible route to the smoking bench.	\$ 1,013	7	Medium		
Building	16	Denton Senior Center	71	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Building	16	Denton Senior Center	84	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	16	Denton Senior Center	87	The water flow from the spout is too low..	\$ 2,025	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	16	Denton Senior Center	91	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 945	7	Medium		
Building	16	Denton Senior Center	93	The bench is not deep enough.	\$ 1,013	7	Medium		
Building	16	Denton Senior Center	96	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 945	7	Medium		
Building	16	Denton Senior Center	97	The bench is not deep enough.	\$ 1,013	7	Medium		
Building	16	Denton Senior Center	99	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,418	7	Medium		
Building	16	Denton Senior Center	101	The bench is not deep enough.	\$ 1,013	7	Medium		
Building	16	Denton Senior Center	103	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,418	7	Medium		
Building	16	Denton Senior Center	105	The bench is not deep enough.	\$ 1,013	7	Medium		
Building	16	Denton Senior Center	106	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	7	Medium		
Building	16	Denton Senior Center	109	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	7	Medium		
Building	16	Denton Senior Center	110	The coat rack is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	16	Denton Senior Center	114	The medical emergency switch is positioned too high for either a side or front approach.	\$ 473	7	Medium		
Building	16	Denton Senior Center	117	The faucet controls require twisting of the wrist.	\$ 473	7	Medium		
Building	16	Denton Senior Center	118	The coat rack is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	16	Denton Senior Center	122	The emergency alarm is positioned too high for either a side or front approach.	\$ 675	7	Medium		
Building	16	Denton Senior Center	123	The coat rack is positioned too high for either a side or front approach.	\$ 1,350	7	Medium		
Building	16	Denton Senior Center	129	The sink drain pipes are exposed.	\$ 338	7	Medium		
Building	16	Denton Senior Center	130	The microwave is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	16	Denton Senior Center	131	The controls are located such that operation require reaching across burners.	\$ 2,025	7	Medium		
Building	16	Denton Senior Center	132	The hood vent controls are positioned too high for either a side or front approach.	\$ 743	7	Medium		
Building	16	Denton Senior Center	135	Clear floor space has not been provided at the sink.	\$ 338	7	Medium		
Building	16	Denton Senior Center	136	Knee and toe clearance has not been provided at the sink.	\$ 338	7	Medium		
Building	16	Denton Senior Center	142	The medical emergency switch is positioned too high for either a side or front approach.	\$ 473	7	Medium		
Building	20	Electric Administration Building	2	The doorbell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	20	Electric Administration Building	21	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	20	Electric Administration Building	22	Knee clearance at 27 inches off the floor is not 8 inches minimum deep.	\$ 1,013	7	Medium		
Building	20	Electric Administration Building	23	The self closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 338	7	Medium		
Building	20	Electric Administration Building	30	The top rim of the lavatory is too high.	\$ 2,025	7	Medium		
Building	20	Electric Administration Building	31	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 338	7	Medium		
Building	21	Emily Fowler Library	11	There is no accessible route to the trashcan and bench.	\$ 1,013	7	Medium		
Building	21	Emily Fowler Library	25	There is no accessible route to the trash can.	\$ 338	7	Medium		
Building	21	Emily Fowler Library	37	The water bottle filler control is positioned too high for either a side or front approach.	\$ 5,130	7	Medium		
Building	21	Emily Fowler Library	49	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 810	7	Medium		
Building	21	Emily Fowler Library	53	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 810	7	Medium		
Building	22	Engineering and Systems Operations	5	The door bell is positioned too high for either a side or front approach.	\$ 473	7	Medium		
Building	22	Engineering and Systems Operations	6	The door bell is positioned too high for either a side or front approach.	\$ 473	7	Medium		
Building	22	Engineering and Systems Operations	15	The restroom is missing accessible fixtures or elements.	\$ 1,283	7	Medium		
Building	22	Engineering and Systems Operations	16	Knee clearance at 27 inches off the floor is not 8 inches minimum deep.	\$ 1,013	7	Medium		
Building	22	Engineering and Systems Operations	17	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	22	Engineering and Systems Operations	18	The restroom is missing accessible fixtures or elements.	\$ 1,283	7	Medium		
Building	22	Engineering and Systems Operations	19	Knee clearance at 27 inches off the floor is not 8 inches minimum deep.	\$ 1,013	7	Medium		
Building	22	Engineering and Systems Operations	20	The self closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	23	Facilities Management	10	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	23	Facilities Management	20	The self closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	23	Facilities Management	23	The self closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	23	Facilities Management	45	The total number of drinking fountains are not equally divided between those that are accessible to wheelchair users and those that are available to standing persons.	\$ 5,130	7	Medium		
Building	26	Fire Station #2	5	The gate operating hardware is too high.	\$ 743	7	Medium		
Building	26	Fire Station #2	10	The restroom does not include accessible fixtures or elements.	\$ 3,375	7	Medium		
Building	27	Fire Station #3	11	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	29	Fire Station #5	9	There is no accessible route to the flag pole.	\$ 743	7	Medium		
Building	29	Fire Station #5	15	The telephone is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	29	Fire Station #5	19	There are not enough drinking fountains.	\$ 5,130	7	Medium		
Building	30	Fire Station #6	6	The flag pole controls are positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	30	Fire Station #6	13	The telephone is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	30	Fire Station #6	15	There are not enough drinking fountains.	\$ 5,130	7	Medium		
Building	30	Fire Station #6	39	There are not enough drinking fountains.	\$ 5,130	7	Medium		
Building	30	Fire Station #6	40	The clear floor space required at the drinking fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Building	31	Fire Station #7	9	The emergency alarm is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	32	Fire Station #8	7	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	34	Fleet Service Center	24	The total number of drinking fountains are not equally divided between those that are accessible to wheelchair users and those that are available to standing persons.	\$ 5,130	7	Medium		
Building	34	Fleet Service Center	27	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675	7	Medium		
Building	34	Fleet Service Center	28	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	35	Household Hazardous Waste Building	5	The rear grab bar does not extend adequately past the toilet on the wide side.	\$ 338	7	Medium		
Building	36	Landfill Weigh Station	2	There are no accessible tables.	\$ 1,013	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	8	There is no accessible route to the pet waste bag dispenser.	\$ 1,013	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	9	There is no accessible route to the pet waste bag dispenser.	\$ 1,013	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	12	The door bell is positioned too high for either a side or front approach.	\$ 675	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	15	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	27	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	28	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	29	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	36	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	38	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	37	Linda McNatt Animal Care and Adoption Center	43	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	39	LL WTP - Maintenance Building	9	The faucet controls are not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 405	7	Medium		
Building	40	LL WTP - Operations Building	15	The fire extinguisher projects more than 4 inches into the circulation path.  Wall-mounted objects that have leading edges between 27 inches and 80 inches from the floor must not project more than 4 inches into the circulation path. Protruding objects that extend to the floor or within 27 inches of the floor are cane detectable and are therefore not hazardous. Where it is necessary or desirable to have objects protrude from the wall a manner of cane detection must be provided.	\$ 675	7	Medium		
Building	40	LL WTP - Operations Building	29	The top rim of the lavatory is too high.	\$ 2,025	7	Medium		
Building	40	LL WTP - Operations Building	30	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675	7	Medium		
Building	44	Master Recycling Services - Building 101	5	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	46	MLK Jr Recreation Center	36	The doorbell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	46	MLK Jr Recreation Center	55	The vending machine operations are positioned too high for either a side or front approach.	\$ 3,375	7	Medium		
Building	46	MLK Jr Recreation Center	56	There is no drinking fountain for standing persons.	\$ 5,130	7	Medium		
Building	46	MLK Jr Recreation Center	66	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675	7	Medium		
Building	46	MLK Jr Recreation Center	67	Compliant knee space has not been provided under the lavatory.	\$ 2,025	7	Medium		
Building	46	MLK Jr Recreation Center	70	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Building	46	MLK Jr Recreation Center	76	Compliant knee space has not been provided under the lavatory.	\$ 2,025	7	Medium		
Building	46	MLK Jr Recreation Center	80	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675	7	Medium		
Building	46	MLK Jr Recreation Center	81	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Building	46	MLK Jr Recreation Center	85	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Building	46	MLK Jr Recreation Center	86	The top rim of the lavatory is too high.	\$ 2,025	7	Medium		
Building	46	MLK Jr Recreation Center	87	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Building	46	MLK Jr Recreation Center	92	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Building	46	MLK Jr Recreation Center	93	The top rim of the lavatory is too high.	\$ 2,025	7	Medium		
Building	46	MLK Jr Recreation Center	94	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Building	46	MLK Jr Recreation Center	119	The wheelchair spaces are not integrated within the seating area.	\$ 3,375	7	Medium		
Building	46	MLK Jr Recreation Center	121	The drinking fountain is not accessible.  Requires tight grasping to operate and knee and toe clearance are not provided	\$ 6,075	7	Medium		
Building	46	MLK Jr Recreation Center	123	The hooks for equipment are positioned too high for either a side or front approach.	\$ 675	7	Medium		
Building	46	MLK Jr Recreation Center	128	The stove hood controls are positioned too high for either a side or front approach.	\$ 2,025	7	Medium		
Building	47	Natatorium	25	The comment box is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	47	Natatorium	26	The vending machine operations are positioned too high for either a side or front approach.	\$ 2,025	7	Medium		
Building	47	Natatorium	33	The water faucet is not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 506	7	Medium		
Building	47	Natatorium	47	There is not enough knee clearance under the drinking fountain.	\$ 5,130	7	Medium		
Building	48	New Central Fire Station	5	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	48	New Central Fire Station	21	The emergency button is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	48	New Central Fire Station	22	There is not enough knee clearance under the drinking fountain.	\$ 2,025	7	Medium		
Building	48	New Central Fire Station	23	The spout for the drinking fountain is too low.	\$ 2,025	7	Medium		
Building	48	New Central Fire Station	29	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	48	New Central Fire Station	33	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	48	New Central Fire Station	39	There is not enough knee clearance under the drinking fountain.	\$ 2,025	7	Medium		
Building	48	New Central Fire Station	40	The spout for the drinking fountain is too low.	\$ 2,025	7	Medium		
Building	48	New Central Fire Station	47	The maneuvering clearance on the pull side of the door is obstructed.	\$ 1,013	7	Medium		
Building	48	New Central Fire Station	60	There is not enough knee clearance under the drinking fountain.	\$ 2,025	7	Medium		
Building	48	New Central Fire Station	61	The spout for the drinking fountain is too low.	\$ 2,025	7	Medium		
Building	48	New Central Fire Station	88	There is not enough knee clearance under the drinking fountain.	\$ 2,025	7	Medium		
Building	48	New Central Fire Station	89	The spout for the drinking fountain is too low.	\$ 2,025	7	Medium		
Building	49	North Branch Library	20	There is no accessible route to the table.	\$ 2,025	7	Medium		
Building	49	North Branch Library	21	There is no accessible route to the table.	\$ 2,025	7	Medium		
Building	49	North Branch Library	22	There is no accessible route to the trash can.	\$ 338	7	Medium		
Building	49	North Branch Library	40	The telephone is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	49	North Branch Library	41	The water flow from the spout is too low.	\$ 3,375	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	49	North Branch Library	42	The water bottle filler is positioned too high for either a side or front approach.	\$ 3,375	7	Medium		
Building	49	North Branch Library	44	The spout for the drinking fountain is too high.	\$ 3,375	7	Medium		
Building	49	North Branch Library	45	The water flow from the spout is too low.	\$ -	7	Medium		
Building	49	North Branch Library	46	The water bottle filler is positioned too high for either a side or front approach.	\$ 3,375	7	Medium		
Building	49	North Branch Library	53	The vending machine operations is positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	49	North Branch Library	72	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	49	North Branch Library	73	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Building	49	North Branch Library	79	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	49	North Branch Library	80	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Building	50	North Lakes Annex	23	There is no accessible route to the bench.	\$ 3,375	7	Medium		
Building	50	North Lakes Annex	24	There is not enough knee clearance under the drinking fountain.	\$ 5,130	7	Medium		
Building	50	North Lakes Annex	31	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 810	7	Medium		
Building	50	North Lakes Annex	32	Accessible lockers are not provided.	\$ 2,025	7	Medium		
Building	50	North Lakes Annex	33	There is no compliant bench within the room.	\$ 338	7	Medium		
Building	50	North Lakes Annex	35	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 810	7	Medium		
Building	50	North Lakes Annex	36	Accessible lockers are not provided.	\$ 2,025	7	Medium		
Building	50	North Lakes Annex	37	There is no compliant bench within the room.	\$ 338	7	Medium		
Building	50	North Lakes Annex	39	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 405	7	Medium		
Building	50	North Lakes Annex	41	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 405	7	Medium		
Building	51	North Lakes Recreation Center	25	The water flow from the spout is too low.	\$ 506	7	Medium		
Building	51	North Lakes Recreation Center	27	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	51	North Lakes Recreation Center	31	The total number of drinking fountains are not equally divided between those that are accessible to wheelchair users and those that are available to standing persons. The center has 4 fountains: 3 accessible 1 standing	\$ 5,130	7	Medium		
Building	51	North Lakes Recreation Center	42	The lock boxes are not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 1,013	7	Medium		
Building	51	North Lakes Recreation Center	49	Knee and toe space has not been provided at the sink.	\$ 1,013	7	Medium		
Building	51	North Lakes Recreation Center	56	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	7	Medium		
Building	51	North Lakes Recreation Center	67	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	51	North Lakes Recreation Center	68	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	51	North Lakes Recreation Center	76	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	51	North Lakes Recreation Center	77	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	7	Medium		
Building	52	PCRP - Administration	38	The total number of drinking fountains are not equally divided between those that are accessible to wheelchair users and those that are available to standing persons.	\$ 5,130	7	Medium		
Building	52	PCRP - Administration	39	The total number of drinking fountains are not equally divided between those that are accessible to wheelchair users and those that are available to standing persons.	\$ 5,130	7	Medium		
Building	59	PCRP - Pretreatment Building	3	The faucet controls require twisting of the wrist.	\$ 4,050	7	Medium		
Building	59	PCRP - Pretreatment Building	6	The faucet controls require twisting of the wrist.	\$ 405	7	Medium		
Building	59	PCRP - Pretreatment Building	8	The faucet controls require twisting of the wrist.	\$ 405	7	Medium		
Building	59	PCRP - Pretreatment Building	9	The faucet controls require twisting of the wrist.	\$ 405	7	Medium		
Building	62	Service Center	25	The bench does not meet the depth requirements.	\$ 1,013	7	Medium		
Building	62	Service Center	27	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Building	62	Service Center	31	Compliant knee space has not been provided under the lavatory.	\$ 2,700	7	Medium		
Building	62	Service Center	36	The bench does not meet the depth requirements.	\$ 1,013	7	Medium		
Building	62	Service Center	38	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	62	Service Center	43	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	62	Service Center	48	The top rim of the lavatory is too high.	\$ 2,700	7	Medium		
Building	62	Service Center	49	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	62	Service Center	53	The required clear floor space is not deep enough at the fountain.	\$ 3,375	7	Medium		
Building	62	Service Center	57	The fire alarm is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	62	Service Center	62	The soap and paper towel dispenser are positioned too high for either a side or front approach.	\$ 675	7	Medium		
Building	62	Service Center	63	The AED device is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	62	Service Center	93	The AED device is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	62	Service Center	94	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	7	Medium		
Building	62	Service Center	95	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	7	Medium		
Building	62	Service Center	102	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	7	Medium		
Building	62	Service Center	103	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	7	Medium		
Building	62	Service Center	134	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	7	Medium		
Building	62	Service Center	135	The AED device is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	62	Service Center	136	The vending machine operation is positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Building	65	Solid Waste Services Building	23	The required clear floor space is not deep enough.	\$ 338	7	Medium		
Building	65	Solid Waste Services Building	24	The knee clearance is not compliant.	\$ 5,130	7	Medium		
Building	65	Solid Waste Services Building	51	The required clear floor space is not deep enough.	\$ 1,013	7	Medium		
Building	66	South Branch Library	16	The door bell is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	66	South Branch Library	29	The charging station is positioned too high for either a side or front approach.	\$ 338	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	66	South Branch Library	37	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 10,125	7	Medium		
Building	66	South Branch Library	41	The water and drain pipes under the lavatory are not adequately insulated.	\$ 675	7	Medium		
Building	66	South Branch Library	42	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 945	7	Medium		
Building	69	Traffic Control	6	The mailbox is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	71	Truck Wash	1	The drop box is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Building	72	Utility Office/Field Operations	13	The required clear floor space at the drinking fountain is not deep enough.	\$ 5,130	7	Medium		
Building	72	Utility Office/Field Operations	14	The water fountains projects into the circulation path.	\$ -	7	Medium		
Building	11	Civic Center	45	The water flow from the spout is too low..	\$ 2,025	8	Medium		
Building	23	Facilities Management	33	There is not enough knee clearance under the drinking fountain.	\$ 2,025	8	Medium		
Building	26	Fire Station #2	26	The water flow from the spout is too low.	\$ 2,025	8	Medium		
Building	29	Fire Station #5	20	The required clear floor space is not wide enough.	\$ 2,025	8	Medium		
Building	29	Fire Station #5	21	The knee clearance is not compliant.	\$ 1,013	8	Medium		
Building	29	Fire Station #5	22	There is not enough toe space clearance at the drinking fountain.	\$ -	8	Medium		
Park	1	Avondale Park	4	The access aisle contains dilapidated striping.	\$ 473	5	Medium		
Park	1	Avondale Park	6	There is no accessible route to the port-o-let.	\$ 2,025	5	Medium		
Park	1	Avondale Park	14	The bench is not accessible because there is not adequate clear floor space.	\$ 743	5	Medium		
Park	1	Avondale Park	23	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	1	Avondale Park	24	The gate does not provide at least 32 inches between the face of the gate and the opposite stop.	\$ 2,025	5	Medium		
Park	2	Bowling Green Park	14	There is no accessible route to the community garden.	\$ 3,375	5	Medium		
Park	2	Bowling Green Park	16	There are not enough accessible elevated play components.	\$ 3,375	5	Medium		
Park	3	Briercliff Park	10	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	4	Carl Young Sr. Park	2	There is no accessible route to the multi-purpose fields.	\$ 2,025	5	Medium		
Park	4	Carl Young Sr. Park	25	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	4	Carl Young Sr. Park	26	There is no accessible route to the playground.	\$ 3,375	5	Medium		
Park	4	Carl Young Sr. Park	27	There is no accessible route to the swings.	\$ 3,375	5	Medium		
Park	4	Carl Young Sr. Park	28	The transfer platform is not within the compliant range above the ground. The height of transfer platforms shall be 11 inches minimum and 18 inches maximum measured to the top of the surface from the ground or floor surface.	\$ 2,025	5	Medium		
Park	4	Carl Young Sr. Park	30	The maneuvering clearance on the push side of the door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Park	4	Carl Young Sr. Park	32	The maneuvering clearance on the push side of the door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Park	5	Carnegie Ridge Park	3	There is no accessible route to connect the sidewalk to the playground.	\$ 2,025	5	Medium		
Park	6	Clear Creek Natural Heritage Center	5	There are no accessible tables.	\$ 1,013	5	Medium		
Park	6	Clear Creek Natural Heritage Center	12	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Park	6	Clear Creek Natural Heritage Center	13	The door operating hardware is not accessible.	\$ 506	5	Medium		
Park	6	Clear Creek Natural Heritage Center	19	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 2,025	5	Medium		
Park	6	Clear Creek Natural Heritage Center	31	The maneuvering clearance at the entrance door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Park	9	Cross Timbers Park North	11	There is no accessible route to the playground.	\$ 2,025	5	Medium		
Park	9	Cross Timbers Park North	23	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	10	Cross Timbers Park South	1	There is no accessible route to the volleyball court.	\$ 2,025	5	Medium		
Park	10	Cross Timbers Park South	2	There is no accessible route to the grill.	\$ 2,025	5	Medium		
Park	10	Cross Timbers Park South	3	There is no accessible route to the picnic table.	\$ 2,025	5	Medium		
Park	10	Cross Timbers Park South	4	The transfer space is sloped greater than 2 percent.	\$ 2,025	5	Medium		
Park	11	Denia Park	6	The striping and markings for the accessible parking stall is dilapidated and in need of repair or maintenance.	\$ 338	5	Medium		
Park	11	Denia Park	34	There is no accessible route to the table and grill.	\$ 2,025	5	Medium		
Park	11	Denia Park	35	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	11	Denia Park	69	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Park	11	Denia Park	73	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Park	11	Denia Park	75	The gate does not have a smooth surface at the bottom on the push side.	\$ 473	5	Medium		
Park	11	Denia Park	76	There is no accessible route to connect the sidewalk to the playground.	\$ 2,025	5	Medium		
Park	11	Denia Park	77	There is no accessible route to connect the sidewalk to the playground.	\$ 2,025	5	Medium		
Park	11	Denia Park	78	The transfer platform is not within the compliant range above the ground.	\$ 2,025	5	Medium		
Park	11	Denia Park	80	The transfer platform is not within the compliant range above the ground.	\$ 2,025	5	Medium		
Park	11	Denia Park	84	The softball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	11	Denia Park	85	The softball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	11	Denia Park	86	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	11	Denia Park	87	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	11	Denia Park	92	The softball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	11	Denia Park	93	The softball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	11	Denia Park	95	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	11	Denia Park	96	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	11	Denia Park	97	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	11	Denia Park	102	The softball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	11	Denia Park	104	There are no accessible tables.	\$ 1,013	5	Medium		
Park	11	Denia Park	106	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	11	Denia Park	107	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	11	Denia Park	108	The gate does not open at least 90 degrees.	\$ 675	5	Medium		
Park	11	Denia Park	109	The gate does not provide at least 32 inches between the face of the gate and the opposite stop.	\$ 2,700	5	Medium		
Park	11	Denia Park	110	The gate does not provide at least 32 inches between the face of the gate and the opposite stop.	\$ 2,700	5	Medium		
Park	11	Denia Park	111	There is no accessible route to the hockey rink.	\$ 2,025	5	Medium		
Park	11	Denia Park	112	There is no accessible route to the basketball court.	\$ 2,025	5	Medium		
Park	11	Denia Park	113	There is no accessible route to the grill.	\$ 1,013	5	Medium		
Park	11	Denia Park	114	There are no accessible tables.	\$ 1,013	5	Medium		
Park	11	Denia Park	115	There is no accessible route to the multipurpose field.	\$ 2,025	5	Medium		
Park	12	Evers Park	102	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	12	Evers Park	103	The door does not open at least 90 degrees.	\$ 675	5	Medium		
Park	12	Evers Park	109	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Park	12	Evers Park	111	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	12	Evers Park	112	The door does not open at least 90 degrees.	\$ 675	5	Medium		
Park	12	Evers Park	115	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Park	12	Evers Park	116	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	5	Medium		
Park	12	Evers Park	117	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	12	Evers Park	128	The walkway contains abrupt vertical edges or variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	129	The walkway contains abrupt vertical edges and variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	131	There are no accessible scorer's table.	\$ 1,013	5	Medium		
Park	12	Evers Park	133	There are no accessible scorer's table.	\$ 1,013	5	Medium		
Park	12	Evers Park	135	The gate does not open at least 90 degrees and does not have a 10 inch smooth surface at the bottom.	\$ 2,025	5	Medium		
Park	12	Evers Park	136	The baseball participation area is not on an accessible route.	\$ 1,013	5	Medium		
Park	12	Evers Park	137	The walkway contains abrupt vertical edges and variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	138	The baseball participation area is not on an accessible route.	\$ 1,013	5	Medium		
Park	12	Evers Park	139	The baseball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	12	Evers Park	140	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	141	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	142	The walkway contains abrupt vertical edges and variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	143	The walkway contains abrupt vertical edges and variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	145	There are no accessible scorer's table.	\$ 1,013	5	Medium		
Park	12	Evers Park	149	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	150	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	152	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	154	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	155	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	156	There are no accessible scorer's table.	\$ 1,013	5	Medium		
Park	12	Evers Park	158	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	159	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	160	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	161	The gates do not have a smooth surface at the bottom on the push side.	\$ 3,038	5	Medium		
Park	12	Evers Park	163	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	164	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	165	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	166	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	167	The walkway contains abrupt vertical edges and variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	168	There are no accessible scorer's table.	\$ 1,013	5	Medium		
Park	12	Evers Park	169	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	170	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	172	There are no accessible scorer's tables.	\$ 1,013	5	Medium		
Park	12	Evers Park	173	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	174	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	175	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	176	There is no accessible route to connect the sidewalk to the ball field and dugout.	\$ 2,025	5	Medium		
Park	12	Evers Park	177	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	178	There is step at the entrances onto the ball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	179	No wheelchair seating is provided at the bleacher seating areas at the baseball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	181	There is no accessible route to connect the sidewalk to the ball field and dugout.	\$ 2,025	5	Medium		
Park	12	Evers Park	182	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	183	There is step at the entrances onto the ball field.	\$ 2,025	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	12	Evers Park	184	No accessible wheelchair seating is provided.	\$ 2,025	5	Medium		
Park	12	Evers Park	185	There is step at the entrances onto the ball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	186	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	187	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	188	There is no accessible route to connect the sidewalk to the ball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	189	There is step at the entrances onto the ball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	190	No accessible wheelchair seating is provided.	\$ 2,025	5	Medium		
Park	12	Evers Park	191	No accessible wheelchair seating is provided.	\$ 2,025	5	Medium		
Park	12	Evers Park	192	There is no accessible route to connect the sidewalk to the ball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	193	There is no accessible route to connect the sidewalk to the ball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	194	There is no accessible route to connect the sidewalk to the ball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	196	No accessible wheelchair seating is provided.	\$ 2,025	5	Medium		
Park	12	Evers Park	197	No accessible wheelchair seating is provided.	\$ 2,025	5	Medium		
Park	12	Evers Park	198	There is no accessible route to the dugout.	\$ 2,025	5	Medium		
Park	12	Evers Park	199	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	200	There is step at the entrances onto the ball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	201	There is step at the entrances onto the ball field.	\$ 2,025	5	Medium		
Park	12	Evers Park	202	An accessible wheelchair space is not provided in the team/player seating area.	\$ 1,013	5	Medium		
Park	12	Evers Park	204	There are no accessible scorer's tables.	\$ 1,013	5	Medium		
Park	12	Evers Park	206	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	207	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	208	There is no accessible route to connect the sidewalk to the ball field and dugout.	\$ 2,025	5	Medium		
Park	12	Evers Park	209	There is no accessible route to connect the sidewalk to the ball field and dugout.	\$ 2,025	5	Medium		
Park	12	Evers Park	210	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	213	The stairway only has a handrail on one side.	\$ 2,025	5	Medium		
Park	12	Evers Park	215	The stairway only has a handrail on one side.	\$ 2,025	5	Medium		
Park	12	Evers Park	216	The stairway only has a handrail on one side.	\$ 2,025	5	Medium		
Park	12	Evers Park	217	The gate does not open at least 90 degrees.	\$ 2,025	5	Medium		
Park	12	Evers Park	218	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	5	Medium		
Park	12	Evers Park	219	The ball field participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	12	Evers Park	220	The ball field participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	12	Evers Park	221	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	5	Medium		
Park	12	Evers Park	222	There are no accessible scorer's table.	\$ 1,013	5	Medium		
Park	12	Evers Park	224	The stairway tread contains a change in elevation.	\$ 3,375	5	Medium		
Park	13	Fred Moore Park	21	There is no accessible route to the bleachers.	\$ 2,025	5	Medium		
Park	13	Fred Moore Park	28	There is no accessible route to the bleachers.	\$ 2,025	5	Medium		
Park	13	Fred Moore Park	39	There is no accessible route to the bleachers.	\$ 3,375	5	Medium		
Park	13	Fred Moore Park	40	The baseball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	13	Fred Moore Park	42	There is no accessible route to the scorer's area.	\$ 2,025	5	Medium		
Park	13	Fred Moore Park	43	Wheelchair spaces shall be provided in assembly areas with fixed seating.	\$ 3,375	5	Medium		
Park	13	Fred Moore Park	44	Wheelchair spaces shall be provided in assembly areas with fixed seating.	\$ 3,375	5	Medium		
Park	13	Fred Moore Park	46	There is no accessible route to the bleachers.	\$ 3,375	5	Medium		
Park	13	Fred Moore Park	47	The baseball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	13	Fred Moore Park	48	There are no accessible tables.	\$ 1,013	5	Medium		
Park	13	Fred Moore Park	49	There is no accessible route to the grill.	\$ 1,013	5	Medium		
Park	13	Fred Moore Park	50	There are no accessible tables.	\$ 1,013	5	Medium		
Park	13	Fred Moore Park	51	There are no accessible tables.	\$ 1,013	5	Medium		
Park	13	Fred Moore Park	54	There is no accessible route to the grill.	\$ 1,013	5	Medium		
Park	13	Fred Moore Park	55	There is no accessible route to the bleachers.	\$ 2,025	5	Medium		
Park	13	Fred Moore Park	56	Wheelchair spaces shall be provided in assembly areas with fixed seating.	\$ 3,375	5	Medium		
Park	14	Frontier Park	1	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	14	Frontier Park	3	There is no accessible route to the table.	\$ 1,013	5	Medium		
Park	15	Goldfield Tennis Center	12	The bleacher is not accessible because there is not adequate clear floor space for an approach.	\$ 2,025	5	Medium		
Park	15	Goldfield Tennis Center	15	The bleacher is not accessible because there is not adequate clear floor space for an approach.	\$ 2,025	5	Medium		
Park	15	Goldfield Tennis Center	16	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	15	Goldfield Tennis Center	17	The bleacher is not accessible because there is not adequate clear floor space for an approach.	\$ 2,025	5	Medium		
Park	15	Goldfield Tennis Center	25	The gate does not provide at least 32 inches between the face of the gate and the opposite stop.	\$ 3,375	5	Medium		
Park	15	Goldfield Tennis Center	26	There is no accessible route to the bench.	\$ 2,025	5	Medium		
Park	15	Goldfield Tennis Center	27	There is no accessible route to the bench.	\$ 2,025	5	Medium		
Park	15	Goldfield Tennis Center	29	The threshold is greater than 1/2 inch high.	\$ 2,025	5	Medium		
Park	15	Goldfield Tennis Center	30	The threshold is greater than 1/2 inch high.	\$ 2,025	5	Medium		
Park	15	Goldfield Tennis Center	31	The threshold is greater than 1/2 inch high.	\$ 2,025	5	Medium		
Park	15	Goldfield Tennis Center	32	There are no accessible tables.	\$ 1,013	5	Medium		
Park	15	Goldfield Tennis Center	33	The transaction counter is too high.	\$ 2,700	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	15	Goldfield Tennis Center	39	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Park	17	Industrial Park	1	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	5	Medium		
Park	17	Industrial Park	3	There are no accessible tables.	\$ 1,013	5	Medium		
Park	20	Joe Skiles Park	10	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	20	Joe Skiles Park	11	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	20	Joe Skiles Park	12	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	20	Joe Skiles Park	13	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	20	Joe Skiles Park	14	The gate does not provide at least 32 inches between the face of the gate and the opposite stop.	\$ 2,700	5	Medium		
Park	20	Joe Skiles Park	15	The gate does not provide at least 32 inches between the face of the gate and the opposite stop.	\$ 2,700	5	Medium		
Park	20	Joe Skiles Park	16	There is no accessible route to connect the sidewalk to the playground.	\$ 2,025	5	Medium		
Park	20	Joe Skiles Park	19	There is no accessible route to the picnic shelter.	\$ 2,025	5	Medium		
Park	21	Lake Forest Park	32	The gate does not have a smooth surface at the bottom on the push side and requires more than 5 pounds of force to open.	\$ 1,013	5	Medium		
Park	21	Lake Forest Park	33	The maneuvering clearance on the pull side of the gate extends less than 18 inches on the latch side.	\$ 2,025	5	Medium		
Park	21	Lake Forest Park	34	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 1,013	5	Medium		
Park	21	Lake Forest Park	39	There is no accessible route to the picnic area.	\$ 3,375	5	Medium		
Park	21	Lake Forest Park	43	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	21	Lake Forest Park	44	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,485	5	Medium		
Park	21	Lake Forest Park	49	The maneuvering clearance on the pull side of the gate extends less than 18 inches on the latch side.	\$ 2,025	5	Medium		
Park	21	Lake Forest Park	50	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 1,148	5	Medium		
Park	21	Lake Forest Park	55	The gate does not have a smooth surface at the bottom on the push side and requires more than 5 pounds of force to open.	\$ 1,013	5	Medium		
Park	21	Lake Forest Park	56	The gate does not have a smooth surface at the bottom on the push side and requires more than 5 pounds of force to open.	\$ 2,025	5	Medium		
Park	21	Lake Forest Park	57	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	21	Lake Forest Park	59	There are no accessible tables.	\$ 1,013	5	Medium		
Park	21	Lake Forest Park	62	The transfer platform is not level.	\$ 3,375	5	Medium		
Park	22	Mack Park	18	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	22	Mack Park	27	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	22	Mack Park	28	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	22	Mack Park	42	There is no accessible route to the tables.	\$ 1,013	5	Medium		
Park	22	Mack Park	43	There is no accessible route to the water fountain.	\$ 2,025	5	Medium		
Park	22	Mack Park	44	The portable public restroom is not compliant.	\$ 4,725	5	Medium		
Park	22	Mack Park	46	There is no accessible route to the tables and trash can.	\$ 2,025	5	Medium		
Park	22	Mack Park	50	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	22	Mack Park	51	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	22	Mack Park	52	There is no accessible route to connect the sidewalk to the playground.	\$ 2,025	5	Medium		
Park	22	Mack Park	53	There is no accessible route to connect the sidewalk to the playground.	\$ 2,025	5	Medium		
Park	22	Mack Park	57	The transfer space is sloped greater than 2 percent.	\$ 2,025	5	Medium		
Park	22	Mack Park	58	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	22	Mack Park	79	The baseball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	22	Mack Park	80	The baseball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	22	Mack Park	81	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	22	Mack Park	82	There is no accessible route to the bull pen.	\$ 2,025	5	Medium		
Park	22	Mack Park	84	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	22	Mack Park	86	The floor surface at the bleachers does not appear to be firm stable or slip resistant.	\$ 3,375	5	Medium		
Park	22	Mack Park	88	There is no accessible route to the bull pen.	\$ 2,025	5	Medium		
Park	22	Mack Park	90	The floor surface at the bleachers does not appear to be firm stable or slip resistant.	\$ 3,375	5	Medium		
Park	22	Mack Park	92	The baseball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	22	Mack Park	93	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	22	Mack Park	94	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	22	Mack Park	95	The baseball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	22	Mack Park	96	There is no accessible route to the bull pen.	\$ 2,025	5	Medium		
Park	22	Mack Park	99	The wheelchair seating spaces are not on an accessible route.	\$ 2,025	5	Medium		
Park	22	Mack Park	101	The floor surface at the bleachers does not appear to be firm stable or slip resistant.	\$ 3,375	5	Medium		
Park	22	Mack Park	102	There is no accessible route to the bull pen.	\$ 2,025	5	Medium		
Park	22	Mack Park	103	The floor surface at the bleachers does not appear to be firm stable or slip resistant.	\$ 3,375	5	Medium		
Park	22	Mack Park	104	The floor surface at the bleachers does not appear to be firm stable or slip resistant.	\$ 3,375	5	Medium		
Park	22	Mack Park	106	The baseball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	22	Mack Park	107	The baseball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	22	Mack Park	109	An accessible wheelchair space is not provided in the player seating area.	\$ 2,025	5	Medium		
Park	22	Mack Park	110	An accessible wheelchair space is not provided in the player seating area.	\$ 2,025	5	Medium		
Park	22	Mack Park	111	There is no accessible route to the bull pen.	\$ 2,025	5	Medium		
Park	22	Mack Park	115	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	22	Mack Park	116	There is no accessible route to the table.	\$ 1,013	5	Medium		
Park	22	Mack Park	117	The gate does not provide at least 32 inches between the face of the gate and the opposite stop.	\$ 3,375	5	Medium		
Park	22	Mack Park	119	The wheelchair seating spaces are not on an accessible route.	\$ 2,025	5	Medium		
Park	22	Mack Park	120	The wheelchair seating spaces are not on an accessible route.	\$ 2,025	5	Medium		
Park	23	Martin Luther King Jr. Park	1	There is no accessible route to the picnic tables.	\$ 2,025	5	Medium		
Park	23	Martin Luther King Jr. Park	2	There are no accessible tables.	\$ 1,013	5	Medium		
Park	23	Martin Luther King Jr. Park	4	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	23	Martin Luther King Jr. Park	5	There is no accessible route to the multipurpose field.	\$ 2,025	5	Medium		
Park	23	Martin Luther King Jr. Park	6	There is no accessible route to the multipurpose field.	\$ 2,025	5	Medium		
Park	24	McKenna Park	4	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	24	McKenna Park	8	There is no accessible route to the picnic table and grill.	\$ 1,013	5	Medium		
Park	24	McKenna Park	19	The portable public restroom is not compliant.	\$ 2,025	5	Medium		
Park	24	McKenna Park	23	There is no accessible route to the tables.	\$ 2,025	5	Medium		
Park	24	McKenna Park	37	There is no accessible route to the tables.	\$ 2,025	5	Medium		
Park	24	McKenna Park	38	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	24	McKenna Park	45	There is no accessible route to the grill.	\$ 1,013	5	Medium		
Park	24	McKenna Park	46	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	24	McKenna Park	64	There are no accessible tables.	\$ 1,013	5	Medium		
Park	24	McKenna Park	65	There is no accessible route to the grill.	\$ 1,013	5	Medium		
Park	25	Milam Park	10	Based on the number of seats provided in this area the minimum number of wheelchair spaces has not been provided.	\$ 3,375	5	Medium		
Park	26	Nette Shultz Park	16	There is no accessible route to the multi-purpose field.	\$ 2,025	5	Medium		
Park	26	Nette Shultz Park	17	There is no accessible route to the multi-purpose field.	\$ 2,025	5	Medium		
Park	26	Nette Shultz Park	19	The benches are not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	26	Nette Shultz Park	21	There is no accessible route to the bench.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	7	The accessible parking stall is not wide enough.	\$ 338	5	Medium		
Park	27	North Lakes Park	49	The access aisle is not a minimum 5 feet wide.	\$ 338	5	Medium		
Park	27	North Lakes Park	55	The access aisle is not a minimum 5 feet wide.	\$ 338	5	Medium		
Park	27	North Lakes Park	60	The striping and markings for the access aisle are dilapidated and in need of repair.	\$ 338	5	Medium		
Park	27	North Lakes Park	111	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	115	There is no accessible route to the picnic area.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	116	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	117	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	118	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	119	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	137	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 743	5	Medium		
Park	27	North Lakes Park	163	There are no accessible tables.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	169	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	177	There are no accessible tables.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	184	The wheelchair seating spaces are not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	185	The football participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	186	The football participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	188	The wheelchair seating spaces are not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	189	The football participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	191	The wheelchair seating spaces are not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	193	The football participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	197	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Park	27	North Lakes Park	198	There are no accessible tables.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	201	The door does not open at least 90 degrees.	\$ 675	5	Medium		
Park	27	North Lakes Park	204	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Park	27	North Lakes Park	207	The door does not open at least 90 degrees.	\$ 675	5	Medium		
Park	27	North Lakes Park	211	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 3,375	5	Medium		
Park	27	North Lakes Park	213	An accessible wheelchair space is not provided in the player seating area.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	214	There is no accessible scorer's table.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	216	The softball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	217	The softball participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	218	An accessible wheelchair space is not provided in the player seating area.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	226	There are no accessible scorer's table.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	230	Access from the dugouts to the field has an abrupt vertical edge greater than 1/4 inch.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	231	There is no accessible scorer's table.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	236	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	237	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	239	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	27	North Lakes Park	244	There is no accessible scorer's table.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	248	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	252	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	258	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	264	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	267	There is no accessible scorer's table.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	269	There is no accessible scorer's table.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	282	The door operating hardware is not accessible.	\$ 506	5	Medium		
Park	27	North Lakes Park	283	There are no accessible tables.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	292	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	27	North Lakes Park	293	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	27	North Lakes Park	294	The threshold has a vertical change greater than 1/4 inch.	\$ 675	5	Medium		
Park	27	North Lakes Park	296	The door does not open at least 90 degrees.	\$ 675	5	Medium		
Park	27	North Lakes Park	297	The maneuvering clearance on the pull side of the door extends less than 18 inches beyond the latch side of the door.	\$ 338	5	Medium		
Park	27	North Lakes Park	298	The maneuvering clearance at the door is obstructed.	\$ 675	5	Medium		
Park	27	North Lakes Park	299	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	300	The door closer is less than 78 inches off the finished floor.	\$ 743	5	Medium		
Park	27	North Lakes Park	301	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Park	27	North Lakes Park	305	The soccer participation area is not on an accessible route.	\$ 6,750	5	Medium		
Park	27	North Lakes Park	311	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	313	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	314	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	317	There is no accessible route to the tables.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	319	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	321	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	322	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	323	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	324	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	325	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	326	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	327	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	328	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	330	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	331	There is no accessible route of travel to the table.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	335	The gate does not have a smooth surface at the bottom on the push side (2 gates).	\$ 1,485	5	Medium		
Park	27	North Lakes Park	336	The gate does not have a smooth surface at the bottom on the push side (2 gates).	\$ 1,485	5	Medium		
Park	27	North Lakes Park	338	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	339	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	343	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	346	There is no accessible route to the shelter.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	347	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	349	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	350	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	351	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	352	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	353	The gate does not have a smooth surface at the bottom on the push side.	\$ 743	5	Medium		
Park	27	North Lakes Park	360	There is no accessible route to the swings.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	370	There is no accessible route to the picnic area.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	371	There is no accessible floor route to the picnic area.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	372	The accessible table is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	373	There are no accessible tables.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	374	There is no accessible route to the pavilion.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	376	There is no accessible route to the pavilion.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	377	There are no accessible tables.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	378	There are no accessible tables.	\$ 1,013	5	Medium		
Park	27	North Lakes Park	383	The volleyball court participation area is not on an accessible route.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	385	Not enough of the railings guards or handrails are at the allowable height.	\$ 3,375	5	Medium		
Park	27	North Lakes Park	388	There is no accessible route to the airfield shelters.	\$ 4,725	5	Medium		
Park	27	North Lakes Park	390	The portable public restroom is not compliant.	\$ 3,375	5	Medium		
Park	27	North Lakes Park	392	There is no accessible route to the portable restroom.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	394	There is no accessible route to the first tee box.	\$ 2,025	5	Medium		
Park	27	North Lakes Park	395	The portable public restroom is not compliant.	\$ 3,375	5	Medium		
Park	30	Owsley Park	1	There is no accessible route to the dog waste dispenser and it is out of compliant reach ranges.	\$ 1,013	5	Medium		
Park	30	Owsley Park	9	The transfer platform is not within the compliant range above the ground.	\$ 2,025	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	30	Owsley Park	10	The transfer platform is not within the compliant range above the ground.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	5	There is no accessible route to the tables.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	8	There is no accessible route to the picnic area.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	11	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	12	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	31	Quakertown Park	13	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	14	There is no accessible route to the table and grill.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	15	There is no accessible route to the bench.	\$ 675	5	Medium		
Park	31	Quakertown Park	16	There is no accessible route to the picnic area.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	17	There is no accessible route to the picnic area.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	18	There is no accessible route to the bench.	\$ 1,013	5	Medium		
Park	31	Quakertown Park	19	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	20	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	21	There is no accessible route to the table and electrical outlet.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	23	There is no accessible route to the table and electrical outlet.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	24	There is no accessible route to the table electrical outlet and trash cans.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	25	There is no accessible route to the table and electrical outlet.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	26	There is no accessible route to the picnic area.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	27	There is no accessible route to the grill and trash cans.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	28	There is no accessible route to the table and electrical outlet.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	36	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	31	Quakertown Park	37	The walkway contains changes in level greater than a 1/2 inch high that should be ramped.	\$ 3,375	5	Medium		
Park	31	Quakertown Park	41	The transfer platform is not within the compliant range above the ground.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	43	The transfer platform is not within the compliant range above the ground.	\$ 2,025	5	Medium		
Park	31	Quakertown Park	46	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	31	Quakertown Park	48	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	31	Quakertown Park	50	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	31	Quakertown Park	52	The maneuvering clearance at the door exceeds 2 percent slope.	\$ 3,375	5	Medium		
Park	35	South Lakes Park	12	There is no accessible route to the table trash can and grill.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	15	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	35	South Lakes Park	27	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	35	South Lakes Park	28	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	35	South Lakes Park	30	There is no accessible route to the table trash cans and grill.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	39	There is no accessible route to the table trash cans and grill.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	40	There is no accessible route to the sand volleyball and table.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	43	There is no accessible route to the tables trash cans and grill.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	44	There is no accessible route to the table trash cans and grill.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	45	There is no accessible route to the table trash cans and grill.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	46	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	35	South Lakes Park	53	There is no accessible route to the table.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	92	There is no accessible route to the grill.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	93	There are no accessible tables.	\$ 1,013	5	Medium		
Park	35	South Lakes Park	94	There are no accessible tables.	\$ 1,013	5	Medium		
Park	35	South Lakes Park	97	There are no accessible tables.	\$ 1,013	5	Medium		
Park	35	South Lakes Park	100	There is no accessible route to the grill.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	112	The transfer platform is not a compliant size.	\$ 3,375	5	Medium		
Park	35	South Lakes Park	128	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	35	South Lakes Park	129	Access to the playground contains a running slope and a change in elevation greater than 1/2 inch.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	130	The transfer platform is not within the compliant range above the ground.	\$ 2,025	5	Medium		
Park	35	South Lakes Park	131	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	35	South Lakes Park	136	Not enough of the railings guards or handrails are at the allowable height. At least 25 percent of the railings guards or handrails shall be 34 inches maximum above the ground or deck surface.	\$ 4,725	5	Medium		
Park	35	South Lakes Park	137	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	5	There is no accessible route to the grill.	\$ 2,025	5	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	10	There is no accessible route to the grill.	\$ 2,025	5	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	5	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	18	There is no accessible route to the grill.	\$ 2,025	5	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	19	There is no accessible route to the bench.	\$ 2,025	5	Medium		
Park	37	Water Works Park	24	The transaction counter is too high.	\$ 3,375	5	Medium		
Park	37	Water Works Park	25	The gate does not have a smooth surface at the bottom on the push side.	\$ 675	5	Medium		
Park	37	Water Works Park	27	The locker rental machine has not been provided with a tactile control.	\$ 4,725	5	Medium		
Park	37	Water Works Park	28	Accessible lockers are not provided.	\$ 3,375	5	Medium		
Park	37	Water Works Park	29	The bench is not deep enough.	\$ 1,013	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	37	Water Works Park	35	There are no accessible tables at the tiki bar concession stand.	\$ 1,013	5	Medium		
Park	37	Water Works Park	36	There are no accessible tables.	\$ 1,013	5	Medium		
Park	37	Water Works Park	52	There are no accessible tables.	\$ 1,013	5	Medium		
Park	37	Water Works Park	64	There are no accessible tables.	\$ 1,013	5	Medium		
Park	37	Water Works Park	66	The swimming pool lift is noncompliant. Footrests shall be provided and shall move with the seat lift was not operational at the time of evaluations only one accessible entry provided for the lazy river.	\$ 3,375	5	Medium		
Park	37	Water Works Park	68	There are no accessible tables.	\$ 1,013	5	Medium		
Park	37	Water Works Park	73	There are no accessible tables.	\$ 1,013	5	Medium		
Park	37	Water Works Park	77	There are no accessible tables.	\$ 1,013	5	Medium		
Park	37	Water Works Park	87	There are no accessible tables.	\$ 1,013	5	Medium		
Park	37	Water Works Park	88	There is no accessible route to the volleyball court.	\$ 2,025	5	Medium		
Park	37	Water Works Park	95	There are no accessible tables.	\$ 1,013	5	Medium		
Park	37	Water Works Park	96	The landing at the entrance doors exceeds 2 percent slope.	\$ 4,725	5	Medium		
Park	37	Water Works Park	103	The maneuvering clearance on the pull side of the exterior door is obstructed.	\$ 2,025	5	Medium		
Park	37	Water Works Park	104	There is no accessible route to the bike rack.	\$ 3,375	5	Medium		
Park	37	Water Works Park	117	The maneuvering clearance at the door is obstructed.	\$ 1,013	5	Medium		
Park	37	Water Works Park	118	The maneuvering clearance at the door is obstructed.	\$ 675	5	Medium		
Park	37	Water Works Park	119	The doors have a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	5	Medium		
Park	37	Water Works Park	120	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Park	37	Water Works Park	121	The transaction counter is too high.	\$ 3,375	5	Medium		
Park	37	Water Works Park	122	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration addition or construction of existing facilities which predate The Americans with Disabilities Act (ADA) of 1990.  Under the Code of Federal Regulations Section 35.151(b)(2) State and Local Government Title II entities may provide programmatic access where alterations to existing facilities would result in undue financial and administrative burdens.  For Example A public entity has six courtrooms in two existing buildings and determines that only three of those courtrooms and the public use and common use areas serving those courtrooms in one building are needed to be made accessible in order to satisfy its program access obligations. The entity must comply with 2010 Standards unless compliance would result in undue financial and administrative burdens and must take other actions that would not result in an undue financial burden to ensure access to persons with disabilities. This may include the scheduling of the various types of cases hearings etc. in accessible courtrooms and relocating them where necessary to accommodate persons with disabilities. Having a defined program and effective communication process in place to ensure the public and employees can request accommodations is necessary to ensure equal access to the county's court system.  Program access is not part of this evaluation and this information is being provided as an advisory only.	\$ -	5	Medium		
Park	37	Water Works Park	126	The threshold is greater than 1/2 inch high.	\$ 675	5	Medium		
Park	37	Water Works Park	127	The maneuvering clearance perpendicular to the door is not 54 inches minimum.	\$ 3,375	5	Medium		
Park	37	Water Works Park	128	The transaction counter is too high.	\$ 3,375	5	Medium		
Park	1	Avondale Park	2	The van stall is missing a sign identifying it as a van accessible stall.	\$ -	6	Medium		
Park	1	Avondale Park	7	Parked vehicles reduce the required width of the accessible route.	\$ 1,620	6	Medium		
Park	1	Avondale Park	8	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Park	1	Avondale Park	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	1	Avondale Park	11	The accessible route contains surface materials that does not provide for a stable firm slip-resistant surface.	\$ 675	6	Medium		
Park	1	Avondale Park	25	There is no accessible route to the multipurpose fields.	\$ 3,375	6	Medium		
Park	3	Briercliff Park	8	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	3	Briercliff Park	9	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	4	Carl Young Sr. Park	1	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 4,050	6	Medium		
Park	4	Carl Young Sr. Park	18	The drinking fountain projects from the wall into the pedestrian way with its leading edge above 27 inches from the floor.	\$ 675	6	Medium		
Park	4	Carl Young Sr. Park	20	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Park	4	Carl Young Sr. Park	23	Parked vehicles reduce the required width of the accessible route.	\$ 1,013	6	Medium		
Park	4	Carl Young Sr. Park	29	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	4	Carl Young Sr. Park	31	The restroom does not include accessible fixtures or elements. The side grab bar is not long enough the toilet paper dispenser obstructs the side grab bar the rear grab bard does not extend 24 inches on the wide side of the toilet the baby changing station is mounted too high the bench is not deep enough or have back support the lavatory is in the toilets clear floor space and the faucet controls do not remain open for a minimum of 10 seconds.	\$ 4,050	6	Medium		
Park	4	Carl Young Sr. Park	33	The restroom does not include accessible fixtures or elements. The side grab bar is not long enough the toilet paper dispenser obstructs the side grab bar the rear grab bard does not extend 24 inches on the wide side of the toilet the baby changing station is mounted too high the bench is not deep enough or have back support the lavatory is in the toilets clear floor space and the faucet controls do not remain open for a minimum of 10 seconds.	\$ 4,050	6	Medium		
Park	5	Carnegie Ridge Park	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	6	There is no accessible route to the trail information.	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	7	There is no accessible route to the tables.	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	8	There is no accessible route to the bench.	\$ 1,013	6	Medium		
Park	6	Clear Creek Natural Heritage Center	9	There is no accessible route to the trail head and bench.	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	10	There is no accessible route to the bench.	\$ 1,013	6	Medium		
Park	6	Clear Creek Natural Heritage Center	11	There is no accessible route to the bench.	\$ 1,013	6	Medium		
Park	6	Clear Creek Natural Heritage Center	14	Compliant knee space has not been provided under the lavatory.	\$ 2,700	6	Medium		
Park	6	Clear Creek Natural Heritage Center	18	A clear floor space is not provided in front of the sign.	\$ 1,013	6	Medium		
Park	6	Clear Creek Natural Heritage Center	20	The restroom does not include accessible fixtures or elements. The door is not self-closing and is missing a loop handle on the outside the coat hook is too high the rear and side grab bars are mounted too high the toilet paper dispenser is not the correct distance from the front of the toilet and the stall width is not wide enough.	\$ 4,050	6	Medium		
Park	6	Clear Creek Natural Heritage Center	22	The restroom does not include accessible fixtures or elements. The door is not self-closing and is missing a loop handle on the outside the coat hook is too high the rear and side grab bars are mounted too high the toilet paper dispenser is not the correct distance from the front of the toilet and the stall width is not wide enough.	\$ 4,050	6	Medium		
Park	6	Clear Creek Natural Heritage Center	24	There is no accessible route from the parking area to the shelters.	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	25	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	26	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	27	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	28	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	29	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	30	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	6	Clear Creek Natural Heritage Center	32	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration addition or construction of existing facilities which predate The Americans with Disabilities Act (ADA) of 1990.	\$ -	6	Medium		
Park	6	Clear Creek Natural Heritage Center	33	The walking surface is obstructed. A 36 inch wide minimum walking surface is required.	\$ 675	6	Medium		
Park	9	Cross Timbers Park North	3	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	9	Cross Timbers Park North	13	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	9	Cross Timbers Park North	14	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	9	Cross Timbers Park North	15	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	10	Cross Timbers Park South	5	The transfer steps do not have a level surface.	\$ 3,375	6	Medium		
Park	10	Cross Timbers Park South	8	Compliance with ASTM F1951 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	10	Cross Timbers Park South	9	Compliance with ASTM F1951 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	11	Denia Park	3	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	11	Denia Park	7	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	11	Denia Park	8	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Park	11	Denia Park	10	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Park	11	Denia Park	11	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	11	Denia Park	13	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	11	Denia Park	15	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Park	11	Denia Park	16	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	11	Denia Park	19	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Park	11	Denia Park	20	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	11	Denia Park	21	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	11	Denia Park	22	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	11	Denia Park	23	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	11	Denia Park	24	The required parking signage is missing.	\$ 338	6	Medium		
Park	11	Denia Park	25	The required parking signage is missing.	\$ 338	6	Medium		
Park	11	Denia Park	27	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	11	Denia Park	29	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	11	Denia Park	30	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	11	Denia Park	36	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	11	Denia Park	37	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	11	Denia Park	38	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	11	Denia Park	39	The walkway contains abrupt vertical edges and/or variations over 1/4 inch (2 panels).	\$ 1,013	6	Medium		
Park	11	Denia Park	40	The walkway contains abrupt vertical edges and/or variations over 1/4 inch (2 panels).	\$ 1,013	6	Medium		
Park	11	Denia Park	41	The walkway contains abrupt vertical edges and/or variations over 1/4 inch (11 panels).	\$ 2,025	6	Medium		
Park	11	Denia Park	42	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	11	Denia Park	43	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	11	Denia Park	44	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Park	11	Denia Park	45	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Park	11	Denia Park	46	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ -	6	Medium		
Park	11	Denia Park	47	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ -	6	Medium		
Park	11	Denia Park	48	The water fountain projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Park	11	Denia Park	49	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	11	Denia Park	51	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	11	Denia Park	52	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	11	Denia Park	53	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	11	Denia Park	54	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	11	Denia Park	55	The information box projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Park	11	Denia Park	56	The electrical boxes projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Park	11	Denia Park	57	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	11	Denia Park	58	The handrail does not have a compliant extension at the bottom of the stair flight.	\$ 675	6	Medium		
Park	11	Denia Park	59	The stair risers are not tall enough. Stair treads shall be no less than 11 inches deep measured from riser to riser. Stair riser heights shall be 7 inches maximum and 4 inches minimum. On any given flight of stairs all steps shall have uniform riser height and uniform tread widths.	\$ 2,025	6	Medium		
Park	11	Denia Park	60	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	11	Denia Park	61	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	11	Denia Park	62	The walkway contains abrupt vertical edges and/or variations over 1/4 inch (6 panels).	\$ 2,025	6	Medium		
Park	11	Denia Park	63	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	11	Denia Park	64	The required edge protection is missing.	\$ 2,025	6	Medium		
Park	11	Denia Park	65	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	11	Denia Park	70	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	11	Denia Park	71	The restroom does not include accessible fixtures or elements. The compartment door is not self-closing and is missing an inside loop handle the trash can is in the toilets clear floor space and the toilet seat is too high.	\$ 3,375	6	Medium		
Park	11	Denia Park	74	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	11	Denia Park	79	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	12	Evers Park	4	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Park	12	Evers Park	6	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Park	12	Evers Park	8	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Park	12	Evers Park	9	The required parking signage is missing.	\$ 338	6	Medium		
Park	12	Evers Park	10	The access aisle is not a minimum 5 feet wide.	\$ 473	6	Medium		
Park	12	Evers Park	11	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	12	Evers Park	12	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	12	Evers Park	14	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	12	Evers Park	15	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	12	Evers Park	16	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Park	12	Evers Park	17	The required parking signage is missing.	\$ 338	6	Medium		
Park	12	Evers Park	19	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	12	Evers Park	20	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Park	12	Evers Park	21	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	6	Medium		
Park	12	Evers Park	22	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	12	Evers Park	23	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Park	12	Evers Park	25	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Park	12	Evers Park	29	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	12	Evers Park	34	The curb ramp contains at 8.6 percent running slope.	\$ 3,375	6	Medium		
Park	12	Evers Park	35	The curb ramp on the accessible route contains a 2.9 percent cross slope.	\$ -	6	Medium		
Park	12	Evers Park	42	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Park	12	Evers Park	45	The electrical box projects into the headroom clearance in the circulation path.	\$ 743	6	Medium		
Park	12	Evers Park	46	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	12	Evers Park	47	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	12	Evers Park	48	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	12	Evers Park	55	The top of the curb ramp does not have a level landing.	\$ 2,025	6	Medium		
Park	12	Evers Park	58	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	12	Evers Park	61	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	12	Evers Park	65	The drinking fountain projects from the wall into the pedestrian way with its leading edge above 27 inches from the floor.	\$ 743	6	Medium		
Park	12	Evers Park	66	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	6	Medium		
Park	12	Evers Park	71	The electrical boxes project into the headroom clearance in the circulation path.	\$ 1,485	6	Medium		
Park	12	Evers Park	72	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	12	Evers Park	75	There is no accessible route to the baseball fields.	\$ 473	6	Medium		
Park	12	Evers Park	76	The stairway handrails are missing compliant elements.	\$ 2,025	6	Medium		
Park	12	Evers Park	79	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	12	Evers Park	80	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	12	Evers Park	82	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	12	Evers Park	83	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	12	Evers Park	85	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	12	Evers Park	86	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	12	Evers Park	87	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	12	Evers Park	89	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	12	Evers Park	95	The restroom does not include accessible fixtures or elements.	\$ 2,025	6	Medium		
Park	12	Evers Park	98	The restroom does not include accessible fixtures or elements.	\$ 2,025	6	Medium		
Park	12	Evers Park	101	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	12	Evers Park	104	The restroom does not include accessible fixtures or elements.	\$ 4,725	6	Medium		
Park	12	Evers Park	105	The urinal is confined on three sides and does not have the required clear floor space.	\$ 2,025	6	Medium		
Park	12	Evers Park	110	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	12	Evers Park	113	The restroom does not include accessible fixtures or elements.	\$ 4,725	6	Medium		
Park	12	Evers Park	122	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	13	Fred Moore Park	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	10	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	13	Fred Moore Park	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	24	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	6	Medium		
Park	13	Fred Moore Park	25	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	26	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	13	Fred Moore Park	27	The concrete expansion joints are spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	13	Fred Moore Park	29	There is no accessible route to the table.	\$ 1,013	6	Medium		
Park	13	Fred Moore Park	32	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	13	Fred Moore Park	34	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	13	Fred Moore Park	35	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	13	Fred Moore Park	38	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	13	Fred Moore Park	53	The water source is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	6	Medium		
Park	13	Fred Moore Park	57	The stairway only has a handrail on one side.	\$ 1,013	6	Medium		
Park	13	Fred Moore Park	58	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Park	13	Fred Moore Park	59	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Park	13	Fred Moore Park	60	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Park	13	Fred Moore Park	61	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Park	13	Fred Moore Park	62	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Park	13	Fred Moore Park	64	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	1	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	15	Goldfield Tennis Center	2	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	15	Goldfield Tennis Center	3	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	15	Goldfield Tennis Center	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	13	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	20	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	21	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	15	Goldfield Tennis Center	23	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	15	Goldfield Tennis Center	24	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	15	Goldfield Tennis Center	35	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	15	Goldfield Tennis Center	36	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	15	Goldfield Tennis Center	37	The restroom does not include accessible fixtures or elements.  The toilet center line is incorrect the flush controls are on the wrong side the rear grab bar is not the correct dimensions the side grab bar is not long enough and mounted too far off the back wall the toilet paper dispenser is not the correct distance from the front of the toilet the lavatory trash can and paper towel dispenser are in the toilets clear floor space the paper towel dispenser and mirror are mounted too high and the lavatory pipes are not insulated.	\$ 4,050	6	Medium		
Park	15	Goldfield Tennis Center	38	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	15	Goldfield Tennis Center	40	The restroom does not include accessible fixtures or elements.  The toilet center line is incorrect the flush controls are on the wrong side the rear grab bar is not the correct dimensions the side grab bar is not long enough and mounted too far off the back wall the toilet paper dispenser is not the correct distance from the front of the toilet the lavatory and paper towel dispenser are in the toilets clear floor space the paper towel dispenser and mirror are mounted too high the hand dryer is a protruding object and the lavatory pipes are not insulated.	\$ 4,050	6	Medium		
Park	17	Industrial Park	2	There is no accessible route to the table.	\$ 2,025	6	Medium		
Park	17	Industrial Park	4	There is no accessible route to the table.	\$ 2,025	6	Medium		
Park	19	Jimmy Carter Park	7	Water accumulates on the stairs.	\$ 2,025	6	Medium		
Park	19	Jimmy Carter Park	8	Stairways must have handrails on both sides.	\$ 2,025	6	Medium		
Park	19	Jimmy Carter Park	9	The stair risers are not tall enough.	\$ 2,025	6	Medium		
Park	19	Jimmy Carter Park	11	Stairways must have handrails on both sides.	\$ 2,025	6	Medium		
Park	19	Jimmy Carter Park	15	The curb ramp on the accessible route has a cross slope greater than 2 percent.	\$ 3,375	6	Medium		
Park	19	Jimmy Carter Park	16	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Park	20	Joe Skiles Park	1	There is a change in level greater than 1/4 inch.	\$ 1,013	6	Medium		
Park	20	Joe Skiles Park	2	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	6	Medium		
Park	20	Joe Skiles Park	3	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	20	Joe Skiles Park	5	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Park	20	Joe Skiles Park	9	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	6	Medium		
Park	20	Joe Skiles Park	17	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	21	Lake Forest Park	1	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 1,013	6	Medium		
Park	21	Lake Forest Park	2	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	21	Lake Forest Park	3	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Park	21	Lake Forest Park	4	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Park	21	Lake Forest Park	5	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	21	Lake Forest Park	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	21	Lake Forest Park	7	Parked vehicles reduce the required width of the accessible route.	\$ 4,725	6	Medium		
Park	21	Lake Forest Park	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	21	Lake Forest Park	10	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	21	Lake Forest Park	11	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	21	Lake Forest Park	12	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	21	Lake Forest Park	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	21	Lake Forest Park	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	21	Lake Forest Park	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	21	Lake Forest Park	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	21	Lake Forest Park	20	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	21	Lake Forest Park	63	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	21	Lake Forest Park	64	The portable public restroom is not compliant.	\$ 13,500	6	Medium		
Park	22	Mack Park	1	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Park	22	Mack Park	2	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ -	6	Medium		
Park	22	Mack Park	3	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	22	Mack Park	4	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Park	22	Mack Park	5	The required parking signage is missing.	\$ 338	6	Medium		
Park	22	Mack Park	6	The accessible parking stall is not wide enough.	\$ 405	6	Medium		
Park	22	Mack Park	7	The accessible parking stall is not wide enough.	\$ 405	6	Medium		
Park	22	Mack Park	8	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	22	Mack Park	9	The required parking signage is missing.	\$ 338	6	Medium		
Park	22	Mack Park	10	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 675	6	Medium		
Park	22	Mack Park	11	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Park	22	Mack Park	12	The access aisle contains surface irregularities.	\$ 675	6	Medium		
Park	22	Mack Park	13	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Park	22	Mack Park	14	The walkway contains abrupt vertical edges and/or variations over 1/4 inch down the entire length of the path.	\$ 2,025	6	Medium		
Park	22	Mack Park	15	The walking surface is obstructed by the table.	\$ 338	6	Medium		
Park	22	Mack Park	16	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	22	Mack Park	21	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	22	Mack Park	22	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	22	Mack Park	24	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Park	22	Mack Park	29	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	22	Mack Park	30	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	22	Mack Park	31	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	22	Mack Park	33	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	22	Mack Park	34	The electrical box projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Park	22	Mack Park	35	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	22	Mack Park	36	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	22	Mack Park	37	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	22	Mack Park	38	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	22	Mack Park	39	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 675	6	Medium		
Park	22	Mack Park	45	There is no accessible route to the portable restroom.	\$ 1,013	6	Medium		
Park	22	Mack Park	61	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Park	22	Mack Park	62	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	22	Mack Park	66	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	22	Mack Park	70	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	22	Mack Park	74	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	23	Martin Luther King Jr. Park	10	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	23	Martin Luther King Jr. Park	11	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	23	Martin Luther King Jr. Park	12	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	24	McKenna Park	2	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	24	McKenna Park	3	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	6	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	24	McKenna Park	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	24	McKenna Park	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	24	McKenna Park	12	The required edge protection is missing.	\$ 2,025	6	Medium		
Park	24	McKenna Park	13	The stair risers are not the correct height.	\$ 4,725	6	Medium		
Park	24	McKenna Park	14	Stairways must have handrails on both sides.	\$ 2,025	6	Medium		
Park	24	McKenna Park	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	24	McKenna Park	16	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 743	6	Medium		
Park	24	McKenna Park	17	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	22	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	25	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	24	McKenna Park	26	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	6	Medium		
Park	24	McKenna Park	27	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Park	24	McKenna Park	28	There is no accessible route to the table.	\$ 1,013	6	Medium		
Park	24	McKenna Park	29	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	30	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	31	There is no accessible route to the tables.	\$ 2,025	6	Medium		
Park	24	McKenna Park	33	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Park	24	McKenna Park	34	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	35	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	41	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	24	McKenna Park	42	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	24	McKenna Park	43	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	24	McKenna Park	44	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	47	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	48	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	49	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	50	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	53	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	24	McKenna Park	54	Stairways must have handrails on both sides.	\$ 2,025	6	Medium		
Park	24	McKenna Park	55	The top of the handrail gripping surface is not within a compliant range.  The top of handrail gripping surfaces shall be 20 inches minimum and 28 inches maximum above the ramp surface.	\$ 2,025	6	Medium		
Park	24	McKenna Park	56	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	24	McKenna Park	57	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	24	McKenna Park	59	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	24	McKenna Park	63	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	6	Medium		
Park	25	Milam Park	2	The van stall is missing a sign identifying it as a van accessible stall.	\$ -	6	Medium		
Park	25	Milam Park	3	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	6	Medium		
Park	25	Milam Park	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	25	Milam Park	7	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	25	Milam Park	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 473	6	Medium		
Park	25	Milam Park	17	The transfer platform is not within the compliant range above the ground.	\$ 2,025	6	Medium		
Park	25	Milam Park	19	The transfer platform is not level.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	25	Milam Park	20	The transfer platform is not within the compliant range above the ground.	\$ 2,025	6	Medium		
Park	25	Milam Park	22	Compliance with ASTM F1951 and ASTM 1292 has not been determined.	\$ 7,425	6	Medium		
Park	26	Nette Shultz Park	2	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	26	Nette Shultz Park	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Park	26	Nette Shultz Park	14	The gate does not have a smooth surface at the bottom on the push side.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	2	The required parking signage is missing.	\$ 338	6	Medium		
Park	27	North Lakes Park	3	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	4	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	6	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	8	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	9	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	11	The access aisle is not located on an accessible route of travel.	\$ 675	6	Medium		
Park	27	North Lakes Park	13	The running slope of the access aisle (long dimension) exceeds 2 percent.	-	6	Medium		
Park	27	North Lakes Park	14	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	25	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	26	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	6	Medium		
Park	27	North Lakes Park	27	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	28	The required parking signage is missing.	\$ 338	6	Medium		
Park	27	North Lakes Park	29	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	31	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	33	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	34	The required parking signage is missing.	\$ 338	6	Medium		
Park	27	North Lakes Park	36	The required parking signage is missing.	\$ 338	6	Medium		
Park	27	North Lakes Park	38	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	40	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	27	North Lakes Park	45	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	46	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	47	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	48	The access aisle is not located on an accessible route of travel.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	50	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	51	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	6	Medium		
Park	27	North Lakes Park	52	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	27	North Lakes Park	53	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	54	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	56	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	57	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	58	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	27	North Lakes Park	59	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	62	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	63	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	64	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Park	27	North Lakes Park	66	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	67	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ -	6	Medium		
Park	27	North Lakes Park	68	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	6	Medium		
Park	27	North Lakes Park	69	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	27	North Lakes Park	71	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Park	27	North Lakes Park	73	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ -	6	Medium		
Park	27	North Lakes Park	75	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	76	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ -	6	Medium		
Park	27	North Lakes Park	78	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	79	The required parking signage is missing.	\$ 338	6	Medium		
Park	27	North Lakes Park	81	The access aisle contains abrupt edges and surface irregularities over a 1/4 inches.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	83	The accessible parking stall is not wide enough.	\$ 338	6	Medium		
Park	27	North Lakes Park	85	The required parking signage is missing.	\$ 338	6	Medium		
Park	27	North Lakes Park	86	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	87	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ -	6	Medium		
Park	27	North Lakes Park	88	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	89	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	90	The parking stall contains abrupt edges and surface irregularities over a 1/4 inch vertical.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	92	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	93	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	27	North Lakes Park	94	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	95	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	27	North Lakes Park	96	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	97	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	98	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	99	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	100	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	101	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	102	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	103	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	104	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	106	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	107	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	109	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	113	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	114	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	121	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	122	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	123	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	124	The walkway contains abrupt vertical edges and/or variations over 1/4 inch (3 panels).	\$ 1,013	6	Medium		
Park	27	North Lakes Park	125	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	126	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	127	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	128	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	129	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	130	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	131	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	132	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	133	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	134	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	135	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	136	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	138	The concrete expansion joint is spaced greater than 1/2 inch (3 panels measuring 97 inches wide by 48 inches deep).	\$ 1,013	6	Medium		
Park	27	North Lakes Park	143	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	144	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	145	The accessible route has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.). Cross slopes are greater than 2 percent across the width of the walk.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	146	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	149	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	150	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	152	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	156	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	158	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	160	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	161	The accessible path of travel has cross slopes greater than 2 percent (11 panels measuring 95 inches wide by 48 inches long.)	\$ 3,375	6	Medium		
Park	27	North Lakes Park	162	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	164	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	165	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	166	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	167	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	168	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	170	The accessible route contains changes in level and loose gravel or surface materials that do not provide for a stable firm slip resistant surface.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	179	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	180	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	181	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	182	There is a change in level greater than 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	194	The kitchen counter top is too high.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	195	Knee and toe clearance has not been provided at the sink.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	200	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	27	North Lakes Park	202	The restroom does not include accessible fixtures or elements. The door is missing an inside loop handle and is not self-closing the coat hook is installed too high the rear grab bar does not extend 12 inches on the closed side of the toilet and the toilet paper dispenser is not installed the correct distance in front of the toilet.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	27	North Lakes Park	206	The room identification sign is noncompliant.	\$ 338	6	Medium		
Park	27	North Lakes Park	208	The restroom does not include accessible fixtures or elements. The door is missing an inside loop handle and is not self-closing the coat hook is installed too high and the toilet paper dispenser is not installed the correct distance in front of the toilet.	\$ 1,620	6	Medium		
Park	27	North Lakes Park	212	The element extends down too close to the route of travel.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	215	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	219	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	222	The bleachers extends down too close to the route of travel.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	223	The element extends down too close to the route of travel.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	224	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	225	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	228	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	229	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	232	The bleacher extends down too close to the route of travel.	\$ 675	6	Medium		
Park	27	North Lakes Park	234	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	235	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	238	The bleachers extends down too close to the route of travel.	\$ 675	6	Medium		
Park	27	North Lakes Park	241	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	242	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	245	The bleachers extends down too close to the route of travel.	\$ 675	6	Medium		
Park	27	North Lakes Park	247	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	249	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	250	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	251	The bleachers extends down too close to the route of travel.	\$ 675	6	Medium		
Park	27	North Lakes Park	254	The restroom does not include accessible fixtures or elements. The door is not self-closing the coat hook is installed too high the rear grab bar is too high the side grab bar is too high and does not extend the correct distance and the toilet paper dispenser is not installed the correct distance in front of the toilet.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	257	The hand dryer projects into the headroom clearance in the circulation path.	\$ 338	6	Medium		
Park	27	North Lakes Park	260	The restroom does not include accessible fixtures or elements. The door is not self-closing the coat hook is installed too high the rear grab bar is too high the side grab bar is too high and does not extend the correct distance the flush control is on the incorrect side and the toilet paper dispenser is not installed the correct distance in front of the toilet.	\$ 4,725	6	Medium		
Park	27	North Lakes Park	263	The hand dryer projects into the headroom clearance in the circulation path.	\$ 338	6	Medium		
Park	27	North Lakes Park	266	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	268	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	273	There is a change in level greater than 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	277	There is a change in level greater than 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	281	The kitchen counter top is too high.	\$ 2,700	6	Medium		
Park	27	North Lakes Park	284	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	286	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	288	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	27	North Lakes Park	289	The mailbox projects into the headroom clearance in the circulation path.	\$ 338	6	Medium		
Park	27	North Lakes Park	295	The restroom does not include accessible fixtures or elements. The lavatory trash can and paper towel dispenser is in the toilets clear floor space the side grab bar is not mounted correctly the toilet paper dispenser is not the correct distance from the front of the toilet and the storage unit obstructs the door maneuvering clearance.	\$ 4,050	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	27	North Lakes Park	306	<p>State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration addition or construction of existing facilities which predate The Americans with Disabilities Act (ADA) of 1990.</p> <p>Under the Code of Federal Regulations Section 35.151(b)(2) State and Local Government Title II entities may provide programmatic access where alterations to existing facilities would result in undue financial and administrative burdens.</p> <p>For Example A public entity has six courtrooms in two existing buildings and determines that only three of those courtrooms and the public use and common use areas serving those courtrooms in one building are needed to be made accessible in order to satisfy its program access obligations. The entity must comply with 2010 Standards unless compliance would result in undue financial and administrative burdens and must take other actions that would not result in an undue financial burden to ensure access to persons with disabilities. This may include the scheduling of the various types of cases hearings etc. in accessible courtrooms and relocating them where necessary to accommodate persons with disabilities. Having a defined program and effective communication process in place to ensure the public and employees can request accommodations is necessary to ensure equal access to the county's court system.</p> <p>Program access is not part of this evaluation and this information is being provided as an advisory only.</p>	\$ -	6	Medium		
Park	27	North Lakes Park	307	<p>The restroom does not include accessible fixtures or elements.</p> <p>The door is missing an inside loop handle and is not self-closing the coat hook is installed too high the rear grab bar is too high and does not extend the correct distance on the open side of the toilet the side grab bar is not mounted correctly the bucket is in the toilets clear floor space and the toilet paper dispenser is not installed the correct distance in front of the toilet.</p>	\$ 4,050	6	Medium		
Park	27	North Lakes Park	309	The hand dryer projects into the headroom clearance in the circulation path.	\$ 473	6	Medium		
Park	27	North Lakes Park	337	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	27	North Lakes Park	354	The transfer platform is not level.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	355	The transfer platform is not within the compliant range above the ground.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	356	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	357	There is no accessible route to the swings.	\$ 1,013	6	Medium		
Park	27	North Lakes Park	359	There is no accessible route to the leap frog area.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	362	The rise of the ramp connecting elevated play components exceeds the maximum allowable.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	365	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	366	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	367	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	6	Medium		
Park	27	North Lakes Park	368	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	375	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	380	The accessible path of travel has cross slopes greater than 2.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	386	The compliant edge protection is not provided.	\$ 3,375	6	Medium		
Park	27	North Lakes Park	387	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	27	North Lakes Park	389	There is no accessible route to the portable restrooms.	\$ 2,025	6	Medium		
Park	30	Owsley Park	3	Stairways must have handrails on both sides.	\$ 2,025	6	Medium		
Park	30	Owsley Park	4	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	30	Owsley Park	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	30	Owsley Park	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	30	Owsley Park	7	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Park	30	Owsley Park	11	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	30	Owsley Park	12	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined..	\$ 4,725	6	Medium		
Park	30	Owsley Park	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,620	6	Medium		
Park	31	Quakertown Park	30	The ramp run has not been provided with edge protection.	\$ 1,013	6	Medium		
Park	31	Quakertown Park	31	<p>The ramp does not have compliant handrails.</p> <p>Handrails are required on both sides of all surfaces that are sloped greater than 5 percent (1:20). Handrails must be between 34 inches and 38 inches above the ramp surface and must extend horizontally 12 inches beyond the top and bottom of the ramp. The diameter of the handrails must be 1 1/4 inches minimum and 2 inches maximum in cross-sectional nominal dimension for circular handrails. Handrail gripping surfaces with a non-circular cross section shall have a perimeter dimension of 4 inches minimum and 6 1/4 inches maximum and a cross-section dimension of 2 1/4 inches maximum.</p>	\$ 2,025	6	Medium		
Park	31	Quakertown Park	33	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ -	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	31	Quakertown Park	34	The stairway handrails are not compliant. Handrails are missing on one side bottom handrail extensions are missing and the handrail gripping surface is not the correct size.	\$ 2,025	6	Medium		
Park	31	Quakertown Park	35	The stairway handrails are not compliant. Handrails are missing on one side bottom handrail extensions are missing and the handrail gripping surface is not the correct size.	\$ 2,025	6	Medium		
Park	31	Quakertown Park	38	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	31	Quakertown Park	45	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend 12 inches on the closed side of the toilet the lavatory and soap dispenser are in the toilets clear floor space the self-closing faucets do not remain open for a minimum of 10 seconds and the baby changing table is too high.	\$ 4,050	6	Medium		
Park	31	Quakertown Park	47	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend 12 inches on the closed side of the toilet the lavatory and soap dispenser are in the toilets clear floor space the self-closing faucets do not remain open for a minimum of 10 seconds and the baby changing table is too high.	\$ 4,050	6	Medium		
Park	31	Quakertown Park	49	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend 12 inches on the closed side of the toilet the lavatory and soap dispenser are in the toilets clear floor space the self-closing faucets do not remain open for a minimum of 10 seconds and the baby changing table is too high.	\$ 4,050	6	Medium		
Park	31	Quakertown Park	51	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend 12 inches on the closed side of the toilet the lavatory and soap dispenser are in the toilets clear floor space the self-closing faucets do not remain open for a minimum of 10 seconds and the baby changing table is too high.	\$ 4,050	6	Medium		
Park	32	Sequoia Park	3	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	34	Skate Works	2	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	34	Skate Works	3	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	35	South Lakes Park	1	There are no van accessible parking stalls. There are a total of 39 parking stalls in the parking lot that could be reasonably associated with this facility. There should be a minimum of 2 accessible stalls with a minimum of 1 being designed as van accessible.	\$ 338	6	Medium		
Park	35	South Lakes Park	2	The required parking signage is missing.	\$ 338	6	Medium		
Park	35	South Lakes Park	3	The parking sign is mounted too low.	\$ 338	6	Medium		
Park	35	South Lakes Park	4	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	6	Medium		
Park	35	South Lakes Park	7	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 4,050	6	Medium		
Park	35	South Lakes Park	8	The required parking signage is missing.	\$ 338	6	Medium		
Park	35	South Lakes Park	9	The required parking signage is missing.	\$ 338	6	Medium		
Park	35	South Lakes Park	10	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	11	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	35	South Lakes Park	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	35	South Lakes Park	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	23	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	35	South Lakes Park	24	There is no accessible route to the information board.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	26	The accessible route has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.). Cross slopes are greater than 2 percent across the width of the walk.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	29	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	31	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	35	South Lakes Park	32	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	35	South Lakes Park	33	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	35	South Lakes Park	34	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	37	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	38	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	41	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	42	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	35	South Lakes Park	47	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	35	South Lakes Park	48	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	49	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	50	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	56	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	57	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	58	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	59	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	60	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	35	South Lakes Park	61	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	62	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	63	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	64	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	65	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	66	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	67	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	68	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	69	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	73	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	77	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Park	35	South Lakes Park	78	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Park	35	South Lakes Park	79	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ 1,013	6	Medium		
Park	35	South Lakes Park	80	The restroom does not include accessible fixtures or elements. The door is missing an outside loop handle and is not self-closing the side grab bar does not extend the correct distance the baby changing table is mounted too high and obstructs the door when in the down position the trash can is in the toilets clear floor space and the stall is not wide enough.	\$ 4,050	6	Medium		
Park	35	South Lakes Park	83	The hand dryer projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Park	35	South Lakes Park	84	The lavatory is confined on three sides and is considered to be installed in an alcove.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	85	The restroom does not include accessible fixtures or elements.	\$ 4,050	6	Medium		
Park	35	South Lakes Park	88	The hand dryer projects more than 4 inches into the circulation path.	\$ 675	6	Medium		
Park	35	South Lakes Park	89	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	98	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	35	South Lakes Park	101	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Park	35	South Lakes Park	107	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	108	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ -	6	Medium		
Park	35	South Lakes Park	109	The top of the handrail gripping surface is not within a compliant range.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	110	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	111	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	117	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	118	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	119	The top of the handrail gripping surface is not within a compliant range.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	120	The top of the handrail gripping surface is not within a compliant range.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	121	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	122	The top of the handrail gripping surface is not within a compliant range.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	123	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	124	The top of the handrail gripping surface is not within a compliant range.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	125	The top of the handrail gripping surface is not within a compliant range.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	126	The ramps exceeds the maximum running slope (direction of travel) allowable of 8.33 percent.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	127	The ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Park	35	South Lakes Park	133	The required edge protection is missing.	\$ 2,025	6	Medium		
Park	35	South Lakes Park	134	Compliance with ASTM F1951 and ASTM 1292 for accessibility for ground surfaces on accessible routes clear floor or ground spaces and turning spaces has not been determined.	\$ 4,725	6	Medium		
Park	35	South Lakes Park	135	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	2	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	3	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	7	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	14	The ramp run has not been provided with edge protection.	\$ 1,013	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	15	The landing at the bottom of the ramp does not meet minimum length requirements.	\$ 2,025	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	16	The landing at the bottom of the ramp has a slope greater than 2 percent.	\$ -	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	17	The handrail extension is not in line with the ramp.	\$ 2,025	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	23	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	24	The transfer space is sloped greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	1	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	37	Water Works Park	5	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	6	Medium		
Park	37	Water Works Park	6	The required parking signage is missing.	\$ 338	6	Medium		
Park	37	Water Works Park	7	The curb ramp has no top landing and has flared sides greater than one unit vertical in 12 units horizontal (8.33-percent slope).	\$ 2,025	6	Medium		
Park	37	Water Works Park	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	9	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	10	The vegetation extends down too close to the route of travel.	\$ 675	6	Medium		
Park	37	Water Works Park	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	37	Water Works Park	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	13	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Park	37	Water Works Park	14	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Park	37	Water Works Park	15	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ -	6	Medium		
Park	37	Water Works Park	16	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	19	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ -	6	Medium		
Park	37	Water Works Park	22	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	23	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	26	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	37	Water Works Park	32	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	33	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	37	Water Works Park	34	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	37	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	38	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	39	The handrails are not at the correct height.	\$ 1,013	6	Medium		
Park	37	Water Works Park	41	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	42	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	37	Water Works Park	43	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	37	Water Works Park	44	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	37	Water Works Park	45	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	46	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	47	The handrail does not extend past the ramp.	\$ 2,025	6	Medium		
Park	37	Water Works Park	48	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Park	37	Water Works Park	49	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	37	Water Works Park	50	The handrail does not extend past the ramp.	\$ 2,025	6	Medium		
Park	37	Water Works Park	51	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	37	Water Works Park	53	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	54	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	55	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	57	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	58	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	60	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	61	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	63	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	37	Water Works Park	67	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	69	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Park	37	Water Works Park	70	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	71	The handrails are not at the correct height.	\$ 1,013	6	Medium		
Park	37	Water Works Park	72	The handrails are not at the correct height.	\$ 1,013	6	Medium		
Park	37	Water Works Park	74	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	75	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	76	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Park	37	Water Works Park	78	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	79	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	80	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	81	The handrail does not extend for the correct distance and/or direction at the bottom of the stairway.	\$ 1,013	6	Medium		
Park	37	Water Works Park	82	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	37	Water Works Park	83	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	37	Water Works Park	84	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	85	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	86	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	92	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	97	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	98	The ramp run has not been provided with edge protection.	\$ 1,013	6	Medium		
Park	37	Water Works Park	99	The ramp does not have compliant handrails.	\$ 1,013	6	Medium		
Park	37	Water Works Park	100	The wall or other obstruction is too close to the handrail which reduces its gripping surface.	\$ 1,013	6	Medium		
Park	37	Water Works Park	101	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	37	Water Works Park	105	The restroom is missing accessible fixtures or elements. The accessible toilet compartment is the only one missing a door the rear and side grab bars are mounted too low the rear grab bar does not extend 12 inches on the closed side of the toilet and the toilet compartment has grating with openings greater than 1/2 inch.	\$ 3,375	6	Medium		
Park	37	Water Works Park	107	The accessible shower is missing accessible features and elements. The grab bars are mounted too low the shower unit is missing features that would allow it to be mounted the bench is broken and coming off of the wall and the shower curtain bar is an overhead obstruction.	\$ 5,400	6	Medium		
Park	37	Water Works Park	109	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Park	37	Water Works Park	112	The restroom is missing accessible fixtures or elements (stall on the right side of restroom). The door is missing an inside loop handle the rear and side grab bars are mounted too low the rear grab bar does not extend 12 inches on the closed side of the toilet the side grab bar is mounted more than 12 inches off the back wall and the toilet compartment has grating with openings greater than 1/2 inch.	\$ 3,375	6	Medium		
Park	37	Water Works Park	113	The restroom is missing accessible fixtures or elements (stall on the left side of restroom). The door is missing an inside loop handle the rear and side grab bars are mounted too low the rear grab bar does not extend 12 inches on the closed side of the toilet and the toilet compartment has grating with openings greater than 1/2 inch.	\$ 3,375	6	Medium		
Park	37	Water Works Park	115	The accessible shower is missing accessible features and elements. The grab bars are mounted too low the shower unit is missing features that would allow it to be mounted the bench is missing and the shower curtain bar is an overhead obstruction.	\$ 5,400	6	Medium		
Park	38	Wheeler Ridge Park	2	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Park	38	Wheeler Ridge Park	4	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Park	1	Avondale Park	15	The pet waste dispenser is positioned too high for either a side or front approach.	\$ 743	7	Medium		
Park	1	Avondale Park	16	The clear floor space required at the trash cans contains a slope greater than 2 percent.	\$ 2,025	7	Medium		
Park	1	Avondale Park	17	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	1	Avondale Park	18	There is no accessible route to the trash cans.	\$ 1,013	7	Medium		
Park	1	Avondale Park	19	There is no accessible route to the tables and grill.	\$ 2,025	7	Medium		
Park	1	Avondale Park	20	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	1	Avondale Park	26	There are no accessible tables.	\$ 2,025	7	Medium		
Park	1	Avondale Park	27	The grill is not accessible because there is not adequate clear floor space.	\$ 1,013	7	Medium		
Park	2	Bowling Green Park	1	There is no accessible route to the picnic table.	\$ 1,013	7	Medium		
Park	2	Bowling Green Park	2	There are no accessible tables.	\$ 2,025	7	Medium		
Park	2	Bowling Green Park	3	There is no accessible route to the trash can.	\$ 108	7	Medium		
Park	2	Bowling Green Park	5	The bench is not accessible because there is not adequate clear floor space.	\$ 743	7	Medium		
Park	2	Bowling Green Park	6	There is no accessible route to the trash can.	\$ 108	7	Medium		
Park	2	Bowling Green Park	7	The bench is not accessible because there is not adequate clear floor space.	\$ 743	7	Medium		
Park	2	Bowling Green Park	8	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	2	Bowling Green Park	9	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	2	Bowling Green Park	10	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	2	Bowling Green Park	12	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	2	Bowling Green Park	15	The dog waste dispenser and community garden information box are positioned too high for either a side or front approach.	\$ 473	7	Medium		
Park	3	Briercliff Park	1	There is no accessible route to the multipurpose field.	\$ 2,025	7	Medium		
Park	3	Briercliff Park	2	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	3	Briercliff Park	3	The clear floor space required at the element is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	3	Briercliff Park	4	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	3	Briercliff Park	5	There is no accessible route to the multipurpose field.	\$ 2,025	7	Medium		
Park	3	Briercliff Park	6	There is no accessible route to the multipurpose field.	\$ 2,025	7	Medium		
Park	3	Briercliff Park	7	The transfer steps do not provide a means to support transfer.	\$ 1,013	7	Medium		
Park	4	Carl Young Sr. Park	3	There is no accessible route to the trash cans.	\$ 338	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	4	Carl Young Sr. Park	4	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	4	Carl Young Sr. Park	5	There is no accessible route to the grill.	\$ 2,025	7	Medium		
Park	4	Carl Young Sr. Park	6	The fountain was not operational at the time of evaluation and the water flow could not be evaluated.	\$ 675	7	Medium		
Park	4	Carl Young Sr. Park	7	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	4	Carl Young Sr. Park	8	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	4	Carl Young Sr. Park	9	There is no accessible route to the trash cans.	\$ 675	7	Medium		
Park	4	Carl Young Sr. Park	10	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	4	Carl Young Sr. Park	11	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	4	Carl Young Sr. Park	12	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	4	Carl Young Sr. Park	13	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	4	Carl Young Sr. Park	14	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	4	Carl Young Sr. Park	15	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	4	Carl Young Sr. Park	16	There is no accessible route to the trash can and grill.	\$ 2,025	7	Medium		
Park	4	Carl Young Sr. Park	17	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	5	Carnegie Ridge Park	1	The drinking fountain is not accessible. The accessible height fountain does not provide the required knee clearance and the clear floor space contains a slope greater than 2 percent.	\$ 4,050	7	Medium		
Park	5	Carnegie Ridge Park	9	The transfer space is sloped greater than 2 percent.	\$ 2,025	7	Medium		
Park	5	Carnegie Ridge Park	10	There are no accessible tables.	\$ 1,013	7	Medium		
Park	6	Clear Creek Natural Heritage Center	15	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	9	Cross Timbers Park North	2	The grill is not accessible because there is not adequate clear floor space for an approach.	\$ 2,025	7	Medium		
Park	9	Cross Timbers Park North	4	The clear floor space required at the bike rack is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	9	Cross Timbers Park North	5	The clear floor space required at the drinking fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	9	Cross Timbers Park North	6	There is no accessible route to the table.	\$ 2,025	7	Medium		
Park	9	Cross Timbers Park North	7	There is no accessible route to the table.	\$ 2,025	7	Medium		
Park	9	Cross Timbers Park North	8	There are no accessible tables.	\$ 1,013	7	Medium		
Park	9	Cross Timbers Park North	9	There are no accessible tables.	\$ 1,013	7	Medium		
Park	9	Cross Timbers Park North	10	There is no accessible route to the table.	\$ 1,013	7	Medium		
Park	9	Cross Timbers Park North	16	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	9	Cross Timbers Park North	17	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	9	Cross Timbers Park North	19	There are no accessible tables.	\$ 1,013	7	Medium		
Park	9	Cross Timbers Park North	20	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	9	Cross Timbers Park North	21	There is no accessible route to the table.	\$ 1,013	7	Medium		
Park	9	Cross Timbers Park North	22	There is no accessible route to the dog waste bag dispenser and the dispenser is too high.	\$ 1,013	7	Medium		
Park	11	Denia Park	31	The clear floor space required at the trash cans is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	11	Denia Park	67	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Park	11	Denia Park	68	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	11	Denia Park	72	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Park	11	Denia Park	83	There is no accessible scorer's table.	\$ 1,013	7	Medium		
Park	11	Denia Park	88	An accessible wheelchair space is not provided in the player seating area.	\$ 338	7	Medium		
Park	11	Denia Park	89	An accessible wheelchair space is not provided in the player seating area.	\$ 338	7	Medium		
Park	11	Denia Park	90	There is no accessible scorer's table.	\$ 1,013	7	Medium		
Park	11	Denia Park	91	There is no accessible scorer's table.	\$ 1,013	7	Medium		
Park	11	Denia Park	94	There is no accessible route to the bull pen.	\$ 1,013	7	Medium		
Park	11	Denia Park	98	An accessible wheelchair space is not provided in the player seating area.	\$ 338	7	Medium		
Park	11	Denia Park	99	There is no accessible route to the bull pen.	\$ 1,013	7	Medium		
Park	11	Denia Park	100	An accessible wheelchair space is not provided in the player seating area.	\$ 338	7	Medium		
Park	11	Denia Park	101	There is no accessible scorer's table.	\$ 1,013	7	Medium		
Park	11	Denia Park	116	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	12	Evers Park	37	There is no accessible route to the picnic shelter.	\$ 2,025	7	Medium		
Park	12	Evers Park	38	There is no accessible route to the grill.	\$ 2,025	7	Medium		
Park	12	Evers Park	57	There are no accessible tables.	\$ 1,013	7	Medium		
Park	12	Evers Park	62	There is no accessible route to the picnic table grill and trash cans.	\$ 2,025	7	Medium		
Park	12	Evers Park	63	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	12	Evers Park	81	The clear floor space required at the trash cans is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	12	Evers Park	96	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	12	Evers Park	97	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Park	12	Evers Park	99	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	12	Evers Park	100	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Park	12	Evers Park	107	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	12	Evers Park	108	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Park	12	Evers Park	114	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	12	Evers Park	120	There are no accessible tables.	\$ 1,013	7	Medium		
Park	12	Evers Park	124	The bench is not accessible because there is not adequate clear floor space.	\$ 1,013	7	Medium		
Park	12	Evers Park	125	The bench is not accessible because there is not adequate clear floor space.	\$ 1,013	7	Medium		
Park	12	Evers Park	144	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	12	Evers Park	146	The clear floor space required at the element is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	12	Evers Park	147	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	12	Evers Park	148	The clear floor space required at the trash cans is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	12	Evers Park	151	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	12	Evers Park	153	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	12	Evers Park	157	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	12	Evers Park	162	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	12	Evers Park	171	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	12	Evers Park	180	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	12	Evers Park	195	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	12	Evers Park	203	The clear floor space required at the wheelchair seating in the dugout is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	12	Evers Park	205	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	12	Evers Park	212	The clear floor space required at the wheelchair seating is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	12	Evers Park	214	The clear floor space required at the wheelchair seating is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	12	Evers Park	223	The clear floor space required at the wheelchair seating is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	13	Fred Moore Park	2	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	13	Fred Moore Park	3	There is no accessible route to the table.	\$ 2,025	7	Medium		
Park	13	Fred Moore Park	4	There is no accessible route to the table and trash cans.	\$ 2,025	7	Medium		
Park	13	Fred Moore Park	5	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	13	Fred Moore Park	6	There is no accessible route to the electrical box and water supply.	\$ 2,025	7	Medium		
Park	13	Fred Moore Park	7	There is no accessible route to the electrical box and water supply.	\$ 2,025	7	Medium		
Park	13	Fred Moore Park	17	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 675	7	Medium		
Park	13	Fred Moore Park	18	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 675	7	Medium		
Park	13	Fred Moore Park	23	There is no accessible route to the table.	\$ 1,013	7	Medium		
Park	13	Fred Moore Park	30	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	13	Fred Moore Park	37	The transfer platform is not within the compliant range above the ground.	\$ 2,025	7	Medium		
Park	13	Fred Moore Park	41	There is no accessible route to the trash cans.	\$ 1,013	7	Medium		
Park	13	Fred Moore Park	45	There is no accessible route to the trash cans.	\$ 1,013	7	Medium		
Park	13	Fred Moore Park	52	The trash cans are not accessible because there is not adequate clear floor space for an approach.	\$ 338	7	Medium		
Park	14	Frontier Park	2	The trash can is not accessible because there is not adequate clear floor space for an approach.	\$ 473	7	Medium		
Park	15	Goldfield Tennis Center	28	The drinking fountain has multiple violations. The drinking fountain was not operational at the time of evaluation. The fountain is an accessible height fountain and a standing fountain is missing. The fountain also needs a barrier for cane detection.	\$ 5,130	7	Medium		
Park	15	Goldfield Tennis Center	34	The drinking fountain has multiple violations. The fountain is an accessible height fountain and a standing fountain is missing. The fountain is a protruding object and needs a barrier for cane detection.	\$ 5,130	7	Medium		
Park	18	IOOF Cemetery	1	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	2	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	3	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	4	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	5	There is no accessible route to the trash can and table.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	6	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	7	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	8	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	9	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	10	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	11	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	12	There is no accessible route to the informational sign and brochure box.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	13	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	14	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	18	IOOF Cemetery	15	There are no accessible tables.	\$ 1,013	7	Medium		
Park	19	Jimmy Carter Park	4	The bench is not accessible because there is not adequate clear floor space.	\$ 743	7	Medium		
Park	19	Jimmy Carter Park	13	The bench is not accessible because there is not adequate clear floor space.	\$ 743	7	Medium		
Park	19	Jimmy Carter Park	19	There is no accessible route to the bench.	\$ 2,025	7	Medium		
Park	19	Jimmy Carter Park	20	The clear floor space required at the table is greater than 2 percent.	\$ 2,025	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	19	Jimmy Carter Park	21	The clear floor space required at the grill is greater than 2 percent.	\$ 2,025	7	Medium		
Park	20	Joe Skiles Park	4	There is no accessible route to the picnic table.	\$ 2,025	7	Medium		
Park	20	Joe Skiles Park	7	There is no accessible route to the multipurpose field.	\$ 2,025	7	Medium		
Park	20	Joe Skiles Park	8	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	20	Joe Skiles Park	18	There is no accessible route to the basketball court.	\$ 2,025	7	Medium		
Park	20	Joe Skiles Park	20	There are no accessible tables.	\$ 1,013	7	Medium		
Park	20	Joe Skiles Park	21	There is no accessible route to the grill.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	9	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 473	7	Medium		
Park	21	Lake Forest Park	15	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 473	7	Medium		
Park	21	Lake Forest Park	16	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 473	7	Medium		
Park	21	Lake Forest Park	18	The clear floor space required at the element is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	21	Lake Forest Park	21	There is no accessible route to the grill.	\$ 2,025	7	Medium		
Park	21	Lake Forest Park	22	There is no accessible route to the table.	\$ 2,025	7	Medium		
Park	21	Lake Forest Park	23	There is no accessible route to the trash cans.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	24	There is no accessible route to the trash cans.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	25	There is no accessible route to the table.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	26	There is no accessible route to the table.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	27	There is no accessible route to the benches.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	28	There is no accessible route to the trash cans.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	29	There is no accessible route to the table.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	30	There is no accessible route to the table.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	31	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	35	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	36	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	37	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	38	The water dispenser is not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 405	7	Medium		
Park	21	Lake Forest Park	40	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	41	There is no accessible route to the trash cans.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	42	The clear floor space required at the drinking fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	21	Lake Forest Park	45	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	46	The dog waste bag dispenser is positioned too high for either a side or front approach.  Where a forward reach is unobstructed the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.	\$ 473	7	Medium		
Park	21	Lake Forest Park	47	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	48	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	51	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	52	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 1,013	7	Medium		
Park	21	Lake Forest Park	53	There is no accessible route to the table.	\$ 2,025	7	Medium		
Park	21	Lake Forest Park	54	There is no accessible route to the bench.	\$ 2,025	7	Medium		
Park	21	Lake Forest Park	58	There is no accessible route to the dog park elements.	\$ 4,725	7	Medium		
Park	22	Mack Park	17	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	22	Mack Park	20	There is no accessible route to the grill.	\$ 1,013	7	Medium		
Park	22	Mack Park	23	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	22	Mack Park	25	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	22	Mack Park	26	There is no accessible route to the grill.	\$ 1,013	7	Medium		
Park	22	Mack Park	41	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	22	Mack Park	47	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	22	Mack Park	48	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	22	Mack Park	49	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	22	Mack Park	54	The transfer platform is not level.	\$ 2,025	7	Medium		
Park	22	Mack Park	55	The transfer platform is not within the compliant range above the ground.	\$ 2,025	7	Medium		
Park	22	Mack Park	56	The transfer platform is not within the compliant range above the ground.	\$ 2,025	7	Medium		
Park	22	Mack Park	63	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	22	Mack Park	64	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Park	22	Mack Park	67	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	22	Mack Park	68	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Park	22	Mack Park	71	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Park	22	Mack Park	72	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	22	Mack Park	75	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Park	22	Mack Park	76	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	22	Mack Park	78	There is no accessible route to the trash can.	\$ 338	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	22	Mack Park	83	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	22	Mack Park	85	There is no accessible scorer's table.	\$ 1,013	7	Medium		
Park	22	Mack Park	87	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	22	Mack Park	89	There is no accessible scorer's table.	\$ 1,013	7	Medium		
Park	22	Mack Park	91	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	22	Mack Park	97	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	22	Mack Park	98	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	22	Mack Park	100	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	22	Mack Park	105	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	22	Mack Park	108	There is no accessible route to the trash cans.	\$ 1,013	7	Medium		
Park	22	Mack Park	112	The top of the sink is above the allowable height requirement.	\$ 2,700	7	Medium		
Park	22	Mack Park	113	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 473	7	Medium		
Park	22	Mack Park	118	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	23	Martin Luther King Jr. Park	3	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	24	McKenna Park	5	There is no accessible route to the grill.	\$ 1,013	7	Medium		
Park	24	McKenna Park	7	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	24	McKenna Park	18	There is no accessible route to the picnic table and dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	24	McKenna Park	36	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	24	McKenna Park	52	The transfer platform is not level.	\$ 2,025	7	Medium		
Park	24	McKenna Park	62	The trash can is not accessible because there is not adequate clear floor space for an approach.	\$ 338	7	Medium		
Park	25	Milam Park	8	The walking surface is obstructed.	\$ 338	7	Medium		
Park	25	Milam Park	9	The walking surface is obstructed.	\$ 338	7	Medium		
Park	25	Milam Park	13	The bench is not accessible because there is not adequate clear floor space.	\$ 1,013	7	Medium		
Park	25	Milam Park	14	The bench is not accessible because there is not adequate clear floor space.	\$ 1,013	7	Medium		
Park	25	Milam Park	23	There are no accessible tables.	\$ 1,013	7	Medium		
Park	26	Nette Shultz Park	4	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	26	Nette Shultz Park	8	There is no accessible route to the picnic table and grill.	\$ 3,375	7	Medium		
Park	26	Nette Shultz Park	9	There is no accessible route to the picnic table.	\$ 3,375	7	Medium		
Park	26	Nette Shultz Park	10	There is no accessible route to the picnic table and grill.	\$ 3,375	7	Medium		
Park	26	Nette Shultz Park	11	The trash cans are not accessible because there is not adequate clear floor space for either a forward or side approach.	\$ 338	7	Medium		
Park	26	Nette Shultz Park	12	There is no accessible route to the picnic table.	\$ 3,375	7	Medium		
Park	26	Nette Shultz Park	13	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	26	Nette Shultz Park	18	The bench is not accessible because there is not adequate clear floor space.	\$ 743	7	Medium		
Park	26	Nette Shultz Park	20	There is no accessible route to the benches.	\$ 2,025	7	Medium		
Park	26	Nette Shultz Park	22	The transfer platform is not level.	\$ 1,013	7	Medium		
Park	26	Nette Shultz Park	23	Play table has not been arranged for a parallel approach and there is no knee clearance.	\$ 1,013	7	Medium		
Park	26	Nette Shultz Park	24	Knee clearance has not been provided at the play table.	\$ -	7	Medium		
Park	27	North Lakes Park	112	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	27	North Lakes Park	139	The walking surface is obstructed.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	140	The water flow from the spout is too low.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	147	There is no accessible route to the dog waste bag dispenser.	\$ 743	7	Medium		
Park	27	North Lakes Park	148	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	27	North Lakes Park	153	The trash can is out of reach range because the depth of the obstruction is greater than 25 inches.	\$ 338	7	Medium		
Park	27	North Lakes Park	175	The trash cans and dog waste bag dispenser are not accessible because there is not adequate clear floor space for an approach.	\$ 743	7	Medium		
Park	27	North Lakes Park	203	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	27	North Lakes Park	205	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Park	27	North Lakes Park	209	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	27	North Lakes Park	210	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Park	27	North Lakes Park	220	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	221	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	227	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	240	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	243	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	246	The clear floor space required at the bleachers is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	255	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	256	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Park	27	North Lakes Park	259	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	27	North Lakes Park	261	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	262	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Park	27	North Lakes Park	265	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	27	North Lakes Park	271	The self closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	27	North Lakes Park	275	The self closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 506	7	Medium		
Park	27	North Lakes Park	278	The faucet controls require twisting of the wrist.	\$ 405	7	Medium		
Park	27	North Lakes Park	279	The sink drain pipes are exposed.	\$ 338	7	Medium		
Park	27	North Lakes Park	302	The receptacle/switch is not positioned correctly for either a side or front approach.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	303	There is no accessible route to the fountain.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	304	There is no accessible route to the flag pole.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	312	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	315	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	316	There is no accessible route to the fountain.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	318	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	320	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	329	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	332	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	333	There is no accessible route to the fountain and trash can.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	334	There is no accessible route to the benches tables fountain and dog waste bag dispensers.	\$ 3,375	7	Medium		
Park	27	North Lakes Park	340	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	341	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	342	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	344	There is no accessible route to the fountain.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	345	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	348	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	379	There is no accessible route to the water supply.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	381	The grill is not accessible because there is not adequate clear floor space for an approach.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	382	The clear floor space required at the electrical outlet is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	27	North Lakes Park	391	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	27	North Lakes Park	393	There is no accessible route to the trash cans.	\$ 1,013	7	Medium		
Park	28	North Pointe Park	2	There is no accessible route to the trash cans.	\$ 216	7	Medium		
Park	28	North Pointe Park	3	There is no accessible route to the dog waste dispenser.	\$ 1,013	7	Medium		
Park	28	North Pointe Park	4	There is no accessible route to the grill.	\$ 2,025	7	Medium		
Park	28	North Pointe Park	5	There is no accessible route to the picnic table.	\$ 3,375	7	Medium		
Park	28	North Pointe Park	8	The bench is not accessible because there is not adequate clear floor space.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	1	There is no accessible route to the informational sign and brochure box.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	2	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	3	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	4	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	5	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	6	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	7	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	8	There are no accessible tables.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	9	There is no accessible route to the table.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	10	The flag pole operations is positioned too high for either a side or front approach.	\$ 743	7	Medium		
Park	29	Oakwood Cemetery	11	There is no accessible route to the flag pole.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	12	There is no accessible route to the historical designation sign.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	13	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	14	There is no accessible route to the informational sign and brochure box.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	15	There is no accessible route to the trash can.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	16	There is no accessible route to the bench.	\$ 1,013	7	Medium		
Park	29	Oakwood Cemetery	17	There is no accessible route to the veteran memorial.	\$ 1,013	7	Medium		
Park	30	Owsley Park	2	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Park	31	Quakertown Park	1	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	31	Quakertown Park	2	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	31	Quakertown Park	3	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	31	Quakertown Park	4	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	31	Quakertown Park	6	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	31	Quakertown Park	7	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	31	Quakertown Park	9	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	31	Quakertown Park	10	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	31	Quakertown Park	22	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	31	Quakertown Park	29	There is no accessible route to the dog waste bag dispenser and trash cans.	\$ 1,013	7	Medium		
Park	31	Quakertown Park	39	The transfer platform is not within the compliant range above the ground.	\$ 2,025	7	Medium		
Park	31	Quakertown Park	40	The transfer space is sloped greater than 2 percent.	\$ 2,025	7	Medium		
Park	31	Quakertown Park	42	The transfer space is sloped greater than 2 percent.	\$ 2,025	7	Medium		
Park	31	Quakertown Park	44	The transfer space is sloped greater than 2 percent.	\$ 2,025	7	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	34	Skate Works	4	There are no accessible tables.	\$ 1,013	7	Medium		
Park	34	Skate Works	5	The clear floor space required at the water fountain has a change in elevation.	\$ 1,013	7	Medium		
Park	35	South Lakes Park	13	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	35	South Lakes Park	14	The clear floor space required at the trash cans is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	17	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Park	35	South Lakes Park	19	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	35	South Lakes Park	22	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	35	South Lakes Park	25	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	35	South Lakes Park	51	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	52	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	35	South Lakes Park	54	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Park	35	South Lakes Park	55	There is no accessible route to the dog waste bag dispenser.	\$ 1,013	7	Medium		
Park	35	South Lakes Park	70	There is no accessible route to the trash can.	\$ 338	7	Medium		
Park	35	South Lakes Park	71	There is no accessible route to the pet waste bag dispenser.	\$ 1,013	7	Medium		
Park	35	South Lakes Park	72	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	81	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	35	South Lakes Park	82	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 338	7	Medium		
Park	35	South Lakes Park	86	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	7	Medium		
Park	35	South Lakes Park	87	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 338	7	Medium		
Park	35	South Lakes Park	90	The clear floor space for the electrical outlet is obstructed.	\$ 338	7	Medium		
Park	35	South Lakes Park	91	The clear floor space for the electrical outlet is obstructed.	\$ 338	7	Medium		
Park	35	South Lakes Park	95	The electrical outlet is not positioned correctly for either a side or front approach.	\$ 473	7	Medium		
Park	35	South Lakes Park	96	The electrical outlet is not positioned correctly for either a side or front approach.	\$ 473	7	Medium		
Park	35	South Lakes Park	99	The clear floor space required at the accessible table is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	103	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	104	There is no accessible route to the bench.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	105	There is no accessible route to the bench.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	106	There is no accessible route to the bench.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	113	There is no accessible route to the bench and trash can.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	114	There is no accessible route to the bench.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	115	There is no accessible route to the benches.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	116	There is no accessible route to the benches and trash can.	\$ 2,025	7	Medium		
Park	35	South Lakes Park	132	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	1	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 473	7	Medium		
Park	36	Spc. Ernest W. Dallas Jr. Veterans Memorial Park	11	The clear floor space required at the water fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	37	Water Works Park	30	The shower control push button is positioned too high for either a side or front approach.	\$ 743	7	Medium		
Park	37	Water Works Park	31	The clear floor space required at the shower is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	37	Water Works Park	40	The fountain is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Park	37	Water Works Park	65	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	7	Medium		
Park	37	Water Works Park	89	The force required to operate the element exceeds the maximum allowable force.	\$ 743	7	Medium		
Park	37	Water Works Park	90	The clear floor space required at the element is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	37	Water Works Park	91	There is not enough knee clearance under the drinking fountain.	\$ 4,725	7	Medium		
Park	37	Water Works Park	94	There are no accessible tables.	\$ 1,013	7	Medium		
Park	38	Wheeler Ridge Park	1	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	38	Wheeler Ridge Park	5	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Park	38	Wheeler Ridge Park	6	There is no accessible route to the dog waste dispenser.	\$ 1,013	7	Medium		
Park	38	Wheeler Ridge Park	7	There is no accessible route to the dog waste dispenser.	\$ 1,013	7	Medium		
Park	1	Avondale Park	13	The water flow from the spout is too low.	\$ 1,013	8	Medium		
Park	2	Bowling Green Park	4	The water flow from the spout is too low.	\$ 1,013	8	Medium		
Park	12	Evers Park	39	The water flow from the spout is too low.	\$ 1,013	8	Medium		
Park	12	Evers Park	59	The water flow from the spout is too low.	\$ 1,013	8	Medium		
Park	12	Evers Park	60	The water flow from the spout is too low.	\$ 1,013	8	Medium		
Park	12	Evers Park	64	The water flow from the spout is too low.	\$ 1,013	8	Medium		
Park	22	Mack Park	19	The water flow from the spout does not meet minimum height requirements.	\$ 2,025	8	Medium		
Park	22	Mack Park	32	The water flow from the spout does not meet minimum height requirements.	\$ 2,025	8	Medium		
Park	25	Milam Park	5	The water flow from the spout is too low.	\$ 1,013	8	Medium		
Park	26	Nette Shultz Park	5	The water flow from the spout is too low.	\$ 1,013	8	Medium		
Park	28	North Pointe Park	1	The water flow from the spout is too low.	\$ 1,013	8	Medium		
Paved Trail	-999	Preserve at Pecan Creek	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	5	Medium		
Paved Trail	-999	Preserve at Pecan Creek	15	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	-999	Preserve at Pecan Creek	20	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	5	Medium		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	-999	Preserve at Pecan Creek	33	There is no accessible route to the bench.	\$ 2,025	5	Medium		
Paved Trail	1	Avondale Trail	1	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	1	Avondale Trail	4	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	1	Avondale Trail	6	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	1	Avondale Trail	8	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	1	Avondale Trail	9	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	1	Avondale Trail	12	There is no accessible route to the benches and table.	\$ 2,025	5	Medium		
Paved Trail	4	Cooper Creek Trail	37	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	4	Cooper Creek Trail	38	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	6	Denia Trail	8	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	6	Denia Trail	15	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	6	Denia Trail	21	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	6	Denia Trail	22	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	1	The gate does not have a smooth surface at the bottom on the push side.	\$ 338	5	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	2	The gate does not have a smooth surface at the bottom on the push side.	\$ 338	5	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	50	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	5	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	51	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	5	Medium		
Paved Trail	12	Nette Shultz Trail	39	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	13	North Lakes Trail	24	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	18	Sequoia Trail	5	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	34	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	38	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	39	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	56	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	57	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	63	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	69	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	70	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	72	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	85	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	87	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	96	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	19	South Lakes Trail	97	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	5	Medium		
Paved Trail	-999	Preserve at Pecan Creek	1	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	2	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	3	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	14	The accessible route contains loose gravel or surface materials that do not provide for a stable firm and slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	17	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	18	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	23	The accessible route of travel contains a cross slope of 2.9 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	24	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	25	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	26	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	27	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	28	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	29	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	30	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	31	The accessible route of travel contains a cross slope of 2.3 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	-999	Preserve at Pecan Creek	32	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	1	Avondale Trail	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	1	Avondale Trail	10	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	1	Avondale Trail	14	The expansion joint is spaced greater than 1/2 inch.	\$ 2,025	6	Medium		
Paved Trail	1	Avondale Trail	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	1	Avondale Trail	16	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	2	Bowling Green Trail	1	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	2	Bowling Green Trail	2	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	6	Medium		
Paved Trail	2	Bowling Green Trail	3	The accessible route contains surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	2	Bowling Green Trail	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	6	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	15	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	2	Bowling Green Trail	17	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Paved Trail	2	Bowling Green Trail	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Paved Trail	2	Bowling Green Trail	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	22	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	2	Bowling Green Trail	23	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	24	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	25	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	26	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	2	Bowling Green Trail	27	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	2	Bowling Green Trail	28	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	2	Bowling Green Trail	29	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	2	Bowling Green Trail	30	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	3	Carl Young Park Trail	1	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	3	Carl Young Park Trail	2	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	3	Carl Young Park Trail	4	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	3	Carl Young Park Trail	5	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	3	Carl Young Park Trail	6	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	3	Carl Young Park Trail	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	3	Carl Young Park Trail	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	3	Carl Young Park Trail	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	3	Carl Young Park Trail	10	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	3	Carl Young Park Trail	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	3	Carl Young Park Trail	12	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	3	Carl Young Park Trail	13	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	2	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	3	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	9	The accessible route of travel contains a cross slope of 2.5 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	10	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	14	The vegetation extends down too close to the route of travel.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	15	The accessible route of travel contains a cross slope of 2.9 percent and changes in level.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	21	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	23	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	4	Cooper Creek Trail	24	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	25	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	26	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	27	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	28	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	4	Cooper Creek Trail	30	The vegetation extends down too close to the route of travel.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	31	The vegetation extends down too close to the route of travel.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	32	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	33	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	34	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	35	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	36	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	39	The transition from the curb ramp to the walk gutter or street is sloped greater than 5 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	40		\$ -	6	Medium		
Paved Trail	4	Cooper Creek Trail	41	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	42	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	44	The accessible path of travel has cross slopes greater than 2.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	45	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	46	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	48	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	49	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	50	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	51	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	52	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	53	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	54	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 3,375	6	Medium		
Paved Trail	4	Cooper Creek Trail	55	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	4	Cooper Creek Trail	56	The expansion joint is spaced greater than 1/2 inch. Expansion joints run the entire length of the bridge.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	59	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	60	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	61	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	4	Cooper Creek Trail	63	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	4	Cooper Creek Trail	65	The ramp does not have compliant handrails.	\$ 3,375	6	Medium		
Paved Trail	5	Cross Timbers Trail	1	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	5	Cross Timbers Trail	2	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	3	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	5	Cross Timbers Trail	4	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	5	Cross Timbers Trail	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	9	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	12	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	13	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	14	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	15	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	21	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	22	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	5	Cross Timbers Trail	23	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	5	Cross Timbers Trail	24	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	5	Cross Timbers Trail	25	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	6	Denia Trail	1	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	6	Denia Trail	2	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	6	Denia Trail	3	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	6	Denia Trail	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	6	Denia Trail	7	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	6	Denia Trail	9	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	6	Denia Trail	10	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	6	Denia Trail	11	The vegetation extends down too close to the route of travel.	\$ 1,013	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	6	Denia Trail	12	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	6	Denia Trail	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	6	Denia Trail	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	6	Denia Trail	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	6	Denia Trail	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	6	Denia Trail	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	6	Denia Trail	19	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	6	Denia Trail	20	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	6	Denia Trail	23	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	1	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	3	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	4	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	7	Evers Park Trail	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	7	Evers Park Trail	8	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	7	Evers Park Trail	9	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	7	Evers Park Trail	10	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	11	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	7	Evers Park Trail	12	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ -	6	Medium		
Paved Trail	7	Evers Park Trail	13	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	7	Evers Park Trail	16	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	20	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	21	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	22	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	24	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	26	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	27	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	7	Evers Park Trail	29	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	30	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	7	Evers Park Trail	31	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	32	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	7	Evers Park Trail	33	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	7	Evers Park Trail	34	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	7	Evers Park Trail	35	The vegetation extends down too close to the route of travel.	\$ 1,013	6	Medium		
Paved Trail	7	Evers Park Trail	36	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ -	6	Medium		
Paved Trail	7	Evers Park Trail	37	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	7	Evers Park Trail	38	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	7	Evers Park Trail	39	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	40	The accessible path of travel has cross slopes greater than 2 percent and changes in level.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	41	The accessible path of travel has cross slopes greater than 2 percent and changes in level.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	43	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	44	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	7	Evers Park Trail	45	The accessible path of travel has cross slopes greater than 2 percent and changes in level.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	46	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	7	Evers Park Trail	47	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	7	Evers Park Trail	48	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	7	Evers Park Trail	49	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	50	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	51	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	7	Evers Park Trail	52	The walkway contains abrupt vertical edges and/or variations over 1/4 inch. 3 panels of sidewalk with elevation and slope issues.	\$ 2,363	6	Medium		
Paved Trail	7	Evers Park Trail	54	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	56	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	7	Evers Park Trail	57	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	7	Evers Park Trail	58	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	7	Evers Park Trail	59	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	1	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	2	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	3	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	4	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	8	Fred Moore Trail	5	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	6	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	8	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	13	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	15	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	19	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	21	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	22	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	27	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ -	6	Medium		
Paved Trail	8	Fred Moore Trail	30	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Paved Trail	8	Fred Moore Trail	31	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ -	6	Medium		
Paved Trail	8	Fred Moore Trail	33	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	35	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	36	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	37	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	38	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	8	Fred Moore Trail	39	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	40	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	41	The ramp does not have compliant handrails.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	42	The expansion joint is spaced greater than 1/2 inch.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	43	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	44	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	45	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	46	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	47	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	48	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	49	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	50	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	51	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	52	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	53	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	54	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	55	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	56	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	57	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	58	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	59	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	8	Fred Moore Trail	61	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	8	Fred Moore Trail	62	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	8	Fred Moore Trail	63	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	9	Frontier Park Trail	3	The tree limbs extends down too close to the route of travel.	\$ 2,025	6	Medium		
Paved Trail	9	Frontier Park Trail	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Paved Trail	9	Frontier Park Trail	6	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	9	Frontier Park Trail	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	9	Frontier Park Trail	8	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	9	Frontier Park Trail	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	3	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	9	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	11	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	12	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	13	The curb ramp contains an abrupt change in level.	\$ -	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	14	The curb ramp has no top landing and has flared sides greater than one unit vertical in 12 units horizontal (8.33-percent slope).	\$ -	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	22	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	23	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	24	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	25	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	26	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	27	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	28	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	29	The accessible route of travel contains a cross slope of 2.3 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	30	The vegetation extends down too close to the route of travel.	\$ 1,013	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	31	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	32	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	33	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	34	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	35	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	36	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ -	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	37	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ -	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	38	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	39	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	40	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	41	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	42	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	43	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	44	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	45	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	46	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	47	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	48	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	49	The vegetation extends down too close to the route of travel.	\$ 1,013	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	52	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	53	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	54	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	55	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	56	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	57	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	58	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	59	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	60	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	61	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	62	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 1,013	6	Medium		
Paved Trail	10	Katy Trail (Denton Rail Trail)	63	The transition from the curb ramp to the walk gutter or street is not flush and free of abrupt changes in level.	\$ 2,025	6	Medium		







Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	11	Lake Forest Trail	9	The walking surface is obstructed.	\$ 675	6	Medium		
Paved Trail	11	Lake Forest Trail	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	11	Lake Forest Trail	14	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	11	Lake Forest Trail	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	11	Lake Forest Trail	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	11	Lake Forest Trail	17	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	11	Lake Forest Trail	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	11	Lake Forest Trail	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	11	Lake Forest Trail	21	The accessible route contains loose gravel and surface materials that do not provide for a stable firm slip-resistant surface.	\$ 2,025	6	Medium		
Paved Trail	11	Lake Forest Trail	23	There is no accessible route to the trail head.	\$ 3,375	6	Medium		
Paved Trail	11	Lake Forest Trail	24	There is no accessible route to the trail head.	\$ 3,375	6	Medium		
Paved Trail	11	Lake Forest Trail	25	There is no accessible route to the trail head.	\$ 3,375	6	Medium		
Paved Trail	12	Nette Shultz Trail	3	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	5	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	13	The clear floor space required at the fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	14	The clear floor space required at the bench is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	17	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	18	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	21	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	26	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	27	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	28	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	12	Nette Shultz Trail	29	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	30	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	31	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	32	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	12	Nette Shultz Trail	35	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	12	Nette Shultz Trail	36	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	12	Nette Shultz Trail	37	The handrail does not extend past the ramp.	\$ 1,013	6	Medium		
Paved Trail	12	Nette Shultz Trail	38	The handrail does not extend past the ramp.	\$ 1,013	6	Medium		
Paved Trail	12	Nette Shultz Trail	41	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	42	The expansion joint across the bridge are spaced greater than 1/2 inch.	\$ 2,025	6	Medium		
Paved Trail	12	Nette Shultz Trail	43	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	1	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	2	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	5	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	6	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	9	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	13	North Lakes Trail	10	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	14	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	17	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	20	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	13	North Lakes Trail	21	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	22	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	25	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	26	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	27	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	28	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	29	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	30	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	31	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	32	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	33	The ramp does not have compliant handrails.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	34	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	35	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	36	The required edge protection is missing.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	37	The required edge protection is missing.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	38	The expansion joints are spaced greater than 1/2 inch.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	39	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	40	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	41	The accessible path of travel has cross slopes greater than 2 percent and changes in level.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	43	The accessible path of travel has cross slopes greater than 2 percent and changes in level.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	45	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	46	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	49	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	50	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	51	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	52	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	53	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	54	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	55	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	56	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	13	North Lakes Trail	57	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	58	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	59	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	61	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	13	North Lakes Trail	62	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	66	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 13,500	6	Medium		
Paved Trail	13	North Lakes Trail	67	The required edge protection is missing from the ramp run and/or ramp landing.	\$ 1,013	6	Medium		
Paved Trail	13	North Lakes Trail	68	There is no accessible route to the trail head.	\$ 13,500	6	Medium		
Paved Trail	13	North Lakes Trail	69	There is no accessible route to the trail head.	\$ 13,500	6	Medium		
Paved Trail	14	North Pointe Trail	2	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	14	North Pointe Trail	4	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	14	North Pointe Trail	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	14	North Pointe Trail	7	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	6	Medium		
Paved Trail	14	North Pointe Trail	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	14	North Pointe Trail	9	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	14	North Pointe Trail	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	14	North Pointe Trail	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	14	North Pointe Trail	14	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	15	Northwest Denton Trail	1	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	15	Northwest Denton Trail	2	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 1,013	6	Medium		
Paved Trail	15	Northwest Denton Trail	3	The vegetation extends down too close to the route of travel.	\$ 1,013	6	Medium		
Paved Trail	15	Northwest Denton Trail	4	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	15	Northwest Denton Trail	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	15	Northwest Denton Trail	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	15	Northwest Denton Trail	7	The required edge protection is missing.	\$ 1,013	6	Medium		
Paved Trail	15	Northwest Denton Trail	8	The ramp landing has not been provided with edge protection.	\$ 1,013	6	Medium		
Paved Trail	15	Northwest Denton Trail	9	The ramp landing has not been provided with edge protection.	\$ 1,013	6	Medium		
Paved Trail	15	Northwest Denton Trail	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	15	Northwest Denton Trail	11	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	15	Northwest Denton Trail	12	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	15	Northwest Denton Trail	13	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	15	Northwest Denton Trail	14	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	3	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	5	The required edge protection is missing from the ramp run and/or ramp landing.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	6	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	17	Quakertown Trail	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	13	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	15	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	17	The concrete expansion joint is spaced greater than 1/2 inch. Openings in floor or ground surfaces shall not allow passage of a sphere more than 1/2 inch diameter. Elongated openings shall be placed so that the long dimension is perpendicular to the dominant direction of travel.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	18	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	20	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	21	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	22	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	25	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	26	The accessible route of travel contains a cross slope of 3.6 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	27	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	29	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	30	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	31	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 3,375	6	Medium		
Paved Trail	17	Quakertown Trail	32	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	33	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	34	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	35	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	36	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	38	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	39	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	40	The change in level where the gutter meets the curb ramp is greater than 1/4 inch and contains surface materials that are not firm stable and slip-resistant.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	41	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	42	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	43	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	17	Quakertown Trail	44	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	49	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	50	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	51	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	52	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	53	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	17	Quakertown Trail	54	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	17	Quakertown Trail	55	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	17	Quakertown Trail	56	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	57	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	58	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	59	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	60	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	17	Quakertown Trail	61	The change in level where the gutter meets the curb ramp is greater than 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	63	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	17	Quakertown Trail	64	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	1	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	2	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	3	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	7	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	9	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	10	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	11	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	13	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	14	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	16	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	18	Sequoia Trail	17	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	1	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	2	The accessible path of travel has cross slopes greater than 2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	3	The accessible route of travel contains a cross slope of 2.3 percent and changes in elevation.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	6	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	8	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	9	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	12	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	14	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	16	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	17	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	19	The accessible route of travel contains a cross slope of 3.1 and changes in elevation.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	20	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	21	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	23	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	24	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	25	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	26	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	27	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	28	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	29	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	30	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	31	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	32	The accessible route of travel contains a cross slope of 2.5 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	33	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	35	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	36	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	37	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	40	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	42	The ramp does not have compliant handrails. Handrails must be between 34 inches and 38 inches above the surface and the space between handrails and walls must be 1-1/2 inches minimum.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	43	The ramp does not have compliant handrails. Handrails must be between 34 inches and 38 inches above the surface and the space between handrails and walls must be 1-1/2 inches minimum.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	44	The required edge protection is missing.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	45	The required edge protection is missing.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	46	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	47	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	19	South Lakes Trail	48	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	50	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	51	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	52	The ramp does not have compliant handrails. Handrails must be between 34 inches and 38 inches above the surface and the space between handrails and walls must be 1-1/2 inches minimum.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	53	The ramp does not have compliant handrails. Handrails must be between 34 inches and 38 inches above the surface and the space between handrails and walls must be 1-1/2 inches minimum.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	54	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	55	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	58	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	59	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	60	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	61	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	64	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	65	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	67	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	68	The required edge protection is missing.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	73	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	74	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	75	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	77	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	78	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	79	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	80	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	83	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	84	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	86	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	88	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	89	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	90	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	91	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	92	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	93	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	94	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	95	The accessible route of travel contains a cross slope of 3.2 percent and changes in elevation.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	98	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 3,375	6	Medium		
Paved Trail	19	South Lakes Trail	99	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	100	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	101	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	102	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	103	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	105	The accessible route of travel contains a cross slope of 2.2 percent and expansion joints.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	106	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	107	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	19	South Lakes Trail	108	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	109	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	110	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	111	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	112	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	19	South Lakes Trail	113	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	114	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	115	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	19	South Lakes Trail	117	The accessible route contains loose gravel or surface materials that do not provide for a stable firm slip-resistant surface.	\$ 20,250	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	1	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	2	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	3	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	5	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	6	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	7	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	20	Special Ernest W Dallas Jr Trail	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	9	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	10	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	11	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	14	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	15	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	16	The tree limbs extends down too close to the route of travel.	\$ 1,013	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	17	The tree limbs extends down too close to the route of travel.	\$ 1,013	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	21	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	22	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		
Paved Trail	20	Special Ernest W Dallas Jr Trail	23	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	1	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 338	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	2	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	3	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	4	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 338	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	5	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	6	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	7	The concrete expansion joint is spaced greater than 1/2 inch. Three panels of walkway.	\$ 1,013	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	8	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	9	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	10	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	16	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	17	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	19	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 743	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	21	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	22	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 1,013	6	Medium		
Paved Trail	21	Unicorn Lake / Briercliff Trail	23	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	1	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	2	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	3	The curb ramp exceeds the maximum running slope (parallel to the direction of travel) allowable of 8.33 percent.	\$ 3,375	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	4	The curb ramp on the accessible route has cross slopes greater than 2 percent.	\$ -	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	5	The landing of the ramp has a slope greater than 2 percent.	\$ 2,025	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	6	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	7	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	9	The surface at the bottom of the curb ramp exceeds a 5 percent slope immediately adjacent to the curb ramp.	\$ 2,025	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	11	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	12	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	13	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	14	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	15	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	16	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	17	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	18	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	19	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	20	The concrete expansion joint is spaced greater than 1/2 inch.	\$ 675	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	21	The accessible route on the site has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	6	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Paved Trail	22	Wheeler Ridge Trail	22	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	22	Wheeler Ridge Trail	23	The walkway contains abrupt vertical edges and/or variations over 1/4 inch.	\$ 2,025	6	Medium		
Paved Trail	1	Avondale Trail	3	The clear floor space required at the trash cans is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 1,013	7	Medium		
Paved Trail	1	Avondale Trail	7	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Paved Trail	1	Avondale Trail	13	The bridge does not have compliant handrails and handrail extensions.	\$ 2,025	7	Medium		
Paved Trail	2	Bowling Green Trail	9	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Paved Trail	2	Bowling Green Trail	18	The trash cans are not accessible because there is not adequate clear floor space for an approach.	\$ 338	7	Medium		
Paved Trail	4	Cooper Creek Trail	57	The trash can is not accessible because there is not adequate clear floor space for an approach.	\$ 338	7	Medium		
Paved Trail	6	Denia Trail	4	The clear floor space required at the trash can is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	7	Medium		
Paved Trail	11	Lake Forest Trail	11	The trash can and dog waste bag dispenser are not accessible because there is not adequate clear floor space for an approach.	\$ 675	7	Medium		
Paved Trail	11	Lake Forest Trail	12	There is no accessible route to the bench and trash cans.	\$ 3,375	7	Medium		
Paved Trail	11	Lake Forest Trail	13	There is no accessible route to the bench.	\$ 2,025	7	Medium		
Paved Trail	11	Lake Forest Trail	22	There is no accessible route to the bench and trash cans.	\$ 1,013	7	Medium		
Paved Trail	12	Nette Shultz Trail	22	The dog waste bag dispenser is not accessible because there is not adequate clear floor space for an approach.	\$ 675	7	Medium		
Paved Trail	12	Nette Shultz Trail	23	The trash cans are not accessible because there is not adequate clear floor space for an approach.	\$ 338	7	Medium		
Paved Trail	12	Nette Shultz Trail	40	The dog waste bag dispenser is not accessible because there is not adequate clear floor space for an approach.	\$ 675	7	Medium		
Paved Trail	13	North Lakes Trail	8	There is no accessible route to the trash can.	\$ 338	7	Medium		
Paved Trail	13	North Lakes Trail	23	The dog waste bag dispenser is positioned too high for either a side or front approach.	\$ 338	7	Medium		
Paved Trail	13	North Lakes Trail	60	The dog waste bag dispenser is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Paved Trail	13	North Lakes Trail	63	The trash cans and dog waste bag dispenser are not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Paved Trail	15	Northwest Denton Trail	15	The dog waste bag dispenser is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Paved Trail	17	Quakertown Trail	1	There is no accessible route to the dog waste bag dispenser.	\$ 338	7	Medium		
Paved Trail	17	Quakertown Trail	2	There is no accessible route to the trash cans.	\$ 338	7	Medium		
Paved Trail	17	Quakertown Trail	24	The trash cans are not accessible because there is not adequate clear floor space for an approach.	\$ 338	7	Medium		
Paved Trail	18	Sequoia Trail	6	The bench is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Paved Trail	19	South Lakes Trail	49	The trash can and dog waste bag dispenser are not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Paved Trail	19	South Lakes Trail	62	The trash can is not accessible because there is not adequate clear floor space for an approach.	\$ 338	7	Medium		
Paved Trail	19	South Lakes Trail	66	The dog waste bag dispenser is not accessible because there is not adequate clear floor space for an approach.	\$ 1,013	7	Medium		
Paved Trail	19	South Lakes Trail	71	The trash can is not accessible because there is not adequate clear floor space for an approach.	\$ 338	7	Medium		
Paved Trail	19	South Lakes Trail	81	The clear floor space required at accessible drinking fountains is not positioned for a forward approach.	\$ 2,025	7	Medium		
Paved Trail	19	South Lakes Trail	82	The water flow from the spout does not meet minimum height requirements.  The fountain was not operational at the time of evaluation.	\$ 2,025	7	Medium		
Signalized Intersection	3	Intersection of Teasley Ln and Hickory Creek Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Hickory Creek Rd	\$ 54,900	5	Medium		
Signalized Intersection	4	Intersection of Teasley Ln and Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Wheeler Ridge Dr	\$ 71,000	5	Medium		
Signalized Intersection	5	Intersection of Teasley Ln and Robinson Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Robinson Rd	\$ 60,500	5	Medium		
Signalized Intersection	7	Intersection of S Mayhill Rd and I-35E Frontage Rd NB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Mayhill Rd and I-35E Frontage Rd NB	\$ 18,800	5	Medium		
Signalized Intersection	13	Intersection of Colorado Blvd and Medpark Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Colorado Blvd and Medpark Dr	\$ 20,600	5	Medium		
Signalized Intersection	16	Intersection of Brinker Rd and Medpark Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brinker Rd and Medpark Dr	\$ 19,000	5	Medium		
Signalized Intersection	19	Intersection of Lillian Miller Pkwy and I-35E Frontage Rd NB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lillian Miller Pkwy and I-35E Frontage Rd NB	\$ 68,500	5	Medium		
Signalized Intersection	22	Intersection of Teasley Ln and Londonderry Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Londonderry Ln	\$ 22,200	5	Medium		
Signalized Intersection	24	Intersection of Brinker Rd and shopping entrance (Lat. 33.1905; Long. -97.0958)	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brinker Rd and shopping entrance (Lat. 33.1905; Long. -97.0958)	\$ 31,800	5	Medium		
Signalized Intersection	25	Intersection of Teasley Ln and shopping entrance (Lat. 33.1914; Long. -97.1244)	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and shopping entrance (Lat. 33.1914; Long. -97.1244)	\$ 38,800	5	Medium		
Signalized Intersection	26	Intersection of Loop 288 and shopping entrance (Lat. 33.1915; Long. -97.0993)	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loop 288 and shopping entrance (Lat. 33.1915; Long. -97.0993)	\$ 53,800	5	Medium		
Signalized Intersection	27	Intersection of Loop 288 and Brinker Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loop 288 and Brinker Rd	\$ 51,000	5	Medium		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Signalized Intersection	29	Intersection of Teasley Ln and I-35E Frontage Rd NB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and I-35E Frontage Rd NB	\$ 30,700	5	Medium		
Signalized Intersection	31	Intersection of Loop 288 and Spencer Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loop 288 and Spencer Rd	\$ 43,600	5	Medium		
Signalized Intersection	32	Intersection of Fort Worth Dr and I-35E Frontage Rd NB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fort Worth Dr and I-35E Frontage Rd NB	\$ 40,800	5	Medium		
Signalized Intersection	34	Intersection of S Woodrow Ln and Spencer Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Woodrow Ln and Spencer Rd	\$ 26,700	5	Medium		
Signalized Intersection	35	Intersection of S Woodrow Ln and Shady Oaks Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Woodrow Ln and Shady Oaks Dr	\$ 55,300	5	Medium		
Signalized Intersection	37	Intersection of McCormick St and I-35E Frontage Rd NB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of McCormick St and I-35E Frontage Rd NB	\$ 40,500	5	Medium		
Signalized Intersection	38	Intersection of S Carroll Blvd / Fort Worth Dr and Collins St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Carroll Blvd / Fort Worth Dr and Collins St	\$ 72,000	5	Medium		
Signalized Intersection	41	Intersection of S Bell Ave and Eagle Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bell Ave and Eagle Dr	\$ 35,800	5	Medium		
Signalized Intersection	51	Intersection of S Bonnie Brae St and I-35E Frontage Rd NB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bonnie Brae St and I-35E Frontage Rd NB	\$ 23,500	5	Medium		
Signalized Intersection	56	Intersection of S Bell Ave and E Sycamore St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bell Ave and E Sycamore St	\$ 29,200	5	Medium		
Signalized Intersection	57	Intersection of S Locust St and E Sycamore St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Locust St and E Sycamore St	\$ 76,300	5	Medium		
Signalized Intersection	58	Intersection of S Elm St and W Sycamore St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Elm St and W Sycamore St	\$ 84,400	5	Medium		
Signalized Intersection	69	Intersection of S Bonnie Brea St and W Hickory St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bonnie Brea St and W Hickory St	\$ 51,000	5	Medium		
Signalized Intersection	72	Intersection of N Carroll Blvd and W Oak St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and W Oak St	\$ 40,400	5	Medium		
Signalized Intersection	76	Intersection of N Bonnie Brea St and W Oak St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brea St and W Oak St	\$ 72,100	5	Medium		
Signalized Intersection	77	Intersection of E McKinney St and N Wood St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E McKinney St and N Wood St	\$ 50,800	5	Medium		
Signalized Intersection	78	Intersection of N Bell Ave and E McKinney St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bell Ave and E McKinney St	\$ 56,000	5	Medium		
Signalized Intersection	79	Intersection of N Locust St and E McKinney St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Locust St and E McKinney St	\$ 68,100	5	Medium		
Signalized Intersection	81	Intersection of N Elm St and W Parkway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Elm St and W Parkway St	\$ 61,100	5	Medium		
Signalized Intersection	86	Intersection of N Carroll Blvd and Crescent St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Crescent St	\$ 43,200	5	Medium		
Signalized Intersection	99	Intersection of W University Dr and Masch Branch Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and Masch Branch Rd	\$ 53,100	5	Medium		
Signalized Intersection	102	Intersection of N Elm St and Sherman Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Elm St and Sherman Dr	\$ 69,300	5	Medium		
Signalized Intersection	103	Intersection of N Locust St and Sherman Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Locust St and Sherman Dr	\$ 43,900	5	Medium		
Signalized Intersection	104	Intersection of N Carroll Blvd and W Sherman Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and W Sherman Dr	\$ 40,700	5	Medium		
Signalized Intersection	105	Intersection of E University Dr and N Ruddell St / Robinwood Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E University Dr and N Ruddell St / Robinwood Ln	\$ 28,500	5	Medium		
Signalized Intersection	109	Intersection of E University Dr and Mockingbird Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E University Dr and Mockingbird Ln	\$ 35,300	5	Medium		
Signalized Intersection	111	Intersection of N Elm St and FM 2164	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Elm St and FM 2164	\$ 29,300	5	Medium		
Signalized Intersection	112	Intersection of N Locust St and FM 2164	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Locust St and FM 2164	\$ 38,300	5	Medium		
Signalized Intersection	115	Intersection of E Windsor Dr and E Sherman Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Windsor Dr and E Sherman Dr	\$ 49,000	5	Medium		
Signalized Intersection	117	Intersection of I-35 Frontage Rd NB and N Elm St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of I-35 Frontage Rd NB and N Elm St	\$ 67,000	5	Medium		
Signalized Intersection	118	Intersection of State of School Rd and I-35E Frontage Rd SB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of State of School Rd and I-35E Frontage Rd SB	\$ 45,800	5	Medium		
Signalized Intersection	119	Intersection of Lillian Miller Pkwy and I-35E Frontage Rd SB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lillian Miller Pkwy and I-35E Frontage Rd SB	\$ 50,900	5	Medium		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Signalized Intersection	120	Intersection of Teasley Ln and I-35E Frontage Rd SB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and I-35E Frontage Rd SB	\$ 24,900	5	Medium		
Signalized Intersection	121	Intersection of Fort Worth Dr and I-35E Frontage Rd SB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fort Worth Dr and I-35E Frontage Rd SB	\$ 30,100	5	Medium		
Signalized Intersection	122	Intersection of McCormick St and I-35E Frontage Rd SB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of McCormick St and I-35E Frontage Rd SB	\$ 37,800	5	Medium		
Signalized Intersection	11	Intersection of Fort Worth Dr and Country Club Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fort Worth Dr and Country Club Rd	\$ 20,400	6	Medium		
Signalized Intersection	12	Intersection of Colorado Blvd and Edwards Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Colorado Blvd and Edwards Rd	\$ 31,200	7	Medium		
Signalized Intersection	33	Intersection of Teasley Ln and US Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and US Hwy 77	\$ 87,600	7	Medium		
Signalized Intersection	62	Intersection of N Bell Ave and E Hickory St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bell Ave and E Hickory St	\$ 41,300	7	Medium		
Signalized Intersection	82	Intersection of N Locust St and E Parkway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Locust St and E Parkway St	\$ 70,400	7	Medium		
Signalized Intersection	88	Intersection of N Bell St and Administration Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bell St and Administration Dr	\$ 42,300	7	Medium		
Signalized Intersection	91	Intersection of W University Dr and Fulton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and Fulton St	\$ 27,100	7	Medium		
Signalized Intersection	125	Intersection of Noth Texas Blvd and I-35E Frontage Rd SB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Noth Texas Blvd and I-35E Frontage Rd SB	\$ 28,400	7	Medium		
Unpaved Trail	1	Clear Creek Trail	5	The portable public restroom is not compliant.	\$ 1,013	6	Medium		
Unpaved Trail	1	Clear Creek Trail	6	There is no accessible route to the portable restroom.	\$ 2,025	6	Medium		
Unpaved Trail	1	Clear Creek Trail	7	There is no accessible route to the trail maps.	\$ 2,025	6	Medium		
Unpaved Trail	1	Clear Creek Trail	4	There is no accessible route to the trash can.	\$ 338	7	Medium		
PROW Sidewalk	1	Abbot's Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,990	2	Fair		
PROW Sidewalk	16	Amarillo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,680	2	Fair		
PROW Sidewalk	21	Anysa Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,930	2	Fair		
PROW Sidewalk	24	Arrowhead Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,870	2	Fair		
PROW Sidewalk	30	Audra Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,260	2	Fair		
PROW Sidewalk	40	N Ave B	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	2	Fair		
PROW Sidewalk	41	S Ave B	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,260	2	Fair		
PROW Sidewalk	44	S Ave C	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,390	2	Fair		
PROW Sidewalk	47	Ave D	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,870	2	Fair		
PROW Sidewalk	50	N North Texas Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,200	2	Fair		
PROW Sidewalk	68	Barcelona St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	2	Fair		
PROW Sidewalk	78	N Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,960	2	Fair		
PROW Sidewalk	80	Bell Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	2	Fair		
PROW Sidewalk	81	Bellaire Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,570	2	Fair		
PROW Sidewalk	87	Bernard St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,120	2	Fair		
PROW Sidewalk	94	Beverly Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,410	2	Fair		
PROW Sidewalk	106	Bolivar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,470	2	Fair		
PROW Sidewalk	107	N Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,470	2	Fair		
PROW Sidewalk	110	S Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,360	2	Fair		
PROW Sidewalk	117	Boyd St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,280	2	Fair		
PROW Sidewalk	118	Bradley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,990	2	Fair		
PROW Sidewalk	122	S Bradshaw St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,680	2	Fair		
PROW Sidewalk	138	W Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,660	2	Fair		
PROW Sidewalk	139	Brooke St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,720	2	Fair		
PROW Sidewalk	140	Brookfield Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,120	2	Fair		
PROW Sidewalk	145	Brush Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,270	2	Fair		
PROW Sidewalk	171	N Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,250	2	Fair		
PROW Sidewalk	172	S Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 29,650	2	Fair		
PROW Sidewalk	173	Casie Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,080	2	Fair		
PROW Sidewalk	190	Chestnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,230	2	Fair		
PROW Sidewalk	205	E College St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,480	2	Fair		
PROW Sidewalk	206	W College St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,400	2	Fair		
PROW Sidewalk	208	Collier St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	2	Fair		
PROW Sidewalk	210	W Collins St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,050	2	Fair		
PROW Sidewalk	212	Colorado Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,260	2	Fair		
PROW Sidewalk	215	E Congress St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,660	2	Fair		
PROW Sidewalk	216	W Congress St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,680	2	Fair		
PROW Sidewalk	222	Cooper Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,550	2	Fair		
PROW Sidewalk	235	Cornell Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,940	2	Fair		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	242	N Crawford St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,090	2	Fair		
PROW Sidewalk	244	Creek Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,920	2	Fair		
PROW Sidewalk	245	Crescent St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	2	Fair		
PROW Sidewalk	246	Crestmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,040	2	Fair		
PROW Sidewalk	259	Davis St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	2	Fair		
PROW Sidewalk	263	Denton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,650	2	Fair		
PROW Sidewalk	275	Duncan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,600	2	Fair		
PROW Sidewalk	277	Dunes St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,260	2	Fair		
PROW Sidewalk	280	W Eagle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	2	Fair		
PROW Sidewalk	303	Emerson Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 880	2	Fair		
PROW Sidewalk	304	Emery St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,120	2	Fair		
PROW Sidewalk	308	N Exposition St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	2	Fair		
PROW Sidewalk	313	Fallmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,380	2	Fair		
PROW Sidewalk	315	Farris Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,460	2	Fair		
PROW Sidewalk	329	Forrestridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,230	2	Fair		
PROW Sidewalk	334	Fowler Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,280	2	Fair		
PROW Sidewalk	339	Frame St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,610	2	Fair		
PROW Sidewalk	343	Fry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,200	2	Fair		
PROW Sidewalk	344	Fulton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,480	2	Fair		
PROW Sidewalk	350	Gardenview St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,220	2	Fair		
PROW Sidewalk	355	Geesling Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,270	2	Fair		
PROW Sidewalk	357	Georgetown Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	2	Fair		
PROW Sidewalk	360	Glennary Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	2	Fair		
PROW Sidewalk	361	Glenwood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,270	2	Fair		
PROW Sidewalk	367	Grant Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,280	2	Fair		
PROW Sidewalk	370	Greenlee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 700	2	Fair		
PROW Sidewalk	372	Greenway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	2	Fair		
PROW Sidewalk	381	Hann St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,660	2	Fair		
PROW Sidewalk	382	Hanover Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,860	2	Fair		
PROW Sidewalk	390	Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 440	2	Fair		
PROW Sidewalk	393	E Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	2	Fair		
PROW Sidewalk	394	W Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,750	2	Fair		
PROW Sidewalk	402	W Highland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,810	2	Fair		
PROW Sidewalk	417	Hinkle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 770	2	Fair		
PROW Sidewalk	418	E Hobson Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,810	2	Fair		
PROW Sidewalk	444	Inca Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,090	2	Fair		
PROW Sidewalk	446	Industrial St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 910	2	Fair		
PROW Sidewalk	467	John Paine Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,430	2	Fair		
PROW Sidewalk	477	Kendolph Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 700	2	Fair		
PROW Sidewalk	487	Kings Row	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,680	2	Fair		
PROW Sidewalk	500	Lattimore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,340	2	Fair		
PROW Sidewalk	505	Leslie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,650	2	Fair		
PROW Sidewalk	509	Lillian B Miller Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,080	2	Fair		
PROW Sidewalk	530	Longmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,570	2	Fair		
PROW Sidewalk	531	Longridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 730	2	Fair		
PROW Sidewalk	535	Louise St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	2	Fair		
PROW Sidewalk	538	Mack Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,800	2	Fair		
PROW Sidewalk	544	Malone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,860	2	Fair		
PROW Sidewalk	549	Maple St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,750	2	Fair		
PROW Sidewalk	573	S Mayhill Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,240	2	Fair		
PROW Sidewalk	581	E Mckinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,540	2	Fair		
PROW Sidewalk	584	W Mckinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,100	2	Fair		
PROW Sidewalk	586	Meadow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 700	2	Fair		
PROW Sidewalk	593	Meadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,920	2	Fair		
PROW Sidewalk	595	Mercedes Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,400	2	Fair		
PROW Sidewalk	596	Mesa Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	2	Fair		
PROW Sidewalk	620	Mockingbird Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,170	2	Fair		
PROW Sidewalk	621	Mohican Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,200	2	Fair		
PROW Sidewalk	624	Montecito Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70,790	2	Fair		
PROW Sidewalk	626	Monterey Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,440	2	Fair		
PROW Sidewalk	629	Morse St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,270	2	Fair		
PROW Sidewalk	631	Mounts Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,240	2	Fair		
PROW Sidewalk	635	W Mulberry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,580	2	Fair		
PROW Sidewalk	645	Nevada St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,980	2	Fair		
PROW Sidewalk	648	Normal St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,860	2	Fair		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	656	E Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,910	2	Fair		
PROW Sidewalk	660	W Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50,310	2	Fair		
PROW Sidewalk	668	Oakland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,410	2	Fair		
PROW Sidewalk	682	Old North Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,060	2	Fair		
PROW Sidewalk	687	Oriole Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,780	2	Fair		
PROW Sidewalk	699	Panhandle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,980	2	Fair		
PROW Sidewalk	703	E Parkway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 230	2	Fair		
PROW Sidewalk	704	W Parkway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,760	2	Fair		
PROW Sidewalk	705	Parvin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,670	2	Fair		
PROW Sidewalk	709	Peach St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	2	Fair		
PROW Sidewalk	714	E Pecan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,640	2	Fair		
PROW Sidewalk	715	W Pecan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,450	2	Fair		
PROW Sidewalk	718	Pennsylvania Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,410	2	Fair		
PROW Sidewalk	722	Pheasant Hollow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 920	2	Fair		
PROW Sidewalk	742	E Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	2	Fair		
PROW Sidewalk	744	W Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,580	2	Fair		
PROW Sidewalk	765	Redwood Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,670	2	Fair		
PROW Sidewalk	771	Riney Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,340	2	Fair		
PROW Sidewalk	775	Roberts St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,960	2	Fair		
PROW Sidewalk	776	Robertson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,750	2	Fair		
PROW Sidewalk	778	Robinson Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,100	2	Fair		
PROW Sidewalk	814	Schmitz Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,690	2	Fair		
PROW Sidewalk	817	Scripture St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,380	2	Fair		
PROW Sidewalk	819	Second St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,630	2	Fair		
PROW Sidewalk	820	Selene Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,800	2	Fair		
PROW Sidewalk	824	Shadow Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 860	2	Fair		
PROW Sidewalk	825	Shady Oaks Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,130	2	Fair		
PROW Sidewalk	828	Shawnee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	2	Fair		
PROW Sidewalk	831	E Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,640	2	Fair		
PROW Sidewalk	833	W Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,270	2	Fair		
PROW Sidewalk	847	Southridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,740	2	Fair		
PROW Sidewalk	853	Stella St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,370	2	Fair		
PROW Sidewalk	860	Stuart Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,270	2	Fair		
PROW Sidewalk	863	Sun Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,610	2	Fair		
PROW Sidewalk	869	E Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 720	2	Fair		
PROW Sidewalk	871	W Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,970	2	Fair		
PROW Sidewalk	890	Thomas St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 730	2	Fair		
PROW Sidewalk	912	Uland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,990	2	Fair		
PROW Sidewalk	920	Valley View Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,560	2	Fair		
PROW Sidewalk	925	Vine St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,330	2	Fair		
PROW Sidewalk	927	Wainwright St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	2	Fair		
PROW Sidewalk	935	S Welch St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	2	Fair		
PROW Sidewalk	950	Westward St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,370	2	Fair		
PROW Sidewalk	965	Willowwood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,400	2	Fair		
PROW Sidewalk	968	Wilson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,990	2	Fair		
PROW Sidewalk	973	Windbrook St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,630	2	Fair		
PROW Sidewalk	975	E Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,820	2	Fair		
PROW Sidewalk	976	W Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40,560	2	Fair		
PROW Sidewalk	986	N Wood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,840	2	Fair		
PROW Sidewalk	995	Conley Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,060	2	Fair		
PROW Sidewalk	997	S Woodrow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 61,810	2	Fair		
PROW Sidewalk	1000	Worthington Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,000	2	Fair		
PROW Sidewalk	1002	Yellowstone Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,220	2	Fair		
PROW Sidewalk	1012	Paxton Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,510	2	Fair		
PROW Sidewalk	1014	Cobblestone Rv	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,790	2	Fair		
PROW Sidewalk	1016	Long Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,140	2	Fair		
PROW Sidewalk	1021	Deerwood Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,120	2	Fair		
PROW Sidewalk	1022	Deerfield Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,890	2	Fair		
PROW Sidewalk	1030	Royal Oaks Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,230	2	Fair		
PROW Sidewalk	1032	Royal Oaks Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,620	2	Fair		
PROW Sidewalk	1046	Saints Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,330	2	Fair		
PROW Sidewalk	1049	Norfolk Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 910	2	Fair		
PROW Sidewalk	1051	Shenandoah Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,720	2	Fair		
PROW Sidewalk	1053	Blue Ridge Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,390	2	Fair		
PROW Sidewalk	1107	Palo Verde Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,830	2	Fair		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1131	Brinker Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,950	2	Fair		
PROW Sidewalk	1133	Vista Verde Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,740	2	Fair		
PROW Sidewalk	1134	Buena Vista	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,680	2	Fair		
PROW Sidewalk	1179	Shiloh Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,060	2	Fair		
PROW Sidewalk	1181	Potomac Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,490	2	Fair		
PROW Sidewalk	1182	Westcourt Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 840	2	Fair		
PROW Sidewalk	1186	Harvest Glen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,070	2	Fair		
PROW Sidewalk	1187	Harvest Hill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,690	2	Fair		
PROW Sidewalk	1188	High Meadow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,200	2	Fair		
PROW Sidewalk	1192	Visalia Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,390	2	Fair		
PROW Sidewalk	1193	Belmont St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,470	2	Fair		
PROW Sidewalk	1195	Bentwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,750	2	Fair		
PROW Sidewalk	1196	Oakview Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,080	2	Fair		
PROW Sidewalk	1198	Whitetail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,550	2	Fair		
PROW Sidewalk	1201	Chateau Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,150	2	Fair		
PROW Sidewalk	1205	Wildwood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,480	2	Fair		
PROW Sidewalk	1207	Osage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,430	2	Fair		
PROW Sidewalk	1209	Huron Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,430	2	Fair		
PROW Sidewalk	1210	Wind River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,330	2	Fair		
PROW Sidewalk	1212	Chaucer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 940	2	Fair		
PROW Sidewalk	1222	Saint Claire Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,260	2	Fair		
PROW Sidewalk	1224	Loon Lake Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,180	2	Fair		
PROW Sidewalk	1309	Brisas Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,660	2	Fair		
PROW Sidewalk	1314	Moss creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,770	2	Fair		
PROW Sidewalk	1319	Ridgemont Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,860	2	Fair		
PROW Sidewalk	1320	Montecristo Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,680	2	Fair		
PROW Sidewalk	1322	San Marino Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,420	2	Fair		
PROW Sidewalk	1323	Sundown Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,190	2	Fair		
PROW Sidewalk	1324	Lake Country Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,040	2	Fair		
PROW Sidewalk	1325	Clubhouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,830	2	Fair		
PROW Sidewalk	1327	Reata Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 740	2	Fair		
PROW Sidewalk	1328	Ranchman Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,380	2	Fair		
PROW Sidewalk	1330	Summit Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,250	2	Fair		
PROW Sidewalk	1333	Cape Hatteras Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 730	2	Fair		
PROW Sidewalk	1334	W El Paseo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,600	2	Fair		
PROW Sidewalk	1336	Manten Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,360	2	Fair		
PROW Sidewalk	1337	La Vista Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,860	2	Fair		
PROW Sidewalk	1338	Calvert Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,050	2	Fair		
PROW Sidewalk	1344	Gessner Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,510	2	Fair		
PROW Sidewalk	1347	San Felipe Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,970	2	Fair		
PROW Sidewalk	1348	Willowick Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,590	2	Fair		
PROW Sidewalk	1351	Kirby Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,820	2	Fair		
PROW Sidewalk	1353	Wintercreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,610	2	Fair		
PROW Sidewalk	1354	Kappwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,680	2	Fair		
PROW Sidewalk	1356	Montevideo Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,770	2	Fair		
PROW Sidewalk	1359	Field Bend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,060	2	Fair		
PROW Sidewalk	1361	Great Bear Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,600	2	Fair		
PROW Sidewalk	1362	Geneva Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,910	2	Fair		
PROW Sidewalk	1363	Ottawa Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,900	2	Fair		
PROW Sidewalk	1364	Tahoe Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,570	2	Fair		
PROW Sidewalk	1366	Kariba Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,370	2	Fair		
PROW Sidewalk	1369	Como Lake Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,170	2	Fair		
PROW Sidewalk	1370	Herring Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,580	2	Fair		
PROW Sidewalk	1371	Crater Lake Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,340	2	Fair		
PROW Sidewalk	1372	Meredith Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,010	2	Fair		
PROW Sidewalk	1373	Villanova Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,030	2	Fair		
PROW Sidewalk	1374	Marquette Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,490	2	Fair		
PROW Sidewalk	1376	Centenary Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,330	2	Fair		
PROW Sidewalk	1377	Harvard Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,540	2	Fair		
PROW Sidewalk	1379	Glendora Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,230	2	Fair		
PROW Sidewalk	1380	Mira Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,620	2	Fair		
PROW Sidewalk	1398	Marble Cove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,900	2	Fair		
PROW Sidewalk	1399	White Dove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,410	2	Fair		
PROW Sidewalk	1400	Rushing Spring Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 890	2	Fair		
PROW Sidewalk	1401	Silent Star Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,560	2	Fair		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1402	Eagle Wing Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,960	2	Fair		
PROW Sidewalk	1404	Clear River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,610	2	Fair		
PROW Sidewalk	1405	Cherry Tree Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,150	2	Fair		
PROW Sidewalk	1406	Hazelwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,270	2	Fair		
PROW Sidewalk	1407	Seven Oaks Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,980	2	Fair		
PROW Sidewalk	1408	Early Dawn Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,680	2	Fair		
PROW Sidewalk	1409	Serenity Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 42,160	2	Fair		
PROW Sidewalk	1410	Swan Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,520	2	Fair		
PROW Sidewalk	1411	Glen Falls Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,280	2	Fair		
PROW Sidewalk	1412	Canoe Ridge Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,870	2	Fair		
PROW Sidewalk	1416	Northway	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,750	2	Fair		
PROW Sidewalk	1417	Frost Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,370	2	Fair		
PROW Sidewalk	1419	Val Verde Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,880	2	Fair		
PROW Sidewalk	1420	Bent Oaks Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,540	2	Fair		
PROW Sidewalk	1421	Briary Trace Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,920	2	Fair		
PROW Sidewalk	1424	Indigo Terrace St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,220	2	Fair		
PROW Sidewalk	1426	Lakeview Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,820	2	Fair		
PROW Sidewalk	1436	La Mirada	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,450	2	Fair		
PROW Sidewalk	1440	Inwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,710	2	Fair		
PROW Sidewalk	1441	Crenshaw Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,100	2	Fair		
PROW Sidewalk	1442	Pine Hills Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,510	2	Fair		
PROW Sidewalk	1443	Palmetto Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,040	2	Fair		
PROW Sidewalk	1444	Hayling Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,430	2	Fair		
PROW Sidewalk	1445	Alderbrook Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,550	2	Fair		
PROW Sidewalk	1446	Maggie's Meadow	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,930	2	Fair		
PROW Sidewalk	1450	Paco Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,590	2	Fair		
PROW Sidewalk	1454	Bentgate Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,600	2	Fair		
PROW Sidewalk	1455	Teasbend Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,360	2	Fair		
PROW Sidewalk	1457	Winding Stream Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,410	2	Fair		
PROW Sidewalk	1459	Rambling Brook Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,320	2	Fair		
PROW Sidewalk	1473	Crapemyrtle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,520	2	Fair		
PROW Sidewalk	1477	Boxwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 800	2	Fair		
PROW Sidewalk	1498	Mustang Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,360	2	Fair		
PROW Sidewalk	1500	Pinto Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,640	2	Fair		
PROW Sidewalk	1501	Paint Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,890	2	Fair		
PROW Sidewalk	1502	Hereford Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,830	2	Fair		
PROW Sidewalk	1503	Big Horn Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,540	2	Fair		
PROW Sidewalk	1504	Palamino Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,860	2	Fair		
PROW Sidewalk	1505	Arabian Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,430	2	Fair		
PROW Sidewalk	1506	Fiste St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,690	2	Fair		
PROW Sidewalk	1508	Savage Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,670	2	Fair		
PROW Sidewalk	1509	Cruise St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,380	2	Fair		
PROW Sidewalk	1510	Dixon Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,640	2	Fair		
PROW Sidewalk	1521	Creekdale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,610	2	Fair		
PROW Sidewalk	1523	Riverpass Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,950	2	Fair		
PROW Sidewalk	1524	Sunburst Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,810	2	Fair		
PROW Sidewalk	1526	Ashwood Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,090	2	Fair		
PROW Sidewalk	1527	Riverchase Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,750	2	Fair		
PROW Sidewalk	1528	Waterside Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,950	2	Fair		
PROW Sidewalk	1530	Dawnlight Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,200	2	Fair		
PROW Sidewalk	1531	Baybrooke Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,900	2	Fair		
PROW Sidewalk	1541	Yale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,850	2	Fair		
PROW Sidewalk	1547	Valencia Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,200	2	Fair		
PROW Sidewalk	1571	Mosspoint Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,310	2	Fair		
PROW Sidewalk	1573	Blue Sky Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 730	2	Fair		
PROW Sidewalk	1574	Harvest Moon Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,520	2	Fair		
PROW Sidewalk	1575	Sirius Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	2	Fair		
PROW Sidewalk	1579	Par Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,650	2	Fair		
PROW Sidewalk	1581	Atlantic Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,370	2	Fair		
PROW Sidewalk	1583	Nicosia St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	2	Fair		
PROW Sidewalk	1585	Hermalinda Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,660	2	Fair		
PROW Sidewalk	1586	Morin Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,270	2	Fair		
PROW Sidewalk	1587	Chon Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,270	2	Fair		
PROW Sidewalk	1588	Beatriz Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,050	2	Fair		
PROW Sidewalk	1589	Eufemia Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,480	2	Fair		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1590	Santos Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,300	2	Fair		
PROW Sidewalk	1591	Constantina Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,470	2	Fair		
PROW Sidewalk	1594	Dunlavy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,820	2	Fair		
PROW Sidewalk	1602	Las Brisas Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,870	2	Fair		
PROW Sidewalk	1603	Purbeck Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,130	2	Fair		
PROW Sidewalk	1604	Algarve Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,330	2	Fair		
PROW Sidewalk	1605	Black Butte Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,950	2	Fair		
PROW Sidewalk	1606	Luck Hole Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,940	2	Fair		
PROW Sidewalk	1610	Lighthouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,540	2	Fair		
PROW Sidewalk	1611	Ocean Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,920	2	Fair		
PROW Sidewalk	1613	Nautical Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,500	2	Fair		
PROW Sidewalk	1615	Vinyard Way St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,280	2	Fair		
PROW Sidewalk	1616	Claret Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,830	2	Fair		
PROW Sidewalk	1618	Provence Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,570	2	Fair		
PROW Sidewalk	1622	Alsace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,550	2	Fair		
PROW Sidewalk	1623	Napa Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,720	2	Fair		
PROW Sidewalk	1629	Stoneway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,300	2	Fair		
PROW Sidewalk	1630	Circle View Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,220	2	Fair		
PROW Sidewalk	1637	Belmont Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,310	2	Fair		
PROW Sidewalk	1639	Lone Star Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,080	2	Fair		
PROW Sidewalk	1652	Fox Sedge Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,550	2	Fair		
PROW Sidewalk	1671	Hudsonwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,450	2	Fair		
PROW Sidewalk	1676	Stockton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,740	2	Fair		
PROW Sidewalk	1681	Ramsey Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,870	2	Fair		
PROW Sidewalk	1689	Depaul Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,170	2	Fair		
PROW Sidewalk	1690	Syracuse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,670	2	Fair		
PROW Sidewalk	1691	Miramar Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,920	2	Fair		
PROW Sidewalk	1711	Waters Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 640	2	Fair		
PROW Sidewalk	1712	Tripp Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,190	2	Fair		
PROW Sidewalk	1714	Northpointe Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,770	2	Fair		
PROW Sidewalk	1715	Chapel Hill Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,800	2	Fair		
PROW Sidewalk	1717	Skelton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,390	2	Fair		
PROW Sidewalk	1720	Creekway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,880	2	Fair		
PROW Sidewalk	1721	Parkplace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,120	2	Fair		
PROW Sidewalk	1722	Brookside Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,430	2	Fair		
PROW Sidewalk	1724	Trailridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,890	2	Fair		
PROW Sidewalk	1730	Greenmeadow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,720	2	Fair		
PROW Sidewalk	1732	Meadowglen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,470	2	Fair		
PROW Sidewalk	1737	Penina Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,340	2	Fair		
PROW Sidewalk	1742	Club View Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,980	2	Fair		
PROW Sidewalk	1743	Fairway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	2	Fair		
PROW Sidewalk	1745	Crooked Stick Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,710	2	Fair		
PROW Sidewalk	1746	Sawgrass Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,180	2	Fair		
PROW Sidewalk	1748	Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,290	2	Fair		
PROW Sidewalk	1749	Friesian Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,320	2	Fair		
PROW Sidewalk	1750	Andalusian Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,320	2	Fair		
PROW Sidewalk	1751	Lipizzan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,200	2	Fair		
PROW Sidewalk	1757	Morgan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	2	Fair		
PROW Sidewalk	1759	Rocky Mountain Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,310	2	Fair		
PROW Sidewalk	1763	Sombrero Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,660	2	Fair		
PROW Sidewalk	1766	Tristan Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,510	2	Fair		
PROW Sidewalk	1771	Carrigan Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,050	2	Fair		
PROW Sidewalk	1786	Berry Down Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,760	2	Fair		
PROW Sidewalk	1787	Logan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,050	2	Fair		
PROW Sidewalk	1789	Beall St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,840	2	Fair		
PROW Sidewalk	1790	Bay Meadow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	2	Fair		
PROW Sidewalk	1797	Merlot Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,390	2	Fair		
PROW Sidewalk	1804	Thoroughbred Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,760	2	Fair		
PROW Sidewalk	1806	Thistle Ridge	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,020	2	Fair		
PROW Sidewalk	1810	Vickery Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,290	2	Fair		
PROW Sidewalk	1811	Thistle Hill	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,200	2	Fair		
PROW Sidewalk	1813	Ricks Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,750	2	Fair		
PROW Sidewalk	1830	Englefield Green	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,440	2	Fair		
PROW Sidewalk	1833	Bray Village Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,420	2	Fair		
PROW Sidewalk	1837	English Manor Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,930	2	Fair		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1838	Lost Pony Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,620	2	Fair		
PROW Sidewalk	1839	Green Ivy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,440	2	Fair		
PROW Sidewalk	1843	Paddock Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,360	2	Fair		
PROW Sidewalk	1846	Saddleback Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,790	2	Fair		
PROW Sidewalk	1848	Mercer Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,140	2	Fair		
PROW Sidewalk	1849	Carson Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,810	2	Fair		
PROW Sidewalk	1850	Groveland Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,400	2	Fair		
PROW Sidewalk	1852	Pineoak Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,480	2	Fair		
PROW Sidewalk	1853	Swiss Pine Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,700	2	Fair		
PROW Sidewalk	1870	Gable Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,390	2	Fair		
PROW Sidewalk	1875	Silver Sage Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	2	Fair		
PROW Sidewalk	1877	Water Oak Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,510	2	Fair		
PROW Sidewalk	1878	Union Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,360	2	Fair		
PROW Sidewalk	1880	Shelby Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,560	2	Fair		
PROW Sidewalk	1881	Dakota Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	2	Fair		
PROW Sidewalk	1888	Saddle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,870	2	Fair		
PROW Sidewalk	1889	Rustic Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,260	2	Fair		
PROW Sidewalk	1890	Wellston Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,420	2	Fair		
PROW Sidewalk	1891	Groveland Terrace	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,530	2	Fair		
PROW Sidewalk	1892	Longleaf Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,390	2	Fair		
PROW Sidewalk	1894	Corral Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,500	2	Fair		
PROW Sidewalk	1895	Lipizzan Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,330	2	Fair		
PROW Sidewalk	1908	San Lucas Lane	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	2	Fair		
PROW Sidewalk	1914	Tawakoni Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	2	Fair		
PROW Sidewalk	1915	Eagle Mountain Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 920	2	Fair		
PROW Sidewalk	1917	Granbury Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,600	2	Fair		
PROW Sidewalk	1923	Claydon Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,150	2	Fair		
PROW Sidewalk	1924	Clarendon Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 990	2	Fair		
PROW Sidewalk	1925	Westglen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,590	2	Fair		
PROW Sidewalk	1929	Mark Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,290	2	Fair		
PROW Sidewalk	1975	Mockernut Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,820	2	Fair		
PROW Sidewalk	1997	Miranda Place	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,170	2	Fair		
PROW Sidewalk	1998	Alta Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,140	2	Fair		
PROW Sidewalk	2059	Hill Alley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	2	Fair		
PROW Sidewalk	2519	New Ballinger Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,350	2	Fair		
PROW Sidewalk	2532	Windhaven Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 170	2	Fair		
PROW Sidewalk	2536	Roxbury St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,530	2	Fair		
PROW Sidewalk	2553	Bayshore Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 470	2	Fair		
PROW Sidewalk	2603	Red Fox Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,150	2	Fair		
PROW Sidewalk	1	Abbot's Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,160	2	Marginal		
PROW Sidewalk	16	Amarillo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,960	2	Marginal		
PROW Sidewalk	21	Anysa Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,080	2	Marginal		
PROW Sidewalk	28	Atlas Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,420	2	Marginal		
PROW Sidewalk	30	Audra Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,990	2	Marginal		
PROW Sidewalk	32	N Austin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,930	2	Marginal		
PROW Sidewalk	34	S Austin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,530	2	Marginal		
PROW Sidewalk	41	S Ave B	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,030	2	Marginal		
PROW Sidewalk	44	S Ave C	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,680	2	Marginal		
PROW Sidewalk	50	N North Texas Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,430	2	Marginal		
PROW Sidewalk	78	N Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,020	2	Marginal		
PROW Sidewalk	79	S Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,500	2	Marginal		
PROW Sidewalk	87	Bernard St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,300	2	Marginal		
PROW Sidewalk	93	Beth St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	2	Marginal		
PROW Sidewalk	106	Bolivar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,960	2	Marginal		
PROW Sidewalk	107	N Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 35,440	2	Marginal		
PROW Sidewalk	110	S Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,560	2	Marginal		
PROW Sidewalk	117	Boyd St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,570	2	Marginal		
PROW Sidewalk	118	Bradley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 950	2	Marginal		
PROW Sidewalk	134	Broadway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	2	Marginal		
PROW Sidewalk	136	Broken Arrow Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,990	2	Marginal		
PROW Sidewalk	138	W Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,390	2	Marginal		
PROW Sidewalk	139	Brooke St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,480	2	Marginal		
PROW Sidewalk	147	Bryan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,030	2	Marginal		
PROW Sidewalk	152	Burning Tree Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,760	2	Marginal		
PROW Sidewalk	171	N Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,800	2	Marginal		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	172	S Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,750	2	Marginal		
PROW Sidewalk	178	Central Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,060	2	Marginal		
PROW Sidewalk	183	Chapel Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	2	Marginal		
PROW Sidewalk	190	Chestnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,920	2	Marginal		
PROW Sidewalk	201	Cleveland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	2	Marginal		
PROW Sidewalk	204	Coit St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 840	2	Marginal		
PROW Sidewalk	206	W College St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,080	2	Marginal		
PROW Sidewalk	208	Collier St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	2	Marginal		
PROW Sidewalk	212	Colorado Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 32,620	2	Marginal		
PROW Sidewalk	216	W Congress St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,760	2	Marginal		
PROW Sidewalk	222	Cooper Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,970	2	Marginal		
PROW Sidewalk	226	Corbin Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 870	2	Marginal		
PROW Sidewalk	231	Cordell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,510	2	Marginal		
PROW Sidewalk	244	Creek Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,710	2	Marginal		
PROW Sidewalk	245	Crescent St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,510	2	Marginal		
PROW Sidewalk	254	Daniel St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	2	Marginal		
PROW Sidewalk	259	Davis St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	2	Marginal		
PROW Sidewalk	263	Denton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,110	2	Marginal		
PROW Sidewalk	270	Doubleoak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,920	2	Marginal		
PROW Sidewalk	273	Duchess Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,690	2	Marginal		
PROW Sidewalk	274	Dudley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	2	Marginal		
PROW Sidewalk	275	Duncan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,970	2	Marginal		
PROW Sidewalk	276	Dunes Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,340	2	Marginal		
PROW Sidewalk	277	Dunes St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,640	2	Marginal		
PROW Sidewalk	280	W Eagle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,520	2	Marginal		
PROW Sidewalk	297	Egan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,150	2	Marginal		
PROW Sidewalk	303	Emerson Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,110	2	Marginal		
PROW Sidewalk	304	Emery St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,540	2	Marginal		
PROW Sidewalk	306	Evers Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,660	2	Marginal		
PROW Sidewalk	309	S Exposition St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	2	Marginal		
PROW Sidewalk	328	Forest St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,920	2	Marginal		
PROW Sidewalk	329	Forrestridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,820	2	Marginal		
PROW Sidewalk	339	Frame St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,490	2	Marginal		
PROW Sidewalk	343	Fry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,330	2	Marginal		
PROW Sidewalk	344	Fulton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 28,510	2	Marginal		
PROW Sidewalk	361	Glenwood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,550	2	Marginal		
PROW Sidewalk	367	Grant Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,340	2	Marginal		
PROW Sidewalk	370	Greenlee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,780	2	Marginal		
PROW Sidewalk	372	Greenway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,150	2	Marginal		
PROW Sidewalk	382	Hanover Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,730	2	Marginal		
PROW Sidewalk	390	Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,450	2	Marginal		
PROW Sidewalk	391	Heritage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,640	2	Marginal		
PROW Sidewalk	393	E Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,480	2	Marginal		
PROW Sidewalk	394	W Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 44,440	2	Marginal		
PROW Sidewalk	397	Hickory Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,790	2	Marginal		
PROW Sidewalk	402	W Highland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,890	2	Marginal		
PROW Sidewalk	413	Hillcrest St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,040	2	Marginal		
PROW Sidewalk	417	Hinkle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,800	2	Marginal		
PROW Sidewalk	446	Industrial St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,220	2	Marginal		
PROW Sidewalk	453	Jacqueline Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,890	2	Marginal		
PROW Sidewalk	477	Kendolph Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,200	2	Marginal		
PROW Sidewalk	487	Kings Row	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,020	2	Marginal		
PROW Sidewalk	505	Leslie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,690	2	Marginal		
PROW Sidewalk	509	Lillian B Miller Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,680	2	Marginal		
PROW Sidewalk	527	Londonderry Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,440	2	Marginal		
PROW Sidewalk	530	Longmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,310	2	Marginal		
PROW Sidewalk	537	Lynhurst Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,020	2	Marginal		
PROW Sidewalk	538	Mack Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,720	2	Marginal		
PROW Sidewalk	544	Malone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,760	2	Marginal		
PROW Sidewalk	549	Maple St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,110	2	Marginal		
PROW Sidewalk	558	Marietta St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,990	2	Marginal		
PROW Sidewalk	561	Marshall St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	2	Marginal		
PROW Sidewalk	573	S Mayhill Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,770	2	Marginal		
PROW Sidewalk	578	Mccormick St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,220	2	Marginal		
PROW Sidewalk	581	E Mckinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,920	2	Marginal		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	584	W McKinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,630	2	Marginal		
PROW Sidewalk	586	Meadow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,490	2	Marginal		
PROW Sidewalk	595	Mercedes Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,740	2	Marginal		
PROW Sidewalk	596	Mesa Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,360	2	Marginal		
PROW Sidewalk	602	Mill St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 270	2	Marginal		
PROW Sidewalk	605	Miller St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,590	2	Marginal		
PROW Sidewalk	610	Mingo Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,510	2	Marginal		
PROW Sidewalk	620	Mockingbird Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,730	2	Marginal		
PROW Sidewalk	621	Mohican Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,550	2	Marginal		
PROW Sidewalk	624	Montecito Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,030	2	Marginal		
PROW Sidewalk	629	Morse St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,790	2	Marginal		
PROW Sidewalk	631	Mounts Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,440	2	Marginal		
PROW Sidewalk	635	W Mulberry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,610	2	Marginal		
PROW Sidewalk	642	Navajo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,900	2	Marginal		
PROW Sidewalk	645	Nevada St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,320	2	Marginal		
PROW Sidewalk	660	W Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,890	2	Marginal		
PROW Sidewalk	663	Oak Tree Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,980	2	Marginal		
PROW Sidewalk	668	Oakland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 39,150	2	Marginal		
PROW Sidewalk	682	Old North Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	2	Marginal		
PROW Sidewalk	683	Old Orchard Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,320	2	Marginal		
PROW Sidewalk	695	Paisley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 27,030	2	Marginal		
PROW Sidewalk	699	Panhandle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,890	2	Marginal		
PROW Sidewalk	704	W Parkway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,110	2	Marginal		
PROW Sidewalk	705	Parvin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,060	2	Marginal		
PROW Sidewalk	709	Peach St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,020	2	Marginal		
PROW Sidewalk	714	E Pecan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,440	2	Marginal		
PROW Sidewalk	718	Pennsylvania Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,150	2	Marginal		
PROW Sidewalk	720	Pershing Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,720	2	Marginal		
PROW Sidewalk	722	Pheasant Hollow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,760	2	Marginal		
PROW Sidewalk	733	Plum Hollow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,220	2	Marginal		
PROW Sidewalk	739	Ponder Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,870	2	Marginal		
PROW Sidewalk	742	E Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,670	2	Marginal		
PROW Sidewalk	744	W Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,880	2	Marginal		
PROW Sidewalk	775	Roberts St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	2	Marginal		
PROW Sidewalk	776	Robertson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,960	2	Marginal		
PROW Sidewalk	778	Robinson Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,330	2	Marginal		
PROW Sidewalk	789	N Ruddell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 37,440	2	Marginal		
PROW Sidewalk	790	S Ruddell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,150	2	Marginal		
PROW Sidewalk	794	E Ryan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 970	2	Marginal		
PROW Sidewalk	798	Sagewood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,660	2	Marginal		
PROW Sidewalk	812	Savannah Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,170	2	Marginal		
PROW Sidewalk	813	Sawyer Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,140	2	Marginal		
PROW Sidewalk	814	Schmitz Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,120	2	Marginal		
PROW Sidewalk	815	Schuyler St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,920	2	Marginal		
PROW Sidewalk	817	Scripture St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,030	2	Marginal		
PROW Sidewalk	819	Second St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,810	2	Marginal		
PROW Sidewalk	824	Shadow Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,470	2	Marginal		
PROW Sidewalk	831	E Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,040	2	Marginal		
PROW Sidewalk	838	Simmons St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,530	2	Marginal		
PROW Sidewalk	847	Southridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,450	2	Marginal		
PROW Sidewalk	859	Stroud St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,620	2	Marginal		
PROW Sidewalk	860	Stuart Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,190	2	Marginal		
PROW Sidewalk	863	Sun Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,910	2	Marginal		
PROW Sidewalk	865	Sunset St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,030	2	Marginal		
PROW Sidewalk	871	W Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 26,480	2	Marginal		
PROW Sidewalk	880	Teasley Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,480	2	Marginal		
PROW Sidewalk	887	Texas St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,680	2	Marginal		
PROW Sidewalk	888	E Third St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,930	2	Marginal		
PROW Sidewalk	890	Thomas St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,500	2	Marginal		
PROW Sidewalk	891	Thunderbird Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,020	2	Marginal		
PROW Sidewalk	912	Uland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 470	2	Marginal		
PROW Sidewalk	915	Underwood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,540	2	Marginal		
PROW Sidewalk	925	Vine St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,400	2	Marginal		
PROW Sidewalk	926	Virginia Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 270	2	Marginal		
PROW Sidewalk	935	S Welch St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,210	2	Marginal		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	944	Westgate Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,070	2	Marginal		
PROW Sidewalk	952	Westwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,800	2	Marginal		
PROW Sidewalk	958	Williams St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,730	2	Marginal		
PROW Sidewalk	965	Willowwood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,030	2	Marginal		
PROW Sidewalk	967	Wilshire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 680	2	Marginal		
PROW Sidewalk	968	Wilson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,990	2	Marginal		
PROW Sidewalk	975	E Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 27,840	2	Marginal		
PROW Sidewalk	976	W Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 42,540	2	Marginal		
PROW Sidewalk	986	N Wood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,740	2	Marginal		
PROW Sidewalk	997	S Woodrow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,270	2	Marginal		
PROW Sidewalk	1002	Yellowstone Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,820	2	Marginal		
PROW Sidewalk	1009	Oak Valley	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,510	2	Marginal		
PROW Sidewalk	1010	Timber Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 32,490	2	Marginal		
PROW Sidewalk	1014	Cobblestone Rw	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,040	2	Marginal		
PROW Sidewalk	1022	Deerfield Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,850	2	Marginal		
PROW Sidewalk	1023	Staghorn Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,710	2	Marginal		
PROW Sidewalk	1030	Royal Oaks Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,320	2	Marginal		
PROW Sidewalk	1031	Royal Oaks Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,950	2	Marginal		
PROW Sidewalk	1033	Wellington Oaks Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 42,220	2	Marginal		
PROW Sidewalk	1035	Wellington Oaks Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 890	2	Marginal		
PROW Sidewalk	1045	Antler Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,650	2	Marginal		
PROW Sidewalk	1047	Ashley Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,930	2	Marginal		
PROW Sidewalk	1048	Hunters Ridge Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,780	2	Marginal		
PROW Sidewalk	1049	Norfolk Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	2	Marginal		
PROW Sidewalk	1050	Cumberland Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,070	2	Marginal		
PROW Sidewalk	1051	Shenandoah Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,910	2	Marginal		
PROW Sidewalk	1053	Blue Ridge Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,520	2	Marginal		
PROW Sidewalk	1054	Richmond Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,200	2	Marginal		
PROW Sidewalk	1055	Natchez Trace	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,830	2	Marginal		
PROW Sidewalk	1107	Palo Verde Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,810	2	Marginal		
PROW Sidewalk	1131	Brinker Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,820	2	Marginal		
PROW Sidewalk	1134	Buena Vista	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,060	2	Marginal		
PROW Sidewalk	1177	Balboa Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,090	2	Marginal		
PROW Sidewalk	1178	Lido Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,710	2	Marginal		
PROW Sidewalk	1179	Shiloh Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,660	2	Marginal		
PROW Sidewalk	1185	Hemingway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,540	2	Marginal		
PROW Sidewalk	1192	Visalia Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,580	2	Marginal		
PROW Sidewalk	1193	Belmont St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,190	2	Marginal		
PROW Sidewalk	1194	Remington St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,120	2	Marginal		
PROW Sidewalk	1196	Oakview Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,010	2	Marginal		
PROW Sidewalk	1198	Whitetail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,170	2	Marginal		
PROW Sidewalk	1200	Hope St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,870	2	Marginal		
PROW Sidewalk	1203	Parkhaven Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,600	2	Marginal		
PROW Sidewalk	1204	Overlake Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,690	2	Marginal		
PROW Sidewalk	1205	Wildwood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,470	2	Marginal		
PROW Sidewalk	1206	Whitefish Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,520	2	Marginal		
PROW Sidewalk	1207	Osage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,220	2	Marginal		
PROW Sidewalk	1208	Lake Fork Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,100	2	Marginal		
PROW Sidewalk	1210	Wind River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,820	2	Marginal		
PROW Sidewalk	1212	Chaucer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,570	2	Marginal		
PROW Sidewalk	1223	Lamprey Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,180	2	Marginal		
PROW Sidewalk	1224	Loon Lake Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 38,030	2	Marginal		
PROW Sidewalk	1309	Brisas Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,940	2	Marginal		
PROW Sidewalk	1315	Bent Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,880	2	Marginal		
PROW Sidewalk	1316	Springcreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,110	2	Marginal		
PROW Sidewalk	1317	Creekbend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,700	2	Marginal		
PROW Sidewalk	1319	Ridgemont Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,700	2	Marginal		
PROW Sidewalk	1320	Montecristo Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,170	2	Marginal		
PROW Sidewalk	1321	Monte Carlo Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,300	2	Marginal		
PROW Sidewalk	1323	Sundown Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,640	2	Marginal		
PROW Sidewalk	1324	Lake Country Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,880	2	Marginal		
PROW Sidewalk	1325	Clubhouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,290	2	Marginal		
PROW Sidewalk	1328	Ranchman Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,550	2	Marginal		
PROW Sidewalk	1329	Longhorn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,140	2	Marginal		
PROW Sidewalk	1330	Summit Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,640	2	Marginal		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1332	Lakeside Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,090	2	Marginal		
PROW Sidewalk	1334	W El Paseo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,570	2	Marginal		
PROW Sidewalk	1335	Le Sage Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,760	2	Marginal		
PROW Sidewalk	1336	Manten Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,740	2	Marginal		
PROW Sidewalk	1338	Calvert Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,990	2	Marginal		
PROW Sidewalk	1343	Heights Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,500	2	Marginal		
PROW Sidewalk	1344	Gessner Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,150	2	Marginal		
PROW Sidewalk	1345	Westheimer Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,320	2	Marginal		
PROW Sidewalk	1346	Fondren Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,660	2	Marginal		
PROW Sidewalk	1347	San Felipe Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,170	2	Marginal		
PROW Sidewalk	1349	Chimney Rock Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,940	2	Marginal		
PROW Sidewalk	1350	Memorial Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,070	2	Marginal		
PROW Sidewalk	1351	Kirby Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 37,420	2	Marginal		
PROW Sidewalk	1352	Greenbend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,400	2	Marginal		
PROW Sidewalk	1353	Wintercreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,470	2	Marginal		
PROW Sidewalk	1354	Kappwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,770	2	Marginal		
PROW Sidewalk	1356	Montevideo Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,420	2	Marginal		
PROW Sidewalk	1359	Field Bend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,330	2	Marginal		
PROW Sidewalk	1361	Great Bear Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,150	2	Marginal		
PROW Sidewalk	1362	Geneva Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,650	2	Marginal		
PROW Sidewalk	1363	Ottawa Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,260	2	Marginal		
PROW Sidewalk	1364	Tahoe Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,380	2	Marginal		
PROW Sidewalk	1365	Caddo Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,900	2	Marginal		
PROW Sidewalk	1366	Kariba Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,690	2	Marginal		
PROW Sidewalk	1368	St. Johns Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,510	2	Marginal		
PROW Sidewalk	1373	Villanova Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,920	2	Marginal		
PROW Sidewalk	1374	Marquette Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,700	2	Marginal		
PROW Sidewalk	1375	Stanford Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,520	2	Marginal		
PROW Sidewalk	1376	Centenary Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,770	2	Marginal		
PROW Sidewalk	1377	Harvard Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,490	2	Marginal		
PROW Sidewalk	1399	White Dove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,500	2	Marginal		
PROW Sidewalk	1400	Rushing Spring Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,470	2	Marginal		
PROW Sidewalk	1401	Silent Star Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,330	2	Marginal		
PROW Sidewalk	1404	Clear River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,680	2	Marginal		
PROW Sidewalk	1407	Seven Oaks Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,110	2	Marginal		
PROW Sidewalk	1408	Early Dawn Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,320	2	Marginal		
PROW Sidewalk	1409	Serenity Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,580	2	Marginal		
PROW Sidewalk	1411	Glen Falls Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 56,880	2	Marginal		
PROW Sidewalk	1419	Val Verde Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,570	2	Marginal		
PROW Sidewalk	1420	Bent Oaks Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 920	2	Marginal		
PROW Sidewalk	1423	Newport Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,520	2	Marginal		
PROW Sidewalk	1435	Poinsettia Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,710	2	Marginal		
PROW Sidewalk	1437	La Fonta	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,830	2	Marginal		
PROW Sidewalk	1440	Inwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,240	2	Marginal		
PROW Sidewalk	1441	Crenshaw Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,860	2	Marginal		
PROW Sidewalk	1442	Pine Hills Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,590	2	Marginal		
PROW Sidewalk	1444	Hayling Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,820	2	Marginal		
PROW Sidewalk	1445	Alderbrook Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,190	2	Marginal		
PROW Sidewalk	1447	Sharon Rose Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,700	2	Marginal		
PROW Sidewalk	1448	Andrew Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,420	2	Marginal		
PROW Sidewalk	1449	Regency Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,670	2	Marginal		
PROW Sidewalk	1450	Paco Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,690	2	Marginal		
PROW Sidewalk	1451	Leon Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,510	2	Marginal		
PROW Sidewalk	1454	Bentgate Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,180	2	Marginal		
PROW Sidewalk	1459	Rambling Brook Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,600	2	Marginal		
PROW Sidewalk	1485	Desert Willow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 760	2	Marginal		
PROW Sidewalk	1500	Pinto Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,950	2	Marginal		
PROW Sidewalk	1502	Hereford Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,500	2	Marginal		
PROW Sidewalk	1503	Big Horn Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,650	2	Marginal		
PROW Sidewalk	1506	Fiste St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 840	2	Marginal		
PROW Sidewalk	1507	Hayes St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,130	2	Marginal		
PROW Sidewalk	1510	Dixon Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,870	2	Marginal		
PROW Sidewalk	1521	Creekdale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,070	2	Marginal		
PROW Sidewalk	1523	Riverpass Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,160	2	Marginal		
PROW Sidewalk	1524	Sunburst Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,500	2	Marginal		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1525	Raintree Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,860	2	Marginal		
PROW Sidewalk	1527	Riverchase Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,960	2	Marginal		
PROW Sidewalk	1528	Waterside Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,480	2	Marginal		
PROW Sidewalk	1529	Nightfall Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,920	2	Marginal		
PROW Sidewalk	1530	Dawnlight Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,760	2	Marginal		
PROW Sidewalk	1540	Merrimack Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,740	2	Marginal		
PROW Sidewalk	1541	Yale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,820	2	Marginal		
PROW Sidewalk	1543	Donner Lake Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,590	2	Marginal		
PROW Sidewalk	1544	Kootenay	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,170	2	Marginal		
PROW Sidewalk	1545	Saranac Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,530	2	Marginal		
PROW Sidewalk	1547	Valencia Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,530	2	Marginal		
PROW Sidewalk	1548	Union Lake Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,890	2	Marginal		
PROW Sidewalk	1549	Waterton Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,260	2	Marginal		
PROW Sidewalk	1550	Widgeon Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,520	2	Marginal		
PROW Sidewalk	1573	Blue Sky Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,120	2	Marginal		
PROW Sidewalk	1576	Kentucky Derby Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,800	2	Marginal		
PROW Sidewalk	1584	Crisoforo Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,530	2	Marginal		
PROW Sidewalk	1585	Hermalinda Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,060	2	Marginal		
PROW Sidewalk	1586	Morin Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,750	2	Marginal		
PROW Sidewalk	1588	Beatriz Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,520	2	Marginal		
PROW Sidewalk	1590	Santos Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,340	2	Marginal		
PROW Sidewalk	1593	Briar Forest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,540	2	Marginal		
PROW Sidewalk	1594	Dunlavy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,970	2	Marginal		
PROW Sidewalk	1595	Weslayan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,640	2	Marginal		
PROW Sidewalk	1596	Hilcroft Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 22,540	2	Marginal		
PROW Sidewalk	1597	Bissonet Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,830	2	Marginal		
PROW Sidewalk	1598	Falcon Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,990	2	Marginal		
PROW Sidewalk	1600	Lamplighter Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,140	2	Marginal		
PROW Sidewalk	1604	Algarve Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,980	2	Marginal		
PROW Sidewalk	1610	Lighthouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,960	2	Marginal		
PROW Sidewalk	1611	Ocean Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,380	2	Marginal		
PROW Sidewalk	1612	Coral Cove	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,350	2	Marginal		
PROW Sidewalk	1613	Nautical Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,200	2	Marginal		
PROW Sidewalk	1614	Sonoma Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,200	2	Marginal		
PROW Sidewalk	1615	Vinyard Way St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,750	2	Marginal		
PROW Sidewalk	1617	Claret Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,680	2	Marginal		
PROW Sidewalk	1618	Provence Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,610	2	Marginal		
PROW Sidewalk	1620	Loire Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,360	2	Marginal		
PROW Sidewalk	1623	Napa Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,340	2	Marginal		
PROW Sidewalk	1624	Vintage Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,700	2	Marginal		
PROW Sidewalk	1629	Stoneway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,540	2	Marginal		
PROW Sidewalk	1631	Edgefield Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,210	2	Marginal		
PROW Sidewalk	1678	Wicker Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,930	2	Marginal		
PROW Sidewalk	1685	Drexel Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,560	2	Marginal		
PROW Sidewalk	1686	Marymount Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,410	2	Marginal		
PROW Sidewalk	1688	Purdue Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,800	2	Marginal		
PROW Sidewalk	1709	Cope St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,050	2	Marginal		
PROW Sidewalk	1710	Comer St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,190	2	Marginal		
PROW Sidewalk	1712	Tripp Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,860	2	Marginal		
PROW Sidewalk	1713	Mckamy Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,950	2	Marginal		
PROW Sidewalk	1714	Northpointe Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,180	2	Marginal		
PROW Sidewalk	1716	Doris Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,490	2	Marginal		
PROW Sidewalk	1732	Meadowglen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,780	2	Marginal		
PROW Sidewalk	1737	Penina Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,000	2	Marginal		
PROW Sidewalk	1738	San Lorenzo Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,060	2	Marginal		
PROW Sidewalk	1746	Sawgrass Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,980	2	Marginal		
PROW Sidewalk	1748	Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,720	2	Marginal		
PROW Sidewalk	1749	Friesian Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,780	2	Marginal		
PROW Sidewalk	1750	Andalusian Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,890	2	Marginal		
PROW Sidewalk	1751	Lipizzan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,160	2	Marginal		
PROW Sidewalk	1752	Breton Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,760	2	Marginal		
PROW Sidewalk	1754	Spanish Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,230	2	Marginal		
PROW Sidewalk	1755	Clydesdale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 41,300	2	Marginal		
PROW Sidewalk	1760	Lance Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,100	2	Marginal		
PROW Sidewalk	1762	Chase Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,270	2	Marginal		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1764	Cyrus Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,580	2	Marginal		
PROW Sidewalk	1765	Teal Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,580	2	Marginal		
PROW Sidewalk	1767	Diamond Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,440	2	Marginal		
PROW Sidewalk	1770	Evan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,630	2	Marginal		
PROW Sidewalk	1771	Carrigan Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,990	2	Marginal		
PROW Sidewalk	1784	Stockbridge Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,160	2	Marginal		
PROW Sidewalk	1792	Aqueduct Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,820	2	Marginal		
PROW Sidewalk	1796	Rhone Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,380	2	Marginal		
PROW Sidewalk	1798	Butler Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,660	2	Marginal		
PROW Sidewalk	1799	Salon Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,740	2	Marginal		
PROW Sidewalk	1800	Thackery Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,730	2	Marginal		
PROW Sidewalk	1801	Countess Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,460	2	Marginal		
PROW Sidewalk	1802	Highfield Park	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,640	2	Marginal		
PROW Sidewalk	1803	St James Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,400	2	Marginal		
PROW Sidewalk	1804	Thoroughbred Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 32,320	2	Marginal		
PROW Sidewalk	1811	Thistle Hill	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,640	2	Marginal		
PROW Sidewalk	1823	Raleigh Path	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,870	2	Marginal		
PROW Sidewalk	1829	Unicorn Lake Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,880	2	Marginal		
PROW Sidewalk	1833	Bray Village Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,840	2	Marginal		
PROW Sidewalk	1840	English Saddle Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,750	2	Marginal		
PROW Sidewalk	1841	Bareback Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,260	2	Marginal		
PROW Sidewalk	1844	Desert Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,740	2	Marginal		
PROW Sidewalk	1878	Union Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 560	2	Marginal		
PROW Sidewalk	1888	Saddle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,180	2	Marginal		
PROW Sidewalk	1891	Groveland Terrace	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,360	2	Marginal		
PROW Sidewalk	1892	Longleaf Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	2	Marginal		
PROW Sidewalk	1894	Corral Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,900	2	Marginal		
PROW Sidewalk	1895	Lipizzan Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,770	2	Marginal		
PROW Sidewalk	1907	Del Rey Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 660	2	Marginal		
PROW Sidewalk	1914	Tawakoni Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,330	2	Marginal		
PROW Sidewalk	1920	Toledo Bend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 890	2	Marginal		
PROW Sidewalk	1927	Pecan Tree Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,810	2	Marginal		
PROW Sidewalk	1928	Nora Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,550	2	Marginal		
PROW Sidewalk	1973	Stonecrop Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,770	2	Marginal		
PROW Sidewalk	1979	Shagbark Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,890	2	Marginal		
PROW Sidewalk	1990	Shoreline	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,280	2	Marginal		
PROW Sidewalk	1993	Darien Place	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,030	2	Marginal		
PROW Sidewalk	1995	Cadena Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,940	2	Marginal		
PROW Sidewalk	2506	El Dorado Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	2	Marginal		
PROW Sidewalk	2530	Cuddy Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	2	Marginal		
PROW Sidewalk	2538	Hialeah Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,800	2	Marginal		
PROW Sidewalk	2542	Fanita Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,850	2	Marginal		
PROW Sidewalk	2602	Stonetrail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	2	Marginal		
PROW Sidewalk	2618	Shy Creek Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	2	Marginal		
Building	3	Airport Terminal and Admin Building	35	The rim of the urinal is above the maximum allowable height.	\$ 1,755	9	Low		
Building	3	Airport Terminal and Admin Building	40	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	5	American Legion Hall Senior Center	42	The water closet compartment is missing a loop handle on both sides of the door.	\$ 675	9	Low		
Building	5	American Legion Hall Senior Center	47	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	5	American Legion Hall Senior Center	48	The baby changing table is too high when folded down.	\$ -	9	Low		
Building	5	American Legion Hall Senior Center	51	The compartment door is not self-closing.	\$ 338	9	Low		
Building	5	American Legion Hall Senior Center	56	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	5	American Legion Hall Senior Center	57	The baby changing table is too high when folded down.	\$ -	9	Low		
Building	6	Monsignor King Outreach Center	21	The doorbell is positioned too high for either a side or front approach at 61 inches.	\$ 675	9	Low		
Building	6	Monsignor King Outreach Center	22	The mailbox is positioned too high for either a side or front approach at 65 inches.	\$ 675	9	Low		
Building	6	Monsignor King Outreach Center	23	The doorbell is positioned too high for either a side or front approach at 56 inches.	\$ 675	9	Low		
Building	6	Monsignor King Outreach Center	31	The paper towel dispenser and soap dispenser are positioned too high for either a side or front approach.	\$ 675	9	Low		
Building	6	Monsignor King Outreach Center	50	The compartment door is not self-closing and missing an outside loop handle.	\$ 675	9	Low		
Building	7	Center for Visual Arts	45	The rim of the urinal is above the maximum allowable height.	\$ 1,755	9	Low		
Building	7	Center for Visual Arts	46	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	7	Center for Visual Arts	47	The feminine produce dispenser is not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 540	9	Low		
Building	7	Center for Visual Arts	53	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	7	Center for Visual Arts	73	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	7	Center for Visual Arts	91	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	8	City Hall	55	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	9	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	8	City Hall	78	The rim of the urinal is above the maximum allowable height.	\$ 1,755	9	Low		
Building	8	City Hall	80	The side grab bar does not extend far enough from the rear wall.	\$ 338	9	Low		
Building	8	City Hall	81	The soap dispenser's operation mechanism is too high off the floor.	\$ 675	9	Low		
Building	8	City Hall	84	The side grab bar does not extend far enough from the rear wall.	\$ 338	9	Low		
Building	8	City Hall	85	The toilet seat cover dispenser is mounted too close to the top of the grab bar minimizing the gripping surface.	\$ 338	9	Low		
Building	8	City Hall	86	The soap dispenser's operation mechanism is too high off the floor.	\$ 675	9	Low		
Building	8	City Hall	90	The rim of the urinal is above the maximum allowable height.	\$ 1,755	9	Low		
Building	8	City Hall	93	The mirror is mounted too high.	\$ 338	9	Low		
Building	8	City Hall	94	The lavatory's clear floor space obstructed by the trash can.	\$ 338	9	Low		
Building	8	City Hall	95	The soap dispenser's operation mechanism is too high off the floor.	\$ 675	9	Low		
Building	8	City Hall	99	The mirror is mounted too high.	\$ 338	9	Low		
Building	8	City Hall	101	The lavatory's clear floor space obstructed by the trash can.	\$ 338	9	Low		
Building	9	City Hall East (Municipal Complex)	133	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	9	City Hall East (Municipal Complex)	134	The soap dispenser's operation mechanism is too high off the floor.	\$ 675	9	Low		
Building	11	Civic Center	54	The mirror is mounted too high (2 sinks on the left).	\$ 675	9	Low		
Building	11	Civic Center	55	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	11	Civic Center	59	The coat hook is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	11	Civic Center	61	The feminine product dispenser is not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 540	9	Low		
Building	11	Civic Center	63	The mirror is mounted too high (3 mirrors).	\$ 743	9	Low		
Building	11	Civic Center	64	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	11	Civic Center	70	The soap and paper towel dispenser are positioned too high for either a side or front approach.	\$ 675	9	Low		
Building	11	Civic Center	79	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	12	Civic Center Pool	43	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	12	Civic Center Pool	44	The rim of the urinal is above the maximum allowable height.	\$ 1,755	9	Low		
Building	12	Civic Center Pool	45	The water closet compartment is missing a loop handle on the inside of the door and is not self-closing.	\$ 473	9	Low		
Building	12	Civic Center Pool	48	The mirror is mounted too high.	\$ 1,013	9	Low		
Building	12	Civic Center Pool	49	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	12	Civic Center Pool	55	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	12	Civic Center Pool	58	The mirror is mounted too high.	\$ 1,013	9	Low		
Building	13	Denia Recreation Center	26	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	13	Denia Recreation Center	32	The restroom is missing accessible fixtures or elements.	\$ 743	9	Low		
Building	13	Denia Recreation Center	39	The hand dryer operation mechanism is too high off the floor.	\$ 473	9	Low		
Building	13	Denia Recreation Center	40	The restroom is missing accessible fixtures or elements.	\$ 743	9	Low		
Building	13	Denia Recreation Center	46	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 338	9	Low		
Building	13	Denia Recreation Center	52	The paper towel dispensers are positioned too high for either a side or front approach.	\$ 1,013	9	Low		
Building	13	Denia Recreation Center	54	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	14	Denton Development Center	31	The baby changing table operating mechanism is outside reach range and does not have the required clear floor space.	\$ 810	9	Low		
Building	14	Denton Development Center	34	The baby changing table operating mechanism is outside reach range and does not have the required clear floor space.	\$ 810	9	Low		
Building	16	Denton Senior Center	83	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	16	Denton Senior Center	88	The top of the sink is above the allowable height requirement.	\$ 2,025	9	Low		
Building	16	Denton Senior Center	92	The hand sanitizer dispenser operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	16	Denton Senior Center	95	The hand sanitizer dispenser operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	16	Denton Senior Center	98	The restroom is missing accessible fixtures or elements. The accessible stall door is not self-closing and missing a loop handle on the outside. The roll of toilet paper obstructs the side grab bar from the bottom.	\$ 675	9	Low		
Building	16	Denton Senior Center	102	The water closet compartment door is missing a loop handle on the outside.	\$ 405	9	Low		
Building	16	Denton Senior Center	119	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 473	9	Low		
Building	16	Denton Senior Center	133	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 473	9	Low		
Building	16	Denton Senior Center	134	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 473	9	Low		
Building	20	Electric Administration Building	24	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	20	Electric Administration Building	25	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	20	Electric Administration Building	26	The mirror is mounted too high.	\$ 338	9	Low		
Building	21	Emily Fowler Library	36	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	21	Emily Fowler Library	50	The paper towel dispenser's operation mechanism is too high off the floor and requires tight grasping and twisting of the wrist.	\$ 473	9	Low		
Building	21	Emily Fowler Library	51	The feminine product dispenser is not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 540	9	Low		
Building	23	Facilities Management	21	The paper towel dispenser's operation mechanism is too high off the floor and is an obstruction.	\$ 338	9	Low		
Building	23	Facilities Management	24	The paper towel dispenser's operation mechanism is too high off the floor and is an obstruction.	\$ 338	9	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	34	Fleet Service Center	26	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the rear grab bar does not extend the correct distance on the closed side of the toilet the side grab bar is too far off the back wall and the toilet paper dispenser is not installed the correct distance in front of the toilet.	\$ 2,025	9	Low		
Building	34	Fleet Service Center	29	The restroom is missing accessible fixtures or elements. The side grab bar does not extend the correct distance the self-closing faucet does not remain open a minimum of 10 seconds the mirror is mounted too high the paper towel dispenser is mounted too high the trash can and cabinet are in the toilet clear floor space.	\$ 2,025	9	Low		
Building	35	Household Hazardous Waste Building	6	The toilet paper is not installed within the compliant range in front of the toilet.	\$ 338	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	16	The vending machine operations are positioned too high for either a side or front approach.	\$ 2,025	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	23	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	24	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	25	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	33	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	34	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	35	The restroom is missing accessible fixtures or elements. The toilet seat cover dispenser is too high and the toilet paper obstructs the side grab bar and is mounted the incorrect distance in front of the toilet.	\$ 1,013	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	37	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 675	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	40	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	41	The restroom is missing accessible fixtures or elements. The toilet seat cover dispenser is too high and the toilet paper obstructs the side grab bar and is mounted the incorrect distance in front of the toilet.	\$ 1,013	9	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	42	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 675	9	Low		
Building	40	LL WTP - Operations Building	7	The door bell is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	40	LL WTP - Operations Building	25	The rim of the urinal is above the maximum allowable height.	\$ 1,755	9	Low		
Building	42	LRR WTP - Admin Building	35	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	42	LRR WTP - Admin Building	36	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle and the rear grab bar is obstructed by the toilet refresher.	\$ 1,013	9	Low		
Building	42	LRR WTP - Admin Building	37	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	42	LRR WTP - Admin Building	39	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the toilet refresher trash receptacle and feminine product dispenser are in the toilets clear floor space and the feminine product dispenser requires the twisting or the wrist to operate	\$ 1,283	9	Low		
Building	42	LRR WTP - Admin Building	40	The paper towel dispenser's operation mechanism is too high off the floor. Dispensers must have all operable parts a maximum of 48 inches above the floor.	\$ 338	9	Low		
Building	42	LRR WTP - Admin Building	41	The shower curtain rod extends down too close to the route of travel.	\$ 338	9	Low		
Building	42	LRR WTP - Admin Building	45	The water closet compartment is missing a loop handle on the one side of the door.	\$ 338	9	Low		
Building	42	LRR WTP - Admin Building	53	The compartment door is not self-closing.	\$ 338	9	Low		
Building	42	LRR WTP - Admin Building	54	The water closet compartment is missing a loop handle on the one side of the door.	\$ 338	9	Low		
Building	42	LRR WTP - Admin Building	55	The grab bar is obstructed by the toilet refresher.	\$ 338	9	Low		
Building	46	MLK Jr Recreation Center	60	The rim of the urinal is above the maximum allowable height and the urinal is located in a alcove with no clear floor space.	\$ 3,375	9	Low		
Building	46	MLK Jr Recreation Center	63	The hand dryer operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	46	MLK Jr Recreation Center	68	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	46	MLK Jr Recreation Center	73	The hand dryer operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	46	MLK Jr Recreation Center	84	The rim of the urinal is above the maximum allowable height.	\$ 1,755	9	Low		
Building	46	MLK Jr Recreation Center	88	The soap dispenser is out of reach range because the depth of the obstruction is greater than 25 inches.	\$ 338	9	Low		
Building	46	MLK Jr Recreation Center	95	The soap dispenser is out of reach range because the depth of the obstruction is greater than 25 inches.	\$ 338	9	Low		
Building	46	MLK Jr Recreation Center	103	The door bell is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	46	MLK Jr Recreation Center	129	The paper towel and soap dispenser are positioned too high for either a side or front approach.	\$ 675	9	Low		
Building	47	Natatorium	39	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	47	Natatorium	40	The compartment door is not self-closing and missing an inside loop handle.	\$ 473	9	Low		
Building	47	Natatorium	41	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	47	Natatorium	42	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	47	Natatorium	43	The feminine product dispenser is not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 540	9	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	47	Natorium	44	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	47	Natorium	45	The compartment door is not self-closing and is missing an inside loop handle.	\$ 473	9	Low		
Building	47	Natorium	46	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	47	Natorium	48	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	9	Low		
Building	47	Natorium	50	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend 12 inches on the closed side of the toilet the door is not self-closing and the door is missing an inside loop handle.	\$ 2,025	9	Low		
Building	47	Natorium	52	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	9	Low		
Building	47	Natorium	54	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	47	Natorium	56	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	9	Low		
Building	47	Natorium	57	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	47	Natorium	59	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	9	Low		
Building	47	Natorium	61	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	9	Low		
Building	47	Natorium	63	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend 12 inches on the closed side of the toilet the side grab bar is more than 12 inches off the back wall the door is not self-closing and the door is missing an inside loop handle.	\$ 1,755	9	Low		
Building	47	Natorium	65	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	9	Low		
Building	47	Natorium	68	The paper towel dispenser's and hand sanitizer dispenser is too high off the floor.	\$ 675	9	Low		
Building	47	Natorium	70	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	48	New Central Fire Station	30	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 338	9	Low		
Building	48	New Central Fire Station	34	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 338	9	Low		
Building	48	New Central Fire Station	53	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 338	9	Low		
Building	48	New Central Fire Station	59	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 338	9	Low		
Building	49	North Branch Library	70	The restroom is missing accessible fixtures or elements. The rear and side grab bars are too high the toilet paper dispenser is not the correct distance from the front of the toilet the door is not self-closing and is missing a loop handle and the coat hook is too high.	\$ 2,025	9	Low		
Building	49	North Branch Library	71	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	49	North Branch Library	74	The clear floor space only allows for a forward approach and the soap dispenser is out of reach range.	\$ 338	9	Low		
Building	49	North Branch Library	75	The hand dryer projects into the headroom clearance in the circulation path.	\$ 338	9	Low		
Building	49	North Branch Library	77	The restroom is missing accessible fixtures or elements. The rear grab bar is too high the side grab bar does not extend the correct distance the toilet paper dispenser is not the correct distance from the front of the toilet the door is not self-closing and is missing a loop handle and the coat hook is too high.	\$ 2,025	9	Low		
Building	49	North Branch Library	78	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	49	North Branch Library	81	The clear floor space only allows for a forward approach and the soap dispenser is out of reach range.	\$ 338	9	Low		
Building	49	North Branch Library	82	The hand dryer projects into the headroom clearance in the circulation path.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	28	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	36	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	39	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	40	The coat rack is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	45	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	46	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	50	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	58	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	59	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	62	The rim of the urinal is above the maximum allowable height.	\$ 1,755	9	Low		
Building	51	North Lakes Recreation Center	64	The coat rack is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	69	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	73	The coat rack is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	78	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	51	North Lakes Recreation Center	79	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	51	North Lakes Recreation Center	92	The restroom is missing accessible fixtures or elements. The coat hook is too high and the paper towel dispenser is too high.	\$ 1,013	9	Low		
Building	56	PCRP - New Administration Building	7	The vending machine operations are positioned too high for either a side or front approach.	\$ 2,025	9	Low		
Building	61	Quebec Hangars	31	The side grab bar does not extend far enough from the rear wall.	\$ 540	9	Low		
Building	61	Quebec Hangars	32	The rear grab bar is too high.	\$ 338	9	Low		
Building	61	Quebec Hangars	33	The side grab bar is too high.	\$ -	9	Low		
Building	61	Quebec Hangars	34	The required 56 inches by 60 inches clear floor space for the toilet has been obstructed by the trash can.	\$ 338	9	Low		
Building	62	Service Center	26	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	9	Low		
Building	62	Service Center	28	The mirror is mounted too high.	\$ 338	9	Low		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	62	Service Center	29	The soap dispenser's operation mechanism is too high off the floor.	\$ 675	9	Low		
Building	62	Service Center	30	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	62	Service Center	37	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	9	Low		
Building	62	Service Center	39	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Building	62	Service Center	40	The paper towel dispenser's operation mechanism is too high off the floor and requires tight grasping to operate.	\$ 338	9	Low		
Building	62	Service Center	46	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	9	Low		
Building	66	South Branch Library	33	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Building	69	Traffic Control	10	The exit button is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	72	Utility Office/Field Operations	23	The door bell is positioned too high for either a side or front approach.	\$ 338	9	Low		
Building	26	Fire Station #2	25	The required clear floor space is not wide enough.	\$ 1,013	10	Low		
Building	28	Fire Station #4	28	The required clear floor space is not wide enough.	\$ 473	10	Low		
Building	1	Airport Control Tower	2	The video call system is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	1	Airport Control Tower	3	The elevator audible signal to indicate direction of travel is missing and/or non compliant.	\$ 2,025	11	Low		
Building	1	Airport Control Tower	4	The elevator does not have a star on both jambs at the main entry level.	\$ 2,025	11	Low		
Building	1	Airport Control Tower	5	The restroom does not include any accessible fixtures or accessories. The side grab bar is not long enough and is too high the rear grab bar is not long enough and it too high the lavatory is in the toilets clear floor space and the lavatory does not have the correct clear floor space.	\$ 5,400	11	Low		
Building	1	Airport Control Tower	6	The coat rack is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	1	Airport Control Tower	7	The video call system is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	1	Airport Control Tower	8	The platform lift is not accessible because there is not adequate clear floor space within the lift.	\$ 6,075	11	Low		
Building	1	Airport Control Tower	9	The platform lift controls were not functional and did not allow for the return of the lift from the opposite (raised or lowered) position to allow for unassisted entry.	\$ 3,375	11	Low		
Building	2	Airport LESA	5	The stairway contains open risers.	\$ 2,025	11	Low		
Building	2	Airport LESA	8	The side grab bar is too high.	\$ 338	11	Low		
Building	2	Airport LESA	9	The rear grab bar is too high.	\$ 338	11	Low		
Building	2	Airport LESA	10	The toilet is not located within the range allowed from the side wall or partition.	\$ 2,700	11	Low		
Building	2	Airport LESA	11	The toilet paper is not installed within the compliant range in front of the toilet.	\$ 338	11	Low		
Building	2	Airport LESA	12	The clear floor space around the toilet is obstructed.	\$ 4,050	11	Low		
Building	2	Airport LESA	13	There are no accessible bathing and shower facilities.	\$ 4,725	11	Low		
Building	2	Airport LESA	14	The mirror is mounted too high.	\$ 338	11	Low		
Building	4	Alternative Fuel Island	1	The fuel pump controls are positioned too high for either a side or front approach (3 total).	\$ 3,375	11	Low		
Building	4	Alternative Fuel Island	2	The gas pump controls are positioned too high for either a side or front approach.	\$ 3,375	11	Low		
Building	4	Alternative Fuel Island	3	The emergency valve is positioned too high for either a side or front approach.	\$ 3,375	11	Low		
Building	4	Alternative Fuel Island	4	The shut off control is positioned too high for either a side or front approach.	\$ 3,375	11	Low		
Building	7	Center for Visual Arts	102	The restroom is missing accessible fixtures or elements.	\$ 4,050	11	Low		
Building	8	City Hall	47	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	8	City Hall	48	The button is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	8	City Hall	51	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	11	Low		
Building	8	City Hall	52	Knee clearance has not been provided underneath the sink.	\$ 675	11	Low		
Building	8	City Hall	74	Knee clearance has not been provided underneath the sink.	\$ 1,013	11	Low		
Building	8	City Hall	75	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	11	Low		
Building	8	City Hall	76	The microwaves are positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	8	City Hall	102	The restroom is missing accessible fixtures or elements. The toilet seat is too high the toilet paper dispenser is not the correct distance from the front of the toilet the lavatory is too high the mirror is too high the paper towel dispenser is too high and the lavatory pipes are not insulated.	\$ 4,050	11	Low		
Building	8	City Hall	105	The restroom is missing accessible fixtures or elements. The door is not wide enough the side and rear grab bars are missing the toilet seat is too low the toilet center line is incorrect the toilet paper dispenser is not the correct distance from the front of the toilet the lavatory is in the toilet clear floor space the mirror is too high the paper towel dispenser and soap dispenser are too high the door lock is too high and the lavatory pipes are not insulated.	\$ 4,050	11	Low		
Building	8	City Hall	107	The restroom is missing accessible fixtures or elements. The door is not wide enough the side and rear grab bars are missing the toilet seat is too low the toilet center line is incorrect the flush control is on the wrong side the toilet paper dispenser is not the correct distance from the front of the toilet the lavatory is in the toilet clear floor space the mirror is too high the paper towel dispenser and soap dispenser are too high the door lock is too high the napkin disposal is too high and the lavatory pipes are not insulated.	\$ 4,050	11	Low		
Building	9	City Hall East (Municipal Complex)	5	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	11	Low		
Building	9	City Hall East (Municipal Complex)	57	Knee and toe clearance has not been provided at the sink.	\$ 2,700	11	Low		
Building	9	City Hall East (Municipal Complex)	80	The controls are located such that operation require reaching across burners.	\$ 2,295	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	9	City Hall East (Municipal Complex)	82	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	9	City Hall East (Municipal Complex)	86	The memo postings are positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	9	City Hall East (Municipal Complex)	87	The stairway handrails are not compliant. The handrails have the following issues: Installed at the incorrect height the bottom handrail extensions are missing or extend incorrectly the handrail gripping surface is not the correct size.	\$ 2,025	11	Low		
Building	9	City Hall East (Municipal Complex)	88	The vending machines are positioned too high for either a side or front approach.	\$ 1,013	11	Low		
Building	9	City Hall East (Municipal Complex)	89	There are no accessible tables.	\$ 1,013	11	Low		
Building	9	City Hall East (Municipal Complex)	90	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	9	City Hall East (Municipal Complex)	91	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	9	City Hall East (Municipal Complex)	96	The restroom is missing accessible fixtures or elements. The door is missing an inside and outside loop handle the rear grab bar is not mounted correctly the side grab bar does not extend the correct distance from the back wall the toilet paper dispenser is not located the correct distance in front of the toilet and the table obstructs the maneuvering clearance.	\$ 2,025	11	Low		
Building	9	City Hall East (Municipal Complex)	97	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	11	Low		
Building	9	City Hall East (Municipal Complex)	98	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 2,025	11	Low		
Building	9	City Hall East (Municipal Complex)	99	The receptacle/switch is not positioned correctly for either a side or front approach.	\$ 338	11	Low		
Building	9	City Hall East (Municipal Complex)	101	The restroom is missing accessible fixtures or elements. The rear grab bar is not mounted correctly the side grab bar does not extend the correct distance from the back wall the toilet paper dispenser is not located the correct distance in front of the toilet and the table obstructs the maneuvering clearance.	\$ 2,025	11	Low		
Building	9	City Hall East (Municipal Complex)	102	Compliant knee space has not been provided under the lavatory.	\$ 2,700	11	Low		
Building	9	City Hall East (Municipal Complex)	103	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	11	Low		
Building	9	City Hall East (Municipal Complex)	106	The sink drain pipes are exposed.	\$ 338	11	Low		
Building	9	City Hall East (Municipal Complex)	112	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	9	City Hall East (Municipal Complex)	117	There is no accessible route to the judge's bench.	\$ 1,080	11	Low		
Building	9	City Hall East (Municipal Complex)	121	The restroom is missing accessible fixtures or elements. The restroom does not have the wheelchair turning space the flush control is on the wrong side the toilet paper dispenser is not located the correct distance in front of the toilet the toilet is too low the paper towel dispenser obstructs the rear grab bar the sink pipes are not insulated and the sink is in the door maneuvering space.	\$ 4,050	11	Low		
Building	9	City Hall East (Municipal Complex)	122	The restroom is missing accessible fixtures or elements. The wall sign is noncompliant the restroom does not have the wheelchair turning space the toilet center line is incorrect the flush control is on the wrong side the toilet paper dispenser is not located the correct distance in front of the toilet the toilet is too low the rear grab bar is not installed correctly the paper towel dispenser obstructs the rear grab bar the sink pipes are not insulated the sink does not have knee clearance the storage unit is in the toilet clear floor space the paper towel and toilet seat cover dispensers are mounted too high and the sink is in the toilets clear floor space.	\$ 4,050	11	Low		
Building	10	City Hall West	17	The badge reader is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	10	City Hall West	18	The badge reader is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	11	Civic Center	19	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	11	Low		
Building	11	Civic Center	69	Knee and toe clearance has not been provided at the sink.	\$ 3,375	11	Low		
Building	11	Civic Center	71	The switch is not positioned correctly for either a side or front approach.	\$ 473	11	Low		
Building	12	Civic Center Pool	60	The restroom is missing accessible fixtures or elements. The chemical storage is in the toilets clear floor space the paper towel dispenser is mounted too high the mirror is too high and door maneuvering clearance is obstructed by the lavatory.	\$ 3,375	11	Low		
Building	12	Civic Center Pool	62	The work surface is not within the allowable range.	\$ 1,013	11	Low		
Building	12	Civic Center Pool	63	The work surface is not within the allowable range.	\$ 2,025	11	Low		
Building	12	Civic Center Pool	64	The telephone is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	12	Civic Center Pool	65	The paper towel dispenser is positioned too high for either a side or front approach and requires tight grasping to operate.	\$ 338	11	Low		
Building	12	Civic Center Pool	66	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	12	Civic Center Pool	70	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	12	Civic Center Pool	71	The faucet controls require twisting of the wrist.	\$ 506	11	Low		
Building	12	Civic Center Pool	72	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 473	11	Low		
Building	12	Civic Center Pool	73	The paper towel dispenser is positioned too high for either a side or front approach and requires tight grasping to operate.	\$ 338	11	Low		
Building	12	Civic Center Pool	74	The door lock is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	13	Denia Recreation Center	28	The vision light panels exceed height requirements.	\$ 1,013	11	Low		
Building	13	Denia Recreation Center	60	The vision light panels exceed height requirements.	\$ 1,013	11	Low		
Building	14	Denton Development Center	12	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	14	Denton Development Center	13	The soap dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	14	Denton Development Center	14	The soap dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	14	Denton Development Center	15	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	14	Denton Development Center	16	The paper towel dispenser is positioned too high for either a side or front approach. Barrier:	\$ 338	11	Low		
Building	14	Denton Development Center	17	The soap dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	14	Denton Development Center	18	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	11	Low		
Building	14	Denton Development Center	19	The shower curtain rod extends down too close to the route of travel.	\$ 338	11	Low		
Building	14	Denton Development Center	20	The self-closing faucet controls do not stay open for a minimum of 10 seconds.	\$ 1,013	11	Low		
Building	14	Denton Development Center	21	The shower curtain rod extends down too close to the route of travel.	\$ 338	11	Low		
Building	14	Denton Development Center	22	There are no accessible tables.	\$ 1,013	11	Low		
Building	14	Denton Development Center	23	The work surface is not within the allowable range.	\$ 1,013	11	Low		
Building	14	Denton Development Center	24	The route of travel does not provide a minimum width of 36 inches. The clear width shall be permitted to be reduced to 32 inches minimum for a length of 24 inches maximum provided that reduced width segments are separated by segments that are 48 inches long minimum and 36 inches wide minimum.	\$ 1,013	11	Low		
Building	15	Denton Energy Center	9	The clear floor space required at the eye wash station is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	11	Low		
Building	15	Denton Energy Center	10	The eye wash station is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	15	Denton Energy Center	11	The eye wash station is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	15	Denton Energy Center	12	The controls are located such that operation require reaching across burners.	\$ 2,295	11	Low		
Building	15	Denton Energy Center	13	The microwave is positioned too high for either a side or front approach.	\$ 473	11	Low		
Building	15	Denton Energy Center	14	Knee clearance has not been provided underneath the sink.	\$ 2,025	11	Low		
Building	15	Denton Energy Center	16	The bench's back rest is not long enough.	\$ 1,013	11	Low		
Building	15	Denton Energy Center	17	The route of travel does not provide a minimum width of 36 inches.	\$ 4,725	11	Low		
Building	15	Denton Energy Center	19	The restroom does not include accessible fixtures or elements. The toilet centerline is incorrect the lavatory is in the toilets clear floor space and the rear grab bar will need to be remounted so it extends from the centerline of the water closet 12" minimum on the wall side and 24" minimum on the wide side once the toilet centerline is corrected.	\$ 4,050	11	Low		
Building	16	Denton Senior Center	44	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	11	Low		
Building	19	ECO-W.E.R.C.S. at Pecan Creek	1	The parking lot is missing accessible parking spaces and is not firm stable and slip-resistant.	\$ 3,375	11	Low		
Building	19	ECO-W.E.R.C.S. at Pecan Creek	2	There is no accessible route of travel to the building.	\$ 3,375	11	Low		
Building	19	ECO-W.E.R.C.S. at Pecan Creek	3	The restroom is missing accessible fixtures or elements.	\$ 3,375	11	Low		
Building	20	Electric Administration Building	19	The door exceeds the maximum allowable opening force.	\$ 338	11	Low		
Building	20	Electric Administration Building	33	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	11	Low		
Building	20	Electric Administration Building	36	The doors have a door stop which prevents them from having a smooth surface at the bottom.	\$ 675	11	Low		
Building	20	Electric Administration Building	37	The doors have a door stop which prevents it from having a smooth surface at the bottom.	\$ 675	11	Low		
Building	20	Electric Administration Building	38	The restroom is missing accessible fixtures or elements.	\$ 4,050	11	Low		
Building	20	Electric Administration Building	39	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	20	Electric Administration Building	40	The controls are located such that operation require reaching across burners.	\$ 2,025	11	Low		
Building	20	Electric Administration Building	41	Knee clearance has not been provided underneath the sink.	\$ 1,013	11	Low		
Building	20	Electric Administration Building	42	The kitchen counter top is too high.	\$ 3,375	11	Low		
Building	20	Electric Administration Building	44	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 338	11	Low		
Building	20	Electric Administration Building	45	The top of the sink is above the allowable height requirement.	\$ 3,375	11	Low		
Building	20	Electric Administration Building	46	The paper towel dispenser and soap dispenser are positioned too high for either a side or front approach.	\$ 675	11	Low		
Building	20	Electric Administration Building	47	The U-shaped kitchen is not wide enough.	\$ 7,425	11	Low		
Building	21	Emily Fowler Library	55	The telephone is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	21	Emily Fowler Library	56	The restroom is missing accessible fixtures or elements.	\$ 1,283	11	Low		
Building	22	Engineering and Systems Operations	10	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	22	Engineering and Systems Operations	11	Knee and toe clearance has not been provided at the sink.	\$ 3,375	11	Low		
Building	22	Engineering and Systems Operations	12	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	11	Low		
Building	22	Engineering and Systems Operations	13	The telephone is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	23	Facilities Management	29	The clearance in front of the transfer type compartment is not the minimum required size.	\$ 2,025	11	Low		
Building	23	Facilities Management	30	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	11	Low		
Building	23	Facilities Management	31	There is no compliant bench in the locker room.	\$ 1,013	11	Low		
Building	23	Facilities Management	32	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	11	Low		
Building	23	Facilities Management	34	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	23	Facilities Management	39	The controls are located such that operation require reaching across burners.	\$ 2,295	11	Low		
Building	23	Facilities Management	40	The microwave is positioned too high for either a side or front approach.	\$ 473	11	Low		
Building	23	Facilities Management	41	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,620	11	Low		
Building	23	Facilities Management	44	The controls are located such that operation require reaching across burners.	\$ 3,375	11	Low		
Building	23	Facilities Management	46	The paper towel and soap dispenser are positioned too high for either a side or front approach.	\$ 675	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	25	Fire Outdoor Classroom (Fire Station #7)	3	The drinking fountain is not accessible. The accessible height fountain does not provide the required knee clearance excessive force greater than 5 pounds is required to operate the fountain and the fountains are protruding objects and need barriers for cane detection.	\$ 5,130	11	Low		
Building	25	Fire Outdoor Classroom (Fire Station #7)	4	The restroom is missing accessible fixtures or accessories. The toilet centerline is incorrect the trash can is in the toilet's clear floor space the lavatory faucet controls only remain open for 3 seconds the rear grab bar is not long enough and the floor drain is too low resulting is a slope greater than 2 percent.	\$ 3,375	11	Low		
Building	26	Fire Station #2	11	The stairway only has a handrail on one side.	\$ 1,013	11	Low		
Building	26	Fire Station #2	13	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	26	Fire Station #2	14	The microwave is positioned too high for either a side or front approach.	\$ 473	11	Low		
Building	26	Fire Station #2	15	Knee and toe space has not been provided at the sink.	\$ 2,700	11	Low		
Building	26	Fire Station #2	16	Knee and toe space has not been provided at the sink.	\$ 3,375	11	Low		
Building	26	Fire Station #2	17	The restroom does not include accessible fixtures or elements.	\$ 3,375	11	Low		
Building	26	Fire Station #2	19	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	11	Low		
Building	26	Fire Station #2	22	The restroom does not include accessible fixtures or elements.	\$ 3,375	11	Low		
Building	26	Fire Station #2	23	The restroom does not include accessible fixtures or elements.	\$ 3,375	11	Low		
Building	26	Fire Station #2	24	The restroom does not include accessible fixtures or elements.	\$ 1,013	11	Low		
Building	26	Fire Station #2	27	The telephone is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	27	Fire Station #3	2	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	11	Low		
Building	27	Fire Station #3	12	The stairway only has a handrail on one side.	\$ 1,013	11	Low		
Building	27	Fire Station #3	13	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	27	Fire Station #3	15	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the lavatory does not have knee or toe clearance the coat hooks are too high and the shower seat is missing.	\$ 2,700	11	Low		
Building	27	Fire Station #3	16	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the lavatory does not have knee or toe clearance the coat hooks are too high and the shower seat is missing.	\$ 2,700	11	Low		
Building	27	Fire Station #3	17	The maneuvering clearance at the door is obstructed.	\$ 473	11	Low		
Building	27	Fire Station #3	18	The clear floor space around the toilet is obstructed by the shelving.	\$ 338	11	Low		
Building	27	Fire Station #3	19	The coat hooks are installed greater than 48 inches above the finished floor.	\$ 338	11	Low		
Building	27	Fire Station #3	20	The clear floor space around the toilet is obstructed by the shelving.	\$ 338	11	Low		
Building	27	Fire Station #3	21	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the coat hooks are too high and the shower seat is missing.	\$ 2,025	11	Low		
Building	27	Fire Station #3	22	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the lavatory does not have knee or toe clearance the coat hooks are too high and the shower seat is missing.	\$ 2,025	11	Low		
Building	27	Fire Station #3	23	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the lavatory does not have knee or toe clearance the coat hooks are too high and the shower seat is missing.	\$ 2,025	11	Low		
Building	28	Fire Station #4	17	The stairway only has a handrail on one side.	\$ 1,013	11	Low		
Building	28	Fire Station #4	18	The kitchen counter top is too high.	\$ 3,375	11	Low		
Building	28	Fire Station #4	19	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	28	Fire Station #4	20	The microwave is positioned too high for either a side or front approach.	\$ 473	11	Low		
Building	28	Fire Station #4	21	The sink drain pipes are exposed.	\$ 338	11	Low		
Building	28	Fire Station #4	24	The restroom does not include accessible fixtures or elements.	\$ 3,375	11	Low		
Building	28	Fire Station #4	25	The restroom does not include accessible fixtures or elements.	\$ 3,375	11	Low		
Building	28	Fire Station #4	26	The restroom does not include accessible fixtures or elements.	\$ 3,375	11	Low		
Building	28	Fire Station #4	27	The restroom does not include accessible fixtures or elements.	\$ 2,025	11	Low		
Building	29	Fire Station #5	25	The kitchen counter top is too high.	\$ 4,725	11	Low		
Building	29	Fire Station #5	26	Knee and toe clearance has not been provided at the sink.	\$ 3,375	11	Low		
Building	29	Fire Station #5	27	The top of the sink is above the allowable height requirement.	\$ -	11	Low		
Building	29	Fire Station #5	29	The restroom does not include accessible fixtures or elements.	\$ 4,050	11	Low		
Building	29	Fire Station #5	31	The restroom does not include accessible fixtures or elements.	\$ 6,075	11	Low		
Building	29	Fire Station #5	32	The route of travel does not provide a minimum width of 36 inches.	\$ 743	11	Low		
Building	29	Fire Station #5	33	The door opening does not provide at least 32 inches between the face of the door and the opposite stop.	\$ 2,025	11	Low		
Building	29	Fire Station #5	34	The route of travel does not provide a minimum width of 36 inches.	\$ 1,013	11	Low		
Building	29	Fire Station #5	35	The restroom does not include accessible fixtures or elements.	\$ 4,050	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	29	Fire Station #5	36	The television projects into the headroom clearance in the circulation path.	\$ 473	11	Low		
Building	29	Fire Station #5	38	The door has a door stop which prevents it from having a smooth surface at the bottom.	\$ 338	11	Low		
Building	29	Fire Station #5	40	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	29	Fire Station #5	43	There is a change in level greater than 1/4 inch.	\$ 2,025	11	Low		
Building	29	Fire Station #5	47	The vision light panels (glazing/window) exceed height requirements.	\$ 2,025	11	Low		
Building	29	Fire Station #5	50	The vision light panels (glazing/window) exceed height requirements.	\$ 4,050	11	Low		
Building	30	Fire Station #6	3	The key pad is positioned too high for either a side or front approach.	\$ 506	11	Low		
Building	30	Fire Station #6	16	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	30	Fire Station #6	17	Knee and toe space has not been provided at the sink.	\$ -	11	Low		
Building	30	Fire Station #6	18	The kitchen counter top is too high.	\$ 3,375	11	Low		
Building	30	Fire Station #6	19	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	30	Fire Station #6	22	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	30	Fire Station #6	24	The restroom does not contain any accessible elements. Toilet is in an alcove with no clear floor space grab bars missing lavatory does not provide knee and toe clearance lavatory rim height is too high and no accessible shower.	\$ 4,050	11	Low		
Building	30	Fire Station #6	29	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	30	Fire Station #6	31	The restroom is missing accessible fixtures or elements. Door contains knob style hardware clear floor space not provided at the toilet flush control is located on the wrong side grab bars missing no accessible shower lavatory is too high and does not have knee clearance change in level at the door and the door maneuvering clearance is obstructed.	\$ 4,050	11	Low		
Building	30	Fire Station #6	32	The restroom is missing accessible fixtures or elements. Door contains knob style hardware clear floor space not provided at the toilet flush control is located on the wrong side grab bars missing urinal is too high no accessible shower lavatory is too high and does not have knee clearance change in level at the door and at floor drain and the door maneuvering clearance is obstructed.	\$ 4,050	11	Low		
Building	30	Fire Station #6	37	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	30	Fire Station #6	44	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	30	Fire Station #6	45	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	31	Fire Station #7	1	The surfaces of the accessible parking spaces and access aisles are not firm stable and slip resistant.	\$ 10,125	11	Low		
Building	31	Fire Station #7	8	The mail box is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	31	Fire Station #7	15	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	31	Fire Station #7	16	Knee and toe clearance has not been provided at the sink.	\$ 2,700	11	Low		
Building	31	Fire Station #7	17	The kitchen counter top is too high.	\$ 7,425	11	Low		
Building	31	Fire Station #7	18	The vending machine operations are positioned too high for either a side or front approach.	\$ 2,025	11	Low		
Building	31	Fire Station #7	22	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the lavatory is in the toilet clear floor space the toilet paper dispenser is located at an incorrect distance in front of the toilet the coat hook is too high and there is no accessible shower.	\$ 4,050	11	Low		
Building	31	Fire Station #7	23	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the lavatory is in the toilet clear floor space the flush control in on the wrong side the toilet seat is too low the lavatory pipes are not insulated the toilet paper dispenser is located at an incorrect distance in front of the toilet the coat hook is too high and there is no accessible shower.	\$ 4,050	11	Low		
Building	31	Fire Station #7	24	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the toilet seat is too low the toilet paper dispenser is located at an incorrect distance in front of the toilet the coat hook is too high the door contains a door stop and there is no accessible shower.	\$ 4,050	11	Low		
Building	31	Fire Station #7	25	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the toilet seat is too low the flush control is on the wrong side the toilet paper dispenser is located at an incorrect distance in front of the toilet the coat hook is too high the door contains a door stop and there is no accessible shower.	\$ 4,050	11	Low		
Building	31	Fire Station #7	26	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the toilet seat is too low the flush control is on the wrong side the toilet paper dispenser is located at an incorrect distance in front of the toilet the lavatory is too high the coat hook is too high the door contains a door stop and there is no accessible shower.	\$ 4,050	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	31	Fire Station #7	27	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the toilet seat is too low the toilet paper dispenser is located at an incorrect distance in front of the toilet the coat hook is too high the door contains a door stop and there is no accessible shower.	\$ 4,050	11	Low		
Building	31	Fire Station #7	28	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend the correct distance on the closed side of the toilet the toilet paper dispenser is located at an incorrect distance in front of the toilet the door contains a door stop and a compliant hand held shower unit is missing.	\$ 4,050	11	Low		
Building	32	Fire Station #8	6	The flag pole controls are positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	32	Fire Station #8	8	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	11	Low		
Building	32	Fire Station #8	10	The stairway only has a handrail on one side.	\$ 1,013	11	Low		
Building	32	Fire Station #8	11	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	32	Fire Station #8	15	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the toilet clear floor space is obstructed and the shower seat is missing.	\$ 2,700	11	Low		
Building	32	Fire Station #8	16	The restroom is missing accessible fixtures or elements. The rear grab bars does not extend the correct distance on the closed side of the toilet the toilet paper dispenser is not installed within compliant range in front of the toilet and the transfer space has not been provided at the transfer shower.	\$ 2,700	11	Low		
Building	32	Fire Station #8	17	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the door maneuvering clearance is obstructed the toilet paper dispenser is not installed within compliant range in front of the toilet the paper towel dispenser is too high and there is no accessible shower.	\$ 4,050	11	Low		
Building	32	Fire Station #8	18	The restroom is missing accessible fixtures or elements. The rear and side grab bars are missing the door maneuvering clearance is obstructed the toilet paper dispenser is not installed within compliant range in front of the toilet the paper towel dispenser is too high and there is no accessible shower.	\$ 4,050	11	Low		
Building	33	Fire Station Annex (Old #4)	13	There is no accessible route between elements.	\$ 2,025	11	Low		
Building	33	Fire Station Annex (Old #4)	14	The door operating hardware is not accessible.	\$ 1,013	11	Low		
Building	33	Fire Station Annex (Old #4)	15	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	34	Fleet Service Center	3	The drop box is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	34	Fleet Service Center	7	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	34	Fleet Service Center	11	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	11	Low		
Building	34	Fleet Service Center	12	The controls are located such that operation require reaching across burners.	\$ 2,363	11	Low		
Building	34	Fleet Service Center	13	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	34	Fleet Service Center	14	There are no accessible tables.	\$ 1,013	11	Low		
Building	34	Fleet Service Center	16	The handrails are not at the correct height. The tops of handrails and their extensions must be between 34 inches and 38 inches above the stair nosing or ground.	\$ 2,025	11	Low		
Building	34	Fleet Service Center	20	The soap and paper towel dispenser are positioned too high for either a side or front approach.	\$ 675	11	Low		
Building	34	Fleet Service Center	21	The emergency shower operation is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	34	Fleet Service Center	22	The emergency shower operation is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	34	Fleet Service Center	23	The soap and paper towel dispenser are positioned too high for either a side or front approach.	\$ 675	11	Low		
Building	34	Fleet Service Center	30	The bench is not affixed to a wall or provides back support.	\$ 1,013	11	Low		
Building	35	Household Hazardous Waste Building	10	The eye wash stations is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	36	Landfill Weigh Station	4	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	36	Landfill Weigh Station	5	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	36	Landfill Weigh Station	6	The vision light panels exceed height requirements.	\$ 1,013	11	Low		
Building	36	Landfill Weigh Station	8	The restroom is missing accessible fixtures or elements.	\$ 2,025	11	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	46	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	47	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	48	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	50	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	51	The coat hook is positioned too high for either a side or front approach.	\$ 338	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	37	Linda McNatt Animal Care and Adoption Center	53	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend the correct distance on the open side of the toilet the toilet paper dispenser is not the correct distance from the front of the toilet the paper towel dispenser is too high and the self-closing faucet does not remain open for a minimum of 10 seconds.	\$ 1,283	11	Low		
Building	37	Linda McNatt Animal Care and Adoption Center	54	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend the correct distance on the open side of the toilet the toilet paper dispenser is not the correct distance from the front of the toilet the paper towel dispenser is too high the mirror is in the toilets clear floor space and the self-closing faucet does not remain open for a minimum of 10 seconds.	\$ 2,025	11	Low		
Building	39	LL WTP - Maintenance Building	6	The cleaner dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	39	LL WTP - Maintenance Building	7	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	39	LL WTP - Maintenance Building	8	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	40	LL WTP - Operations Building	16	The paper towel dispenser and soap dispenser are positioned too high for either a side or front approach.	\$ 675	11	Low		
Building	40	LL WTP - Operations Building	17	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	40	LL WTP - Operations Building	18	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	40	LL WTP - Operations Building	19	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	40	LL WTP - Operations Building	20	The controls are located such that operation require reaching across burners.	\$ 2,363	11	Low		
Building	40	LL WTP - Operations Building	26	There are no accessible bathing and shower facilities.	\$ 5,400	11	Low		
Building	40	LL WTP - Operations Building	27	The bench is not deep enough.	\$ 1,013	11	Low		
Building	40	LL WTP - Operations Building	28	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	40	LL WTP - Operations Building	34	The bench is not deep enough.	\$ 1,013	11	Low		
Building	41	LL WTP - Ozone Generator Building	2	The emergency shower operation are positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	41	LL WTP - Ozone Generator Building	5	The soap dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	41	LL WTP - Ozone Generator Building	6	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	14	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	11	Low		
Building	42	LRR WTP - Admin Building	17	The landing at the entrance doors exceeds 2 percent slope.	\$ 2,025	11	Low		
Building	42	LRR WTP - Admin Building	21	The microwave is positioned too high for either a side or front approach.	\$ 473	11	Low		
Building	42	LRR WTP - Admin Building	22	The controls are located such that operation require reaching across burners.	\$ 2,363	11	Low		
Building	42	LRR WTP - Admin Building	24	The telephone is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	25	The paper towel dispensers are positioned too high for either a side or front approach.	\$ 675	11	Low		
Building	42	LRR WTP - Admin Building	30	The emergency shower operations are positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	31	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	32	The soap dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	33	The emergency shower operations are positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	34	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	42	The bench is not deep enough.	\$ 1,013	11	Low		
Building	42	LRR WTP - Admin Building	43	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	42	LRR WTP - Admin Building	44	The compartment door is not self-closing.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	46	The grab bar is obstructed by the toilet refresher.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	47	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	42	LRR WTP - Admin Building	48	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	49	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	51	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	52	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	56	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	42	LRR WTP - Admin Building	58	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	59	The side grab bar is too high.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	60	The feminine product dispenser is not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 338	11	Low		
Building	42	LRR WTP - Admin Building	61	The clear floor space around the toilet is obstructed by the waste receptacle.	\$ 338	11	Low		
Building	43	LRR WTP - Ozone Generation Building	3	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	43	LRR WTP - Ozone Generation Building	4	The eye wash station is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	43	LRR WTP - Ozone Generation Building	5	Gratings are spaced greater than 1/2 inch in the direction of travel.	\$ 2,025	11	Low		
Building	44	Master Recycling Services - Building 101	8	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	44	Master Recycling Services - Building 101	9	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	44	Master Recycling Services - Building 101	10	The restroom does not include accessible fixtures or elements. The toilet center line is incorrect the rear grab bar does not extend the correct distance on the open side of the toilet the side grab bar is not mounted correctly and does not extend the correct distance the toilet paper dispenser is not the correct distance from the front of the toilet the lavatory and trash can are in the toilets clear floor space the paper towel dispenser and mirror are mounted too high the lavatory controls require tight grasping and the lavatory pipes are not insulated.	\$ 4,050	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	44	Master Recycling Services - Building 101	11	The restroom does not include accessible fixtures or elements. The toilet center line is incorrect the rear grab bar does not extend the correct distance on the open side of the toilet the side grab bar is not mounted correctly and does not extend the correct distance the toilet paper dispenser is not the correct distance from the front of the toilet the lavatory and trash can are in the toilets clear floor space the paper towel dispenser and mirror are mounted too high the lavatory controls require tight grasping and the lavatory pipes are not insulated.	\$ 4,050	11	Low		
Building	44	Master Recycling Services - Building 101	13	The restroom does not include accessible fixtures or elements. The toilet flush controls are on the wrong side the rear grab bar does not extend the correct distance on the open side of the toilet the side grab bar is not mounted correctly and does not extend the correct distance the toilet paper dispenser is not the correct distance from the front of the toilet the lavatory is in the toilets clear floor space and the lavatory controls require tight grasping.	\$ 4,050	11	Low		
Building	44	Master Recycling Services - Building 101	15	The restroom does not include accessible fixtures or elements. The rear grab bar does not extend the correct distance on the open side of the toilet the side grab bar is not mounted correctly and does not extend the correct distance the toilet paper dispenser is not the correct distance from the front of the toilet the lavatory is in the toilets clear floor space the paper towel dispenser is mounted too high and the lavatory controls require tight grasping.	\$ 4,050	11	Low		
Building	46	MLK Jr Recreation Center	57	The route of travel does not provide a minimum width of 36 inches.	\$ 3,375	11	Low		
Building	46	MLK Jr Recreation Center	101	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	47	Natatorium	4	The running slope of the access aisle (long dimension) exceeds 2 percent.	\$ 3,375	11	Low		
Building	47	Natatorium	5	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	11	Low		
Building	47	Natatorium	75	The restroom is missing accessible fixtures or elements. The rear grab bar does not extend 12 inches on the closed side of the toilet the side grab bar is more than 12 inches off the back wall the door is not self-closing and the door is missing an inside loop handle.	\$ 2,025	11	Low		
Building	47	Natatorium	76	The mirror is mounted too high.	\$ 338	11	Low		
Building	47	Natatorium	77	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	47	Natatorium	78	The coat hook is installed greater than 48 inches above the finished floor.	\$ 338	11	Low		
Building	47	Natatorium	79	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	48	New Central Fire Station	42	The controls are located such that operation require reaching across burners.	\$ 2,295	11	Low		
Building	48	New Central Fire Station	43	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	48	New Central Fire Station	44	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	48	New Central Fire Station	45	Knee and toe space has not been provided at the sink.	\$ 2,700	11	Low		
Building	48	New Central Fire Station	46	The dispensers projects into the headroom clearance in the circulation path.	\$ 675	11	Low		
Building	48	New Central Fire Station	49	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	48	New Central Fire Station	50	The bench is not deep enough.	\$ 1,013	11	Low		
Building	48	New Central Fire Station	52	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	48	New Central Fire Station	54	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	48	New Central Fire Station	56	The coat hook is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	48	New Central Fire Station	57	The bench is not deep enough.	\$ 1,013	11	Low		
Building	48	New Central Fire Station	58	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	48	New Central Fire Station	63	The vending machine operations is positioned too high for either a side or front approach.	\$ 1,013	11	Low		
Building	48	New Central Fire Station	64	The telephone is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	48	New Central Fire Station	66	The controls are located such that operation require reaching across burners.	\$ 2,295	11	Low		
Building	48	New Central Fire Station	67	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	48	New Central Fire Station	68	The kitchen counter top is too high.	\$ 3,375	11	Low		
Building	48	New Central Fire Station	69	The exercise machine or equipment does not provide compliant clear floor space for transfer.	\$ 3,375	11	Low		
Building	48	New Central Fire Station	71	The restroom is missing accessible fixtures or elements. The shower does not have the correct transfer space the lavatory is in the toilet clear floor space and the rear grab bar does not extend the correct distance on the open side of the toilet.	\$ 4,050	11	Low		
Building	48	New Central Fire Station	73	The restroom is missing accessible fixtures or elements. The shower does not have the correct transfer space the lavatory is in the toilet clear floor space the side grab bar does not extend the correct distance from the wall the rear grab bar does not extend the correct distance on the open side of the toilet and knee clearance is not provided at the lavatory.	\$ 4,050	11	Low		
Building	48	New Central Fire Station	75	The restroom is missing accessible fixtures or elements. The shower does not have the correct transfer space the lavatory is in the toilet clear floor space the side grab bar does not extend the correct distance from the wall the rear grab bar does not extend the correct distance on the open side of the toilet and the coat hook is too high.	\$ 4,050	11	Low		
Building	48	New Central Fire Station	76	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	48	New Central Fire Station	77	The bench is not deep enough.	\$ 1,013	11	Low		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	48	New Central Fire Station	78	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the rear grab bar does not extend the correct distance on the open side of the toilet the side grab bar does not extend the correct distance from the wall and the toilet paper dispenser is not the correct distance in front of the toilet.	\$ 2,025	11	Low		
Building	48	New Central Fire Station	79	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 338	11	Low		
Building	48	New Central Fire Station	80	The bench is not deep enough.	\$ 1,013	11	Low		
Building	48	New Central Fire Station	81	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	48	New Central Fire Station	82	The restroom is missing accessible fixtures or elements. The door is not self-closing and is missing an inside loop handle the side grab bar does not extend the correct distance from the wall and the toilet paper dispenser is not the correct distance in front of the toilet.	\$ 2,025	11	Low		
Building	48	New Central Fire Station	83	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	48	New Central Fire Station	84	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	11	Low		
Building	48	New Central Fire Station	85	The paper towel dispenser projects into the headroom clearance in the circulation path.	\$ 338	11	Low		
Building	48	New Central Fire Station	91	The emergency shower operation is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	49	North Branch Library	90	The security alarm panel is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	49	North Branch Library	92	There are no accessible tables.	\$ 1,013	11	Low		
Building	49	North Branch Library	93	The restroom is missing accessible fixtures or elements. The coat hook is mounted too high the lavatory rim is too high and does not have the required toe and knee clearance the self-closing faucet does not remain open a minimum of 10 seconds and the hand dryer is a protruding object.	\$ 3,713	11	Low		
Building	49	North Branch Library	94	The restroom is missing accessible fixtures or elements. The coat hook is mounted too high the feminine product dispenser requires twisting of the wrist to operate the lavatory does not have the required toe and knee clearance the self-closing faucet does not remain open a minimum of 10 seconds and the hand dryer is a protruding object.	\$ 3,645	11	Low		
Building	52	PCRP - Administration	26	The faucet controls are not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 405	11	Low		
Building	52	PCRP - Administration	27	The faucet controls are not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 405	11	Low		
Building	52	PCRP - Administration	28	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	52	PCRP - Administration	29	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	52	PCRP - Administration	32	The faucet controls are not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 405	11	Low		
Building	52	PCRP - Administration	36	The emergency shower operations is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	52	PCRP - Administration	37	The emergency shower operations is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	52	PCRP - Administration	46	The faucet controls are not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 405	11	Low		
Building	52	PCRP - Administration	47	The faucet controls are not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 405	11	Low		
Building	52	PCRP - Administration	48	The floor drain is set too low in the floor which causes a slope over 2 percent.	\$ 6,075	11	Low		
Building	52	PCRP - Administration	50	The faucet controls are not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 405	11	Low		
Building	52	PCRP - Administration	51	The faucet controls are not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 405	11	Low		
Building	52	PCRP - Administration	55	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	52	PCRP - Administration	57	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	11	Low		
Building	52	PCRP - Administration	58	The mirror is mounted too high.	\$ 338	11	Low		
Building	52	PCRP - Administration	60	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	52	PCRP - Administration	61	The faucet controls require twisting of the wrist.	\$ 405	11	Low		
Building	52	PCRP - Administration	62	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	52	PCRP - Administration	64	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	52	PCRP - Administration	65	The bench is not affixed to a wall or provides back support.	\$ 338	11	Low		
Building	52	PCRP - Administration	67	The rim of the urinal is above the maximum allowable height.	\$ 1,755	11	Low		
Building	52	PCRP - Administration	68	The water and drain pipes under the lavatory are not adequately insulated.	\$ 338	11	Low		
Building	52	PCRP - Administration	69	The mirror is mounted too high.	\$ 338	11	Low		
Building	52	PCRP - Administration	70	There are no accessible shower facilities.	\$ 5,400	11	Low		
Building	52	PCRP - Administration	73	The restroom does not include any accessible fixtures or accessories. The door contains knob style hardware and is not wide enough no turning clearance grab bars are missing the lavatory is in the toilets clear floor space toilet center line is incorrect toilet paper dispenser not installed the correct distance from the toilet and no clear floor space at the lavatory.	\$ 4,050	11	Low		
Building	52	PCRP - Administration	76	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	53	PCRP - Belt Press Building	1	The threshold is greater than 1/2 inch high.	\$ 3,375	11	Low		
Building	53	PCRP - Belt Press Building	5	One drinking fountain is provided and it is for standing persons.	\$ 5,130	11	Low		
Building	53	PCRP - Belt Press Building	6	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	53	PCRP - Belt Press Building	8	The belt press extends down too close to the route of travel.	\$ 20,250	11	Low		
Building	53	PCRP - Belt Press Building	9	The restroom does not include any accessible fixtures or accessories.	\$ 5,400	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	54	PCRP - Beneficial Reuse Building	1	The restroom is missing accessible fixtures or elements. The door contains knob style hardware the lavatory is in the toilets clear floor space the restroom is not large enough to accommodate wheelchair turning space mirror is too high toilet paper dispenser is not located the correct distance in front of toilet grab bars are missing and the lavatory does not have knee and toe clearance.	\$ 4,050	11	Low		
Building	56	PCRP - New Administration Building	10	Knee clearance has not been provided underneath the sink.	\$ 3,375	11	Low		
Building	56	PCRP - New Administration Building	11	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	56	PCRP - New Administration Building	12	The restroom is missing accessible fixtures or elements. The door is not self-closing and the toilet seat cover dispenser is in the toilets clear floor space.	\$ 675	11	Low		
Building	56	PCRP - New Administration Building	13	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	56	PCRP - New Administration Building	14	The urinal is confined on three sides (alcove).	\$ 945	11	Low		
Building	56	PCRP - New Administration Building	15	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	56	PCRP - New Administration Building	16	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	56	PCRP - New Administration Building	17	The lavatory's clear floor space is not a minimum 30 inches wide by 48 inches deep.	\$ 2,025	11	Low		
Building	56	PCRP - New Administration Building	18	The restroom is missing accessible fixtures or elements. The door is not self-closing the door does not open to a 90 degree angle due to the paper towel dispenser the side grab bar does not extend the correct distance and the toilet seat cover dispenser obstructs the rear grab bar.	\$ 1,283	11	Low		
Building	56	PCRP - New Administration Building	19	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	56	PCRP - New Administration Building	20	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	56	PCRP - New Administration Building	21	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	57	PCRP - Old Blower Building	1	The restroom does not include accessible fixtures or elements.	\$ 4,050	11	Low		
Building	57	PCRP - Old Blower Building	3	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	58	PCRP - Operations Building	6	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	58	PCRP - Operations Building	7	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	58	PCRP - Operations Building	8	The faucet controls require twisting of the wrist.	\$ 405	11	Low		
Building	58	PCRP - Operations Building	14	The restroom does not include any accessible fixtures or accessories.	\$ 4,050	11	Low		
Building	59	PCRP - Pretreatment Building	4	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	59	PCRP - Pretreatment Building	5	The eye wash station is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	59	PCRP - Pretreatment Building	7	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	59	PCRP - Pretreatment Building	10	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	59	PCRP - Pretreatment Building	11	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	60	Police Firing Range	1	The portable public restroom is not compliant.	\$ 2,025	11	Low		
Building	60	Police Firing Range	2	The surfaces of the accessible parking spaces and access aisles are not firm stable and slip resistant.	\$ 4,050	11	Low		
Building	60	Police Firing Range	3	There is no accessible route to the outdoor classroom.	\$ 2,025	11	Low		
Building	60	Police Firing Range	4	There is no accessible route to the storage facility.	\$ 2,025	11	Low		
Building	60	Police Firing Range	5	There is no accessible route to the firing stations.	\$ 2,025	11	Low		
Building	61	Quebec Hangars	29	State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration addition or construction of existing facilities which predate The Americans with Disabilities Act (ADA) of 1990.  Under the Code of Federal Regulations Section 35.151(b)(2) State and Local Government Title II entities may provide programmatic access where alterations to existing facilities would result in undue financial and administrative burdens.  For Example A public entity has six courtrooms in two existing buildings and determines that only three of those courtrooms and the public use and common use areas serving those courtrooms in one building are needed to be made accessible in order to satisfy its program access obligations. The entity must comply with 2010 Standards unless compliance would result in undue financial and administrative burdens and must take other actions that would not result in an undue financial burden to ensure access to persons with disabilities. This may include the scheduling of the various types of cases hearings etc. in accessible courtrooms and relocating them where necessary to accommodate persons with disabilities. Having a defined program and effective communication process in place to ensure the public and employees can request accommodations is necessary to ensure equal access to the county's court system.  Program access is not part of this evaluation and this information is being provided as an advisory only.	\$ -	11	Low		
Building	62	Service Center	64	The time clock is not positioned correctly for either a side or front approach.	\$ 338	11	Low		
Building	62	Service Center	65	One drinking fountain is provided and it is for standing persons.	\$ 5,130	11	Low		
Building	62	Service Center	66	Knee and toe clearance has not been provided at the sink.	\$ 3,375	11	Low		
Building	62	Service Center	67	There are no accessible work surfaces.	\$ 1,013	11	Low		
Building	62	Service Center	70	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	62	Service Center	71	The controls are located such that operation require reaching across burners.	\$ 2,295	11	Low		
Building	62	Service Center	72	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	62	Service Center	73	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	62	Service Center	74	The microwaves are positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	62	Service Center	75	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	62	Service Center	76	There are no accessible tables.	\$ 1,013	11	Low		
Building	62	Service Center	77	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	62	Service Center	78	The paper towel dispenser and lens cleaning station are positioned too high for either a side or front approach.	\$ 675	11	Low		
Building	62	Service Center	82	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	62	Service Center	83	The time clock is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	62	Service Center	85	The lens cleaning station is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	62	Service Center	91	The kitchen counter top is too high.	\$ 3,375	11	Low		
Building	62	Service Center	92	The U-shaped kitchen is not wide enough.	\$ 3,375	11	Low		
Building	62	Service Center	98	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	62	Service Center	99	The mirror is mounted too high.	\$ 338	11	Low		
Building	62	Service Center	100	Compliant knee space has not been provided under the lavatory.	\$ 2,700	11	Low		
Building	62	Service Center	106	One drinking fountain is provided and it is for standing persons.	\$ 5,130	11	Low		
Building	62	Service Center	107	The restroom is missing accessible fixtures or elements. Restroom is not large enough to accommodate an accessible water closet lavatory and wheelchair turning space grab bars are missing the lavatory is too high lavatory pipes are not insulated the door maneuvering clearance is obstructed and the soap dispenser is too high.	\$ 5,400	11	Low		
Building	62	Service Center	108	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	62	Service Center	109	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	62	Service Center	110	The soap and paper towel dispenser are positioned too high for either a side or front approach.	\$ 675	11	Low		
Building	62	Service Center	113	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	62	Service Center	114	The controls are located such that operation require reaching across burners.	\$ 2,363	11	Low		
Building	62	Service Center	115	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	62	Service Center	116	Knee and toe space has not been provided at the sink.	\$ 2,700	11	Low		
Building	62	Service Center	119	The soap dispensers are positioned too high for either a side or front approach.	\$ 675	11	Low		
Building	62	Service Center	120	The time clock is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	62	Service Center	123	There are no accessible tables.	\$ 1,013	11	Low		
Building	62	Service Center	124	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	62	Service Center	125	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	62	Service Center	128	There are not enough drinking fountains.	\$ 5,130	11	Low		
Building	62	Service Center	129	The restroom is missing accessible fixtures or elements. The restroom is not large enough to accommodate an accessible restroom grab bars are missing the lavatory is in the toilet clear floor space toilet paper dispenser is installed incorrectly the mirror is too high paper towel and soap dispenser too high the lavatory controls require tight grasping and the pipes are not insulated.	\$ 5,400	11	Low		
Building	63	Solid Waste Fleet/Maintenance Shop	2	The stairway contains open risers.	\$ 4,725	11	Low		
Building	63	Solid Waste Fleet/Maintenance Shop	3	The stairway handrails are missing compliant features.	\$ 2,025	11	Low		
Building	63	Solid Waste Fleet/Maintenance Shop	4	The vision light panels exceed height requirements.	\$ 1,013	11	Low		
Building	63	Solid Waste Fleet/Maintenance Shop	5	The eye wash station controls are positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	63	Solid Waste Fleet/Maintenance Shop	6	One drinking fountain is provided and it is at accessible height.	\$ 5,130	11	Low		
Building	63	Solid Waste Fleet/Maintenance Shop	7	The restroom does not include accessible fixtures or elements.	\$ 3,375	11	Low		
Building	63	Solid Waste Fleet/Maintenance Shop	8	The top of the sink is above the allowable height requirement.	\$ 3,375	11	Low		
Building	65	Solid Waste Services Building	34	The vision light panels (glazing/window) exceed height requirements.	\$ 1,013	11	Low		
Building	65	Solid Waste Services Building	41	The compartment door is not self closing and is missing a loop handle on the inside.	\$ 675	11	Low		
Building	65	Solid Waste Services Building	42	The shower spray cannot be used as both a fixed shower head and as a hand-held unit.	\$ 1,013	11	Low		
Building	65	Solid Waste Services Building	43	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	65	Solid Waste Services Building	44	The restroom does not include any accessible fixtures or accessories. The door is not self-closing and is missing a loop handle on the inside and the toilet seat cover dispenser is mounted too high.	\$ 1,013	11	Low		
Building	65	Solid Waste Services Building	45	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	65	Solid Waste Services Building	46	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	65	Solid Waste Services Building	49	Accessible lockers are not provided.	\$ 3,375	11	Low		
Building	65	Solid Waste Services Building	50	There is no compliant bench within the room.	\$ 1,013	11	Low		
Building	65	Solid Waste Services Building	52	The drinking fountain projects into the headroom clearance in the circulation path.	\$ 675	11	Low		
Building	66	South Branch Library	44	Accessible lockers are not provided.	\$ 2,025	11	Low		
Building	66	South Branch Library	45	The coat rack is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	67	SW Triple Wide	11	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	67	SW Triple Wide	12	The faucet controls require twisting of the wrist.	\$ 405	11	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Building	67	SW Triple Wide	14	The restroom is missing accessible fixtures or elements. The toilets clear floor space is obstructed the rear grab bar is not long enough the side grab bar is missing the toilet paper dispenser is not located in the correct range in front of the toilet the flush control is located on the wrong side the lavatory does not provide the required knee clearance the mirror is too high and the paper towel dispenser is too high.	\$ 4,050	11	Low		
Building	67	SW Triple Wide	17	The restroom is missing accessible fixtures or elements. The toilets clear floor space is obstructed the rear grab bar is not long enough the side grab bar is missing the toilet paper dispenser is not located in the correct range in front of the toilet the lavatory does not provide the required knee clearance the mirror is too high and the paper towel dispenser is too high.	\$ 4,050	11	Low		
Building	69	Traffic Control	9	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	69	Traffic Control	11	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	69	Traffic Control	12	The coffee maker is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	69	Traffic Control	13	The hand sanitizer dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	69	Traffic Control	14	The mail box is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	69	Traffic Control	15	The restroom does not include accessible fixtures or elements. The door is missing a loop handle on the inside and outside rear grab bar does not extend the correct distance on the closed side of the toilet the side grab bar is mounted more than 12 inches off of the back wall the toilet paper dispenser is not the correct distance from the front of the toilet the toilet seat cover dispenser is mounted too high the floor drain is set too low and the coat hook is too high.	\$ 3,375	11	Low		
Building	69	Traffic Control	16	The mirror is mounted too high.	\$ 338	11	Low		
Building	69	Traffic Control	17	The paper towel dispenser is too high off the floor.	\$ 338	11	Low		
Building	69	Traffic Control	19	The restroom does not include accessible fixtures or elements. The rear grab bar does not extend the correct distance on the closed side of the toilet the side grab bar is mounted more than 12 inches off of the back wall the toilet paper dispenser is not the correct distance from the front of the toilet the toilet seat cover dispenser is mounted too high the mirror and paper towel dispenser are too high and cart is in the door maneuvering clearance.	\$ 4,050	11	Low		
Building	70	Transmission Engineering Department Building	8	The vision light panels exceed height requirements.	\$ 1,013	11	Low		
Building	70	Transmission Engineering Department Building	9	The vision light panels exceed height requirements.	\$ 1,013	11	Low		
Building	70	Transmission Engineering Department Building	12	The toilet paper is not installed within the compliant range in front of the toilet.	\$ 338	11	Low		
Building	70	Transmission Engineering Department Building	13	The lavatory's clear floor space is obstructed by the paper towel dispenser and trash can.	\$ 473	11	Low		
Building	70	Transmission Engineering Department Building	14	The mirror is mounted too high.	\$ 338	11	Low		
Building	70	Transmission Engineering Department Building	16	The toilet compartment is missing accessible fixtures or elements.	\$ 1,013	11	Low		
Building	70	Transmission Engineering Department Building	17	The lavatory's clear floor space is obstructed by the paper towel dispenser and trash can.	\$ 473	11	Low		
Building	70	Transmission Engineering Department Building	18	The mirror is mounted too high.	\$ 338	11	Low		
Building	71	Truck Wash	2	The portable restroom is not compliant.	\$ 2,025	11	Low		
Building	72	Utility Office/Field Operations	11	There are no accessible tables.	\$ 1,013	11	Low		
Building	72	Utility Office/Field Operations	16	The vending machine operations are positioned too high for either a side or front approach.	\$ 1,013	11	Low		
Building	72	Utility Office/Field Operations	17	The paper towel dispenser is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	72	Utility Office/Field Operations	18	The controls are located such that operation require reaching across burners.	\$ 2,295	11	Low		
Building	72	Utility Office/Field Operations	19	The microwave is positioned too high for either a side or front approach.	\$ 338	11	Low		
Building	72	Utility Office/Field Operations	20	The stove hood controls are positioned too high for either a side or front approach.	\$ 743	11	Low		
Building	72	Utility Office/Field Operations	21	The top of the sink is above the allowable height requirement.	\$ 2,700	11	Low		
Building	72	Utility Office/Field Operations	22	Knee and toe clearance has not been provided at the sink.	\$ -	11	Low		
Building	72	Utility Office/Field Operations	27	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	72	Utility Office/Field Operations	28	The mirror is mounted too high.	\$ 675	11	Low		
Building	72	Utility Office/Field Operations	29	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	11	Low		
Building	72	Utility Office/Field Operations	30	The hand dryer projects into the headroom clearance in the circulation path.	\$ 338	11	Low		
Building	72	Utility Office/Field Operations	33	Compliant knee space has not been provided under the lavatory.	\$ -	11	Low		
Building	72	Utility Office/Field Operations	36	The top rim of the lavatory is too high.	\$ 2,700	11	Low		
Building	72	Utility Office/Field Operations	37	The mirror is mounted too high.	\$ 338	11	Low		
Building	72	Utility Office/Field Operations	38	The hand dryer projects into the headroom clearance in the circulation path.	\$ 338	11	Low		
Park	6	Clear Creek Natural Heritage Center	16	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 675	9	Low		
Park	6	Clear Creek Natural Heritage Center	17	The soap dispenser's operation mechanism is too high off the floor.	\$ 675	9	Low		
Park	6	Clear Creek Natural Heritage Center	21	The rim of the urinal is above the maximum allowable height.	\$ 1,755	9	Low		
Park	11	Denia Park	66	The compartment door is not self-closing and is missing an inside loop handle.	\$ 338	9	Low		
Park	11	Denia Park	103	The paper towel dispensers are positioned too high for either a side or front approach.	\$ 338	9	Low		
Park	12	Evers Park	106	The top rim of the lavatory is too high.	\$ 2,700	9	Low		
Park	12	Evers Park	118	The top of the sink is above the allowable height requirement.	\$ 2,025	9	Low		
Park	12	Evers Park	119	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Park	12	Evers Park	211	The walkway contains abrupt vertical edges and/or variations over a 1/2 inch.	\$ 2,025	9	Low		
Park	22	Mack Park	65	The compartment door is not self-closing.	\$ 338	9	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	22	Mack Park	69	The compartment door is not self-closing.	\$ 338	9	Low		
Park	22	Mack Park	73	The compartment door is not self-closing.	\$ 338	9	Low		
Park	22	Mack Park	77	The compartment door is not self-closing.	\$ 338	9	Low		
Park	22	Mack Park	114	The stove hood controls are positioned too high for either a side or front approach.	\$ 338	9	Low		
Park	27	North Lakes Park	196	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Park	27	North Lakes Park	253	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Park	27	North Lakes Park	270	The compartment door is not self-closing.	\$ 338	9	Low		
Park	27	North Lakes Park	272	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Park	27	North Lakes Park	274	The compartment door is not self-closing.	\$ 338	9	Low		
Park	27	North Lakes Park	276	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Park	27	North Lakes Park	280	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Park	27	North Lakes Park	308	The mirror is mounted too high.	\$ 338	9	Low		
Park	37	Water Works Park	106	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Park	37	Water Works Park	108	The paper towel dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Park	37	Water Works Park	110	The soap dispenser's operation mechanism is too high off the floor.	\$ 338	9	Low		
Park	37	Water Works Park	111	The feminine produce dispenser is not accessible because it requires tight grasping pinching or twisting of the wrist.	\$ 675	9	Low		
Park	37	Water Works Park	114	The baby changing table operating mechanism is outside reach range.	\$ 810	9	Low		
Park	37	Water Works Park	116	The paper towel dispenser's operation mechanism is too high off the floor (2 dispensers).	\$ 675	9	Low		
Park	7	Cooper Creek Linear Park	1	<p>State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration addition or construction of existing facilities which predate The Americans with Disabilities Act (ADA) of 1990.</p> <p>Under the Code of Federal Regulations Section 35.151(b)(2) State and Local Government Title II entities may provide programmatic access where alterations to existing facilities would result in undue financial and administrative burdens.</p> <p>For Example A public entity has six courtrooms in two existing buildings and determines that only three of those courtrooms and the public use and common use areas serving those courtrooms in one building are needed to be made accessible in order to satisfy its program access obligations. The entity must comply with 2010 Standards unless compliance would result in undue financial and administrative burdens and must take other actions that would not result in an undue financial burden to ensure access to persons with disabilities. This may include the scheduling of the various types of cases hearings etc. in accessible courtrooms and relocating them where necessary to accommodate persons with disabilities. Having a defined program and effective communication process in place to ensure the public and employees can request accommodations is necessary to ensure equal access to the county's court system.</p> <p>Program access is not part of this evaluation and this information is being provided as an advisory only.</p>	\$ -	10	Low		
Park	8	Cooper Glen Park	1	<p>State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration addition or construction of existing facilities which predate The Americans with Disabilities Act (ADA) of 1990.</p> <p>Under the Code of Federal Regulations Section 35.151(b)(2) State and Local Government Title II entities may provide programmatic access where alterations to existing facilities would result in undue financial and administrative burdens.</p> <p>For Example A public entity has six courtrooms in two existing buildings and determines that only three of those courtrooms and the public use and common use areas serving those courtrooms in one building are needed to be made accessible in order to satisfy its program access obligations. The entity must comply with 2010 Standards unless compliance would result in undue financial and administrative burdens and must take other actions that would not result in an undue financial burden to ensure access to persons with disabilities. This may include the scheduling of the various types of cases hearings etc. in accessible courtrooms and relocating them where necessary to accommodate persons with disabilities. Having a defined program and effective communication process in place to ensure the public and employees can request accommodations is necessary to ensure equal access to the county's court system.</p> <p>Program access is not part of this evaluation and this information is being provided as an advisory only.</p>	\$ -	10	Low		
Park	11	Denia Park	32	The clear floor space required at the water fountain is not flat (2% or 1:48 maximum slope) in all directions.	\$ 2,025	10	Low		
Park	11	Denia Park	33	The water flow from the spout does not meet minimum height requirements.	\$ 2,025	10	Low		
Park	27	North Lakes Park	199	The clear floor space required at the fountain is not flat (2 percent or 1:48 maximum slope) in all directions.	\$ 2,025	10	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Park	33	Sherman Park	1	<p>State and local governments have an obligation to make their programs and services accessible to persons with disabilities. This may or may not require the alteration addition or construction of existing facilities which predate The Americans with Disabilities Act (ADA) of 1990.</p> <p>Under the Code of Federal Regulations Section 35.151(b)(2) State and Local Government Title II entities may provide programmatic access where alterations to existing facilities would result in undue financial and administrative burdens.</p> <p>For Example A public entity has six courtrooms in two existing buildings and determines that only three of those courtrooms and the public use and common use areas serving those courtrooms in one building are needed to be made accessible in order to satisfy its program access obligations. The entity must comply with 2010 Standards unless compliance would result in undue financial and administrative burdens and must take other actions that would not result in an undue financial burden to ensure access to persons with disabilities. This may include the scheduling of the various types of cases hearings etc. in accessible courtrooms and relocating them where necessary to accommodate persons with disabilities. Having a defined program and effective communication process in place to ensure the public and employees can request accommodations is necessary to ensure equal access to the county's court system.</p> <p>Program access is not part of this evaluation and this information is being provided as an advisory only.</p>	\$ -	10	Low		
Park	6	Clear Creek Natural Heritage Center	4	The accessible route between the building entrance and the accessible parking has running slopes greater than 5 percent and has not been constructed as a ramp (i.e. handrails edge protection etc.).	\$ 2,025	11	Low		
Park	11	Denia Park	12	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	11	Low		
Park	18	IIOF Cemetery	16	There is no accessible entrance to the building used for storing equipment.	\$ 2,025	11	Low		
Park	27	North Lakes Park	5	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	11	Low		
Park	27	North Lakes Park	32	The running slope (long dimension) of the accessible parking stall exceeds 2 percent.	\$ 3,375	11	Low		
Park	27	North Lakes Park	43	The cross slope (narrow dimension) of the parking stall exceeds 2 percent.	\$ 3,375	11	Low		
Park	27	North Lakes Park	157	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	11	Low		
Park	27	North Lakes Park	233	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	11	Low		
Park	27	North Lakes Park	287	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	11	Low		
Park	37	Water Works Park	3	The cross slope (short dimension) of the access aisle exceeds 2 percent.	\$ 3,375	11	Low		
Park	37	Water Works Park	62	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	11	Low		
Park	37	Water Works Park	123	The paper towel dispenser is positioned too high for either a side or front approach and requires tight grasping to operate.	\$ 473	11	Low		
Park	37	Water Works Park	124	Knee clearance has not been provided at the sink.	\$ 2,700	11	Low		
Park	37	Water Works Park	125	The sink drain pipes are exposed.	\$ 338	11	Low		
Paved Trail	18	Sequoia Trail	4	The accessible path of travel has cross slopes greater than 2 percent.	\$ 2,025	11	Low		
Signalized Intersection	14	Intersection of Lillian Miller Pkwy and Southridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lillian Miller Pkwy and Southridge Dr	\$ 18,900	9	Low		
Signalized Intersection	15	Intersection of Colorado Blvd and Brinker Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Colorado Blvd and Brinker Rd	\$ 48,700	9	Low		
Signalized Intersection	17	Intersection of Lillian Miller Pkwy and shopping entrance (Lat. 33.1849; Long. -97.1087)	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lillian Miller Pkwy and shopping entrance (Lat. 33.1849; Long. -97.1087)	\$ 11,500	9	Low		
Signalized Intersection	20	Intersection of Loop 288 and shopping entrance (Lat. 33.1881; Long. -97.1061)	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loop 288 and shopping entrance (Lat. 33.1881; Long. -97.1061)	\$ 17,800	9	Low		
Signalized Intersection	21	Intersection of Loop 288 and Colorado Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loop 288 and Colorado Blvd	\$ 9,300	9	Low		
Signalized Intersection	28	Intersection of Colorado Blvd and San Jacinto Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Colorado Blvd and San Jacinto Blvd	\$ 14,000	9	Low		
Signalized Intersection	36	Intersection of Shady Oaks Dr and Kerley St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shady Oaks Dr and Kerley St	\$ 10,900	9	Low		
Signalized Intersection	40	Intersection of N Texas Blvd and I-35E Frontage Rd NB	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Texas Blvd and I-35E Frontage Rd NB	\$ 14,600	9	Low		
Signalized Intersection	42	Intersection of N Texas Blvd and Eagle Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Texas Blvd and Eagle Dr	\$ 37,300	9	Low		
Signalized Intersection	44	Intersection of S Carroll Blvd and Eagle Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Carroll Blvd and Eagle Dr	\$ 33,800	9	Low		
Signalized Intersection	46	Intersection of S Welch St and Eagle Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Welch St and Eagle Dr	\$ 22,200	9	Low		
Signalized Intersection	47	Intersection of Eagle Dr and Ave A	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Eagle Dr and Ave A	\$ 39,900	9	Low		
Signalized Intersection	52	Intersection of N Mayhill Rd and E McKinney St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Mayhill Rd and E McKinney St	\$ 28,900	9	Low		
Signalized Intersection	63	Intersection of S Locst St and E Hickory St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Locst St and E Hickory St	\$ 23,400	9	Low		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
Signalized Intersection	64	Intersection of S Elm St and W Hickory St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Elm St and W Hickory St	\$ 29,200	9	Low		
Signalized Intersection	65	Intersection of Carroll Blvd and W Hickory St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Carroll Blvd and W Hickory St	\$ 23,000	9	Low		
Signalized Intersection	70	Intersection of N Locust St and E Oak St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Locust St and E Oak St	\$ 24,800	9	Low		
Signalized Intersection	84	Intersection of N Carroll Blvd and E Parkway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and E Parkway St	\$ 29,600	9	Low		
Signalized Intersection	85	Intersection of N Carroll Blvd and W Congress St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and W Congress St	\$ 42,700	9	Low		
Signalized Intersection	92	Intersection of W University Dr and N Bonnie Brae St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and N Bonnie Brae St	\$ 25,200	9	Low		
Signalized Intersection	93	Intersection of W University Dr and Town Center Tr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and Town Center Tr	\$ 24,700	9	Low		
Signalized Intersection	95	Intersection of W University Dr and Alice St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and Alice St	\$ 13,500	9	Low		
Signalized Intersection	100	Intersection of W University Dr and N Carroll Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W University Dr and N Carroll Blvd	\$ 25,800	9	Low		
Signalized Intersection	8	Intersection of Teasley Ln and Lillian Miller Pkwy	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Lillian Miller Pkwy	\$ 23,100	11	Low		
Signalized Intersection	43	Intersection of Fort Worth Dr / S Elm St and Eagle Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fort Worth Dr / S Elm St and Eagle Dr	\$ 85,500	12	Low		
Signalized Intersection	107	Intersection of E University Dr and N Mayhill Rd / Cooper Creek Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E University Dr and N Mayhill Rd / Cooper Creek Rd	\$ 7,900	13	Low		
PROW Sidewalk	1	Abbot's Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,980	3	Good		
PROW Sidewalk	3	Acme St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,290	3	Good		
PROW Sidewalk	9	Alegre Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,070	3	Good		
PROW Sidewalk	12	Alice St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,740	3	Good		
PROW Sidewalk	16	Amarillo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,040	3	Good		
PROW Sidewalk	17	Amherst Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,110	3	Good		
PROW Sidewalk	20	Anna St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,480	3	Good		
PROW Sidewalk	24	Arrowhead Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,970	3	Good		
PROW Sidewalk	30	Audra Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,850	3	Good		
PROW Sidewalk	32	N Austin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,020	3	Good		
PROW Sidewalk	34	S Austin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,560	3	Good		
PROW Sidewalk	36	Ave A	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,050	3	Good		
PROW Sidewalk	41	S Ave B	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,310	3	Good		
PROW Sidewalk	43	N Ave C	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 770	3	Good		
PROW Sidewalk	44	S Ave C	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,230	3	Good		
PROW Sidewalk	47	Ave D	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,970	3	Good		
PROW Sidewalk	50	N North Texas Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,120	3	Good		
PROW Sidewalk	56	Ave F	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Good		
PROW Sidewalk	59	Ave H	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Good		
PROW Sidewalk	60	Ave S	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 840	3	Good		
PROW Sidewalk	65	Bandera St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 680	3	Good		
PROW Sidewalk	68	Barcelona St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 340	3	Good		
PROW Sidewalk	75	Bayfield Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,540	3	Good		
PROW Sidewalk	78	N Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,810	3	Good		
PROW Sidewalk	79	S Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,330	3	Good		
PROW Sidewalk	82	Bellemead Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,580	3	Good		
PROW Sidewalk	87	Bernard St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,410	3	Good		
PROW Sidewalk	106	Bolivar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,150	3	Good		
PROW Sidewalk	107	N Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,130	3	Good		
PROW Sidewalk	110	S Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,560	3	Good		
PROW Sidewalk	116	Bowling Green St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,480	3	Good		
PROW Sidewalk	117	Boyd St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,120	3	Good		
PROW Sidewalk	118	Bradley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,920	3	Good		
PROW Sidewalk	122	S Bradshaw St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	3	Good		
PROW Sidewalk	134	Broadway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,150	3	Good		
PROW Sidewalk	136	Broken Arrow Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,870	3	Good		
PROW Sidewalk	138	W Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,140	3	Good		
PROW Sidewalk	139	Brooke St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 470	3	Good		
PROW Sidewalk	147	Bryan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,290	3	Good		
PROW Sidewalk	154	Bushey St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,580	3	Good		
PROW Sidewalk	167	Carlton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,650	3	Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	171	N Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,840	3	Good		
PROW Sidewalk	172	S Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,680	3	Good		
PROW Sidewalk	175	N Cedar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,140	3	Good		
PROW Sidewalk	176	S Cedar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 750	3	Good		
PROW Sidewalk	177	Cedar Hill St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,430	3	Good		
PROW Sidewalk	178	Central Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Good		
PROW Sidewalk	183	Chapel Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,240	3	Good		
PROW Sidewalk	185	Charlotte St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,680	3	Good		
PROW Sidewalk	187	Chebi Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 420	3	Good		
PROW Sidewalk	190	Chestnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,990	3	Good		
PROW Sidewalk	201	Cleveland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,370	3	Good		
PROW Sidewalk	204	Coit St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,870	3	Good		
PROW Sidewalk	205	E College St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,830	3	Good		
PROW Sidewalk	206	W College St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,370	3	Good		
PROW Sidewalk	208	Collier St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 200	3	Good		
PROW Sidewalk	210	W Collins St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,370	3	Good		
PROW Sidewalk	212	Colorado Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,470	3	Good		
PROW Sidewalk	216	W Congress St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,070	3	Good		
PROW Sidewalk	222	Cooper Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,000	3	Good		
PROW Sidewalk	231	Cordell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 24,010	3	Good		
PROW Sidewalk	244	Creek Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,700	3	Good		
PROW Sidewalk	245	Crescent St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	3	Good		
PROW Sidewalk	254	Daniel St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 670	3	Good		
PROW Sidewalk	259	Davis St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,810	3	Good		
PROW Sidewalk	262	Denison St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 560	3	Good		
PROW Sidewalk	263	Denton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,990	3	Good		
PROW Sidewalk	274	Dudley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Good		
PROW Sidewalk	275	Duncan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,020	3	Good		
PROW Sidewalk	280	W Eagle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,840	3	Good		
PROW Sidewalk	297	Egan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,040	3	Good		
PROW Sidewalk	303	Emerson Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,290	3	Good		
PROW Sidewalk	306	Evers Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 730	3	Good		
PROW Sidewalk	329	Forrestridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,360	3	Good		
PROW Sidewalk	339	Frame St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,790	3	Good		
PROW Sidewalk	343	Fry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,990	3	Good		
PROW Sidewalk	355	Geesling Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,790	3	Good		
PROW Sidewalk	357	Georgetown Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 910	3	Good		
PROW Sidewalk	359	Glen Garden Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 730	3	Good		
PROW Sidewalk	360	Glenngary Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,160	3	Good		
PROW Sidewalk	367	Grant Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,440	3	Good		
PROW Sidewalk	370	Greenlee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 170	3	Good		
PROW Sidewalk	374	Gregg St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,970	3	Good		
PROW Sidewalk	376	Grove St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,680	3	Good		
PROW Sidewalk	384	Haynes St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,470	3	Good		
PROW Sidewalk	391	Heritage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 670	3	Good		
PROW Sidewalk	392	Hettie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,840	3	Good		
PROW Sidewalk	393	E Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 240	3	Good		
PROW Sidewalk	394	W Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,720	3	Good		
PROW Sidewalk	397	Hickory Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,580	3	Good		
PROW Sidewalk	400	E Highland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Good		
PROW Sidewalk	402	W Highland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,770	3	Good		
PROW Sidewalk	417	Hinkle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,620	3	Good		
PROW Sidewalk	422	Hollyhill Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Good		
PROW Sidewalk	427	Hummingbird Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,380	3	Good		
PROW Sidewalk	457	Jannie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 510	3	Good		
PROW Sidewalk	459	Jason Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	3	Good		
PROW Sidewalk	467	John Paine Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 32,400	3	Good		
PROW Sidewalk	470	Joshua St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	3	Good		
PROW Sidewalk	477	Kendolph Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,680	3	Good		
PROW Sidewalk	482	Kimberly Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 660	3	Good		
PROW Sidewalk	487	Kings Row	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,470	3	Good		
PROW Sidewalk	509	Lillian B Miller Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,460	3	Good		
PROW Sidewalk	513	Lindsey St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 600	3	Good		
PROW Sidewalk	527	Londonderry Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,430	3	Good		
PROW Sidewalk	531	Longridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 520	3	Good		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	536	Lovell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,890	3	Good		
PROW Sidewalk	544	Malone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Good		
PROW Sidewalk	549	Maple St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,900	3	Good		
PROW Sidewalk	559	Market St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 480	3	Good		
PROW Sidewalk	564	N Masch Branch Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	3	Good		
PROW Sidewalk	578	Mccormick St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 810	3	Good		
PROW Sidewalk	581	E Mckinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,750	3	Good		
PROW Sidewalk	584	W Mckinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	3	Good		
PROW Sidewalk	593	Meadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,750	3	Good		
PROW Sidewalk	595	Mercedes Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,940	3	Good		
PROW Sidewalk	596	Mesa Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,400	3	Good		
PROW Sidewalk	610	Mingo Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,390	3	Good		
PROW Sidewalk	620	Mockingbird Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,520	3	Good		
PROW Sidewalk	624	Montecito Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 27,350	3	Good		
PROW Sidewalk	629	Morse St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,410	3	Good		
PROW Sidewalk	631	Mounts Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,100	3	Good		
PROW Sidewalk	633	E Mulberry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,660	3	Good		
PROW Sidewalk	635	W Mulberry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,010	3	Good		
PROW Sidewalk	639	Myrtle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,580	3	Good		
PROW Sidewalk	645	Nevada St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,370	3	Good		
PROW Sidewalk	646	Newton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	3	Good		
PROW Sidewalk	648	Normal St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 600	3	Good		
PROW Sidewalk	651	Northcrest Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,060	3	Good		
PROW Sidewalk	656	E Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,290	3	Good		
PROW Sidewalk	660	W Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 33,170	3	Good		
PROW Sidewalk	663	Oak Tree Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	3	Good		
PROW Sidewalk	668	Oakland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,660	3	Good		
PROW Sidewalk	672	Oakshire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	3	Good		
PROW Sidewalk	680	Old Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,860	3	Good		
PROW Sidewalk	682	Old North Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,460	3	Good		
PROW Sidewalk	687	Oriole Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,800	3	Good		
PROW Sidewalk	692	Pace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,130	3	Good		
PROW Sidewalk	695	Paisley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,350	3	Good		
PROW Sidewalk	697	Palmer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,590	3	Good		
PROW Sidewalk	699	Panhandle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,020	3	Good		
PROW Sidewalk	704	W Parkway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10	3	Good		
PROW Sidewalk	705	Parvin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,900	3	Good		
PROW Sidewalk	726	Pierce St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 610	3	Good		
PROW Sidewalk	732	Pirtle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 470	3	Good		
PROW Sidewalk	739	Ponder Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,400	3	Good		
PROW Sidewalk	742	E Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 510	3	Good		
PROW Sidewalk	744	W Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,050	3	Good		
PROW Sidewalk	754	Primrose Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	3	Good		
PROW Sidewalk	757	Railroad Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,010	3	Good		
PROW Sidewalk	765	Redwood Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,920	3	Good		
PROW Sidewalk	771	Riney Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,720	3	Good		
PROW Sidewalk	776	Robertson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,350	3	Good		
PROW Sidewalk	778	Robinson Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 25,560	3	Good		
PROW Sidewalk	785	Ross St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 750	3	Good		
PROW Sidewalk	790	S Ruddell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,860	3	Good		
PROW Sidewalk	794	E Ryan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,650	3	Good		
PROW Sidewalk	800	Sam Bass Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,710	3	Good		
PROW Sidewalk	809	Santa Monica Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,920	3	Good		
PROW Sidewalk	814	Schmitz Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,950	3	Good		
PROW Sidewalk	815	Schuyler St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,890	3	Good		
PROW Sidewalk	817	Scripture St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,070	3	Good		
PROW Sidewalk	819	Second St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Good		
PROW Sidewalk	821	Seminole Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,240	3	Good		
PROW Sidewalk	824	Shadow Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 970	3	Good		
PROW Sidewalk	828	Shawnee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,370	3	Good		
PROW Sidewalk	831	E Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	3	Good		
PROW Sidewalk	847	Southridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 310	3	Good		
PROW Sidewalk	848	Spencer Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	3	Good		
PROW Sidewalk	859	Stroud St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,270	3	Good		
PROW Sidewalk	860	Stuart Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,330	3	Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	863	Sun Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,500	3	Good		
PROW Sidewalk	865	Sunset St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	3	Good		
PROW Sidewalk	869	E Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,490	3	Good		
PROW Sidewalk	871	W Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,660	3	Good		
PROW Sidewalk	880	Teasley Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,730	3	Good		
PROW Sidewalk	887	Texas St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 700	3	Good		
PROW Sidewalk	888	E Third St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,590	3	Good		
PROW Sidewalk	915	Underwood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 270	3	Good		
PROW Sidewalk	925	Vine St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,520	3	Good		
PROW Sidewalk	929	W Walnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,130	3	Good		
PROW Sidewalk	930	Warren Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,010	3	Good		
PROW Sidewalk	935	S Welch St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,730	3	Good		
PROW Sidewalk	944	Westgate Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Good		
PROW Sidewalk	950	Westward St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 710	3	Good		
PROW Sidewalk	951	Westway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,710	3	Good		
PROW Sidewalk	965	Willowood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,900	3	Good		
PROW Sidewalk	968	Wilson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,110	3	Good		
PROW Sidewalk	975	E Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,120	3	Good		
PROW Sidewalk	976	W Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,750	3	Good		
PROW Sidewalk	984	Withers St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,140	3	Good		
PROW Sidewalk	986	N Wood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Good		
PROW Sidewalk	992	Woodhaven St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20	3	Good		
PROW Sidewalk	993	Woodland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Good		
PROW Sidewalk	995	Conley Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Good		
PROW Sidewalk	997	S Woodrow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,610	3	Good		
PROW Sidewalk	1009	Oak Valley	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,700	3	Good		
PROW Sidewalk	1012	Paxton Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,880	3	Good		
PROW Sidewalk	1016	Long Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,630	3	Good		
PROW Sidewalk	1021	Deerwood Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,510	3	Good		
PROW Sidewalk	1030	Royal Oaks Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 880	3	Good		
PROW Sidewalk	1032	Royal Oaks Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,850	3	Good		
PROW Sidewalk	1044	Fawn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 23,320	3	Good		
PROW Sidewalk	1051	Shenandoah Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,790	3	Good		
PROW Sidewalk	1131	Brinker Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,650	3	Good		
PROW Sidewalk	1133	Vista Verde Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,180	3	Good		
PROW Sidewalk	1134	Buena Vista	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,980	3	Good		
PROW Sidewalk	1180	Stone Mountain Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,570	3	Good		
PROW Sidewalk	1181	Potomac Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,750	3	Good		
PROW Sidewalk	1186	Harvest Glen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,370	3	Good		
PROW Sidewalk	1187	Harvest Hill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,110	3	Good		
PROW Sidewalk	1188	High Meadow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,640	3	Good		
PROW Sidewalk	1193	Belmont St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 670	3	Good		
PROW Sidewalk	1195	Bentwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,770	3	Good		
PROW Sidewalk	1197	Deer Forest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,840	3	Good		
PROW Sidewalk	1200	Hope St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 910	3	Good		
PROW Sidewalk	1205	Wildwood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,520	3	Good		
PROW Sidewalk	1207	Osage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Good		
PROW Sidewalk	1210	Wind River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,360	3	Good		
PROW Sidewalk	1222	Saint Claire Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 710	3	Good		
PROW Sidewalk	1314	Moss creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,490	3	Good		
PROW Sidewalk	1315	Bent Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,640	3	Good		
PROW Sidewalk	1316	Springcreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,530	3	Good		
PROW Sidewalk	1317	Creekbend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 880	3	Good		
PROW Sidewalk	1318	Beechwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	3	Good		
PROW Sidewalk	1321	Monte Carlo Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,400	3	Good		
PROW Sidewalk	1323	Sundown Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,540	3	Good		
PROW Sidewalk	1324	Lake Country Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,470	3	Good		
PROW Sidewalk	1325	Clubhouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,830	3	Good		
PROW Sidewalk	1327	Reata Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 430	3	Good		
PROW Sidewalk	1328	Ranchman Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 190	3	Good		
PROW Sidewalk	1329	Longhorn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,850	3	Good		
PROW Sidewalk	1332	Lakeside Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,450	3	Good		
PROW Sidewalk	1334	W El Paseo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,130	3	Good		
PROW Sidewalk	1336	Manten Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,690	3	Good		
PROW Sidewalk	1343	Heights Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 170	3	Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1344	Gessner Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,460	3	Good		
PROW Sidewalk	1346	Fondren Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,540	3	Good		
PROW Sidewalk	1347	San Felipe Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,140	3	Good		
PROW Sidewalk	1350	Memorial Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,380	3	Good		
PROW Sidewalk	1353	Wintercreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	3	Good		
PROW Sidewalk	1357	Mark Twain Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,250	3	Good		
PROW Sidewalk	1358	Acorn Bend	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,360	3	Good		
PROW Sidewalk	1361	Great Bear Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,900	3	Good		
PROW Sidewalk	1363	Ottawa Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Good		
PROW Sidewalk	1367	Champlain Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 600	3	Good		
PROW Sidewalk	1368	St. Johns Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,090	3	Good		
PROW Sidewalk	1369	Como Lake Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,000	3	Good		
PROW Sidewalk	1371	Crater Lake Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,560	3	Good		
PROW Sidewalk	1372	Meredith Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	3	Good		
PROW Sidewalk	1377	Harvard Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,730	3	Good		
PROW Sidewalk	1380	Mira Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,010	3	Good		
PROW Sidewalk	1398	Marble Cove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,230	3	Good		
PROW Sidewalk	1399	White Dove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,150	3	Good		
PROW Sidewalk	1401	Silent Star Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,240	3	Good		
PROW Sidewalk	1404	Clear River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 940	3	Good		
PROW Sidewalk	1406	Hazelwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	3	Good		
PROW Sidewalk	1407	Seven Oaks Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,250	3	Good		
PROW Sidewalk	1409	Serenity Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,990	3	Good		
PROW Sidewalk	1412	Canoe Ridge Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	3	Good		
PROW Sidewalk	1417	Frost Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,320	3	Good		
PROW Sidewalk	1420	Bent Oaks Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,340	3	Good		
PROW Sidewalk	1422	Spenrock Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	3	Good		
PROW Sidewalk	1423	Newport Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 990	3	Good		
PROW Sidewalk	1425	Penniman Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,440	3	Good		
PROW Sidewalk	1426	Lakeview Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,060	3	Good		
PROW Sidewalk	1435	Poinsettia Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,550	3	Good		
PROW Sidewalk	1436	La Mirada	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,340	3	Good		
PROW Sidewalk	1437	La Fonta	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,110	3	Good		
PROW Sidewalk	1438	Zilda Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,400	3	Good		
PROW Sidewalk	1439	Lockhurst Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,610	3	Good		
PROW Sidewalk	1442	Pine Hills Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,260	3	Good		
PROW Sidewalk	1445	Alderbrook Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,920	3	Good		
PROW Sidewalk	1447	Sharon Rose Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 980	3	Good		
PROW Sidewalk	1448	Andrew Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,660	3	Good		
PROW Sidewalk	1449	Regency Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,160	3	Good		
PROW Sidewalk	1450	Paco Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,430	3	Good		
PROW Sidewalk	1452	Mirror Rock Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,570	3	Good		
PROW Sidewalk	1453	Hidden Path Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,680	3	Good		
PROW Sidewalk	1456	Sweet Cloud Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,620	3	Good		
PROW Sidewalk	1457	Winding Stream Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,820	3	Good		
PROW Sidewalk	1458	Golden Sand Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,540	3	Good		
PROW Sidewalk	1459	Rambling Brook Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,120	3	Good		
PROW Sidewalk	1464	Black Walnut	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,770	3	Good		
PROW Sidewalk	1468	Sun Ray Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	3	Good		
PROW Sidewalk	1480	Lantana Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,730	3	Good		
PROW Sidewalk	1488	Chittamwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Good		
PROW Sidewalk	1498	Mustang Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,110	3	Good		
PROW Sidewalk	1499	Ranch House Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 970	3	Good		
PROW Sidewalk	1500	Pinto Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,380	3	Good		
PROW Sidewalk	1501	Paint Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,780	3	Good		
PROW Sidewalk	1503	Big Horn Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	3	Good		
PROW Sidewalk	1505	Arabian Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,090	3	Good		
PROW Sidewalk	1506	Fiste St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	3	Good		
PROW Sidewalk	1507	Hayes St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,070	3	Good		
PROW Sidewalk	1509	Cruise St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,740	3	Good		
PROW Sidewalk	1510	Dixon Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,620	3	Good		
PROW Sidewalk	1521	Creekdale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40,420	3	Good		
PROW Sidewalk	1522	Dayspring Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,880	3	Good		
PROW Sidewalk	1524	Sunburst Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,490	3	Good		
PROW Sidewalk	1525	Raintree Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,590	3	Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1526	Ashwood Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,090	3	Good		
PROW Sidewalk	1527	Riverchase Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,420	3	Good		
PROW Sidewalk	1540	Merrimack Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 880	3	Good		
PROW Sidewalk	1545	Saranac Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 550	3	Good		
PROW Sidewalk	1546	Shoshone Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,240	3	Good		
PROW Sidewalk	1547	Valencia Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,220	3	Good		
PROW Sidewalk	1550	Widgeon Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,120	3	Good		
PROW Sidewalk	1572	Doecrest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,190	3	Good		
PROW Sidewalk	1575	Sirius Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,670	3	Good		
PROW Sidewalk	1576	Kentucky Derby Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,300	3	Good		
PROW Sidewalk	1582	Centre Place Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 680	3	Good		
PROW Sidewalk	1583	Nicosia St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,070	3	Good		
PROW Sidewalk	1585	Hermalinda Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,990	3	Good		
PROW Sidewalk	1586	Morin Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,590	3	Good		
PROW Sidewalk	1588	Beatriz Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,950	3	Good		
PROW Sidewalk	1598	Falcon Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,040	3	Good		
PROW Sidewalk	1599	Bentley Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,570	3	Good		
PROW Sidewalk	1600	Lamplighter Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,590	3	Good		
PROW Sidewalk	1601	Wright Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,450	3	Good		
PROW Sidewalk	1603	Purbeck Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,990	3	Good		
PROW Sidewalk	1604	Algarve Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,390	3	Good		
PROW Sidewalk	1605	Black Butte Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,790	3	Good		
PROW Sidewalk	1610	Lighthouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,090	3	Good		
PROW Sidewalk	1611	Ocean Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,730	3	Good		
PROW Sidewalk	1613	Nautical Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Good		
PROW Sidewalk	1615	Vinyard Way St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,970	3	Good		
PROW Sidewalk	1622	Alsace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,650	3	Good		
PROW Sidewalk	1623	Napa Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,620	3	Good		
PROW Sidewalk	1629	Stoneway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,620	3	Good		
PROW Sidewalk	1630	Circle View Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,360	3	Good		
PROW Sidewalk	1631	Edgefield Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,170	3	Good		
PROW Sidewalk	1632	Moorland Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	3	Good		
PROW Sidewalk	1634	Cordero Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,920	3	Good		
PROW Sidewalk	1635	Triple Crown Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	3	Good		
PROW Sidewalk	1640	Thistledown Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 780	3	Good		
PROW Sidewalk	1671	Hudsonwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	3	Good		
PROW Sidewalk	1675	W Ryan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,300	3	Good		
PROW Sidewalk	1676	Stockton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,570	3	Good		
PROW Sidewalk	1678	Wicker Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,710	3	Good		
PROW Sidewalk	1679	Allen Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,740	3	Good		
PROW Sidewalk	1685	Drexel Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,010	3	Good		
PROW Sidewalk	1686	Marymount Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,300	3	Good		
PROW Sidewalk	1687	Hofstra Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,290	3	Good		
PROW Sidewalk	1688	Purdue Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,320	3	Good		
PROW Sidewalk	1690	Syracuse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	3	Good		
PROW Sidewalk	1693	Shiraz Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,250	3	Good		
PROW Sidewalk	1709	Cope St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	3	Good		
PROW Sidewalk	1710	Comer St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,810	3	Good		
PROW Sidewalk	1712	Tripp Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,210	3	Good		
PROW Sidewalk	1713	Mckamy Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,630	3	Good		
PROW Sidewalk	1717	Skelton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 860	3	Good		
PROW Sidewalk	1720	Creekway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,060	3	Good		
PROW Sidewalk	1721	Parkplace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,690	3	Good		
PROW Sidewalk	1722	Brookside Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,340	3	Good		
PROW Sidewalk	1725	Meadowcreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,100	3	Good		
PROW Sidewalk	1726	Havenway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,270	3	Good		
PROW Sidewalk	1728	Trailway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,260	3	Good		
PROW Sidewalk	1729	Garden Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,290	3	Good		
PROW Sidewalk	1731	Waterhaven Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,670	3	Good		
PROW Sidewalk	1733	Trailside Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Good		
PROW Sidewalk	1735	Meandering Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,680	3	Good		
PROW Sidewalk	1737	Penina Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,640	3	Good		
PROW Sidewalk	1743	Fairway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,560	3	Good		
PROW Sidewalk	1744	Creek View Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,160	3	Good		
PROW Sidewalk	1748	Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,190	3	Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1749	Friesian Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,950	3	Good		
PROW Sidewalk	1750	Andalusian Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,350	3	Good		
PROW Sidewalk	1751	Lipizzan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,050	3	Good		
PROW Sidewalk	1753	Tennessee Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 350	3	Good		
PROW Sidewalk	1755	Clydesdale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,160	3	Good		
PROW Sidewalk	1757	Morgan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,890	3	Good		
PROW Sidewalk	1758	Wheeler Ridge Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,000	3	Good		
PROW Sidewalk	1760	Lance Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,640	3	Good		
PROW Sidewalk	1763	Sombrero Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 810	3	Good		
PROW Sidewalk	1764	Cyrus Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,020	3	Good		
PROW Sidewalk	1785	Quail Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,410	3	Good		
PROW Sidewalk	1788	Allison Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,400	3	Good		
PROW Sidewalk	1789	Beall St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 630	3	Good		
PROW Sidewalk	1791	Pimlico Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,100	3	Good		
PROW Sidewalk	1793	Hialeah Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 600	3	Good		
PROW Sidewalk	1798	Butler Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,900	3	Good		
PROW Sidewalk	1801	Countess Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	3	Good		
PROW Sidewalk	1803	St James Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,560	3	Good		
PROW Sidewalk	1806	Thistle Ridge	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,760	3	Good		
PROW Sidewalk	1807	Matthew Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,820	3	Good		
PROW Sidewalk	1808	Blackberry Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,120	3	Good		
PROW Sidewalk	1811	Thistle Hill	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,880	3	Good		
PROW Sidewalk	1813	Ricks Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Good		
PROW Sidewalk	1815	Prescott Downs Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,310	3	Good		
PROW Sidewalk	1824	Tallahassee Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,050	3	Good		
PROW Sidewalk	1825	Atlanta Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 820	3	Good		
PROW Sidewalk	1826	Trenton Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,020	3	Good		
PROW Sidewalk	1829	Unicorn Lake Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 800	3	Good		
PROW Sidewalk	1830	Englefield Green	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	3	Good		
PROW Sidewalk	1831	Savill Garden	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,040	3	Good		
PROW Sidewalk	1832	Windsor Farms Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,490	3	Good		
PROW Sidewalk	1833	Bray Village Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Good		
PROW Sidewalk	1837	English Manor Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,240	3	Good		
PROW Sidewalk	1838	Lost Pony Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 670	3	Good		
PROW Sidewalk	1839	Green Ivy Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,340	3	Good		
PROW Sidewalk	1840	English Saddle Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,650	3	Good		
PROW Sidewalk	1842	Lonesome Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,440	3	Good		
PROW Sidewalk	1844	Desert Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,470	3	Good		
PROW Sidewalk	1846	Saddleback Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,680	3	Good		
PROW Sidewalk	1847	Rugby Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,740	3	Good		
PROW Sidewalk	1870	Gable Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,030	3	Good		
PROW Sidewalk	1878	Union Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,250	3	Good		
PROW Sidewalk	1880	Shelby Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,030	3	Good		
PROW Sidewalk	1881	Dakota Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,780	3	Good		
PROW Sidewalk	1887	Saddle Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,990	3	Good		
PROW Sidewalk	1889	Rustic Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Good		
PROW Sidewalk	1891	Groveland Terrace	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,730	3	Good		
PROW Sidewalk	1892	Longleaf Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,690	3	Good		
PROW Sidewalk	1894	Corral Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,610	3	Good		
PROW Sidewalk	1898	Soledad Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	3	Good		
PROW Sidewalk	1904	Camino Real Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Good		
PROW Sidewalk	1907	Del Rey Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	3	Good		
PROW Sidewalk	1908	San Lucas Lane	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,090	3	Good		
PROW Sidewalk	1911	Meadowedge Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,450	3	Good		
PROW Sidewalk	1912	Cotten Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,480	3	Good		
PROW Sidewalk	1913	Fallmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,260	3	Good		
PROW Sidewalk	1914	Tawakoni Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Good		
PROW Sidewalk	1915	Eagle Mountain Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,150	3	Good		
PROW Sidewalk	1919	Balmorhea Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,830	3	Good		
PROW Sidewalk	1920	Toledo Bend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 880	3	Good		
PROW Sidewalk	1921	Amistad Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,230	3	Good		
PROW Sidewalk	1922	Athens Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,170	3	Good		
PROW Sidewalk	1925	Westglen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,840	3	Good		
PROW Sidewalk	1926	Central Village Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,550	3	Good		
PROW Sidewalk	1927	Pecan Tree Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1928	Nora Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,070	3	Good		
PROW Sidewalk	1961	Medpark Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Good		
PROW Sidewalk	1962	Somerest Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 770	3	Good		
PROW Sidewalk	1972	Buckthorn Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	3	Good		
PROW Sidewalk	1973	Stonecrop Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,930	3	Good		
PROW Sidewalk	1974	Woodbine Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,990	3	Good		
PROW Sidewalk	1975	Mockernut Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,290	3	Good		
PROW Sidewalk	1977	Tucker Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,190	3	Good		
PROW Sidewalk	1978	Lacewood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,870	3	Good		
PROW Sidewalk	1979	Shagbark Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,330	3	Good		
PROW Sidewalk	1990	Shoreline	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,110	3	Good		
PROW Sidewalk	1992	Elysian St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,800	3	Good		
PROW Sidewalk	1997	Miranda Place	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,870	3	Good		
PROW Sidewalk	1998	Alta Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,090	3	Good		
PROW Sidewalk	1999	Redondo Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,110	3	Good		
PROW Sidewalk	2000	Erin Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 550	3	Good		
PROW Sidewalk	2052	Trailhead Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 630	3	Good		
PROW Sidewalk	2497	Frontier Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,250	3	Good		
PROW Sidewalk	2498	Estacado Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Good		
PROW Sidewalk	2499	Pioneer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 450	3	Good		
PROW Sidewalk	2504	Roland Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,030	3	Good		
PROW Sidewalk	2506	El Dorado Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Good		
PROW Sidewalk	2516	Tamarack Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 860	3	Good		
PROW Sidewalk	2518	Benbrook Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,820	3	Good		
PROW Sidewalk	2519	New Ballinger Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,590	3	Good		
PROW Sidewalk	2521	Sweetwater Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 850	3	Good		
PROW Sidewalk	2533	Crosstrees Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	3	Good		
PROW Sidewalk	2534	Ringtail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 600	3	Good		
PROW Sidewalk	2536	Roxbury St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,770	3	Good		
PROW Sidewalk	2538	Hialeah Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,260	3	Good		
PROW Sidewalk	2541	Hollister Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 710	3	Good		
PROW Sidewalk	2556	Wavecrest Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 480	3	Good		
PROW Sidewalk	2558	Rushing Creek	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,400	3	Good		
PROW Sidewalk	2579	Moonsail Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,460	3	Good		
PROW Sidewalk	2585	Masthead Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,660	3	Good		
PROW Sidewalk	2586	Armstrong St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Good		
PROW Sidewalk	2587	Megan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10	3	Good		
PROW Sidewalk	2602	Stonetrail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 870	3	Good		
PROW Sidewalk	2607	Lost Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,190	3	Good		
PROW Sidewalk	2610	Sky Meadow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	3	Good		
PROW Sidewalk	2618	Shy Creek Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,380	3	Good		
PROW Sidewalk	2619	Summer Stream Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,520	3	Good		
PROW Sidewalk	2621	Stillhouse Hollow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Good		
PROW Sidewalk	2626	Meadowtrail Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,440	3	Good		
PROW Sidewalk	2627	Ann Arbor Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,630	3	Good		
PROW Sidewalk	2628	Empire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10	3	Good		
PROW Sidewalk	2630	Chicory Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,510	3	Good		
PROW Sidewalk	2631	Chicory Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,640	3	Good		
PROW Sidewalk	2632	Grassland Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,780	3	Good		
PROW Sidewalk	2635	Eaglestone Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,060	3	Good		
PROW Sidewalk	2636	Brentwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	3	Good		
PROW Sidewalk	1	Abbot's Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,920	3	Very Good		
PROW Sidewalk	3	Acme St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	3	Very Good		
PROW Sidewalk	16	Amarillo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,030	3	Very Good		
PROW Sidewalk	20	Anna St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,550	3	Very Good		
PROW Sidewalk	21	Anysa Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20	3	Very Good		
PROW Sidewalk	29	Auburn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 420	3	Very Good		
PROW Sidewalk	30	Audra Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,730	3	Very Good		
PROW Sidewalk	32	N Austin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,110	3	Very Good		
PROW Sidewalk	36	Ave A	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,450	3	Very Good		
PROW Sidewalk	40	N Ave B	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Very Good		
PROW Sidewalk	41	S Ave B	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 600	3	Very Good		
PROW Sidewalk	44	S Ave C	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 950	3	Very Good		
PROW Sidewalk	47	Ave D	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 780	3	Very Good		
PROW Sidewalk	50	N North Texas Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,720	3	Very Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	52	Barbara St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Very Good		
PROW Sidewalk	75	Bayfield Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 620	3	Very Good		
PROW Sidewalk	78	N Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,270	3	Very Good		
PROW Sidewalk	79	S Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,240	3	Very Good		
PROW Sidewalk	83	Benjiman St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,190	3	Very Good		
PROW Sidewalk	87	Bernard St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,110	3	Very Good		
PROW Sidewalk	106	Bolivar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 18,290	3	Very Good		
PROW Sidewalk	107	N Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,340	3	Very Good		
PROW Sidewalk	110	S Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 910	3	Very Good		
PROW Sidewalk	117	Boyd St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 950	3	Very Good		
PROW Sidewalk	121	N Bradshaw St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Very Good		
PROW Sidewalk	130	Brighton Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,390	3	Very Good		
PROW Sidewalk	138	W Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,670	3	Very Good		
PROW Sidewalk	145	Brush Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 280	3	Very Good		
PROW Sidewalk	147	Bryan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,510	3	Very Good		
PROW Sidewalk	165	Cardinal Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,900	3	Very Good		
PROW Sidewalk	167	Carlton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	3	Very Good		
PROW Sidewalk	171	N Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,300	3	Very Good		
PROW Sidewalk	172	S Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,080	3	Very Good		
PROW Sidewalk	173	Casie Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 920	3	Very Good		
PROW Sidewalk	175	N Cedar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,370	3	Very Good		
PROW Sidewalk	176	S Cedar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 770	3	Very Good		
PROW Sidewalk	178	Central Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 520	3	Very Good		
PROW Sidewalk	185	Charlotte St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Very Good		
PROW Sidewalk	187	Chebi Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,980	3	Very Good		
PROW Sidewalk	190	Chestnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,670	3	Very Good		
PROW Sidewalk	197	Christopher Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,330	3	Very Good		
PROW Sidewalk	201	Cleveland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	3	Very Good		
PROW Sidewalk	212	Colorado Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,130	3	Very Good		
PROW Sidewalk	215	E Congress St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,380	3	Very Good		
PROW Sidewalk	216	W Congress St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	3	Very Good		
PROW Sidewalk	219	Cook St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 430	3	Very Good		
PROW Sidewalk	222	Cooper Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 720	3	Very Good		
PROW Sidewalk	226	Corbin Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Very Good		
PROW Sidewalk	231	Cordell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,310	3	Very Good		
PROW Sidewalk	235	Cornell Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Very Good		
PROW Sidewalk	245	Crescent St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,890	3	Very Good		
PROW Sidewalk	250	Cross Timber St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,380	3	Very Good		
PROW Sidewalk	257	E Daugherty St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 810	3	Very Good		
PROW Sidewalk	270	Doubleoak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Very Good		
PROW Sidewalk	273	Duchess Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 270	3	Very Good		
PROW Sidewalk	274	Dudley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,480	3	Very Good		
PROW Sidewalk	275	Duncan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,060	3	Very Good		
PROW Sidewalk	280	W Eagle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,050	3	Very Good		
PROW Sidewalk	297	Egan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,090	3	Very Good		
PROW Sidewalk	303	Emerson Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Very Good		
PROW Sidewalk	313	Fallmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 490	3	Very Good		
PROW Sidewalk	314	Fannin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 620	3	Very Good		
PROW Sidewalk	315	Farris Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,680	3	Very Good		
PROW Sidewalk	317	Ferguson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 280	3	Very Good		
PROW Sidewalk	318	First St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 950	3	Very Good		
PROW Sidewalk	329	Forrestridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,200	3	Very Good		
PROW Sidewalk	339	Frame St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,060	3	Very Good		
PROW Sidewalk	343	Fry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 200	3	Very Good		
PROW Sidewalk	344	Fulton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,600	3	Very Good		
PROW Sidewalk	350	Gardenview St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,060	3	Very Good		
PROW Sidewalk	353	Gay Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 450	3	Very Good		
PROW Sidewalk	355	Geesling Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Very Good		
PROW Sidewalk	359	Glen Garden Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Very Good		
PROW Sidewalk	361	Glenwood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Very Good		
PROW Sidewalk	367	Grant Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 270	3	Very Good		
PROW Sidewalk	370	Greenlee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,830	3	Very Good		
PROW Sidewalk	372	Greenway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 660	3	Very Good		
PROW Sidewalk	374	Gregg St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 890	3	Very Good		
PROW Sidewalk	381	Hann St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,670	3	Very Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	388	Helm Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Very Good		
PROW Sidewalk	390	Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,270	3	Very Good		
PROW Sidewalk	391	Heritage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 190	3	Very Good		
PROW Sidewalk	393	E Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,580	3	Very Good		
PROW Sidewalk	394	W Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,600	3	Very Good		
PROW Sidewalk	397	Hickory Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 15,720	3	Very Good		
PROW Sidewalk	402	W Highland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,870	3	Very Good		
PROW Sidewalk	417	Hinkle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,420	3	Very Good		
PROW Sidewalk	418	E Hobson Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,020	3	Very Good		
PROW Sidewalk	444	Inca Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	3	Very Good		
PROW Sidewalk	454	Jagoe St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,350	3	Very Good		
PROW Sidewalk	455	James St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Very Good		
PROW Sidewalk	467	John Paine Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,610	3	Very Good		
PROW Sidewalk	487	Kings Row	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,170	3	Very Good		
PROW Sidewalk	509	Lillian B Miller Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,640	3	Very Good		
PROW Sidewalk	512	Linden Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,080	3	Very Good		
PROW Sidewalk	526	S Locust St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,340	3	Very Good		
PROW Sidewalk	527	Londonderry Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,910	3	Very Good		
PROW Sidewalk	531	Longridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Very Good		
PROW Sidewalk	535	Louise St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 510	3	Very Good		
PROW Sidewalk	537	Lynhurst Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 280	3	Very Good		
PROW Sidewalk	538	Mack Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,010	3	Very Good		
PROW Sidewalk	544	Malone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,390	3	Very Good		
PROW Sidewalk	545	Manhattan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 680	3	Very Good		
PROW Sidewalk	549	Maple St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,680	3	Very Good		
PROW Sidewalk	562	Martin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 510	3	Very Good		
PROW Sidewalk	564	N Masch Branch Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,610	3	Very Good		
PROW Sidewalk	573	S Mayhill Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,190	3	Very Good		
PROW Sidewalk	578	Mccormick St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 600	3	Very Good		
PROW Sidewalk	581	E Mckinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,850	3	Very Good		
PROW Sidewalk	584	W Mckinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 720	3	Very Good		
PROW Sidewalk	593	Meadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,590	3	Very Good		
PROW Sidewalk	596	Mesa Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Very Good		
PROW Sidewalk	602	Mill St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 380	3	Very Good		
PROW Sidewalk	610	Mingo Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	3	Very Good		
PROW Sidewalk	620	Mockingbird Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,190	3	Very Good		
PROW Sidewalk	621	Mohican Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,900	3	Very Good		
PROW Sidewalk	624	Montecito Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,360	3	Very Good		
PROW Sidewalk	626	Monterey Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,660	3	Very Good		
PROW Sidewalk	629	Morse St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,650	3	Very Good		
PROW Sidewalk	631	Mounts Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,010	3	Very Good		
PROW Sidewalk	635	W Mulberry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,880	3	Very Good		
PROW Sidewalk	638	Mulkey Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 520	3	Very Good		
PROW Sidewalk	646	Newton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,240	3	Very Good		
PROW Sidewalk	648	Normal St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,820	3	Very Good		
PROW Sidewalk	649	Norman St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,150	3	Very Good		
PROW Sidewalk	655	Nottingham Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,130	3	Very Good		
PROW Sidewalk	656	E Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,220	3	Very Good		
PROW Sidewalk	660	W Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,390	3	Very Good		
PROW Sidewalk	668	Oakland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Very Good		
PROW Sidewalk	672	Oakshire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,380	3	Very Good		
PROW Sidewalk	682	Old North Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,430	3	Very Good		
PROW Sidewalk	683	Old Orchard Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Very Good		
PROW Sidewalk	692	Pace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 520	3	Very Good		
PROW Sidewalk	695	Paisley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,490	3	Very Good		
PROW Sidewalk	697	Palmer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Very Good		
PROW Sidewalk	699	Panhandle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,350	3	Very Good		
PROW Sidewalk	703	E Parkway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,760	3	Very Good		
PROW Sidewalk	705	Parvin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,820	3	Very Good		
PROW Sidewalk	707	Pauline St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 640	3	Very Good		
PROW Sidewalk	713	Pearl St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,030	3	Very Good		
PROW Sidewalk	729	Piner St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20	3	Very Good		
PROW Sidewalk	739	Ponder Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 680	3	Very Good		
PROW Sidewalk	742	E Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,760	3	Very Good		
PROW Sidewalk	744	W Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,730	3	Very Good		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	765	Redwood Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,860	3	Very Good		
PROW Sidewalk	767	Regal Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,480	3	Very Good		
PROW Sidewalk	771	Riney Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,000	3	Very Good		
PROW Sidewalk	776	Robertson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Very Good		
PROW Sidewalk	778	Robinson Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,920	3	Very Good		
PROW Sidewalk	790	S Ruddell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,000	3	Very Good		
PROW Sidewalk	794	E Ryan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,690	3	Very Good		
PROW Sidewalk	800	Sam Bass Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 850	3	Very Good		
PROW Sidewalk	802	San Jacinto Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Very Good		
PROW Sidewalk	805	Sandpiper Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 700	3	Very Good		
PROW Sidewalk	811	Sauls Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,170	3	Very Good		
PROW Sidewalk	814	Schmitz Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,070	3	Very Good		
PROW Sidewalk	815	Schuyler St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Very Good		
PROW Sidewalk	817	Scripture St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,390	3	Very Good		
PROW Sidewalk	819	Second St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Very Good		
PROW Sidewalk	820	Selene Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 240	3	Very Good		
PROW Sidewalk	824	Shadow Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	3	Very Good		
PROW Sidewalk	825	Shady Oaks Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,720	3	Very Good		
PROW Sidewalk	828	Shawnee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,930	3	Very Good		
PROW Sidewalk	831	E Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,750	3	Very Good		
PROW Sidewalk	833	W Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,950	3	Very Good		
PROW Sidewalk	847	Southridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,270	3	Very Good		
PROW Sidewalk	848	Spencer Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 770	3	Very Good		
PROW Sidewalk	849	Spring Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,330	3	Very Good		
PROW Sidewalk	860	Stuart Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,220	3	Very Good		
PROW Sidewalk	863	Sun Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,060	3	Very Good		
PROW Sidewalk	869	E Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,590	3	Very Good		
PROW Sidewalk	871	W Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,100	3	Very Good		
PROW Sidewalk	880	Teasley Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,240	3	Very Good		
PROW Sidewalk	887	Texas St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,120	3	Very Good		
PROW Sidewalk	888	E Third St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	3	Very Good		
PROW Sidewalk	912	Uland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 540	3	Very Good		
PROW Sidewalk	925	Vine St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,270	3	Very Good		
PROW Sidewalk	927	Wainwright St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 520	3	Very Good		
PROW Sidewalk	928	E Walnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	3	Very Good		
PROW Sidewalk	935	S Welch St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,220	3	Very Good		
PROW Sidewalk	944	Westgate Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Very Good		
PROW Sidewalk	946	Westminster St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 440	3	Very Good		
PROW Sidewalk	950	Westward St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	3	Very Good		
PROW Sidewalk	952	Westwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,960	3	Very Good		
PROW Sidewalk	965	Willowood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	3	Very Good		
PROW Sidewalk	966	Salem Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 490	3	Very Good		
PROW Sidewalk	967	Wilshire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Very Good		
PROW Sidewalk	968	Wilson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 450	3	Very Good		
PROW Sidewalk	975	E Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,180	3	Very Good		
PROW Sidewalk	976	W Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,190	3	Very Good		
PROW Sidewalk	987	S Wood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Very Good		
PROW Sidewalk	988	Woodbrook St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 660	3	Very Good		
PROW Sidewalk	992	Woodhaven St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	3	Very Good		
PROW Sidewalk	996	Riverine Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,020	3	Very Good		
PROW Sidewalk	997	S Woodrow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,080	3	Very Good		
PROW Sidewalk	1000	Worthington Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 820	3	Very Good		
PROW Sidewalk	1008	Oak Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Very Good		
PROW Sidewalk	1009	Oak Valley	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Very Good		
PROW Sidewalk	1011	Liam Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 690	3	Very Good		
PROW Sidewalk	1012	Paxton Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Very Good		
PROW Sidewalk	1014	Cobblestone Rw	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 470	3	Very Good		
PROW Sidewalk	1021	Deerwood Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,450	3	Very Good		
PROW Sidewalk	1031	Royal Oaks Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,060	3	Very Good		
PROW Sidewalk	1034	Wellington Oaks Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,470	3	Very Good		
PROW Sidewalk	1035	Wellington Oaks Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 430	3	Very Good		
PROW Sidewalk	1048	Hunters Ridge Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 200	3	Very Good		
PROW Sidewalk	1107	Palo Verde Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,360	3	Very Good		
PROW Sidewalk	1122	Hardaway Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Very Good		
PROW Sidewalk	1128	Red Oak Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,530	3	Very Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1129	Post Oak Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,590	3	Very Good		
PROW Sidewalk	1131	Brinker Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,830	3	Very Good		
PROW Sidewalk	1133	Vista Verde Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,150	3	Very Good		
PROW Sidewalk	1179	Shiloh Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,100	3	Very Good		
PROW Sidewalk	1182	Westcourt Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 330	3	Very Good		
PROW Sidewalk	1185	Hemingway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Very Good		
PROW Sidewalk	1193	Belmont St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 890	3	Very Good		
PROW Sidewalk	1194	Remington St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,100	3	Very Good		
PROW Sidewalk	1197	Deer Forest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,940	3	Very Good		
PROW Sidewalk	1200	Hope St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Very Good		
PROW Sidewalk	1204	Overlake Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,160	3	Very Good		
PROW Sidewalk	1205	Wildwood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,070	3	Very Good		
PROW Sidewalk	1207	Osage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	3	Very Good		
PROW Sidewalk	1210	Wind River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,780	3	Very Good		
PROW Sidewalk	1212	Chaucer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,790	3	Very Good		
PROW Sidewalk	1314	Moss creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,150	3	Very Good		
PROW Sidewalk	1315	Bent Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	3	Very Good		
PROW Sidewalk	1318	Beechwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 320	3	Very Good		
PROW Sidewalk	1321	Monte Carlo Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,020	3	Very Good		
PROW Sidewalk	1323	Sundown Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,240	3	Very Good		
PROW Sidewalk	1324	Lake Country Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 750	3	Very Good		
PROW Sidewalk	1325	Clubhouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,820	3	Very Good		
PROW Sidewalk	1326	Spur Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	3	Very Good		
PROW Sidewalk	1328	Ranchman Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,550	3	Very Good		
PROW Sidewalk	1331	Hollow Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,280	3	Very Good		
PROW Sidewalk	1336	Manten Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,870	3	Very Good		
PROW Sidewalk	1337	La Vista Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Very Good		
PROW Sidewalk	1344	Gessner Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,540	3	Very Good		
PROW Sidewalk	1351	Kirby Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	3	Very Good		
PROW Sidewalk	1353	Wintercreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,490	3	Very Good		
PROW Sidewalk	1354	Kappwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,570	3	Very Good		
PROW Sidewalk	1355	Pinehurst Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,890	3	Very Good		
PROW Sidewalk	1358	Acorn Bend	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,180	3	Very Good		
PROW Sidewalk	1361	Great Bear Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,500	3	Very Good		
PROW Sidewalk	1367	Champlain Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,040	3	Very Good		
PROW Sidewalk	1368	St. Johns Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,980	3	Very Good		
PROW Sidewalk	1370	Herring Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,070	3	Very Good		
PROW Sidewalk	1371	Crater Lake Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 790	3	Very Good		
PROW Sidewalk	1376	Centenary Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,250	3	Very Good		
PROW Sidewalk	1377	Harvard Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,660	3	Very Good		
PROW Sidewalk	1380	Mira Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,860	3	Very Good		
PROW Sidewalk	1381	Almonte Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 900	3	Very Good		
PROW Sidewalk	1400	Rushing Spring Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,310	3	Very Good		
PROW Sidewalk	1402	Eagle Wing Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,510	3	Very Good		
PROW Sidewalk	1404	Clear River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,660	3	Very Good		
PROW Sidewalk	1407	Seven Oaks Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,560	3	Very Good		
PROW Sidewalk	1409	Serenity Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,520	3	Very Good		
PROW Sidewalk	1410	Swan Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,160	3	Very Good		
PROW Sidewalk	1412	Canoe Ridge Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 950	3	Very Good		
PROW Sidewalk	1414	Overlook Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,810	3	Very Good		
PROW Sidewalk	1415	Southway	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,200	3	Very Good		
PROW Sidewalk	1416	Northway	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,920	3	Very Good		
PROW Sidewalk	1423	Newport Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,040	3	Very Good		
PROW Sidewalk	1425	Penniman Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,680	3	Very Good		
PROW Sidewalk	1426	Lakeview Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10,340	3	Very Good		
PROW Sidewalk	1435	Poinsettia Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 490	3	Very Good		
PROW Sidewalk	1438	Zilda Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,290	3	Very Good		
PROW Sidewalk	1439	Lockhurst Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 420	3	Very Good		
PROW Sidewalk	1441	Crenshaw Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 540	3	Very Good		
PROW Sidewalk	1442	Pine Hills Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,530	3	Very Good		
PROW Sidewalk	1446	Maggie's Meadow	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,870	3	Very Good		
PROW Sidewalk	1448	Andrew Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Very Good		
PROW Sidewalk	1456	Sweet Cloud Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	3	Very Good		
PROW Sidewalk	1461	Indian Paint Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 230	3	Very Good		
PROW Sidewalk	1462	Baytree Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,900	3	Very Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1464	Black Walnut	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,220	3	Very Good		
PROW Sidewalk	1465	Hawthorn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 340	3	Very Good		
PROW Sidewalk	1468	Sun Ray Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,830	3	Very Good		
PROW Sidewalk	1476	Boxwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,760	3	Very Good		
PROW Sidewalk	1478	Daisy Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,670	3	Very Good		
PROW Sidewalk	1481	Plumbago Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Very Good		
PROW Sidewalk	1483	Burr Oak Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Very Good		
PROW Sidewalk	1485	Desert Willow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	3	Very Good		
PROW Sidewalk	1487	Red Cedar Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Very Good		
PROW Sidewalk	1498	Mustang Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,660	3	Very Good		
PROW Sidewalk	1501	Paint Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,240	3	Very Good		
PROW Sidewalk	1503	Big Horn Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,340	3	Very Good		
PROW Sidewalk	1508	Savage Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,100	3	Very Good		
PROW Sidewalk	1509	Cruise St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,730	3	Very Good		
PROW Sidewalk	1510	Dixon Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 230	3	Very Good		
PROW Sidewalk	1521	Creekdale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 16,720	3	Very Good		
PROW Sidewalk	1524	Sunburst Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,470	3	Very Good		
PROW Sidewalk	1525	Raintree Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,850	3	Very Good		
PROW Sidewalk	1527	Riverchase Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,630	3	Very Good		
PROW Sidewalk	1529	Nightfall Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 920	3	Very Good		
PROW Sidewalk	1530	Dawnlight Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,810	3	Very Good		
PROW Sidewalk	1531	Baybrooke Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 480	3	Very Good		
PROW Sidewalk	1541	Yale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,720	3	Very Good		
PROW Sidewalk	1547	Valencia Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	3	Very Good		
PROW Sidewalk	1551	Livingston Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,980	3	Very Good		
PROW Sidewalk	1552	Jefferson Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,850	3	Very Good		
PROW Sidewalk	1570	Shoal Bend	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,190	3	Very Good		
PROW Sidewalk	1571	Mosspoint Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,560	3	Very Good		
PROW Sidewalk	1572	Doecrest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 180	3	Very Good		
PROW Sidewalk	1574	Harvest Moon Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,000	3	Very Good		
PROW Sidewalk	1575	Sirius Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 310	3	Very Good		
PROW Sidewalk	1576	Kentucky Derby Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,620	3	Very Good		
PROW Sidewalk	1577	Preakness Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,790	3	Very Good		
PROW Sidewalk	1578	Meadowlands Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,790	3	Very Good		
PROW Sidewalk	1579	Par Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Very Good		
PROW Sidewalk	1582	Centre Place Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,010	3	Very Good		
PROW Sidewalk	1583	Nicosia St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,730	3	Very Good		
PROW Sidewalk	1585	Hermalinda Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,200	3	Very Good		
PROW Sidewalk	1586	Morin Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,830	3	Very Good		
PROW Sidewalk	1588	Beatriz Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,500	3	Very Good		
PROW Sidewalk	1589	Eufemia Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,310	3	Very Good		
PROW Sidewalk	1590	Santos Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,300	3	Very Good		
PROW Sidewalk	1593	Briar Forest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,420	3	Very Good		
PROW Sidewalk	1599	Bentley Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 990	3	Very Good		
PROW Sidewalk	1601	Wright Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,400	3	Very Good		
PROW Sidewalk	1603	Purbeck Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,270	3	Very Good		
PROW Sidewalk	1604	Algarve Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,270	3	Very Good		
PROW Sidewalk	1610	Lighthouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,010	3	Very Good		
PROW Sidewalk	1614	Sonoma Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,460	3	Very Good		
PROW Sidewalk	1615	Vinyard Way St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,030	3	Very Good		
PROW Sidewalk	1618	Provence Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,710	3	Very Good		
PROW Sidewalk	1619	Piedmonte Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Very Good		
PROW Sidewalk	1622	Alsace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,180	3	Very Good		
PROW Sidewalk	1623	Napa Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,950	3	Very Good		
PROW Sidewalk	1624	Vintage Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,570	3	Very Good		
PROW Sidewalk	1626	Fairfax Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,100	3	Very Good		
PROW Sidewalk	1627	Pomerol Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 840	3	Very Good		
PROW Sidewalk	1628	Tuscany Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,830	3	Very Good		
PROW Sidewalk	1630	Circle View Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,310	3	Very Good		
PROW Sidewalk	1632	Moorland Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 880	3	Very Good		
PROW Sidewalk	1635	Triple Crown Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,350	3	Very Good		
PROW Sidewalk	1637	Belmont Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Very Good		
PROW Sidewalk	1638	Del Mar Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,110	3	Very Good		
PROW Sidewalk	1639	Lone Star Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,540	3	Very Good		
PROW Sidewalk	1640	Thistledown Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Very Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1650	Cattail Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 840	3	Very Good		
PROW Sidewalk	1671	Hudsonwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 560	3	Very Good		
PROW Sidewalk	1675	W Ryan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,150	3	Very Good		
PROW Sidewalk	1676	Stockton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 17,560	3	Very Good		
PROW Sidewalk	1678	Wicker Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,800	3	Very Good		
PROW Sidewalk	1679	Allen Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,010	3	Very Good		
PROW Sidewalk	1680	Telese Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,610	3	Very Good		
PROW Sidewalk	1682	Stacy Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Very Good		
PROW Sidewalk	1683	Malli Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,410	3	Very Good		
PROW Sidewalk	1685	Drexel Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,100	3	Very Good		
PROW Sidewalk	1686	Marymount Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	3	Very Good		
PROW Sidewalk	1687	Hofstra Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 150	3	Very Good		
PROW Sidewalk	1689	Depaul Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,010	3	Very Good		
PROW Sidewalk	1692	Berkley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,340	3	Very Good		
PROW Sidewalk	1693	Shiraz Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	3	Very Good		
PROW Sidewalk	1699	Russell Newman Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 170	3	Very Good		
PROW Sidewalk	1709	Cope St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,290	3	Very Good		
PROW Sidewalk	1710	Comer St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Very Good		
PROW Sidewalk	1713	Mckamy Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 180	3	Very Good		
PROW Sidewalk	1714	Northpointe Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 640	3	Very Good		
PROW Sidewalk	1715	Chapel Hill Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,940	3	Very Good		
PROW Sidewalk	1716	Doris Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,240	3	Very Good		
PROW Sidewalk	1717	Skelton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	3	Very Good		
PROW Sidewalk	1720	Creekway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,430	3	Very Good		
PROW Sidewalk	1721	Parkplace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,340	3	Very Good		
PROW Sidewalk	1722	Brookside Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 21,680	3	Very Good		
PROW Sidewalk	1723	Meadowpark Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,140	3	Very Good		
PROW Sidewalk	1725	Meadowcreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	3	Very Good		
PROW Sidewalk	1726	Havenway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,840	3	Very Good		
PROW Sidewalk	1727	Lakeway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,480	3	Very Good		
PROW Sidewalk	1729	Garden Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 880	3	Very Good		
PROW Sidewalk	1730	Greenmeadow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,660	3	Very Good		
PROW Sidewalk	1732	Meadowglen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,530	3	Very Good		
PROW Sidewalk	1735	Meandering Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,150	3	Very Good		
PROW Sidewalk	1742	Club View Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,880	3	Very Good		
PROW Sidewalk	1744	Creek View Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Very Good		
PROW Sidewalk	1745	Crooked Stick Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,790	3	Very Good		
PROW Sidewalk	1746	Sawgrass Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,500	3	Very Good		
PROW Sidewalk	1747	Club View Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,030	3	Very Good		
PROW Sidewalk	1748	Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,550	3	Very Good		
PROW Sidewalk	1749	Friesian Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	3	Very Good		
PROW Sidewalk	1752	Breton Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 660	3	Very Good		
PROW Sidewalk	1754	Spanish Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 810	3	Very Good		
PROW Sidewalk	1756	Lusitano Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 920	3	Very Good		
PROW Sidewalk	1758	Wheeler Ridge Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 740	3	Very Good		
PROW Sidewalk	1759	Rocky Mountain Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 440	3	Very Good		
PROW Sidewalk	1761	Pres Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 700	3	Very Good		
PROW Sidewalk	1762	Chase Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,520	3	Very Good		
PROW Sidewalk	1763	Sombrero Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,450	3	Very Good		
PROW Sidewalk	1764	Cyrus Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,320	3	Very Good		
PROW Sidewalk	1767	Diamond Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 420	3	Very Good		
PROW Sidewalk	1768	Canton Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,080	3	Very Good		
PROW Sidewalk	1770	Evan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,440	3	Very Good		
PROW Sidewalk	1784	Stockbridge Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,720	3	Very Good		
PROW Sidewalk	1785	Quail Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,790	3	Very Good		
PROW Sidewalk	1789	Beall St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Very Good		
PROW Sidewalk	1790	Bay Meadow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,720	3	Very Good		
PROW Sidewalk	1792	Aqueduct Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,080	3	Very Good		
PROW Sidewalk	1794	Pinot Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,610	3	Very Good		
PROW Sidewalk	1795	Riesling Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,700	3	Very Good		
PROW Sidewalk	1796	Rhone Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,850	3	Very Good		
PROW Sidewalk	1804	Thoroughbred Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,470	3	Very Good		
PROW Sidewalk	1807	Matthew Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Very Good		
PROW Sidewalk	1808	Blackberry Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 690	3	Very Good		
PROW Sidewalk	1811	Thistle Hill	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,340	3	Very Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1812	Thistle Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	3	Very Good		
PROW Sidewalk	1815	Prescott Downs Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Very Good		
PROW Sidewalk	1825	Atlanta Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 200	3	Very Good		
PROW Sidewalk	1828	Springfield St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,790	3	Very Good		
PROW Sidewalk	1829	Unicorn Lake Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,100	3	Very Good		
PROW Sidewalk	1830	Englefield Green	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 860	3	Very Good		
PROW Sidewalk	1831	Savill Garden	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,600	3	Very Good		
PROW Sidewalk	1832	Windsor Farms Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,660	3	Very Good		
PROW Sidewalk	1833	Bray Village Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,820	3	Very Good		
PROW Sidewalk	1834	Eton Place	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,740	3	Very Good		
PROW Sidewalk	1838	Lost Pony Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,260	3	Very Good		
PROW Sidewalk	1840	English Saddle Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,330	3	Very Good		
PROW Sidewalk	1841	Bareback Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,080	3	Very Good		
PROW Sidewalk	1845	Quarterhorse Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 670	3	Very Good		
PROW Sidewalk	1846	Saddleback Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Very Good		
PROW Sidewalk	1848	Mercer Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 510	3	Very Good		
PROW Sidewalk	1849	Carson Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,120	3	Very Good		
PROW Sidewalk	1851	Stone Oak Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,850	3	Very Good		
PROW Sidewalk	1852	Pineoak Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	3	Very Good		
PROW Sidewalk	1854	Altius Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Very Good		
PROW Sidewalk	1875	Silver Sage Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 430	3	Very Good		
PROW Sidewalk	1878	Union Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,580	3	Very Good		
PROW Sidewalk	1880	Shelby Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,010	3	Very Good		
PROW Sidewalk	1881	Dakota Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,240	3	Very Good		
PROW Sidewalk	1890	Wellston Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,230	3	Very Good		
PROW Sidewalk	1891	Groveland Terrace	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 260	3	Very Good		
PROW Sidewalk	1893	Highpoint Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,130	3	Very Good		
PROW Sidewalk	1894	Corral Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,330	3	Very Good		
PROW Sidewalk	1895	Lipizzan Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,440	3	Very Good		
PROW Sidewalk	1896	Spyglass Hill Lane	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 310	3	Very Good		
PROW Sidewalk	1898	Soledad Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Very Good		
PROW Sidewalk	1903	Oceanview Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	3	Very Good		
PROW Sidewalk	1904	Camino Real Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,450	3	Very Good		
PROW Sidewalk	1905	Dolores Place	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Very Good		
PROW Sidewalk	1908	San Lucas Lane	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 380	3	Very Good		
PROW Sidewalk	1910	Fairmount Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,320	3	Very Good		
PROW Sidewalk	1911	Meadowedge Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,290	3	Very Good		
PROW Sidewalk	1913	Fallmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 560	3	Very Good		
PROW Sidewalk	1914	Tawakoni Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,260	3	Very Good		
PROW Sidewalk	1915	Eagle Mountain Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,770	3	Very Good		
PROW Sidewalk	1916	Gilmer Way Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,380	3	Very Good		
PROW Sidewalk	1917	Granbury Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,000	3	Very Good		
PROW Sidewalk	1918	Millers Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,980	3	Very Good		
PROW Sidewalk	1919	Balmorehea Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,190	3	Very Good		
PROW Sidewalk	1920	Toledo Bend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,060	3	Very Good		
PROW Sidewalk	1921	Amistad Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,090	3	Very Good		
PROW Sidewalk	1922	Athens Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,630	3	Very Good		
PROW Sidewalk	1923	Claydon Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,880	3	Very Good		
PROW Sidewalk	1924	Clarendon Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,440	3	Very Good		
PROW Sidewalk	1926	Central Village Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,760	3	Very Good		
PROW Sidewalk	1927	Pecan Tree Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,020	3	Very Good		
PROW Sidewalk	1928	Nora Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,620	3	Very Good		
PROW Sidewalk	1929	Mark Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 970	3	Very Good		
PROW Sidewalk	1930	Matt Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Very Good		
PROW Sidewalk	1943	Bishop Pine Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Very Good		
PROW Sidewalk	1961	Medpark Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 430	3	Very Good		
PROW Sidewalk	1962	Somerest Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Very Good		
PROW Sidewalk	1963	Barrymore Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	3	Very Good		
PROW Sidewalk	1967	Sweetgate Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 330	3	Very Good		
PROW Sidewalk	1972	Buckthorn Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 19,150	3	Very Good		
PROW Sidewalk	1973	Stonecrop Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Very Good		
PROW Sidewalk	1974	Woodbine Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,950	3	Very Good		
PROW Sidewalk	1976	Loblolly Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Very Good		
PROW Sidewalk	1977	Tucker Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 560	3	Very Good		
PROW Sidewalk	1978	Lacewood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,410	3	Very Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1979	Shagbark Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 480	3	Very Good		
PROW Sidewalk	1980	Joe Van Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	3	Very Good		
PROW Sidewalk	1981	Hornbeam St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,730	3	Very Good		
PROW Sidewalk	1990	Shoreline	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,330	3	Very Good		
PROW Sidewalk	1994	Colina Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,890	3	Very Good		
PROW Sidewalk	1995	Cadena Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,760	3	Very Good		
PROW Sidewalk	1996	Bonita Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,610	3	Very Good		
PROW Sidewalk	1997	Miranda Place	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,830	3	Very Good		
PROW Sidewalk	1998	Alta Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,000	3	Very Good		
PROW Sidewalk	1999	Redondo Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,070	3	Very Good		
PROW Sidewalk	2000	Erin Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 820	3	Very Good		
PROW Sidewalk	2046	Discovery Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,900	3	Very Good		
PROW Sidewalk	2051	Stockade Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,310	3	Very Good		
PROW Sidewalk	2052	Trailhead Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Very Good		
PROW Sidewalk	2056	S. Western Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20,660	3	Very Good		
PROW Sidewalk	2059	Hill Alley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 150	3	Very Good		
PROW Sidewalk	2490	Hidden Meadows Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 550	3	Very Good		
PROW Sidewalk	2497	Frontier Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,900	3	Very Good		
PROW Sidewalk	2498	Estacado Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,710	3	Very Good		
PROW Sidewalk	2499	Pioneer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,390	3	Very Good		
PROW Sidewalk	2504	Roland Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,290	3	Very Good		
PROW Sidewalk	2506	El Dorado Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 440	3	Very Good		
PROW Sidewalk	2507	Casa Grande Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,110	3	Very Good		
PROW Sidewalk	2516	Tamarack Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,190	3	Very Good		
PROW Sidewalk	2519	New Ballinger Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	3	Very Good		
PROW Sidewalk	2520	Wichita Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,500	3	Very Good		
PROW Sidewalk	2521	Sweetwater Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,060	3	Very Good		
PROW Sidewalk	2530	Cuddy Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,190	3	Very Good		
PROW Sidewalk	2531	Rockcrest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,340	3	Very Good		
PROW Sidewalk	2533	Crosstrees Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,140	3	Very Good		
PROW Sidewalk	2536	Roxbury St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,390	3	Very Good		
PROW Sidewalk	2537	Leonis Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	3	Very Good		
PROW Sidewalk	2538	Hialeah Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,980	3	Very Good		
PROW Sidewalk	2539	Nob Hill Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 760	3	Very Good		
PROW Sidewalk	2540	Linda Vista St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,030	3	Very Good		
PROW Sidewalk	2541	Hollister Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,510	3	Very Good		
PROW Sidewalk	2542	Fanita Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,040	3	Very Good		
PROW Sidewalk	2543	Pavilion Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,790	3	Very Good		
PROW Sidewalk	2544	Sapphire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,230	3	Very Good		
PROW Sidewalk	2545	Vineland Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,840	3	Very Good		
PROW Sidewalk	2549	Sea Cove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Very Good		
PROW Sidewalk	2550	Peninsula Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 890	3	Very Good		
PROW Sidewalk	2557	Del Rey Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 540	3	Very Good		
PROW Sidewalk	2559	Roaring Creek	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,390	3	Very Good		
PROW Sidewalk	2579	Moonsail Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,530	3	Very Good		
PROW Sidewalk	2586	Armstrong St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Very Good		
PROW Sidewalk	2587	Megan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,330	3	Very Good		
PROW Sidewalk	2588	Province St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	3	Very Good		
PROW Sidewalk	2589	Dominion St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 760	3	Very Good		
PROW Sidewalk	2590	Realm St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 710	3	Very Good		
PROW Sidewalk	2602	Stonetraill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 320	3	Very Good		
PROW Sidewalk	2603	Red Fox Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,010	3	Very Good		
PROW Sidewalk	2608	Doe Creek Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,990	3	Very Good		
PROW Sidewalk	2618	Shy Creek Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 920	3	Very Good		
PROW Sidewalk	2619	Summer Stream Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,070	3	Very Good		
PROW Sidewalk	2620	Princewood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,570	3	Very Good		
PROW Sidewalk	2621	Stillhouse Hollow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 14,130	3	Very Good		
PROW Sidewalk	2623	Marble Falls Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,020	3	Very Good		
PROW Sidewalk	2625	Mudstone Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	3	Very Good		
PROW Sidewalk	2626	Meadowtrail Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,620	3	Very Good		
PROW Sidewalk	2627	Ann Arbor Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,620	3	Very Good		
PROW Sidewalk	2628	Empire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,190	3	Very Good		
PROW Sidewalk	2630	Chicory Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,070	3	Very Good		
PROW Sidewalk	2631	Chicory Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,040	3	Very Good		
PROW Sidewalk	2632	Grassland Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,170	3	Very Good		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	2636	Brentwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	3	Very Good		
PROW Sidewalk	2637	Greystone Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	3	Very Good		
PROW Sidewalk	2639	Davenport Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Very Good		
PROW Sidewalk	2641	Canongate Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	3	Very Good		
PROW Sidewalk	2643	Corsair Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,790	3	Very Good		
PROW Sidewalk	2644	Gennaker Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Very Good		
PROW Sidewalk	10	Alexander St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Excellent		
PROW Sidewalk	12	Alice St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Excellent		
PROW Sidewalk	16	Amarillo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 330	3	Excellent		
PROW Sidewalk	18	Anderson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,060	3	Excellent		
PROW Sidewalk	20	Anna St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 380	3	Excellent		
PROW Sidewalk	21	Anysa Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,910	3	Excellent		
PROW Sidewalk	30	Audra Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,480	3	Excellent		
PROW Sidewalk	32	N Austin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,640	3	Excellent		
PROW Sidewalk	34	S Austin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Excellent		
PROW Sidewalk	36	Ave A	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,390	3	Excellent		
PROW Sidewalk	40	N Ave B	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Excellent		
PROW Sidewalk	43	N Ave C	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 150	3	Excellent		
PROW Sidewalk	44	S Ave C	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 560	3	Excellent		
PROW Sidewalk	47	Ave D	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Excellent		
PROW Sidewalk	50	N North Texas Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,370	3	Excellent		
PROW Sidewalk	52	Barbara St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 750	3	Excellent		
PROW Sidewalk	59	Ave H	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,360	3	Excellent		
PROW Sidewalk	60	Ave S	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10	3	Excellent		
PROW Sidewalk	68	Barcelona St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	3	Excellent		
PROW Sidewalk	71	Barthold Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Excellent		
PROW Sidewalk	75	Bayfield Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,050	3	Excellent		
PROW Sidewalk	76	Beatty St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 230	3	Excellent		
PROW Sidewalk	78	N Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,220	3	Excellent		
PROW Sidewalk	79	S Bell Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,020	3	Excellent		
PROW Sidewalk	80	Bell Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	81	Bellaire Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	3	Excellent		
PROW Sidewalk	87	Bernard St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,910	3	Excellent		
PROW Sidewalk	106	Bolivar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,260	3	Excellent		
PROW Sidewalk	107	N Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,980	3	Excellent		
PROW Sidewalk	110	S Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 630	3	Excellent		
PROW Sidewalk	117	Boyd St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 550	3	Excellent		
PROW Sidewalk	122	S Bradshaw St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 200	3	Excellent		
PROW Sidewalk	138	W Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 950	3	Excellent		
PROW Sidewalk	147	Bryan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 910	3	Excellent		
PROW Sidewalk	154	Bushey St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Excellent		
PROW Sidewalk	161	Campbell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	165	Cardinal Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,400	3	Excellent		
PROW Sidewalk	171	N Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,330	3	Excellent		
PROW Sidewalk	172	S Carroll Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 900	3	Excellent		
PROW Sidewalk	175	N Cedar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,450	3	Excellent		
PROW Sidewalk	176	S Cedar St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 430	3	Excellent		
PROW Sidewalk	178	Central Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	185	Charlotte St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Excellent		
PROW Sidewalk	187	Chebi Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,670	3	Excellent		
PROW Sidewalk	190	Chestnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,410	3	Excellent		
PROW Sidewalk	196	Choctaw Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,180	3	Excellent		
PROW Sidewalk	201	Cleveland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 780	3	Excellent		
PROW Sidewalk	210	W Collins St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Excellent		
PROW Sidewalk	212	Colorado Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 13,020	3	Excellent		
PROW Sidewalk	215	E Congress St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 350	3	Excellent		
PROW Sidewalk	216	W Congress St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,610	3	Excellent		
PROW Sidewalk	219	Cook St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,120	3	Excellent		
PROW Sidewalk	222	Cooper Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	226	Corbin Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,520	3	Excellent		
PROW Sidewalk	231	Cordell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Excellent		
PROW Sidewalk	242	N Crawford St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,290	3	Excellent		
PROW Sidewalk	244	Creek Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30	3	Excellent		
PROW Sidewalk	245	Crescent St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Excellent		
PROW Sidewalk	250	Cross Timber St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Excellent		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	259	Davis St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 320	3	Excellent		
PROW Sidewalk	262	Denison St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	3	Excellent		
PROW Sidewalk	263	Denton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Excellent		
PROW Sidewalk	270	Doubleoak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Excellent		
PROW Sidewalk	273	Duchess Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 990	3	Excellent		
PROW Sidewalk	274	Dudley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		
PROW Sidewalk	275	Duncan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Excellent		
PROW Sidewalk	277	Dunes St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 180	3	Excellent		
PROW Sidewalk	280	W Eagle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,160	3	Excellent		
PROW Sidewalk	287	Ector St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 240	3	Excellent		
PROW Sidewalk	292	Edwards Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,310	3	Excellent		
PROW Sidewalk	297	Egan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,340	3	Excellent		
PROW Sidewalk	303	Emerson Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Excellent		
PROW Sidewalk	304	Emery St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,700	3	Excellent		
PROW Sidewalk	306	Evers Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 900	3	Excellent		
PROW Sidewalk	309	S Exposition St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 710	3	Excellent		
PROW Sidewalk	313	Fallmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	314	Fannin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 180	3	Excellent		
PROW Sidewalk	318	First St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Excellent		
PROW Sidewalk	329	Forrestridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Excellent		
PROW Sidewalk	338	Foxwood Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	3	Excellent		
PROW Sidewalk	339	Frame St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	343	Fry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Excellent		
PROW Sidewalk	344	Fulton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,460	3	Excellent		
PROW Sidewalk	350	Gardenview St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,810	3	Excellent		
PROW Sidewalk	353	Gay Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		
PROW Sidewalk	355	Geesling Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,700	3	Excellent		
PROW Sidewalk	357	Georgetown Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Excellent		
PROW Sidewalk	360	Glenngary Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,620	3	Excellent		
PROW Sidewalk	361	Glenwood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10	3	Excellent		
PROW Sidewalk	365	Grace Temple Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	367	Grant Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30	3	Excellent		
PROW Sidewalk	370	Greenlee St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 660	3	Excellent		
PROW Sidewalk	372	Greenway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 330	3	Excellent		
PROW Sidewalk	381	Hann St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	3	Excellent		
PROW Sidewalk	382	Hanover Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 310	3	Excellent		
PROW Sidewalk	384	Haynes St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,440	3	Excellent		
PROW Sidewalk	388	Helm Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Excellent		
PROW Sidewalk	390	Hercules Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 710	3	Excellent		
PROW Sidewalk	391	Heritage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30	3	Excellent		
PROW Sidewalk	392	Hettie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 160	3	Excellent		
PROW Sidewalk	393	E Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,970	3	Excellent		
PROW Sidewalk	394	W Hickory St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,120	3	Excellent		
PROW Sidewalk	397	Hickory Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,490	3	Excellent		
PROW Sidewalk	402	W Highland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,550	3	Excellent		
PROW Sidewalk	424	Houston Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	425	Howard Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 550	3	Excellent		
PROW Sidewalk	446	Industrial St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 560	3	Excellent		
PROW Sidewalk	449	Inglewood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,550	3	Excellent		
PROW Sidewalk	450	Inman St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,570	3	Excellent		
PROW Sidewalk	451	loof St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10	3	Excellent		
PROW Sidewalk	452	Jackson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 610	3	Excellent		
PROW Sidewalk	454	Jagoe St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,620	3	Excellent		
PROW Sidewalk	459	Jason Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,070	3	Excellent		
PROW Sidewalk	461	Jim Christal Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 740	3	Excellent		
PROW Sidewalk	467	John Paine Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,160	3	Excellent		
PROW Sidewalk	470	Joshua St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,390	3	Excellent		
PROW Sidewalk	475	Karina St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 310	3	Excellent		
PROW Sidewalk	478	Kent St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30	3	Excellent		
PROW Sidewalk	480	Kerley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,270	3	Excellent		
PROW Sidewalk	482	Kimberly Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,960	3	Excellent		
PROW Sidewalk	487	Kings Row	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,310	3	Excellent		
PROW Sidewalk	495	Lakey St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 350	3	Excellent		
PROW Sidewalk	509	Lillian B Miller Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,650	3	Excellent		
PROW Sidewalk	512	Linden Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30	3	Excellent		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	513	Lindsey St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,350	3	Excellent		
PROW Sidewalk	526	S Locust St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	3	Excellent		
PROW Sidewalk	530	Longmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 150	3	Excellent		
PROW Sidewalk	535	Louise St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Excellent		
PROW Sidewalk	537	Lynhurst Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 340	3	Excellent		
PROW Sidewalk	538	Mack Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 190	3	Excellent		
PROW Sidewalk	544	Malone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 890	3	Excellent		
PROW Sidewalk	549	Maple St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,220	3	Excellent		
PROW Sidewalk	559	Market St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 610	3	Excellent		
PROW Sidewalk	564	N Masch Branch Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,430	3	Excellent		
PROW Sidewalk	570	N Mayhill Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,620	3	Excellent		
PROW Sidewalk	573	S Mayhill Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,910	3	Excellent		
PROW Sidewalk	578	Mccormick St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 11,110	3	Excellent		
PROW Sidewalk	581	E Mckinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,010	3	Excellent		
PROW Sidewalk	584	W Mckinney St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Excellent		
PROW Sidewalk	590	Meadow View Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Excellent		
PROW Sidewalk	593	Meadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 970	3	Excellent		
PROW Sidewalk	596	Mesa Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Excellent		
PROW Sidewalk	599	Metro St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,540	3	Excellent		
PROW Sidewalk	602	Mill St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Excellent		
PROW Sidewalk	610	Mingo Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 640	3	Excellent		
PROW Sidewalk	618	Mistywood Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	3	Excellent		
PROW Sidewalk	620	Mockingbird Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,430	3	Excellent		
PROW Sidewalk	624	Montecito Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,090	3	Excellent		
PROW Sidewalk	629	Morse St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,740	3	Excellent		
PROW Sidewalk	631	Mounts Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	633	E Mulberry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,650	3	Excellent		
PROW Sidewalk	635	W Mulberry St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,310	3	Excellent		
PROW Sidewalk	638	Mulkey Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 440	3	Excellent		
PROW Sidewalk	639	Myrtle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	3	Excellent		
PROW Sidewalk	642	Navajo St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 320	3	Excellent		
PROW Sidewalk	646	Newton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 270	3	Excellent		
PROW Sidewalk	649	Norman St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Excellent		
PROW Sidewalk	651	Northcrest Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Excellent		
PROW Sidewalk	655	Nottingham Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,150	3	Excellent		
PROW Sidewalk	656	E Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 630	3	Excellent		
PROW Sidewalk	660	W Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,750	3	Excellent		
PROW Sidewalk	668	Oakland St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,050	3	Excellent		
PROW Sidewalk	682	Old North Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		
PROW Sidewalk	687	Oriole Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Excellent		
PROW Sidewalk	692	Pace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,140	3	Excellent		
PROW Sidewalk	695	Paisley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,120	3	Excellent		
PROW Sidewalk	697	Palmer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 190	3	Excellent		
PROW Sidewalk	699	Panhandle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,910	3	Excellent		
PROW Sidewalk	704	W Parkway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20	3	Excellent		
PROW Sidewalk	705	Parvin St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 860	3	Excellent		
PROW Sidewalk	713	Pearl St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	3	Excellent		
PROW Sidewalk	720	Pershing Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,240	3	Excellent		
PROW Sidewalk	729	Piner St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 260	3	Excellent		
PROW Sidewalk	732	Pirtle St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		
PROW Sidewalk	735	Pockrus Page Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,930	3	Excellent		
PROW Sidewalk	739	Ponder Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Excellent		
PROW Sidewalk	742	E Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,160	3	Excellent		
PROW Sidewalk	744	W Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 380	3	Excellent		
PROW Sidewalk	754	Primrose Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Excellent		
PROW Sidewalk	757	Railroad Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	765	Redwood Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,120	3	Excellent		
PROW Sidewalk	767	Regal Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10	3	Excellent		
PROW Sidewalk	771	Riney Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,630	3	Excellent		
PROW Sidewalk	776	Robertson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Excellent		
PROW Sidewalk	778	Robinson Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,170	3	Excellent		
PROW Sidewalk	786	Royal Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 510	3	Excellent		
PROW Sidewalk	789	N Ruddell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	790	S Ruddell St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,530	3	Excellent		
PROW Sidewalk	794	E Ryan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,340	3	Excellent		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	800	Sam Bass Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20	3	Excellent		
PROW Sidewalk	802	San Jacinto Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 190	3	Excellent		
PROW Sidewalk	809	Santa Monica Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		
PROW Sidewalk	813	Sawyer Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 910	3	Excellent		
PROW Sidewalk	814	Schmitz Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 150	3	Excellent		
PROW Sidewalk	815	Schuyler St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 540	3	Excellent		
PROW Sidewalk	817	Scripture St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,620	3	Excellent		
PROW Sidewalk	819	Second St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 550	3	Excellent		
PROW Sidewalk	825	Shady Oaks Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,180	3	Excellent		
PROW Sidewalk	826	Shady Shores Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	3	Excellent		
PROW Sidewalk	831	E Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,150	3	Excellent		
PROW Sidewalk	833	W Sherman Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 680	3	Excellent		
PROW Sidewalk	847	Southridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 740	3	Excellent		
PROW Sidewalk	848	Spencer Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 12,790	3	Excellent		
PROW Sidewalk	851	Stanley St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Excellent		
PROW Sidewalk	853	Stella St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 420	3	Excellent		
PROW Sidewalk	856	Stonegate Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		
PROW Sidewalk	863	Sun Valley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 750	3	Excellent		
PROW Sidewalk	865	Sunset St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 150	3	Excellent		
PROW Sidewalk	869	E Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,180	3	Excellent		
PROW Sidewalk	871	W Sycamore St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,930	3	Excellent		
PROW Sidewalk	877	Taliaferro St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 640	3	Excellent		
PROW Sidewalk	880	Teasley Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 700	3	Excellent		
PROW Sidewalk	887	Texas St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 690	3	Excellent		
PROW Sidewalk	888	E Third St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,580	3	Excellent		
PROW Sidewalk	889	W Third St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Excellent		
PROW Sidewalk	915	Underwood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	3	Excellent		
PROW Sidewalk	925	Vine St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	3	Excellent		
PROW Sidewalk	927	Wainwright St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,050	3	Excellent		
PROW Sidewalk	929	W Walnut St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,560	3	Excellent		
PROW Sidewalk	933	N Welch St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 190	3	Excellent		
PROW Sidewalk	935	S Welch St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 750	3	Excellent		
PROW Sidewalk	943	Westchester St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,760	3	Excellent		
PROW Sidewalk	950	Westward St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Excellent		
PROW Sidewalk	951	Westway St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	965	Willowood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,670	3	Excellent		
PROW Sidewalk	967	Wilshire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	968	Wilson St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 190	3	Excellent		
PROW Sidewalk	975	E Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 840	3	Excellent		
PROW Sidewalk	976	W Windsor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,780	3	Excellent		
PROW Sidewalk	984	Withers St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	3	Excellent		
PROW Sidewalk	986	N Wood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Excellent		
PROW Sidewalk	987	S Wood St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Excellent		
PROW Sidewalk	995	Conley Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,060	3	Excellent		
PROW Sidewalk	996	Riverine Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20	3	Excellent		
PROW Sidewalk	997	S Woodrow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,950	3	Excellent		
PROW Sidewalk	1000	Worthington Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Excellent		
PROW Sidewalk	1002	Yellowstone Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,060	3	Excellent		
PROW Sidewalk	1007	Whispering Oaks	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,220	3	Excellent		
PROW Sidewalk	1008	Oak Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,710	3	Excellent		
PROW Sidewalk	1009	Oak Valley	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	3	Excellent		
PROW Sidewalk	1011	Liam Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Excellent		
PROW Sidewalk	1012	Paxton Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Excellent		
PROW Sidewalk	1016	Long Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,430	3	Excellent		
PROW Sidewalk	1122	Hardaway Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Excellent		
PROW Sidewalk	1128	Red Oak Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 450	3	Excellent		
PROW Sidewalk	1129	Post Oak Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 620	3	Excellent		
PROW Sidewalk	1131	Brinker Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,100	3	Excellent		
PROW Sidewalk	1182	Westcourt Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,730	3	Excellent		
PROW Sidewalk	1183	Springside Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30	3	Excellent		
PROW Sidewalk	1184	Blackford Oakes	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	1185	Hemingway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	3	Excellent		
PROW Sidewalk	1186	Harvest Glen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Excellent		
PROW Sidewalk	1193	Belmont St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Excellent		
PROW Sidewalk	1194	Remington St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1199	Providence St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,610	3	Excellent		
PROW Sidewalk	1200	Hope St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 710	3	Excellent		
PROW Sidewalk	1203	Parkhaven Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,420	3	Excellent		
PROW Sidewalk	1207	Osage Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,250	3	Excellent		
PROW Sidewalk	1210	Wind River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,340	3	Excellent		
PROW Sidewalk	1222	Saint Claire Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 320	3	Excellent		
PROW Sidewalk	1315	Bent Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Excellent		
PROW Sidewalk	1321	Monte Carlo Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	3	Excellent		
PROW Sidewalk	1323	Sundown Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 520	3	Excellent		
PROW Sidewalk	1324	Lake Country Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 280	3	Excellent		
PROW Sidewalk	1325	Clubhouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,460	3	Excellent		
PROW Sidewalk	1328	Ranchman Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Excellent		
PROW Sidewalk	1331	Hollow Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,750	3	Excellent		
PROW Sidewalk	1336	Manten Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	3	Excellent		
PROW Sidewalk	1339	Kossmann Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 270	3	Excellent		
PROW Sidewalk	1340	Paulie Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,760	3	Excellent		
PROW Sidewalk	1341	Whiting Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,370	3	Excellent		
PROW Sidewalk	1353	Wintercreek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	3	Excellent		
PROW Sidewalk	1357	Mark Twain Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	1360	Charter Bend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 420	3	Excellent		
PROW Sidewalk	1361	Great Bear Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,180	3	Excellent		
PROW Sidewalk	1367	Champlain Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 730	3	Excellent		
PROW Sidewalk	1369	Como Lake Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	1371	Crater Lake Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 200	3	Excellent		
PROW Sidewalk	1376	Centenary Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Excellent		
PROW Sidewalk	1377	Harvard Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,550	3	Excellent		
PROW Sidewalk	1381	Almonte Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Excellent		
PROW Sidewalk	1398	Marble Cove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,330	3	Excellent		
PROW Sidewalk	1399	White Dove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	1401	Silent Star Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Excellent		
PROW Sidewalk	1403	Country Home Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 310	3	Excellent		
PROW Sidewalk	1404	Clear River Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 170	3	Excellent		
PROW Sidewalk	1407	Seven Oaks Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,240	3	Excellent		
PROW Sidewalk	1409	Serenity Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,100	3	Excellent		
PROW Sidewalk	1410	Swan Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,610	3	Excellent		
PROW Sidewalk	1413	Lookout Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,200	3	Excellent		
PROW Sidewalk	1416	Northway	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,690	3	Excellent		
PROW Sidewalk	1422	Spencer Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	3	Excellent		
PROW Sidewalk	1426	Lakeview Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 9,270	3	Excellent		
PROW Sidewalk	1435	Poinsettia Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	1448	Andrew Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 690	3	Excellent		
PROW Sidewalk	1451	Leon Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	1452	Mirror Rock Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,440	3	Excellent		
PROW Sidewalk	1455	Teasbend Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	3	Excellent		
PROW Sidewalk	1458	Golden Sand Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 200	3	Excellent		
PROW Sidewalk	1460	Mild Creek Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	3	Excellent		
PROW Sidewalk	1461	Indian Paint Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 860	3	Excellent		
PROW Sidewalk	1462	Baytree Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 680	3	Excellent		
PROW Sidewalk	1463	Trumpet Vine	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 990	3	Excellent		
PROW Sidewalk	1464	Black Walnut	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,900	3	Excellent		
PROW Sidewalk	1465	Hawthorn Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 940	3	Excellent		
PROW Sidewalk	1466	Barberry Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 540	3	Excellent		
PROW Sidewalk	1467	Begonia Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Excellent		
PROW Sidewalk	1468	Sun Ray Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,530	3	Excellent		
PROW Sidewalk	1469	Redbud Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	3	Excellent		
PROW Sidewalk	1470	Dogwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,270	3	Excellent		
PROW Sidewalk	1471	Photinia Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,010	3	Excellent		
PROW Sidewalk	1472	Desert Holly Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 330	3	Excellent		
PROW Sidewalk	1473	Crapemyrtle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 260	3	Excellent		
PROW Sidewalk	1474	Crossvine Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 520	3	Excellent		
PROW Sidewalk	1476	Boxwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,970	3	Excellent		
PROW Sidewalk	1477	Boxwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Excellent		
PROW Sidewalk	1478	Daisy Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Excellent		
PROW Sidewalk	1479	Sweetgum Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 630	3	Excellent		
PROW Sidewalk	1480	Lantana Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 540	3	Excellent		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1481	Plumbago Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 890	3	Excellent		
PROW Sidewalk	1482	Aster Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 170	3	Excellent		
PROW Sidewalk	1483	Burr Oak Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,320	3	Excellent		
PROW Sidewalk	1484	Smoketree Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,410	3	Excellent		
PROW Sidewalk	1485	Desert Willow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,330	3	Excellent		
PROW Sidewalk	1486	Chittamwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	3	Excellent		
PROW Sidewalk	1487	Red Cedar Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		
PROW Sidewalk	1488	Chittamwood Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 150	3	Excellent		
PROW Sidewalk	1489	Silktree Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	3	Excellent		
PROW Sidewalk	1498	Mustang Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,210	3	Excellent		
PROW Sidewalk	1499	Ranch House Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,170	3	Excellent		
PROW Sidewalk	1500	Pinto Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 450	3	Excellent		
PROW Sidewalk	1503	Big Horn Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	3	Excellent		
PROW Sidewalk	1504	Palamino Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	3	Excellent		
PROW Sidewalk	1511	Abby Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,140	3	Excellent		
PROW Sidewalk	1512	Kayanne Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,730	3	Excellent		
PROW Sidewalk	1513	Cole Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	3	Excellent		
PROW Sidewalk	1514	Jeffrey Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 640	3	Excellent		
PROW Sidewalk	1521	Creekdale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	3	Excellent		
PROW Sidewalk	1524	Sunburst Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Excellent		
PROW Sidewalk	1527	Riverchase Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Excellent		
PROW Sidewalk	1528	Waterside Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Excellent		
PROW Sidewalk	1531	Baybrooke Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	3	Excellent		
PROW Sidewalk	1551	Livingston Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,590	3	Excellent		
PROW Sidewalk	1552	Jefferson Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,340	3	Excellent		
PROW Sidewalk	1569	Settlement Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,470	3	Excellent		
PROW Sidewalk	1570	Shoal Bend	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,650	3	Excellent		
PROW Sidewalk	1571	Mosspoint Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 320	3	Excellent		
PROW Sidewalk	1572	Doecrest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 480	3	Excellent		
PROW Sidewalk	1575	Sirius Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	1576	Kentucky Derby Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Excellent		
PROW Sidewalk	1578	Meadowlands Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 330	3	Excellent		
PROW Sidewalk	1579	Par Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,280	3	Excellent		
PROW Sidewalk	1580	Birdie Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Excellent		
PROW Sidewalk	1582	Centre Place Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,710	3	Excellent		
PROW Sidewalk	1583	Nicosia St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,360	3	Excellent		
PROW Sidewalk	1586	Morin Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Excellent		
PROW Sidewalk	1587	Chon Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	3	Excellent		
PROW Sidewalk	1588	Beatriz Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,140	3	Excellent		
PROW Sidewalk	1590	Santos Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 510	3	Excellent		
PROW Sidewalk	1598	Falcon Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,000	3	Excellent		
PROW Sidewalk	1599	Bentley Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,860	3	Excellent		
PROW Sidewalk	1600	Lamplighter Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	3	Excellent		
PROW Sidewalk	1603	Purbeck Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Excellent		
PROW Sidewalk	1604	Algarve Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,140	3	Excellent		
PROW Sidewalk	1610	Lighthouse Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,060	3	Excellent		
PROW Sidewalk	1611	Ocean Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	1614	Sonoma Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 540	3	Excellent		
PROW Sidewalk	1615	Vinyard Way St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 350	3	Excellent		
PROW Sidewalk	1616	Claret Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 150	3	Excellent		
PROW Sidewalk	1617	Claret Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Excellent		
PROW Sidewalk	1619	Piedmonte Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 240	3	Excellent		
PROW Sidewalk	1620	Loire Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	3	Excellent		
PROW Sidewalk	1621	Sonoma Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	3	Excellent		
PROW Sidewalk	1624	Vintage Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,060	3	Excellent		
PROW Sidewalk	1627	Pomerol Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 420	3	Excellent		
PROW Sidewalk	1634	Cordero Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,040	3	Excellent		
PROW Sidewalk	1636	Nolen Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 230	3	Excellent		
PROW Sidewalk	1637	Belmont Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,150	3	Excellent		
PROW Sidewalk	1638	Del Mar Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,380	3	Excellent		
PROW Sidewalk	1639	Lone Star Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,930	3	Excellent		
PROW Sidewalk	1640	Thistledown Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,640	3	Excellent		
PROW Sidewalk	1645	Juniper Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Excellent		
PROW Sidewalk	1647	Goldenrod Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	3	Excellent		
PROW Sidewalk	1648	Marsh Rail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,840	3	Excellent		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1649	Moor Hen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,180	3	Excellent		
PROW Sidewalk	1650	Cattail Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Excellent		
PROW Sidewalk	1651	Heron Pond Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 680	3	Excellent		
PROW Sidewalk	1652	Fox Sedge Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,290	3	Excellent		
PROW Sidewalk	1653	Waterlily Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Excellent		
PROW Sidewalk	1671	Hudsonwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Excellent		
PROW Sidewalk	1675	W Ryan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 280	3	Excellent		
PROW Sidewalk	1676	Stockton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	1677	Mockingbird Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	1678	Wicker Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 450	3	Excellent		
PROW Sidewalk	1679	Allen Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	3	Excellent		
PROW Sidewalk	1681	Ramsey Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 640	3	Excellent		
PROW Sidewalk	1682	Stacy Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Excellent		
PROW Sidewalk	1683	Malli Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 200	3	Excellent		
PROW Sidewalk	1689	Depaul Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Excellent		
PROW Sidewalk	1692	Berkley Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 270	3	Excellent		
PROW Sidewalk	1694	Cedar Creek Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 180	3	Excellent		
PROW Sidewalk	1699	Russell Newman Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,070	3	Excellent		
PROW Sidewalk	1710	Comer St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 790	3	Excellent		
PROW Sidewalk	1713	Mckamy Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	1716	Doris Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Excellent		
PROW Sidewalk	1717	Skelton St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		
PROW Sidewalk	1721	Parkplace Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,310	3	Excellent		
PROW Sidewalk	1722	Brookside Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,170	3	Excellent		
PROW Sidewalk	1723	Meadowpark Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,010	3	Excellent		
PROW Sidewalk	1724	Trailridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	3	Excellent		
PROW Sidewalk	1726	Havenway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Excellent		
PROW Sidewalk	1727	Lakeway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 700	3	Excellent		
PROW Sidewalk	1732	Meadowglen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 820	3	Excellent		
PROW Sidewalk	1733	Trailside Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	1735	Meandering Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,770	3	Excellent		
PROW Sidewalk	1736	Education Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Excellent		
PROW Sidewalk	1742	Club View Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,280	3	Excellent		
PROW Sidewalk	1743	Fairway Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 100	3	Excellent		
PROW Sidewalk	1744	Creek View Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 50	3	Excellent		
PROW Sidewalk	1748	Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,330	3	Excellent		
PROW Sidewalk	1751	Lipizzan Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 6,900	3	Excellent		
PROW Sidewalk	1752	Breton Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,110	3	Excellent		
PROW Sidewalk	1756	Lusitano Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	1760	Lance Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,660	3	Excellent		
PROW Sidewalk	1761	Pres Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 620	3	Excellent		
PROW Sidewalk	1762	Chase Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,100	3	Excellent		
PROW Sidewalk	1764	Cyrus Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Excellent		
PROW Sidewalk	1765	Teal Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	1768	Canton Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,380	3	Excellent		
PROW Sidewalk	1784	Stockbridge Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,090	3	Excellent		
PROW Sidewalk	1785	Quail Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 870	3	Excellent		
PROW Sidewalk	1786	Berry Down Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Excellent		
PROW Sidewalk	1789	Beall St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 320	3	Excellent		
PROW Sidewalk	1790	Bay Meadow Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,720	3	Excellent		
PROW Sidewalk	1792	Aqueduct Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 690	3	Excellent		
PROW Sidewalk	1793	Hialeah Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Excellent		
PROW Sidewalk	1794	Pinot Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 170	3	Excellent		
PROW Sidewalk	1795	Riesling Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 420	3	Excellent		
PROW Sidewalk	1796	Rhone Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 610	3	Excellent		
PROW Sidewalk	1800	Thackery Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,270	3	Excellent		
PROW Sidewalk	1804	Thoroughbred Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 700	3	Excellent		
PROW Sidewalk	1806	Thistle Ridge	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 440	3	Excellent		
PROW Sidewalk	1807	Matthew Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 190	3	Excellent		
PROW Sidewalk	1808	Blackberry Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 670	3	Excellent		
PROW Sidewalk	1809	Cheek St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 310	3	Excellent		
PROW Sidewalk	1810	Vickery Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	1811	Thistle Hill	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 340	3	Excellent		
PROW Sidewalk	1812	Thistle Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 800	3	Excellent		
PROW Sidewalk	1813	Ricks Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 380	3	Excellent		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1815	Prescott Downs Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,310	3	Excellent		
PROW Sidewalk	1822	Prominence Pkwy	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 940	3	Excellent		
PROW Sidewalk	1823	Raleigh Path	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,920	3	Excellent		
PROW Sidewalk	1824	Tallahassee Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Excellent		
PROW Sidewalk	1825	Atlanta Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 990	3	Excellent		
PROW Sidewalk	1826	Trenton Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Excellent		
PROW Sidewalk	1827	Madison Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Excellent		
PROW Sidewalk	1828	Springfield St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 600	3	Excellent		
PROW Sidewalk	1829	Unicorn Lake Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 8,750	3	Excellent		
PROW Sidewalk	1830	Englefield Green	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 720	3	Excellent		
PROW Sidewalk	1831	Savill Garden	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10	3	Excellent		
PROW Sidewalk	1832	Windsor Farms Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	3	Excellent		
PROW Sidewalk	1833	Bray Village Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Excellent		
PROW Sidewalk	1834	Eton Place	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 510	3	Excellent		
PROW Sidewalk	1837	English Manor Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,790	3	Excellent		
PROW Sidewalk	1838	Lost Pony Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	1841	Bareback Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,520	3	Excellent		
PROW Sidewalk	1843	Paddock Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,050	3	Excellent		
PROW Sidewalk	1846	Saddleback Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 170	3	Excellent		
PROW Sidewalk	1847	Rugby Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	3	Excellent		
PROW Sidewalk	1871	Hallum Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	3	Excellent		
PROW Sidewalk	1873	Pecan Grove Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 350	3	Excellent		
PROW Sidewalk	1874	Aspenhill Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Excellent		
PROW Sidewalk	1875	Silver Sage Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 560	3	Excellent		
PROW Sidewalk	1876	Springtree St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,160	3	Excellent		
PROW Sidewalk	1877	Water Oak Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,700	3	Excellent		
PROW Sidewalk	1878	Union Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 920	3	Excellent		
PROW Sidewalk	1880	Shelby Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 520	3	Excellent		
PROW Sidewalk	1881	Dakota Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,960	3	Excellent		
PROW Sidewalk	1882	Dana Lane	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,490	3	Excellent		
PROW Sidewalk	1887	Saddle Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,400	3	Excellent		
PROW Sidewalk	1893	Highpoint Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,550	3	Excellent		
PROW Sidewalk	1896	Spyglass Hill Lane	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	3	Excellent		
PROW Sidewalk	1897	Pebble Beach Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 810	3	Excellent		
PROW Sidewalk	1898	Soledad Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,060	3	Excellent		
PROW Sidewalk	1900	Windy Point Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 660	3	Excellent		
PROW Sidewalk	1901	Cliffside Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	3	Excellent		
PROW Sidewalk	1902	Surf St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	3	Excellent		
PROW Sidewalk	1903	Oceanview Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,950	3	Excellent		
PROW Sidewalk	1904	Camino Real Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,950	3	Excellent		
PROW Sidewalk	1905	Dolores Place	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,200	3	Excellent		
PROW Sidewalk	1906	Galante Lane	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Excellent		
PROW Sidewalk	1907	Del Rey Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,430	3	Excellent		
PROW Sidewalk	1908	San Lucas Lane	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,890	3	Excellent		
PROW Sidewalk	1909	Monte Verde Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,630	3	Excellent		
PROW Sidewalk	1910	Fairmount Park Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,890	3	Excellent		
PROW Sidewalk	1911	Meadowedge Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	3	Excellent		
PROW Sidewalk	1913	Fallmeadow St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,400	3	Excellent		
PROW Sidewalk	1914	Tawakoni Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,430	3	Excellent		
PROW Sidewalk	1915	Eagle Mountain Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 920	3	Excellent		
PROW Sidewalk	1916	Gilmer Way Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 80	3	Excellent		
PROW Sidewalk	1917	Granbury Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	3	Excellent		
PROW Sidewalk	1918	Millers Creek Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Excellent		
PROW Sidewalk	1919	Balmorhea Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Excellent		
PROW Sidewalk	1920	Toledo Bend Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 160	3	Excellent		
PROW Sidewalk	1921	Amistad Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 330	3	Excellent		
PROW Sidewalk	1922	Athens Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,970	3	Excellent		
PROW Sidewalk	1924	Clarendon Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 800	3	Excellent		
PROW Sidewalk	1925	Westglen Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,280	3	Excellent		
PROW Sidewalk	1926	Central Village Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20	3	Excellent		
PROW Sidewalk	1927	Pecan Tree Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 110	3	Excellent		
PROW Sidewalk	1929	Mark Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	1930	Matt Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 60	3	Excellent		
PROW Sidewalk	1943	Bishop Pine Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,990	3	Excellent		
PROW Sidewalk	1945	Evening Wind Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,800	3	Excellent		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	1946	Capetown Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,700	3	Excellent		
PROW Sidewalk	1961	Medpark Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,110	3	Excellent		
PROW Sidewalk	1962	Somerest Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 10	3	Excellent		
PROW Sidewalk	1963	Barrymore Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Excellent		
PROW Sidewalk	1964	Jackpine Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 280	3	Excellent		
PROW Sidewalk	1965	Hinkley Oak Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,480	3	Excellent		
PROW Sidewalk	1966	Hinkley Oak Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Excellent		
PROW Sidewalk	1967	Sweetgate Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,470	3	Excellent		
PROW Sidewalk	1968	Valley Stream Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 450	3	Excellent		
PROW Sidewalk	1969	Caribou Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 220	3	Excellent		
PROW Sidewalk	1970	Barrydale Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Excellent		
PROW Sidewalk	1971	Potterstone St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,240	3	Excellent		
PROW Sidewalk	1972	Buckthorn Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,410	3	Excellent		
PROW Sidewalk	1973	Stonecrop Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 940	3	Excellent		
PROW Sidewalk	1975	Mockernut Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 230	3	Excellent		
PROW Sidewalk	1976	Loblolly Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Excellent		
PROW Sidewalk	1977	Tucker Trail	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 180	3	Excellent		
PROW Sidewalk	1979	Shagbark Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	3	Excellent		
PROW Sidewalk	1980	Joe Van Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 230	3	Excellent		
PROW Sidewalk	1981	Hornbeam St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,350	3	Excellent		
PROW Sidewalk	1982	Blake St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 780	3	Excellent		
PROW Sidewalk	1990	Shoreline	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 610	3	Excellent		
PROW Sidewalk	1992	Elysian St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 660	3	Excellent		
PROW Sidewalk	1996	Bonita Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 690	3	Excellent		
PROW Sidewalk	1997	Miranda Place	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,330	3	Excellent		
PROW Sidewalk	1998	Alta Vista Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 960	3	Excellent		
PROW Sidewalk	1999	Redondo Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 140	3	Excellent		
PROW Sidewalk	2052	Trailhead Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Excellent		
PROW Sidewalk	2053	Wagon Trail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Excellent		
PROW Sidewalk	2054	Wrangler Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 420	3	Excellent		
PROW Sidewalk	2055	N. Western Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 580	3	Excellent		
PROW Sidewalk	2056	S. Western Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 7,080	3	Excellent		
PROW Sidewalk	2486	Red Wolfe Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,050	3	Excellent		
PROW Sidewalk	2487	Barnhill Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 230	3	Excellent		
PROW Sidewalk	2488	Apple Valley Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 160	3	Excellent		
PROW Sidewalk	2489	Remuda Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 340	3	Excellent		
PROW Sidewalk	2490	Hidden Meadows Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,920	3	Excellent		
PROW Sidewalk	2491	Forrest Willow Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 380	3	Excellent		
PROW Sidewalk	2492	Autumn Path Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 970	3	Excellent		
PROW Sidewalk	2493	Glen Crest Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,670	3	Excellent		
PROW Sidewalk	2494	Town Center Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	2497	Frontier Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 5,000	3	Excellent		
PROW Sidewalk	2499	Pioneer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,960	3	Excellent		
PROW Sidewalk	2506	El Dorado Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,550	3	Excellent		
PROW Sidewalk	2508	Knoll Pines Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,090	3	Excellent		
PROW Sidewalk	2509	Glenwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 750	3	Excellent		
PROW Sidewalk	2510	Longmont Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 610	3	Excellent		
PROW Sidewalk	2511	Loveland Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 460	3	Excellent		
PROW Sidewalk	2512	Salida Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Excellent		
PROW Sidewalk	2513	Gunnison Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,270	3	Excellent		
PROW Sidewalk	2514	Green River Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,240	3	Excellent		
PROW Sidewalk	2515	Wasatch Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	Excellent		
PROW Sidewalk	2516	Tamarack Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,850	3	Excellent		
PROW Sidewalk	2518	Benbrook Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 330	3	Excellent		
PROW Sidewalk	2519	New Ballinger Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,130	3	Excellent		
PROW Sidewalk	2520	Wichita Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,210	3	Excellent		
PROW Sidewalk	2521	Sweetwater Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 180	3	Excellent		
PROW Sidewalk	2522	Hawks View Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 820	3	Excellent		
PROW Sidewalk	2523	Key Largo Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 180	3	Excellent		
PROW Sidewalk	2524	Apple Valley Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,120	3	Excellent		
PROW Sidewalk	2525	Summer Oaks Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 680	3	Excellent		
PROW Sidewalk	2526	Summer Trail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,040	3	Excellent		
PROW Sidewalk	2527	Spring Meadows Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 970	3	Excellent		
PROW Sidewalk	2528	Fall Leaf Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,290	3	Excellent		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	2529	Split Rock Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 240	3	Excellent		
PROW Sidewalk	2530	Cuddy Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,740	3	Excellent		
PROW Sidewalk	2531	Rockcrest Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 300	3	Excellent		
PROW Sidewalk	2532	Windhaven Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,570	3	Excellent		
PROW Sidewalk	2533	Crosstrees Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,880	3	Excellent		
PROW Sidewalk	2534	Ringtail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 800	3	Excellent		
PROW Sidewalk	2535	Commodore Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	3	Excellent		
PROW Sidewalk	2536	Roxbury St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,100	3	Excellent		
PROW Sidewalk	2537	Leonis Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,920	3	Excellent		
PROW Sidewalk	2538	Hialeah Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,800	3	Excellent		
PROW Sidewalk	2539	Nob Hill Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 880	3	Excellent		
PROW Sidewalk	2543	Pavilion Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	3	Excellent		
PROW Sidewalk	2545	Vineland Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 400	3	Excellent		
PROW Sidewalk	2549	Sea Cove Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,290	3	Excellent		
PROW Sidewalk	2550	Peninsula Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 470	3	Excellent		
PROW Sidewalk	2551	Wharfside Pl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,360	3	Excellent		
PROW Sidewalk	2552	Marina Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,270	3	Excellent		
PROW Sidewalk	2553	Bayshore Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 280	3	Excellent		
PROW Sidewalk	2554	Pelican Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 160	3	Excellent		
PROW Sidewalk	2555	Seaside Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 840	3	Excellent		
PROW Sidewalk	2556	Wavecrest Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 490	3	Excellent		
PROW Sidewalk	2557	Del Rey Cir	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 90	3	Excellent		
PROW Sidewalk	2558	Rushing Creek	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 130	3	Excellent		
PROW Sidewalk	2559	Roaring Creek	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 4,260	3	Excellent		
PROW Sidewalk	2560	Las Lomas Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Excellent		
PROW Sidewalk	2577	Cabrillo Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 540	3	Excellent		
PROW Sidewalk	2579	Moonsail Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,230	3	Excellent		
PROW Sidewalk	2580	Dawn Oaks Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 770	3	Excellent		
PROW Sidewalk	2581	Hudson Bay Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Excellent		
PROW Sidewalk	2582	Juniperio St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 650	3	Excellent		
PROW Sidewalk	2583	Harbour Mist Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,260	3	Excellent		
PROW Sidewalk	2584	Anchor Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	3	Excellent		
PROW Sidewalk	2585	Masthead Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Excellent		
PROW Sidewalk	2586	Armstrong St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,650	3	Excellent		
PROW Sidewalk	2587	Megan St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 830	3	Excellent		
PROW Sidewalk	2588	Province St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 600	3	Excellent		
PROW Sidewalk	2589	Dominion St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,060	3	Excellent		
PROW Sidewalk	2590	Realm St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 20	3	Excellent		
PROW Sidewalk	2602	Stonetrail Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 410	3	Excellent		
PROW Sidewalk	2603	Red Fox Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 800	3	Excellent		
PROW Sidewalk	2604	Lemon Mint Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 430	3	Excellent		
PROW Sidewalk	2605	Cypress Creek Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 710	3	Excellent		
PROW Sidewalk	2606	Fawn Ridge Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Excellent		
PROW Sidewalk	2607	Lost Creek Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 390	3	Excellent		
PROW Sidewalk	2609	Poppy Valley Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 290	3	Excellent		
PROW Sidewalk	2610	Sky Meadow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 320	3	Excellent		
PROW Sidewalk	2611	Castle Pines Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 930	3	Excellent		
PROW Sidewalk	2613	Falcon Ridge Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 210	3	Excellent		
PROW Sidewalk	2614	Echo Hill Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 630	3	Excellent		
PROW Sidewalk	2615	Alders Gate Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 30	3	Excellent		
PROW Sidewalk	2617	Beaver Creek Ave	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 3,180	3	Excellent		
PROW Sidewalk	2618	Shy Creek Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 370	3	Excellent		
PROW Sidewalk	2619	Summer Stream Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,150	3	Excellent		
PROW Sidewalk	2620	Princewood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,450	3	Excellent		
PROW Sidewalk	2621	Stillhouse Hollow Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,020	3	Excellent		
PROW Sidewalk	2622	Lake Fork Trl	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 610	3	Excellent		
PROW Sidewalk	2623	Marble Falls Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 240	3	Excellent		
PROW Sidewalk	2624	Creekmere Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	3	Excellent		
PROW Sidewalk	2625	Mudstone Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	2626	Meadowtrail Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 730	3	Excellent		
PROW Sidewalk	2627	Ann Arbor Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 440	3	Excellent		
PROW Sidewalk	2628	Empire St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 490	3	Excellent		
PROW Sidewalk	2629	Conroe Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 530	3	Excellent		
PROW Sidewalk	2630	Chicory Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 330	3	Excellent		
PROW Sidewalk	2631	Chicory Ct	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 320	3	Excellent		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Sidewalk	2632	Grassland Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 570	3	Excellent		
PROW Sidewalk	2633	Goldfinch Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 770	3	Excellent		
PROW Sidewalk	2634	Oakbluff Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,660	3	Excellent		
PROW Sidewalk	2635	Eaglesstone Way	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 270	3	Excellent		
PROW Sidewalk	2636	Brentwood Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 120	3	Excellent		
PROW Sidewalk	2637	Greystone Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 40	3	Excellent		
PROW Sidewalk	2639	Davenport Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 190	3	Excellent		
PROW Sidewalk	2640	Becker Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 590	3	Excellent		
PROW Sidewalk	2641	Canongate Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 150	3	Excellent		
PROW Sidewalk	2643	Corsair Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 240	3	Excellent		
PROW Sidewalk	2644	Gennaker Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 2,910	3	Excellent		
PROW Sidewalk	2646	Carmel Hills Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 70	3	Excellent		
PROW Sidewalk	2647	Portola Ln	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 360	3	Excellent		
PROW Sidewalk	107	N Bonnie Brae St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	3	No Sidewalk		
PROW Sidewalk	262	Denison St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	3	No Sidewalk		
PROW Sidewalk	280	W Eagle Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,500	3	No Sidewalk		
PROW Sidewalk	660	W Oak St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	3	No Sidewalk		
PROW Sidewalk	697	Palmer Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,250	3	No Sidewalk		
PROW Sidewalk	742	E Prairie St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	No Sidewalk		
PROW Sidewalk	767	Regal Dr	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 250	3	No Sidewalk		
PROW Sidewalk	794	E Ryan Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,500	3	No Sidewalk		
PROW Sidewalk	920	Valley View Rd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	3	No Sidewalk		
PROW Sidewalk	935	S Welch St	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 1,000	3	No Sidewalk		
PROW Sidewalk	2055	N. Western Blvd	N/A	See facility report and GIS data for detailed sidewalk evaluation findings.	\$ 500	3	No Sidewalk		
PROW Intersection	1000	Intersection of Meandering Creek Dr and Woodland Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meandering Creek Dr and Woodland Trl	\$ 800	N/A **	N/A **		
PROW Intersection	1001	Intersection of Old Alton Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Old Alton Rd and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	1002	Intersection of John Paine Rd and Meandering Creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of John Paine Rd and Meandering Creek Dr	\$ 10,600	N/A **	N/A **		
PROW Intersection	1003	Intersection of Education Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Education Dr and Driveway	\$ 300	N/A **	N/A **		
PROW Intersection	1004	Intersection of Meandering Creek Dr and Education Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meandering Creek Dr and Education Dr	\$ 7,000	N/A **	N/A **		
PROW Intersection	1005	Intersection of Creekway Dr and Parkview Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekway Dr and Parkview Ln	\$ 9,000	N/A **	N/A **		
PROW Intersection	1006	Intersection of Meandering Creek Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meandering Creek Dr and Midblock Crossing	\$ 6,000	N/A **	N/A **		
PROW Intersection	1007	Intersection of John Paine Rd and Creekway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of John Paine Rd and Creekway Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1008	Intersection of Brookside Dr and Parkplace Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookside Dr and Parkplace Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1009	Intersection of Roaring Creek and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roaring Creek and Cul-De-Sac	\$ 4,200	N/A **	N/A **		
PROW Intersection	1010	Intersection of Brookside Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookside Dr and Midblock Crossing	\$ 800	N/A **	N/A **		
PROW Intersection	1011	Intersection of Parkplace Dr and Lakeway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Parkplace Dr and Lakeway Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1012	Intersection of Roaring Creek and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roaring Creek and Midblock Crossing	\$ 1,000	N/A **	N/A **		
PROW Intersection	1013	Intersection of Parkplace Dr and Havenway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Parkplace Dr and Havenway Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1014	Intersection of Parkplace Dr and Creekway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Parkplace Dr and Creekway Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1015	Intersection of Meandering Creek Dr and Rushing Creek	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meandering Creek Dr and Rushing Creek	\$ 7,500	N/A **	N/A **		
PROW Intersection	1016	Intersection of Meandering Creek Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meandering Creek Dr and Driveway	\$ 9,000	N/A **	N/A **		
PROW Intersection	1017	Intersection of Meandering Creek Dr and Carnegie Ridge	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meandering Creek Dr and Carnegie Ridge	\$ 4,100	N/A **	N/A **		
PROW Intersection	1018	Intersection of Meandering Creek Dr and Creekmere Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meandering Creek Dr and Creekmere Dr	\$ 7,000	N/A **	N/A **		
PROW Intersection	1020	Intersection of Brookside Dr and Lakeway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookside Dr and Lakeway Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	1021	Intersection of Parkplace Dr and Meadow Creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Parkplace Dr and Meadow Creek Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1022	Intersection of Roaring Creek and Rushing Creek	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roaring Creek and Rushing Creek	\$ 3,700	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1023	Intersection of Parkplace Dr and Trailway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Parkplace Dr and Trailway Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1024	Intersection of Brookside Dr and Havenway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookside Dr and Havenway Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	1025	Intersection of Parkplace Dr and John Paine Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Parkplace Dr and John Paine Rd	\$ 6,000	N/A **	N/A **		
PROW Intersection	1026	Intersection of Parkplace Dr and Garden Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Parkplace Dr and Garden Ct	\$ 9,000	N/A **	N/A **		
PROW Intersection	1027	Intersection of Brookside Dr and Meadowpark Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookside Dr and Meadowpark Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1028	Intersection of Lakeway Dr and Marble Falls Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeway Dr and Marble Falls Dr	\$ 6,400	N/A **	N/A **		
PROW Intersection	1029	Intersection of Meadowcreek Dr and Meadowglen Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadowcreek Dr and Meadowglen Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1030	Intersection of Meadowglen Dr and Waterhaven Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadowglen Dr and Waterhaven Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1031	Intersection of Meadowglen Dr and Trailway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadowglen Dr and Trailway Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1032	Intersection of Balmorhea Dr and Meadowpark Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Balmorhea Dr and Meadowpark Dr	\$ 7,300	N/A **	N/A **		
PROW Intersection	1033	Intersection of Seven Oaks Ln and Glen Falls Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Seven Oaks Ln and Glen Falls Ln	\$ 7,500	N/A **	N/A **		
PROW Intersection	1034	Intersection of Lakeway Dr and Havenway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeway Dr and Havenway Dr	\$ 10,700	N/A **	N/A **		
PROW Intersection	1035	Intersection of Brookside Dr and Meadow Creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookside Dr and Meadow Creek Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	1036	Intersection of Balmorhea Dr and Toledo Bend	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Balmorhea Dr and Toledo Bend	\$ 11,800	N/A **	N/A **		
PROW Intersection	1037	Intersection of Brookside Dr and Greenmeadow Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookside Dr and Greenmeadow Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1038	Intersection of Brookside Dr and Trailridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookside Dr and Trailridge Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1039	Intersection of Stillhouse Hollow Ln and Nocona Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stillhouse Hollow Ln and Nocona Dr	\$ 8,100	N/A **	N/A **		
PROW Intersection	1040	Intersection of Seven Oaks Ln and Harvest Moon Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Seven Oaks Ln and Harvest Moon Trl	\$ 7,500	N/A **	N/A **		
PROW Intersection	1041	Intersection of Stillhouse Hollow Ln and Little Fork Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stillhouse Hollow Ln and Little Fork Trl	\$ 6,700	N/A **	N/A **		
PROW Intersection	1043	Intersection of Brookside Dr and Trailside Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookside Dr and Trailside Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1044	Intersection of Balmorhea Dr and Trailridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Balmorhea Dr and Trailridge Dr	\$ 16,800	N/A **	N/A **		
PROW Intersection	1045	Intersection of Toledo Bend and Millers Creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Toledo Bend and Millers Creek Dr	\$ 8,600	N/A **	N/A **		
PROW Intersection	1046	Intersection of Amistad Ln and John Paine Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Amistad Ln and John Paine Rd	\$ 9,300	N/A **	N/A **		
PROW Intersection	1047	Intersection of John Paine Rd and Trailside Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of John Paine Rd and Trailside Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1048	Intersection of Granbury Dr and Balmorhea Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Granbury Dr and Balmorhea Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1049	Intersection of John Paine Rd and Gilmer Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of John Paine Rd and Gilmer Way	\$ 19,800	N/A **	N/A **		
PROW Intersection	1050	Intersection of Athens Ln and Meadowpark Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Athens Ln and Meadowpark Dr	\$ 4,000	N/A **	N/A **		
PROW Intersection	1051	Intersection of Athens Ln and Toledo Bend Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Athens Ln and Toledo Bend Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1052	Intersection of Amistad Ln and Eagle Mountain Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Amistad Ln and Eagle Mountain Dr	\$ 21,300	N/A **	N/A **		
PROW Intersection	1053	Intersection of Seven Oaks Ln and Swan Park Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Seven Oaks Ln and Swan Park Dr	\$ 10,000	N/A **	N/A **		
PROW Intersection	1054	Intersection of Millers Creek Dr and Granbury Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Millers Creek Dr and Granbury Dr	\$ 6,700	N/A **	N/A **		
PROW Intersection	1055	Intersection of Gilmer Way and Eagle Mountain Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gilmer Way and Eagle Mountain Dr	\$ 10,500	N/A **	N/A **		
PROW Intersection	1056	Intersection of Athens Ln and Conroe Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Athens Ln and Conroe Dr	\$ 13,100	N/A **	N/A **		
PROW Intersection	1057	Intersection of Glen Falls Ln and Blue Sky Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glen Falls Ln and Blue Sky Ln	\$ 8,300	N/A **	N/A **		
PROW Intersection	1058	Intersection of Amistad Ln and Tawakoni Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Amistad Ln and Tawakoni Dr	\$ 15,100	N/A **	N/A **		
PROW Intersection	1059	Intersection of Athens Ln and Grandbury Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Athens Ln and Grandbury Dr	\$ 13,500	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1060	Intersection of Seven Oaks Ln and Serenity Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Seven Oaks Ln and Serenity Way	\$ 7,500	N/A **	N/A **		
PROW Intersection	1061	Intersection of Athens Ln and John Paine Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Athens Ln and John Paine Rd	\$ 22,800	N/A **	N/A **		
PROW Intersection	1062	Intersection of Glen Falls Ln and Swan Park Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glen Falls Ln and Swan Park Dr	\$ 16,000	N/A **	N/A **		
PROW Intersection	1063	Intersection of Mild Creek Ln and Rambling Brook Trail	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mild Creek Ln and Rambling Brook Trail	\$ 6,500	N/A **	N/A **		
PROW Intersection	1064	Intersection of Clear River Ln and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clear River Ln and Cul-De-Sac	\$ 6,500	N/A **	N/A **		
PROW Intersection	1065	Intersection of Seven Oaks Ln and Rambling Brook Trail	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Seven Oaks Ln and Rambling Brook Trail	\$ 7,500	N/A **	N/A **		
PROW Intersection	1066	Intersection of Athens Ln and Eagle Mountain Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Athens Ln and Eagle Mountain Dr	\$ 18,800	N/A **	N/A **		
PROW Intersection	1067	Intersection of New Ballinger Dr and Amistad Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of New Ballinger Dr and Amistad Ln	\$ 21,300	N/A **	N/A **		
PROW Intersection	1068	Intersection of Conroe Dr and Texoma Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Conroe Dr and Texoma Ln	\$ 900	N/A **	N/A **		
PROW Intersection	1069	Intersection of Glen Falls Ln and Serenity Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glen Falls Ln and Serenity Way	\$ 9,000	N/A **	N/A **		
PROW Intersection	1070	Intersection of New Ballinger Dr and Wichita Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of New Ballinger Dr and Wichita Ln	\$ 10,500	N/A **	N/A **		
PROW Intersection	1071	Intersection of Athens Ln and Tawakoni Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Athens Ln and Tawakoni Dr	\$ 7,400	N/A **	N/A **		
PROW Intersection	1072	Intersection of Athens Ln and New Ballinger Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Athens Ln and New Ballinger Dr	\$ 18,600	N/A **	N/A **		
PROW Intersection	1073	Intersection of Glen Falls Ln and Early Dawn Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glen Falls Ln and Early Dawn Trl	\$ 9,000	N/A **	N/A **		
PROW Intersection	1074	Intersection of Seven Oaks Ln and Glen Falls Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Seven Oaks Ln and Glen Falls Ln	\$ 7,800	N/A **	N/A **		
PROW Intersection	1075	Intersection of Clear River Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clear River Ln and Midblock Crossing	\$ 5,300	N/A **	N/A **		
PROW Intersection	1076	Intersection of Montecito Dr and Charter Bend	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Charter Bend	\$ 9,000	N/A **	N/A **		
PROW Intersection	1077	Intersection of Montecito Dr and Field Bend Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Field Bend Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1078	Intersection of Montecito Dr and Settlement	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Settlement	\$ 8,500	N/A **	N/A **		
PROW Intersection	1079	Intersection of Montecito Dr and Swan Park	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Swan Park	\$ 9,300	N/A **	N/A **		
PROW Intersection	1080	Intersection of Montecito Dr and Serenity Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Serenity Way	\$ 9,300	N/A **	N/A **		
PROW Intersection	1081	Intersection of Clear River Ln and Sweet Cloud Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clear River Ln and Sweet Cloud Way	\$ 5,300	N/A **	N/A **		
PROW Intersection	1082	Intersection of Sweet Cloud Way and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sweet Cloud Way and Midblock Crossing	\$ 4,500	N/A **	N/A **		
PROW Intersection	1083	Intersection of Canoe Ridge Ln and Sweet Cloud Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Canoe Ridge Ln and Sweet Cloud Way	\$ 4,500	N/A **	N/A **		
PROW Intersection	1084	Intersection of Winding Stream Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Winding Stream Dr and Corridor End	\$ 6,500	N/A **	N/A **		
PROW Intersection	1085	Intersection of Montecito Dr and Hidden Path Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Hidden Path Ln	\$ 8,000	N/A **	N/A **		
PROW Intersection	1086	Intersection of Montecito Dr and Mirror Rock Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Mirror Rock Ln	\$ 7,800	N/A **	N/A **		
PROW Intersection	1087	Intersection of Montecito Dr and Seven Oaks Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Seven Oaks Ln	\$ 14,300	N/A **	N/A **		
PROW Intersection	1088	Intersection of Acorn Bend Rd and Field Bend Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Acorn Bend Rd and Field Bend Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1089	Intersection of Montecito Dr and Hazel Wood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Hazel Wood Dr	\$ 10,000	N/A **	N/A **		
PROW Intersection	1090	Intersection of Fairway Dr and Clubview Ct (West)	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fairway Dr and Clubview Ct (West)	\$ 3,600	N/A **	N/A **		
PROW Intersection	1091	Intersection of Fairway Dr and Clubview Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fairway Dr and Clubview Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	1092	Intersection of Fairway Dr and Clubview Ct (East)	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fairway Dr and Clubview Ct (East)	\$ 12,000	N/A **	N/A **		
PROW Intersection	1093	Intersection of Sweetwater Dr and Athens Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sweetwater Dr and Athens Ln	\$ 12,000	N/A **	N/A **		
PROW Intersection	1094	Intersection of Sweetwater Dr and Wichita Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sweetwater Dr and Wichita Ln	\$ 15,300	N/A **	N/A **		
PROW Intersection	1095	Intersection of Lighthouse Dr and Stonehaven Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lighthouse Dr and Stonehaven Dr	\$ 8,900	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1096	Intersection of Montecito Dr and Clear River Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Clear River Ln	\$ 9,000	N/A **	N/A **		
PROW Intersection	1097	Intersection of Lighthouse Dr and Rockcrest Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lighthouse Dr and Rockcrest Dr	\$ 8,100	N/A **	N/A **		
PROW Intersection	1098	Intersection of Lighthouse Dr and Atlantic Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lighthouse Dr and Atlantic Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1099	Intersection of Lighthouse Dr and Nautical Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lighthouse Dr and Nautical Ln	\$ 11,900	N/A **	N/A **		
PROW Intersection	1100	Intersection of Fm2181 and Lighthouse Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm2181 and Lighthouse Dr	\$ 4,500	N/A **	N/A **		
PROW Intersection	1101	Intersection of Fm2181 and Lighthouse Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm2181 and Lighthouse Dr	\$ 7,100	N/A **	N/A **		
PROW Intersection	1102	Intersection of Lighthouse Dr and Coral Cove	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lighthouse Dr and Coral Cove	\$ 11,800	N/A **	N/A **		
PROW Intersection	1103	Intersection of Lighthouse Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lighthouse Dr and Driveway	\$ 10,300	N/A **	N/A **		
PROW Intersection	1104	Intersection of Lighthouse Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lighthouse Dr and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1105	Intersection of Fairway Dr and Fort Worth Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fairway Dr and Fort Worth Dr	\$ 3,000	N/A **	N/A **		
PROW Intersection	1106	Intersection of Clear River Ln and Cherry Tree Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clear River Ln and Cherry Tree Ln	\$ 4,500	N/A **	N/A **		
PROW Intersection	1107	Intersection of Seven Oaks Ln and Clear River Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Seven Oaks Ln and Clear River Ln	\$ 8,000	N/A **	N/A **		
PROW Intersection	1108	Intersection of Clear River Ln and Eagle Wing Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clear River Ln and Eagle Wing Ln	\$ 8,100	N/A **	N/A **		
PROW Intersection	1109	Intersection of Canoe Ridge Ln and Golden Sand Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Canoe Ridge Ln and Golden Sand Dr	\$ 8,500	N/A **	N/A **		
PROW Intersection	1110	Intersection of Montecito Dr and Golden Sand Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Golden Sand Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1111	Intersection of Windhaven Dr and Stonehaven Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windhaven Dr and Stonehaven Dr	\$ 9,400	N/A **	N/A **		
PROW Intersection	1112	Intersection of Settlement Dr and Shoal Bend	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Settlement Dr and Shoal Bend	\$ 7,500	N/A **	N/A **		
PROW Intersection	1113	Intersection of Ocean Dr and Atlantic Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ocean Dr and Atlantic Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1114	Intersection of Ocean Dr and Coral Cove	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ocean Dr and Coral Cove	\$ 7,700	N/A **	N/A **		
PROW Intersection	1115	Intersection of Ocean Dr and Nautical Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ocean Dr and Nautical Ln	\$ 17,700	N/A **	N/A **		
PROW Intersection	1116	Intersection of Sh2499 and Ocean Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sh2499 and Ocean Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1117	Intersection of Canoe Ridge Ln and Silent Star Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Canoe Ridge Ln and Silent Star Ln	\$ 5,300	N/A **	N/A **		
PROW Intersection	1118	Intersection of Winding Stream Dr and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Winding Stream Dr and Cul-De-Sac	\$ 6,500	N/A **	N/A **		
PROW Intersection	1119	Intersection of Montecito Dr and Silent Star Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Silent Star Ln	\$ 7,000	N/A **	N/A **		
PROW Intersection	1120	Intersection of Nautical Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nautical Ln and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	1121	Intersection of Clubview Dr and Creekview Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clubview Dr and Creekview Ct	\$ 10,100	N/A **	N/A **		
PROW Intersection	1122	Intersection of Montecito Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	1123	Intersection of Montecito Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	1124	Intersection of Swan Park Dr and White Dove Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Swan Park Dr and White Dove Ln	\$ 5,800	N/A **	N/A **		
PROW Intersection	1125	Intersection of White Dove Ln and Serenity Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of White Dove Ln and Serenity Way	\$ 10,300	N/A **	N/A **		
PROW Intersection	1126	Intersection of White Dove Ln and Hidden Path Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of White Dove Ln and Hidden Path Ln	\$ 7,500	N/A **	N/A **		
PROW Intersection	1127	Intersection of Montecito Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Driveway	\$ 500	N/A **	N/A **		
PROW Intersection	1128	Intersection of White Dove Ln and Mirror Rock Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of White Dove Ln and Mirror Rock Ln	\$ 8,300	N/A **	N/A **		
PROW Intersection	1129	Intersection of White Dove Ln and Seven Oaks Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of White Dove Ln and Seven Oaks Ln	\$ 7,500	N/A **	N/A **		
PROW Intersection	1130	Intersection of White Dove Ln and Rushing Spring Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of White Dove Ln and Rushing Spring Dr	\$ 8,300	N/A **	N/A **		
PROW Intersection	1131	Intersection of Clubview Dr and Sawgrass Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clubview Dr and Sawgrass Ln	\$ 15,000	N/A **	N/A **		
PROW Intersection	1132	Intersection of Clubview Dr and Crooked Stick Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clubview Dr and Crooked Stick Ln	\$ 15,000	N/A **	N/A **		
PROW Intersection	1133	Intersection of Crenshaw Ln and Wright Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crenshaw Ln and Wright Ct	\$ 9,000	N/A **	N/A **		
PROW Intersection	1134	Intersection of Crenshaw Ln and Las Brisas Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crenshaw Ln and Las Brisas Ct	\$ 11,000	N/A **	N/A **		
PROW Intersection	1135	Intersection of Nautical Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nautical Ln and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1136	Intersection of Montecito Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	1137	Intersection of Marble Cove Ln and Serenity Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marble Cove Ln and Serenity Way	\$ 9,300	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1138	Intersection of Marble Cove Ln and Rushing Spring Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marble Cove Ln and Rushing Spring Dr	\$ 9,800	N/A **	N/A **		
PROW Intersection	1139	Intersection of Mosspoint Ct and Doecrest Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mosspoint Ct and Doecrest Dr	\$ 10,500	N/A **	N/A **		
PROW Intersection	1140	Intersection of Hickory Creek Rd and Nautical Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Nautical Ln	\$ 6,000	N/A **	N/A **		
PROW Intersection	1141	Intersection of Hickory Creek Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1142	Intersection of Sh2499 and Hickory Creek Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sh2499 and Hickory Creek Rd	\$ 3,800	N/A **	N/A **		
PROW Intersection	1143	Intersection of Montecito Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	1144	Intersection of Hickory Creek Rd and Erin Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Erin Ln	\$ 12,000	N/A **	N/A **		
PROW Intersection	1145	Intersection of Hickory Creek Rd and Serenity Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Serenity Way	\$ 7,500	N/A **	N/A **		
PROW Intersection	1146	Intersection of Hickory Creek Rd and Rushing Spring Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Rushing Spring Dr	\$ 5,500	N/A **	N/A **		
PROW Intersection	1147	Intersection of Hickory Creek Rd and Mosspoint Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Mosspoint Ct	\$ 6,000	N/A **	N/A **		
PROW Intersection	1148	Intersection of Hickory Creek Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	1149	Intersection of Hickory Creek Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Driveway	\$ 1,200	N/A **	N/A **		
PROW Intersection	1150	Intersection of Hickory Creek Rd and Montecito Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Montecito Dr	\$ 11,100	N/A **	N/A **		
PROW Intersection	1151	Intersection of Hickory Creek Rd and Livingston Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Livingston Dr	\$ 3,000	N/A **	N/A **		
PROW Intersection	1152	Intersection of Hickory Creek Rd and Almonte Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Almonte Dr	\$ 3,800	N/A **	N/A **		
PROW Intersection	1153	Intersection of Hickory Creek Rd and Riverpass Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Riverpass Dr	\$ 3,000	N/A **	N/A **		
PROW Intersection	1154	Intersection of Groveland Ter and Erin Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Groveland Ter and Erin Ln	\$ 13,500	N/A **	N/A **		
PROW Intersection	1155	Intersection of Hickory Creek Rd and Waterside Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Waterside Pl	\$ 3,300	N/A **	N/A **		
PROW Intersection	1156	Intersection of Groveland Ter and Lipizzan Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Groveland Ter and Lipizzan Dr	\$ 13,100	N/A **	N/A **		
PROW Intersection	1157	Intersection of Wellston Ln and Groveland Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wellston Ln and Groveland Ct	\$ 19,100	N/A **	N/A **		
PROW Intersection	1158	Intersection of Groveland Ter and Corral Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Groveland Ter and Corral Ln	\$ 19,800	N/A **	N/A **		
PROW Intersection	1159	Intersection of Hickory Creek Rd and Chaucer Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Chaucer Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1160	Intersection of Hickory Creek Rd and Livingston Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hickory Creek Rd and Livingston Dr	\$ 2,300	N/A **	N/A **		
PROW Intersection	1161	Intersection of Sunburst Trl and Dawnlight Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sunburst Trl and Dawnlight Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	1162	Intersection of Dawnlight Dr and Nightfall Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dawnlight Dr and Nightfall Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1163	Intersection of Waterside Pl and Dawnlight Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Waterside Pl and Dawnlight Dr	\$ 3,000	N/A **	N/A **		
PROW Intersection	1164	Intersection of Mira Vista Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mira Vista Dr and Corridor End	\$ 6,000	N/A **	N/A **		
PROW Intersection	1165	Intersection of Wellston Ln and Saddle Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wellston Ln and Saddle Dr	\$ 17,900	N/A **	N/A **		
PROW Intersection	1166	Intersection of Almonte Dr and Buena Vista	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Almonte Dr and Buena Vista	\$ 9,300	N/A **	N/A **		
PROW Intersection	1167	Intersection of Chaucer Dr and Mark Twain Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chaucer Dr and Mark Twain Ln	\$ 9,300	N/A **	N/A **		
PROW Intersection	1168	Intersection of Montecito Dr and Buena Vista Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Buena Vista Dr	\$ 10,400	N/A **	N/A **		
PROW Intersection	1169	Intersection of Frost Ln and Mark Twain Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Frost Ln and Mark Twain Ln	\$ 6,800	N/A **	N/A **		
PROW Intersection	1170	Intersection of Crenshaw Ln and Hayling Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crenshaw Ln and Hayling Way	\$ 13,800	N/A **	N/A **		
PROW Intersection	1171	Intersection of Saddleback Dr and Longleaf Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Saddleback Dr and Longleaf Ln	\$ 13,800	N/A **	N/A **		
PROW Intersection	1172	Intersection of Alderbrook Dr and Crenshaw Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alderbrook Dr and Crenshaw Ln	\$ 10,800	N/A **	N/A **		
PROW Intersection	1173	Intersection of Saddle Dr and Rustic Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Saddle Dr and Rustic Ct	\$ 19,500	N/A **	N/A **		
PROW Intersection	1174	Intersection of Montecito Dr and Vista Verde St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Vista Verde St	\$ 12,300	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1175	Intersection of Mira Vista Dr and Glendora Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mira Vista Dr and Glendora Ct	\$ 9,800	N/A **	N/A **		
PROW Intersection	1177	Intersection of Lipizzan Dr and Corral Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Corral Ln	\$ 15,300	N/A **	N/A **		
PROW Intersection	1178	Intersection of Sunburst Trail and Baybrooke Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sunburst Trail and Baybrooke Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1179	Intersection of Baybrooke Dr and Nightfall Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Baybrooke Dr and Nightfall Dr	\$ 8,600	N/A **	N/A **		
PROW Intersection	1180	Intersection of Purbeck Trl and Swiss Pine Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Purbeck Trl and Swiss Pine Rd	\$ 19,500	N/A **	N/A **		
PROW Intersection	1181	Intersection of Lipizzan Dr and Wellston Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Wellston Ln	\$ 12,900	N/A **	N/A **		
PROW Intersection	1182	Intersection of Waterside Pl and Baybrooke Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Waterside Pl and Baybrooke Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1183	Intersection of Algarve Dr and Swiss Pine Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Algarve Dr and Swiss Pine Rd	\$ 19,500	N/A **	N/A **		
PROW Intersection	1184	Intersection of Montecito Dr and Val Verde Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Val Verde Ct	\$ 7,400	N/A **	N/A **		
PROW Intersection	1185	Intersection of Mira Vista Dr and Cordero Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mira Vista Dr and Cordero Ct	\$ 9,600	N/A **	N/A **		
PROW Intersection	1186	Intersection of Saddleback Dr and Highpoint Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Saddleback Dr and Highpoint Dr	\$ 15,300	N/A **	N/A **		
PROW Intersection	1187	Intersection of Longleaf Ln and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Longleaf Ln and Corridor End	\$ 9,500	N/A **	N/A **		
PROW Intersection	1188	Intersection of Purbeck Trl and Pineoak Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Purbeck Trl and Pineoak Ln	\$ 15,800	N/A **	N/A **		
PROW Intersection	1189	Intersection of Riverchase Trl and Waterside Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Riverchase Trl and Waterside Pl	\$ 8,500	N/A **	N/A **		
PROW Intersection	1190	Intersection of Riverpass Dr and Riverchase Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Riverpass Dr and Riverchase Trl	\$ 4,800	N/A **	N/A **		
PROW Intersection	1191	Intersection of Riverchase Trl and Sunburst Trail	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Riverchase Trl and Sunburst Trail	\$ 12,600	N/A **	N/A **		
PROW Intersection	1192	Intersection of Algarve Dr and Pineoak Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Algarve Dr and Pineoak Ln	\$ 12,800	N/A **	N/A **		
PROW Intersection	1193	Intersection of Lipizzan Dr and Lipizzan Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Lipizzan Ct	\$ 12,000	N/A **	N/A **		
PROW Intersection	1194	Intersection of Mira Vista Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mira Vista Dr and Corridor End	\$ 7,200	N/A **	N/A **		
PROW Intersection	1195	Intersection of Montecito Dr and Palo Verde Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Montecito Dr and Palo Verde Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1196	Intersection of Palo Verde Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Palo Verde Dr and Corridor End	\$ 3,300	N/A **	N/A **		
PROW Intersection	1197	Intersection of Bay Meadow Dr and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bay Meadow Dr and Cul-De-Sac	\$ 6,000	N/A **	N/A **		
PROW Intersection	1198	Intersection of Chaucer Dr and Hemingway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chaucer Dr and Hemingway Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1199	Intersection of Frost Ln and Hemingway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Frost Ln and Hemingway Dr	\$ 8,800	N/A **	N/A **		
PROW Intersection	1200	Intersection of Livingston Dr and Hemingway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Livingston Dr and Hemingway Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	1201	Intersection of Purbeck Trl and Stone Oak Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Purbeck Trl and Stone Oak Blvd	\$ 13,500	N/A **	N/A **		
PROW Intersection	1202	Intersection of Sunburst Trail and Ashwood Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sunburst Trail and Ashwood Pl	\$ 7,300	N/A **	N/A **		
PROW Intersection	1203	Intersection of Algarve Dr and Stone Oak Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Algarve Dr and Stone Oak Blvd	\$ 13,500	N/A **	N/A **		
PROW Intersection	1204	Intersection of Pine Hills Ln and Hayling Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pine Hills Ln and Hayling Way	\$ 10,500	N/A **	N/A **		
PROW Intersection	1205	Intersection of Sh2499 and Pine Hills Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sh2499 and Pine Hills Ln	\$ 6,000	N/A **	N/A **		
PROW Intersection	1206	Intersection of Pine Hills Ln and Alderbrook Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pine Hills Ln and Alderbrook Dr	\$ 15,500	N/A **	N/A **		
PROW Intersection	1207	Intersection of Pine Hills Ln and Purbeck Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pine Hills Ln and Purbeck Trl	\$ 9,000	N/A **	N/A **		
PROW Intersection	1208	Intersection of Pine Hills Ln and Algarve Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pine Hills Ln and Algarve Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1209	Intersection of Paddock Way and English Saddle Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paddock Way and English Saddle Ln	\$ 24,000	N/A **	N/A **		
PROW Intersection	1210	Intersection of Lipizzan Dr and Paddock Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Paddock Way	\$ 12,300	N/A **	N/A **		
PROW Intersection	1211	Intersection of Alderbrook Dr and Palmetto Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alderbrook Dr and Palmetto Ct	\$ 7,000	N/A **	N/A **		
PROW Intersection	1212	Intersection of Bay Meadow Dr and Fairmount Park Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bay Meadow Dr and Fairmount Park Dr	\$ 18,000	N/A **	N/A **		
PROW Intersection	1213	Intersection of Pine Hills Ln and Black Butte Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pine Hills Ln and Black Butte Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	1214	Intersection of Thoroughbred Trail and Highfield Park	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thoroughbred Trail and Highfield Park	\$ 15,000	N/A **	N/A **		
PROW Intersection	1215	Intersection of Penina Trl and Black Butte Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Penina Trl and Black Butte Dr	\$ 6,500	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1217	Intersection of English Saddle Ln and Lonesome Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of English Saddle Ln and Lonesome Trl	\$ 12,800	N/A **	N/A **		
PROW Intersection	1218	Intersection of Prescott Downs Dr and Aqueduct Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Prescott Downs Dr and Aqueduct Dr	\$ 13,100	N/A **	N/A **		
PROW Intersection	1219	Intersection of Bay Meadow Dr and Prescott Downs Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bay Meadow Dr and Prescott Downs Dr	\$ 21,800	N/A **	N/A **		
PROW Intersection	1220	Intersection of Prescott Downs Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Prescott Downs Dr and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1221	Intersection of Thoroughbred Trail and Countess Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thoroughbred Trail and Countess Ln	\$ 20,100	N/A **	N/A **		
PROW Intersection	1222	Intersection of Lipizzan Dr and Quarterhorse Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Quarterhorse Way	\$ 15,000	N/A **	N/A **		
PROW Intersection	1223	Intersection of Saddleback Dr and Quarterhorse Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Saddleback Dr and Quarterhorse Way	\$ 10,200	N/A **	N/A **		
PROW Intersection	1224	Intersection of Penina Trl and Luck Hole Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Penina Trl and Luck Hole Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	1225	Intersection of Pine Hills Ln and Luck Hole Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pine Hills Ln and Luck Hole Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	1226	Intersection of English Manor Rd and Bareback Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of English Manor Rd and Bareback Ln	\$ 15,000	N/A **	N/A **		
PROW Intersection	1227	Intersection of Thoroughbred Trail and Thackery Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thoroughbred Trail and Thackery Dr	\$ 14,000	N/A **	N/A **		
PROW Intersection	1228	Intersection of English Saddle Ln and Bareback Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of English Saddle Ln and Bareback Ln	\$ 12,600	N/A **	N/A **		
PROW Intersection	1229	Intersection of Thistledown Way and Belmont Park Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thistledown Way and Belmont Park Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1230	Intersection of Bay Meadow Dr and Belmont Park Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bay Meadow Dr and Belmont Park Dr	\$ 15,800	N/A **	N/A **		
PROW Intersection	1231	Intersection of Lone Star Ln and Belmont Park Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lone Star Ln and Belmont Park Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1232	Intersection of Sunburst Trl and Dayspring Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sunburst Trl and Dayspring Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1233	Intersection of Raintree Way and Dayspring Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Raintree Way and Dayspring Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1234	Intersection of Penina Trl and San Lorenzo Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Penina Trl and San Lorenzo Dr	\$ 6,500	N/A **	N/A **		
PROW Intersection	1235	Intersection of Wheeler Ridge Dr and Highfield Park	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Dr and Highfield Park	\$ 15,000	N/A **	N/A **		
PROW Intersection	1236	Intersection of Wheeler Ridge Dr and St James Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Dr and St James Pl	\$ 15,000	N/A **	N/A **		
PROW Intersection	1237	Intersection of Pine Hills Ln and San Lorenzo	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pine Hills Ln and San Lorenzo	\$ 9,300	N/A **	N/A **		
PROW Intersection	1238	Intersection of Lipizzan Dr and Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Wheeler Ridge Dr	\$ 24,300	N/A **	N/A **		
PROW Intersection	1239	Intersection of Thoroughbred Trail and Salon Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thoroughbred Trail and Salon Ct	\$ 14,000	N/A **	N/A **		
PROW Intersection	1240	Intersection of Wheeler Ridge Dr and Lone Star Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Dr and Lone Star Ln	\$ 14,800	N/A **	N/A **		
PROW Intersection	1241	Intersection of Creekdale Dr and Dayspring Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Dayspring Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1242	Intersection of Creekdale Dr and Riverchase Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Riverchase Trl	\$ 9,800	N/A **	N/A **		
PROW Intersection	1243	Intersection of Thistledown Way and Del Mar Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thistledown Way and Del Mar Ct	\$ 24,000	N/A **	N/A **		
PROW Intersection	1244	Intersection of Creekdale Dr and Moorland Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Moorland Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1245	Intersection of Del Mar Ct and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Del Mar Ct and Cul-De-Sac	\$ 5,500	N/A **	N/A **		
PROW Intersection	1246	Intersection of Riverpass Dr and Creekdale Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Riverpass Dr and Creekdale Ln	\$ 6,000	N/A **	N/A **		
PROW Intersection	1247	Intersection of Wheeler Ridge Dr and Morgan Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Dr and Morgan Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1248	Intersection of Thistle Way and Creekdale Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thistle Way and Creekdale Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1249	Intersection of Wheeler Ridge Dr and English Manor Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Dr and English Manor Rd	\$ 16,400	N/A **	N/A **		
PROW Intersection	1250	Intersection of Del Mar Ct and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Del Mar Ct and Cul-De-Sac	\$ 9,400	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1252	Intersection of Lone Star Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lone Star Ln and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	1253	Intersection of Thistledown Way and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thistledown Way and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1254	Intersection of Wheeler Ridge Dr and Thackery Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Dr and Thackery Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1255	Intersection of Wheeler Ridge Cir and Breton Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Cir and Breton Dr	\$ 22,900	N/A **	N/A **		
PROW Intersection	1256	Intersection of Circle View Ln and Moorland Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Circle View Ln and Moorland Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1257	Intersection of Circle View Ln and Edgefield Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Circle View Ln and Edgefield Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1258	Intersection of Creekdale Dr and Pimlico Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Pimlico Ct	\$ 19,500	N/A **	N/A **		
PROW Intersection	1259	Intersection of Thistle Way and Vickery Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thistle Way and Vickery Way	\$ 15,300	N/A **	N/A **		
PROW Intersection	1260	Intersection of Vickery Way and Ricks Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vickery Way and Ricks Rd	\$ 9,000	N/A **	N/A **		
PROW Intersection	1261	Intersection of Friesian Ct and Morgan Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Friesian Ct and Morgan Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1262	Intersection of Creekdale Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Driveway	\$ 13,800	N/A **	N/A **		
PROW Intersection	1263	Intersection of Creekdale Dr and Thistledown Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Thistledown Way	\$ 15,000	N/A **	N/A **		
PROW Intersection	1264	Intersection of Creekdale Dr and Hialeah Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Hialeah Dr	\$ 20,000	N/A **	N/A **		
PROW Intersection	1265	Intersection of Breton Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Breton Dr and Driveway	\$ 9,000	N/A **	N/A **		
PROW Intersection	1266	Intersection of Creekdale Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Driveway	\$ 13,500	N/A **	N/A **		
PROW Intersection	1267	Intersection of Thoroughbred Trail and Butler Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thoroughbred Trail and Butler Dr	\$ 15,300	N/A **	N/A **		
PROW Intersection	1268	Intersection of Breton Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Breton Dr and Driveway	\$ 9,000	N/A **	N/A **		
PROW Intersection	1269	Intersection of Friesian Ct and Lusitano Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Friesian Ct and Lusitano Dr	\$ 14,000	N/A **	N/A **		
PROW Intersection	1270	Intersection of Wheeler Ridge Dr and Butler Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Dr and Butler Dr	\$ 15,300	N/A **	N/A **		
PROW Intersection	1271	Intersection of Andalusian Dr and Rocky Mountain Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Andalusian Dr and Rocky Mountain Ln	\$ 15,000	N/A **	N/A **		
PROW Intersection	1272	Intersection of Hialeah Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hialeah Dr and Driveway	\$ 9,800	N/A **	N/A **		
PROW Intersection	1273	Intersection of Thistle Hill and Cheek St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thistle Hill and Cheek St	\$ 10,100	N/A **	N/A **		
PROW Intersection	1274	Intersection of Thistle Way and Cheek St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thistle Way and Cheek St	\$ 12,300	N/A **	N/A **		
PROW Intersection	1275	Intersection of Stoneway Dr and Circle View Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stoneway Dr and Circle View Ln	\$ 9,000	N/A **	N/A **		
PROW Intersection	1276	Intersection of Stoneway Dr and Edgefield Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stoneway Dr and Edgefield Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	1277	Intersection of Riverchase Trl and Stoneway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Riverchase Trl and Stoneway Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1278	Intersection of Creekdale Dr and Oakbluff Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Oakbluff Dr	\$ 7,500	N/A **	N/A **		
PROW Intersection	1279	Intersection of Lipizzan Dr and Rocky Mountain Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Rocky Mountain Ln	\$ 12,800	N/A **	N/A **		
PROW Intersection	1280	Intersection of Thoroughbred Trail and Andalusian Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thoroughbred Trail and Andalusian Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1281	Intersection of Hialeah Dr and Vineland Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hialeah Dr and Vineland Ave	\$ 16,800	N/A **	N/A **		
PROW Intersection	1282	Intersection of Green Ivy Rd and English Manor Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Green Ivy Rd and English Manor Rd	\$ 11,300	N/A **	N/A **		
PROW Intersection	1283	Intersection of Green Ivy Rd and Lost Pony Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Green Ivy Rd and Lost Pony Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1284	Intersection of Andalusian Dr and Lusitano Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Andalusian Dr and Lusitano Dr	\$ 12,800	N/A **	N/A **		
PROW Intersection	1285	Intersection of Wheeler Ridge Dr and Andalusian Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Dr and Andalusian Dr	\$ 24,500	N/A **	N/A **		
PROW Intersection	1286	Intersection of Alta Vista Dr and Cadena Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alta Vista Dr and Cadena Rd	\$ 13,500	N/A **	N/A **		
PROW Intersection	1287	Intersection of Alta Vista Dr and Darien	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alta Vista Dr and Darien	\$ 6,300	N/A **	N/A **		
PROW Intersection	1288	Intersection of Alta Vista Dr and Colina Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alta Vista Dr and Colina Ave	\$ 12,800	N/A **	N/A **		
PROW Intersection	1289	Intersection of Alta Vista Dr and Bonita Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alta Vista Dr and Bonita Ave	\$ 12,300	N/A **	N/A **		
PROW Intersection	1290	Intersection of Fm2181 and Alta Vista Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm2181 and Alta Vista Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1291	Intersection of Breton Dr and Spanish Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Breton Dr and Spanish Ln	\$ 13,300	N/A **	N/A **		
PROW Intersection	1292	Intersection of Eaglestone Way and Goldfinch Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Eaglestone Way and Goldfinch Rd	\$ 12,800	N/A **	N/A **		
PROW Intersection	1293	Intersection of Roxbury St and Sapphire St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roxbury St and Sapphire St	\$ 12,800	N/A **	N/A **		
PROW Intersection	1294	Intersection of Creekdale Dr and Goldfinch Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Goldfinch Rd	\$ 5,200	N/A **	N/A **		
PROW Intersection	1295	Intersection of Lipizzan Dr and Tennessee Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Tennessee Dr	\$ 14,000	N/A **	N/A **		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1296	Intersection of Blackberry Way and Thistle Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Blackberry Way and Thistle Way	\$ 16,200	N/A **	N/A **		
PROW Intersection	1297	Intersection of Blackberry Way and Thistle Hill	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Blackberry Way and Thistle Hill	\$ 15,000	N/A **	N/A **		
PROW Intersection	1298	Intersection of Lipizzan Dr and Lipizzan Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Lipizzan Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1299	Intersection of Lipizzan Dr and Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lipizzan Dr and Wheeler Ridge Dr	\$ 21,600	N/A **	N/A **		
PROW Intersection	1300	Intersection of Creekdale Dr and Grassland Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Grassland Dr	\$ 15,900	N/A **	N/A **		
PROW Intersection	1301	Intersection of Chicory Ct and Grassland Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chicory Ct and Grassland Dr	\$ 12,900	N/A **	N/A **		
PROW Intersection	1302	Intersection of Grassland Dr and Lost Creek Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grassland Dr and Lost Creek Rd	\$ 10,100	N/A **	N/A **		
PROW Intersection	1303	Intersection of Fanita Pl and Pavilion Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fanita Pl and Pavilion Ln	\$ 12,800	N/A **	N/A **		
PROW Intersection	1304	Intersection of Roxbury St and Pavilion Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roxbury St and Pavilion Ln	\$ 19,800	N/A **	N/A **		
PROW Intersection	1305	Intersection of Hialeah Dr and Pavilion Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hialeah Dr and Pavilion Ln	\$ 19,500	N/A **	N/A **		
PROW Intersection	1306	Intersection of Redondo Rd and Darien Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redondo Rd and Darien Pl	\$ 10,100	N/A **	N/A **		
PROW Intersection	1307	Intersection of Redondo Rd and Cadena Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redondo Rd and Cadena Rd	\$ 12,300	N/A **	N/A **		
PROW Intersection	1308	Intersection of Thistle Hill and Matthew Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Thistle Hill and Matthew Ave	\$ 15,000	N/A **	N/A **		
PROW Intersection	1309	Intersection of Redondo Rd and Colina Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redondo Rd and Colina Ave	\$ 18,000	N/A **	N/A **		
PROW Intersection	1310	Intersection of Redondo Rd and Elysian St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redondo Rd and Elysian St	\$ 7,100	N/A **	N/A **		
PROW Intersection	1311	Intersection of Redondo Rd and Bonita Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redondo Rd and Bonita Ave	\$ 12,300	N/A **	N/A **		
PROW Intersection	1312	Intersection of Wheeler Ridge Dr and Clydesdale Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wheeler Ridge Dr and Clydesdale Dr	\$ 21,800	N/A **	N/A **		
PROW Intersection	1313	Intersection of Robinson Rd and State School Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and State School Rd	\$ 7,500	N/A **	N/A **		
PROW Intersection	1315	Intersection of Fanita Pl and Hollister Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fanita Pl and Hollister Ln	\$ 14,600	N/A **	N/A **		
PROW Intersection	1316	Intersection of Roxbury St and Hollister Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roxbury St and Hollister Ln	\$ 13,200	N/A **	N/A **		
PROW Intersection	1317	Intersection of Creekdale Dr and Sky Meadow Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Sky Meadow Ln	\$ 10,100	N/A **	N/A **		
PROW Intersection	1318	Intersection of Robinson Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	1319	Intersection of Miranda Place and Elysian St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Miranda Place and Elysian St	\$ 9,300	N/A **	N/A **		
PROW Intersection	1320	Intersection of Miranda Place and Colina Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Miranda Place and Colina Ave	\$ 10,100	N/A **	N/A **		
PROW Intersection	1321	Intersection of Miranda Place and Hialeah Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Miranda Place and Hialeah Dr	\$ 7,400	N/A **	N/A **		
PROW Intersection	1322	Intersection of Andrew Ave and Thistle Rdg	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Andrew Ave and Thistle Rdg	\$ 10,100	N/A **	N/A **		
PROW Intersection	1323	Intersection of Robinson Rd and Marbellas Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Marbellas Ct	\$ 11,300	N/A **	N/A **		
PROW Intersection	1324	Intersection of Miranda Place and Bonita Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Miranda Place and Bonita Ave	\$ 13,900	N/A **	N/A **		
PROW Intersection	1325	Intersection of Robinson Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	1326	Intersection of Robinson Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Driveway	\$ 6,600	N/A **	N/A **		
PROW Intersection	1327	Intersection of Robinson Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1328	Intersection of Robinson Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Driveway	\$ 2,800	N/A **	N/A **		
PROW Intersection	1329	Intersection of Robinson Rd and Harvard Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Harvard Dr	\$ 4,000	N/A **	N/A **		
PROW Intersection	1330	Intersection of Robinson Rd and Wheeler Ridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Wheeler Ridge Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	1331	Intersection of Sh2499 and Robinson Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sh2499 and Robinson Rd	\$ 20,300	N/A **	N/A **		
PROW Intersection	1332	Intersection of Robinson Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1334	Intersection of Creekdale Dr and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Cul De Sac	\$ 400	N/A **	N/A **		
PROW Intersection	1335	Intersection of Robinson Rd and Berkley Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Berkley Dr	\$ 9,800	N/A **	N/A **		
PROW Intersection	1336	Intersection of Robinson Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1337	Intersection of Robinson Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1338	Intersection of Robinson Rd and Green Ivy Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robinson Rd and Green Ivy Rd	\$ 12,000	N/A **	N/A **		
PROW Intersection	1339	Intersection of Roxbury St and Linda Vista St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roxbury St and Linda Vista St	\$ 14,100	N/A **	N/A **		
PROW Intersection	1340	Intersection of Lost Creek Rd and Chicory Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lost Creek Rd and Chicory Ct	\$ 18,600	N/A **	N/A **		
PROW Intersection	1341	Intersection of Hialeah Dr and Linda Vista St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hialeah Dr and Linda Vista St	\$ 10,100	N/A **	N/A **		
PROW Intersection	1342	Intersection of Creekdale Dr and Doe Creek Trail	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Doe Creek Trail	\$ 7,300	N/A **	N/A **		
PROW Intersection	1343	Intersection of Harvard Dr and St Johns Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harvard Dr and St Johns Dr	\$ 12,100	N/A **	N/A **		
PROW Intersection	1344	Intersection of Miramar Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Miramar Dr and Corridor End	\$ 6,800	N/A **	N/A **		
PROW Intersection	1345	Intersection of Berkley Dr and Marymount Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Berkley Dr and Marymount Dr	\$ 18,600	N/A **	N/A **		
PROW Intersection	1346	Intersection of Drexel Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Drexel Dr and Corridor End	\$ 6,300	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1347	Intersection of Wildwood Ln and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wildwood Ln and Corridor End	\$ 6,600	N/A **	N/A **		
PROW Intersection	1348	Intersection of Wildwood Ln and Overlake Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wildwood Ln and Overlake Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	1349	Intersection of Fm2181 and Wildwood Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm2181 and Wildwood Ln	\$ 5,300	N/A **	N/A **		
PROW Intersection	1350	Intersection of Roxbury St and Nob Hill Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roxbury St and Nob Hill Ct	\$ 9,000	N/A **	N/A **		
PROW Intersection	1351	Intersection of Centenary Dr and St Johns Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Centenary Dr and St Johns Dr	\$ 8,200	N/A **	N/A **		
PROW Intersection	1352	Intersection of Andrew Ave and Sharon Rose Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Andrew Ave and Sharon Rose Ct	\$ 9,300	N/A **	N/A **		
PROW Intersection	1353	Intersection of Red Fox Ln and Lost Creek Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Red Fox Ln and Lost Creek Rd	\$ 7,700	N/A **	N/A **		
PROW Intersection	1354	Intersection of Creekdale Dr and Red Fox Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Red Fox Ln	\$ 15,900	N/A **	N/A **		
PROW Intersection	1355	Intersection of Red Fox Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Red Fox Ln and Midblock Crossing	\$ 3,700	N/A **	N/A **		
PROW Intersection	1356	Intersection of St. Johns Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of St. Johns Dr and Corridor End	\$ 3,000	N/A **	N/A **		
PROW Intersection	1357	Intersection of Harvard Dr and Villanova Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harvard Dr and Villanova Dr	\$ 12,600	N/A **	N/A **		
PROW Intersection	1358	Intersection of Miramar Dr and Hofstra Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Miramar Dr and Hofstra Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1359	Intersection of Hofstra Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hofstra Dr and Midblock Crossing	\$ 6,300	N/A **	N/A **		
PROW Intersection	1360	Intersection of Drexel Dr and Hofstra Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Drexel Dr and Hofstra Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1361	Intersection of Centenary Dr and Villanova Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Centenary Dr and Villanova Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	1362	Intersection of Roxbury St and Leonis Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roxbury St and Leonis Rd	\$ 14,100	N/A **	N/A **		
PROW Intersection	1363	Intersection of Creekdale Dr and Cypress Creek Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Cypress Creek Ln	\$ 3,300	N/A **	N/A **		
PROW Intersection	1364	Intersection of Stonetrail Dr and Cypress Creek Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stonetrail Dr and Cypress Creek Ln	\$ 12,300	N/A **	N/A **		
PROW Intersection	1365	Intersection of Drexel Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Drexel Dr and Midblock Crossing	\$ 6,000	N/A **	N/A **		
PROW Intersection	1366	Intersection of Harvard Dr and Marquette Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harvard Dr and Marquette Dr	\$ 14,600	N/A **	N/A **		
PROW Intersection	1367	Intersection of Creekdale Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1368	Intersection of Centenary Dr and Marquette Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Centenary Dr and Marquette Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1369	Intersection of Miramar Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Miramar Dr and Midblock Crossing	\$ 6,000	N/A **	N/A **		
PROW Intersection	1370	Intersection of Andrew Ave and Maggies Meadow	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Andrew Ave and Maggies Meadow	\$ 11,300	N/A **	N/A **		
PROW Intersection	1371	Intersection of W Ryan Rd and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Ryan Rd and Midblock Crossing	\$ 3,800	N/A **	N/A **		
PROW Intersection	1372	Intersection of Stonetrail Dr and Boulevard Walk	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stonetrail Dr and Boulevard Walk	\$ 6,600	N/A **	N/A **		
PROW Intersection	1373	Intersection of Creekdale Dr and Lemon Mint Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Creekdale Dr and Lemon Mint Ln	\$ 15,300	N/A **	N/A **		
PROW Intersection	1374	Intersection of Drexel Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Drexel Dr and Midblock Crossing	\$ 6,300	N/A **	N/A **		
PROW Intersection	1375	Intersection of Harvard Dr and Stanford Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harvard Dr and Stanford Dr	\$ 13,800	N/A **	N/A **		
PROW Intersection	1376	Intersection of Purdue Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Purdue Dr and Corridor End	\$ 2,300	N/A **	N/A **		
PROW Intersection	1377	Intersection of Drexel Dr and Purdue Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Drexel Dr and Purdue Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	1378	Intersection of Syracuse Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Syracuse Dr and Corridor End	\$ 6,000	N/A **	N/A **		
PROW Intersection	1379	Intersection of Centenary Dr and Stanford Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Centenary Dr and Stanford Dr	\$ 10,100	N/A **	N/A **		
PROW Intersection	1380	Intersection of E Ryan Rd and Duffy's Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Duffy's Way	\$ 400	N/A **	N/A **		
PROW Intersection	1381	Intersection of E Ryan Rd and Andrew Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Andrew Ave	\$ 5,300	N/A **	N/A **		
PROW Intersection	1384	Intersection of E Ryan Rd and Monte Carlo Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Monte Carlo Ln	\$ 6,800	N/A **	N/A **		
PROW Intersection	1385	Intersection of E Ryan Rd and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Corridor End	\$ 3,000	N/A **	N/A **		
PROW Intersection	1386	Intersection of E Ryan Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Driveway	\$ 10,800	N/A **	N/A **		
PROW Intersection	1387	Intersection of E Ryan Rd and Ridgemont Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Ridgemont Ln	\$ 13,800	N/A **	N/A **		
PROW Intersection	1388	Intersection of E Ryan Rd and Roxbury St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Roxbury St	\$ 6,000	N/A **	N/A **		
PROW Intersection	1389	Intersection of W Ryan Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Ryan Rd and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	1391	Intersection of E Ryan Rd and Overlake Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Overlake Dr	\$ 5,000	N/A **	N/A **		
PROW Intersection	1392	Intersection of E Ryan Rd and Parkhaven Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Parkhaven Dr	\$ 5,800	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1393	Intersection of E Ryan Rd and Commodore Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Ryan Rd and Commodore Ct	\$ 3,800	N/A **	N/A **		
PROW Intersection	1395	Intersection of Harvard Dr and Yale Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harvard Dr and Yale Dr	\$ 13,600	N/A **	N/A **		
PROW Intersection	1396	Intersection of Drexel Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Drexel Dr and Corridor End	\$ 6,300	N/A **	N/A **		
PROW Intersection	1397	Intersection of Yale Dr and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Yale Dr and Cul-De-Sac	\$ 6,900	N/A **	N/A **		
PROW Intersection	1398	Intersection of Centenary Dr and Yale Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Centenary Dr and Yale Dr	\$ 10,400	N/A **	N/A **		
PROW Intersection	1399	Intersection of Monte Carlo Ln and Montecristo Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Monte Carlo Ln and Montecristo Ct	\$ 8,700	N/A **	N/A **		
PROW Intersection	1400	Intersection of Depaul Dr and Syracuse Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Depaul Dr and Syracuse Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1402	Intersection of Miramar Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Miramar Dr and Corridor End	\$ 4,300	N/A **	N/A **		
PROW Intersection	1403	Intersection of Commodore Ct and Ringtail Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Commodore Ct and Ringtail Dr	\$ 12,200	N/A **	N/A **		
PROW Intersection	1404	Intersection of Forrestridge Dr and Royal Oaks Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Forrestridge Dr and Royal Oaks Cir	\$ 12,600	N/A **	N/A **		
PROW Intersection	1405	Intersection of Royal Oaks Cir and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Royal Oaks Cir and Cul De Sac	\$ 6,300	N/A **	N/A **		
PROW Intersection	1406	Intersection of Kirby Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kirby Dr and Corridor End	\$ 5,500	N/A **	N/A **		
PROW Intersection	1407	Intersection of San Felipe Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of San Felipe Dr and Corridor End	\$ 5,300	N/A **	N/A **		
PROW Intersection	1408	Intersection of Centenary Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Centenary Dr and Corridor End	\$ 7,400	N/A **	N/A **		
PROW Intersection	1409	Intersection of Merrimack Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Merrimack Dr and Corridor End	\$ 4,000	N/A **	N/A **		
PROW Intersection	1410	Intersection of I 35 E and Lakeview Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of I 35 E and Lakeview Blvd	\$ 7,500	N/A **	N/A **		
PROW Intersection	1411	Intersection of Harvard Dr and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harvard Dr and Cul-De-Sac	\$ 3,800	N/A **	N/A **		
PROW Intersection	1412	Intersection of Monte Carlo Ln and Montevideo Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Monte Carlo Ln and Montevideo Ct	\$ 9,900	N/A **	N/A **		
PROW Intersection	1413	Intersection of Lakeview Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1414	Intersection of Lakeview Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	1415	Intersection of Forrestridge Dr and Royal Oaks Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Forrestridge Dr and Royal Oaks Cir	\$ 12,600	N/A **	N/A **		
PROW Intersection	1416	Intersection of Lakeview Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Driveway	\$ 6,300	N/A **	N/A **		
PROW Intersection	1417	Intersection of Royal Oaks Cir and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Royal Oaks Cir and Cul De Sac	\$ 6,000	N/A **	N/A **		
PROW Intersection	1418	Intersection of Monte Carlo Ln and San Marino Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Monte Carlo Ln and San Marino Ln	\$ 10,100	N/A **	N/A **		
PROW Intersection	1420	Intersection of Gennaker Dr and Hunters Creek Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gennaker Dr and Hunters Creek Rd	\$ 14,300	N/A **	N/A **		
PROW Intersection	1421	Intersection of Gessner Dr and Fondren Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gessner Dr and Fondren Rd	\$ 6,000	N/A **	N/A **		
PROW Intersection	1422	Intersection of Fm 2181 and Heights Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 2181 and Heights Blvd	\$ 7,100	N/A **	N/A **		
PROW Intersection	1423	Intersection of Forrestridge Dr and Wellington Oaks Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Forrestridge Dr and Wellington Oaks Cir	\$ 12,900	N/A **	N/A **		
PROW Intersection	1425	Intersection of Crosstrees Dr and Crosstrees Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crosstrees Dr and Crosstrees Dr	\$ 10,500	N/A **	N/A **		
PROW Intersection	1426	Intersection of Gessner Dr and Heights Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gessner Dr and Heights Blvd	\$ 9,600	N/A **	N/A **		
PROW Intersection	1427	Intersection of Wellington Oaks Cir and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wellington Oaks Cir and Cul De Sac	\$ 5,300	N/A **	N/A **		
PROW Intersection	1428	Intersection of Shady Shores Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shady Shores Rd and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1429	Intersection of Cuddy Dr and Corsair Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cuddy Dr and Corsair Ln	\$ 7,800	N/A **	N/A **		
PROW Intersection	1430	Intersection of Gessner Dr and Westheimer Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gessner Dr and Westheimer Rd	\$ 7,800	N/A **	N/A **		
PROW Intersection	1431	Intersection of Gennaker Dr and Corsair Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gennaker Dr and Corsair Ln	\$ 17,300	N/A **	N/A **		
PROW Intersection	1432	Intersection of Crosstrees Dr and Corsair Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crosstrees Dr and Corsair Ln	\$ 17,300	N/A **	N/A **		
PROW Intersection	1433	Intersection of Fondren Rd and Westheimer Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fondren Rd and Westheimer Rd	\$ 8,600	N/A **	N/A **		
PROW Intersection	1434	Intersection of Sh2499 and State School Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sh2499 and State School Rd	\$ 34,200	N/A **	N/A **		
PROW Intersection	1435	Intersection of Forrestridge Dr and Wellington Oaks Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Forrestridge Dr and Wellington Oaks Cir	\$ 14,900	N/A **	N/A **		
PROW Intersection	1436	Intersection of Cuddy Dr and Skysail Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cuddy Dr and Skysail Ln	\$ 7,800	N/A **	N/A **		
PROW Intersection	1437	Intersection of Kirby Dr and San Felipe Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kirby Dr and San Felipe Dr	\$ 8,500	N/A **	N/A **		
PROW Intersection	1438	Intersection of San Felipe Dr and Chimney Rock Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of San Felipe Dr and Chimney Rock Dr	\$ 8,800	N/A **	N/A **		
PROW Intersection	1439	Intersection of San Felipe Dr and Willowick Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of San Felipe Dr and Willowick Cir	\$ 9,300	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1440	Intersection of Fondren Rd and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fondren Rd and Corridor End	\$ 6,000	N/A **	N/A **		
PROW Intersection	1441	Intersection of Falcon Ct and Bentley Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Falcon Ct and Bentley Ct	\$ 10,500	N/A **	N/A **		
PROW Intersection	1442	Intersection of Fm 2181 and Briar Forest Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 2181 and Briar Forest Dr	\$ 4,800	N/A **	N/A **		
PROW Intersection	1443	Intersection of Skysail Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Skysail Ln and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	1444	Intersection of Wellington Oaks Cir and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wellington Oaks Cir and Cul De Sac	\$ 5,300	N/A **	N/A **		
PROW Intersection	1445	Intersection of Gessner Dr and Briar Forest Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gessner Dr and Briar Forest Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1447	Intersection of Lakeview Blvd and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Corridor End	\$ 3,300	N/A **	N/A **		
PROW Intersection	1449	Intersection of Cuddy Dr and Ranchman Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cuddy Dr and Ranchman Blvd	\$ 5,100	N/A **	N/A **		
PROW Intersection	1451	Intersection of Kirby Dr and Bissonet Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kirby Dr and Bissonet Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1452	Intersection of Dunlavy Rd and Bissonet Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dunlavy Rd and Bissonet Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1453	Intersection of Ranchman Blvd and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ranchman Blvd and Corridor End	\$ 4,100	N/A **	N/A **		
PROW Intersection	1454	Intersection of Forrestridge Dr and Oak Forrest Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Forrestridge Dr and Oak Forrest Cir	\$ 6,000	N/A **	N/A **		
PROW Intersection	1455	Intersection of Visalia Ln and Remington St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Visalia Ln and Remington St	\$ 9,000	N/A **	N/A **		
PROW Intersection	1456	Intersection of Ranchman Blvd and Summit Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ranchman Blvd and Summit Ct	\$ 10,300	N/A **	N/A **		
PROW Intersection	1457	Intersection of Anchor Dr and Monte Carlo Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anchor Dr and Monte Carlo Ln	\$ 16,800	N/A **	N/A **		
PROW Intersection	1458	Intersection of Kirby Dr and Hilcroft Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kirby Dr and Hilcroft Ave	\$ 9,300	N/A **	N/A **		
PROW Intersection	1459	Intersection of Lakeview Blvd and Post Oak Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Post Oak Blvd	\$ 5,900	N/A **	N/A **		
PROW Intersection	1460	Intersection of Anchor Dr and Helm Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anchor Dr and Helm Ln	\$ 13,100	N/A **	N/A **		
PROW Intersection	1461	Intersection of Santa Monica Dr and Lamplighter Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Santa Monica Dr and Lamplighter Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1462	Intersection of Dunlavy Rd and Hilcroft Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dunlavy Rd and Hilcroft Ave	\$ 9,600	N/A **	N/A **		
PROW Intersection	1463	Intersection of Forrestridge Dr and Oak Forrest Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Forrestridge Dr and Oak Forrest Cir	\$ 6,000	N/A **	N/A **		
PROW Intersection	1464	Intersection of Springcreek Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Springcreek Dr and Midblock Crossing	\$ 6,300	N/A **	N/A **		
PROW Intersection	1465	Intersection of Springcreek Dr and Creekbend Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Springcreek Dr and Creekbend Dr	\$ 13,600	N/A **	N/A **		
PROW Intersection	1466	Intersection of Lake Country Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lake Country Dr and Corridor End	\$ 6,000	N/A **	N/A **		
PROW Intersection	1467	Intersection of Sun Ray Dr and Redbud Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Ray Dr and Redbud Dr	\$ 4,200	N/A **	N/A **		
PROW Intersection	1468	Intersection of Sun Ray Dr and Dogwood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Ray Dr and Dogwood Dr	\$ 5,900	N/A **	N/A **		
PROW Intersection	1469	Intersection of Remington St and Bentwood Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Remington St and Bentwood Ct	\$ 9,800	N/A **	N/A **		
PROW Intersection	1470	Intersection of Sun Ray Dr and Fox Sedge Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Ray Dr and Fox Sedge Ln	\$ 15,800	N/A **	N/A **		
PROW Intersection	1471	Intersection of Sun Ray Dr and Heron Pond Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Ray Dr and Heron Pond Ln	\$ 12,300	N/A **	N/A **		
PROW Intersection	1472	Intersection of Lakeview Blvd and Indian Paint Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Indian Paint Way	\$ 15,200	N/A **	N/A **		
PROW Intersection	1473	Intersection of Crapemyrtle Dr and Crossvine Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crapemyrtle Dr and Crossvine Ct	\$ 5,500	N/A **	N/A **		
PROW Intersection	1474	Intersection of Sun Ray Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Ray Dr and Corridor End	\$ 8,300	N/A **	N/A **		
PROW Intersection	1476	Intersection of Kirby Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kirby Dr and Corridor End	\$ 6,000	N/A **	N/A **		
PROW Intersection	1477	Intersection of Moonsail Ln and Monte Carlo Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Moonsail Ln and Monte Carlo Ln	\$ 15,800	N/A **	N/A **		
PROW Intersection	1478	Intersection of Dunlavy Rd and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dunlavy Rd and Corridor End	\$ 6,000	N/A **	N/A **		
PROW Intersection	1479	Intersection of Moonsail Ln and Masthead Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Moonsail Ln and Masthead Dr	\$ 14,000	N/A **	N/A **		
PROW Intersection	1480	Intersection of Gunnison Dr and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gunnison Dr and Cul-De-Sac	\$ 400	N/A **	N/A **		
PROW Intersection	1481	Intersection of Moonsail Ln and Helm Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Moonsail Ln and Helm Ln	\$ 21,300	N/A **	N/A **		
PROW Intersection	1482	Intersection of Beechwood Dr and Springcreek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Beechwood Dr and Springcreek Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1483	Intersection of Fm 1830 and Beechwood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 1830 and Beechwood Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	1484	Intersection of Beechwood Dr and Creekbend Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Beechwood Dr and Creekbend Dr	\$ 13,100	N/A **	N/A **		
PROW Intersection	1485	Intersection of E El Paseo St and Santa Monica Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E El Paseo St and Santa Monica Dr	\$ 4,800	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1486	Intersection of Goldenrod Dr and Heron Pond Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Goldenrod Dr and Heron Pond Ln	\$ 15,000	N/A **	N/A **		
PROW Intersection	1487	Intersection of Springcreek Dr and Wintercreek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Springcreek Dr and Wintercreek Dr	\$ 10,400	N/A **	N/A **		
PROW Intersection	1488	Intersection of Hawthorn Dr and Hawthorn Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hawthorn Dr and Hawthorn Dr	\$ 7,500	N/A **	N/A **		
PROW Intersection	1489	Intersection of Goldenrod Dr and Cattail Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Goldenrod Dr and Cattail Ln	\$ 16,500	N/A **	N/A **		
PROW Intersection	1490	Intersection of W El Paseo St and Remington St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W El Paseo St and Remington St	\$ 12,300	N/A **	N/A **		
PROW Intersection	1491	Intersection of Belmont St and W El Paseo St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Belmont St and W El Paseo St	\$ 16,300	N/A **	N/A **		
PROW Intersection	1492	Intersection of Longhorn Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Longhorn Dr and Corridor End	\$ 6,300	N/A **	N/A **		
PROW Intersection	1493	Intersection of Green River Dr and Loveland Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Green River Dr and Loveland Dr	\$ 4,700	N/A **	N/A **		
PROW Intersection	1494	Intersection of Loveland Dr and Wasatch Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loveland Dr and Wasatch Dr	\$ 8,500	N/A **	N/A **		
PROW Intersection	1495	Intersection of Gunnison Dr and Loveland Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gunnison Dr and Loveland Dr	\$ 11,300	N/A **	N/A **		
PROW Intersection	1496	Intersection of Hawthorn Dr and Baytree Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hawthorn Dr and Baytree Ave	\$ 9,200	N/A **	N/A **		
PROW Intersection	1497	Intersection of Paint Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paint Dr and Corridor End	\$ 6,600	N/A **	N/A **		
PROW Intersection	1498	Intersection of Ranchman Blvd and Hollow Ridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ranchman Blvd and Hollow Ridge Dr	\$ 10,100	N/A **	N/A **		
PROW Intersection	1499	Intersection of W El Paseo St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W El Paseo St and Midblock Crossing	\$ 4,500	N/A **	N/A **		
PROW Intersection	1500	Intersection of Big Horn Trl and Hollow Ridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Big Horn Trl and Hollow Ridge Dr	\$ 10,000	N/A **	N/A **		
PROW Intersection	1501	Intersection of Spinnaker Dr and Masthead Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Spinnaker Dr and Masthead Dr	\$ 12,800	N/A **	N/A **		
PROW Intersection	1502	Intersection of Spinnaker Dr and Monte Carlo Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Spinnaker Dr and Monte Carlo Ln	\$ 14,300	N/A **	N/A **		
PROW Intersection	1503	Intersection of Lakeview Blvd and Black Walnut	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Black Walnut	\$ 14,800	N/A **	N/A **		
PROW Intersection	1504	Intersection of Wintercreek Dr and Beechwood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wintercreek Dr and Beechwood Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	1505	Intersection of Spinnaker Dr and Helm Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Spinnaker Dr and Helm Ln	\$ 16,800	N/A **	N/A **		
PROW Intersection	1506	Intersection of Hawthorn Dr and Trumpet Vine	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hawthorn Dr and Trumpet Vine	\$ 7,500	N/A **	N/A **		
PROW Intersection	1507	Intersection of Indian Paint Way and Begonia Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Indian Paint Way and Begonia Dr	\$ 8,000	N/A **	N/A **		
PROW Intersection	1508	Intersection of Greenbend Dr and Creekbend Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Greenbend Dr and Creekbend Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1509	Intersection of Bent Creek Dr and Springcreek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bent Creek Dr and Springcreek Dr	\$ 5,300	N/A **	N/A **		
PROW Intersection	1510	Intersection of Marsh Rail Dr and Heron Pond Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marsh Rail Dr and Heron Pond Ln	\$ 15,800	N/A **	N/A **		
PROW Intersection	1511	Intersection of Hidden Meadows Trl and Tamarack Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hidden Meadows Trl and Tamarack Ln	\$ 8,400	N/A **	N/A **		
PROW Intersection	1512	Intersection of Hawthorn Dr and Black Walnut	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hawthorn Dr and Black Walnut	\$ 8,000	N/A **	N/A **		
PROW Intersection	1513	Intersection of Marsh Rail Dr and Cattail Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marsh Rail Dr and Cattail Ln	\$ 25,500	N/A **	N/A **		
PROW Intersection	1514	Intersection of Marsh Rail Dr and Green River Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marsh Rail Dr and Green River Dr	\$ 4,700	N/A **	N/A **		
PROW Intersection	1515	Intersection of Ranchman Blvd and Sundown Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ranchman Blvd and Sundown Blvd	\$ 9,800	N/A **	N/A **		
PROW Intersection	1516	Intersection of Marsh Rail Dr and Gunnison Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marsh Rail Dr and Gunnison Dr	\$ 8,700	N/A **	N/A **		
PROW Intersection	1517	Intersection of Wintercreek Dr and Greenbend Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wintercreek Dr and Greenbend Dr	\$ 10,100	N/A **	N/A **		
PROW Intersection	1518	Intersection of Tamarack Ln and Mockernut Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Tamarack Ln and Mockernut Rd	\$ 4,000	N/A **	N/A **		
PROW Intersection	1519	Intersection of Big Horn Trl and Hereford Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Big Horn Trl and Hereford Rd	\$ 9,600	N/A **	N/A **		
PROW Intersection	1520	Intersection of Paint Dr and Hereford Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paint Dr and Hereford Rd	\$ 12,300	N/A **	N/A **		
PROW Intersection	1521	Intersection of Lakeview Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1522	Intersection of Belmont St and Meadowlands Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Belmont St and Meadowlands Dr	\$ 9,100	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1523	Intersection of Meadowlands Dr and Preakness Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadowlands Dr and Preakness Dr	\$ 6,800	N/A **	N/A **		
PROW Intersection	1524	Intersection of Photinia Ave and Indian Paint Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Photinia Ave and Indian Paint Way	\$ 15,000	N/A **	N/A **		
PROW Intersection	1525	Intersection of Photinia Ave and Post Oak Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Photinia Ave and Post Oak Blvd	\$ 2,700	N/A **	N/A **		
PROW Intersection	1526	Intersection of Sundown Blvd and Longhorn Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sundown Blvd and Longhorn Dr	\$ 9,500	N/A **	N/A **		
PROW Intersection	1527	Intersection of Photinia Ave and Redbud Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Photinia Ave and Redbud Dr	\$ 17,800	N/A **	N/A **		
PROW Intersection	1528	Intersection of Fm 1830 and Wintercreek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 1830 and Wintercreek Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	1529	Intersection of Wintercreek Dr and Pinehurst Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wintercreek Dr and Pinehurst Ct	\$ 9,300	N/A **	N/A **		
PROW Intersection	1530	Intersection of Wintercreek Dr and Kappwood Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wintercreek Dr and Kappwood Ct	\$ 9,000	N/A **	N/A **		
PROW Intersection	1531	Intersection of Bent Creek Dr and Moss creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bent Creek Dr and Moss creek Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1532	Intersection of Photinia Ave and Dogwood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Photinia Ave and Dogwood Dr	\$ 16,900	N/A **	N/A **		
PROW Intersection	1533	Intersection of Photinia Ave and Fox Sedge Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Photinia Ave and Fox Sedge Ln	\$ 24,300	N/A **	N/A **		
PROW Intersection	1534	Intersection of Sh2499 and Unicorn Lake Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sh2499 and Unicorn Lake Blvd	\$ 9,000	N/A **	N/A **		
PROW Intersection	1535	Intersection of Photinia Ave and Heron Pond Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Photinia Ave and Heron Pond Ln	\$ 24,000	N/A **	N/A **		
PROW Intersection	1536	Intersection of Photinia Ave and Cattail Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Photinia Ave and Cattail Ln	\$ 15,000	N/A **	N/A **		
PROW Intersection	1537	Intersection of Green River Dr and Longmont Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Green River Dr and Longmont Dr	\$ 6,200	N/A **	N/A **		
PROW Intersection	1538	Intersection of Unicorn Lake Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Unicorn Lake Blvd and Driveway	\$ 5,700	N/A **	N/A **		
PROW Intersection	1539	Intersection of Gunnison Dr and Longmont Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gunnison Dr and Longmont Dr	\$ 5,600	N/A **	N/A **		
PROW Intersection	1540	Intersection of Buckthorn Ln and Hidden Meadows Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Buckthorn Ln and Hidden Meadows Trl	\$ 9,000	N/A **	N/A **		
PROW Intersection	1541	Intersection of Unicorn Lake Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Unicorn Lake Blvd and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1542	Intersection of Ranchman Blvd and Mustang Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ranchman Blvd and Mustang Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1543	Intersection of Paint Dr and Arabian Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paint Dr and Arabian Ave	\$ 9,000	N/A **	N/A **		
PROW Intersection	1544	Intersection of Big Horn Trl and Arabian Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Big Horn Trl and Arabian Ave	\$ 9,000	N/A **	N/A **		
PROW Intersection	1545	Intersection of Moss creek Dr and Bentgate Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Moss creek Dr and Bentgate Ct	\$ 6,300	N/A **	N/A **		
PROW Intersection	1546	Intersection of Trumpet Vine and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Trumpet Vine and Corridor End	\$ 6,500	N/A **	N/A **		
PROW Intersection	1547	Intersection of Baytree Ave and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Baytree Ave and Corridor End	\$ 6,000	N/A **	N/A **		
PROW Intersection	1548	Intersection of Pinehurst Ct and Bent Creek Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pinehurst Ct and Bent Creek Dr	\$ 7,100	N/A **	N/A **		
PROW Intersection	1549	Intersection of Buckthorn Ln and Remuda Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Buckthorn Ln and Remuda Ln	\$ 10,100	N/A **	N/A **		
PROW Intersection	1550	Intersection of Bent Creek Dr and Spenrock Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bent Creek Dr and Spenrock Ct	\$ 9,000	N/A **	N/A **		
PROW Intersection	1551	Intersection of Bent Creek Dr and Kappwood Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bent Creek Dr and Kappwood Ct	\$ 12,600	N/A **	N/A **		
PROW Intersection	1552	Intersection of Desert Holly Way and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Desert Holly Way and Corridor End	\$ 9,000	N/A **	N/A **		
PROW Intersection	1553	Intersection of Redbud Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redbud Dr and Corridor End	\$ 9,000	N/A **	N/A **		
PROW Intersection	1554	Intersection of Vintage Blvd and Provence Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vintage Blvd and Provence Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1555	Intersection of Vintage Blvd and Napa Valley Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vintage Blvd and Napa Valley Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1556	Intersection of Bent Creek Dr and Briary Trace Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bent Creek Dr and Briary Trace Ct	\$ 9,300	N/A **	N/A **		
PROW Intersection	1557	Intersection of Moor Hen Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Moor Hen Dr and Corridor End	\$ 7,500	N/A **	N/A **		
PROW Intersection	1558	Intersection of Buckthorn Ln and Mockernut Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Buckthorn Ln and Mockernut Rd	\$ 14,100	N/A **	N/A **		
PROW Intersection	1559	Intersection of Buckthorn Ln and Woodbine Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Buckthorn Ln and Woodbine Rd	\$ 8,200	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1560	Intersection of Moor Hen Dr and Waterlily Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Moor Hen Dr and Waterlily Way	\$ 16,000	N/A **	N/A **		
PROW Intersection	1561	Intersection of Moor Hen Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Moor Hen Dr and Corridor End	\$ 12,000	N/A **	N/A **		
PROW Intersection	1562	Intersection of Camino Real Trail and Glenwood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Camino Real Trail and Glenwood Dr	\$ 2,900	N/A **	N/A **		
PROW Intersection	1563	Intersection of Mosscreek Dr and Teasbend Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mosscreek Dr and Teasbend Ct	\$ 9,300	N/A **	N/A **		
PROW Intersection	1564	Intersection of Pockrus Page Rd and Post Oak Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pockrus Page Rd and Post Oak Blvd	\$ 800	N/A **	N/A **		
PROW Intersection	1565	Intersection of Lake Country Dr and Reata Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lake Country Dr and Reata Ct	\$ 9,800	N/A **	N/A **		
PROW Intersection	1566	Intersection of Sonoma Dr and Vinyard Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sonoma Dr and Vinyard Way	\$ 9,500	N/A **	N/A **		
PROW Intersection	1567	Intersection of Paint Dr and Pinto Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paint Dr and Pinto Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1568	Intersection of Ranchman Blvd and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ranchman Blvd and Corridor End	\$ 6,800	N/A **	N/A **		
PROW Intersection	1569	Intersection of Big Horn Trl and Pinto Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Big Horn Trl and Pinto Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	1570	Intersection of Buckthorn Ln and Lacewood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Buckthorn Ln and Lacewood Dr	\$ 12,800	N/A **	N/A **		
PROW Intersection	1571	Intersection of Sonoma Dr and Alsace Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sonoma Dr and Alsace Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1572	Intersection of Sombrero Dr and Pinto Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sombrero Dr and Pinto Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1573	Intersection of Sonoma Dr and Provence Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sonoma Dr and Provence Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	1574	Intersection of Sonoma Dr and Napa Valley Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sonoma Dr and Napa Valley Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	1575	Intersection of Pockrus Page Rd and Fox Sedge Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pockrus Page Rd and Fox Sedge Ln	\$ 12,500	N/A **	N/A **		
PROW Intersection	1576	Intersection of Lakeview Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	1577	Intersection of Preakness Dr and Kentucky Derby Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Preakness Dr and Kentucky Derby Dr	\$ 6,800	N/A **	N/A **		
PROW Intersection	1578	Intersection of Buckthorn Ln and Shagbark Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Buckthorn Ln and Shagbark Dr	\$ 12,400	N/A **	N/A **		
PROW Intersection	1579	Intersection of Lakeview Blvd and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Midblock Crossing	\$ 6,900	N/A **	N/A **		
PROW Intersection	1580	Intersection of Kentucky Derby Dr and Belmont St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kentucky Derby Dr and Belmont St	\$ 6,800	N/A **	N/A **		
PROW Intersection	1581	Intersection of Pockrus Page Rd and Waterlily Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pockrus Page Rd and Waterlily Way	\$ 12,800	N/A **	N/A **		
PROW Intersection	1582	Intersection of Kentucky Derby Dr and Triple Crown Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kentucky Derby Dr and Triple Crown Ct	\$ 10,500	N/A **	N/A **		
PROW Intersection	1583	Intersection of Mosscreek Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mosscreek Dr and Midblock Crossing	\$ 6,300	N/A **	N/A **		
PROW Intersection	1584	Intersection of Pockrus Page Rd and Camino Real Trail	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pockrus Page Rd and Camino Real Trail	\$ 19,700	N/A **	N/A **		
PROW Intersection	1585	Intersection of Sundown Blvd and Clubhouse Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sundown Blvd and Clubhouse Dr	\$ 10,400	N/A **	N/A **		
PROW Intersection	1586	Intersection of Pockrus Page Rd and Cliffside Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pockrus Page Rd and Cliffside Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	1587	Intersection of Stonecrop Trl and Mockernut Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stonecrop Trl and Mockernut Rd	\$ 15,800	N/A **	N/A **		
PROW Intersection	1588	Intersection of Stonecrop Trl and Tucker St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stonecrop Trl and Tucker St	\$ 10,400	N/A **	N/A **		
PROW Intersection	1589	Intersection of Stonecrop Trl and Remuda Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stonecrop Trl and Remuda Ln	\$ 7,000	N/A **	N/A **		
PROW Intersection	1590	Intersection of Lake Country Dr and Lakeside Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lake Country Dr and Lakeside Ct	\$ 9,500	N/A **	N/A **		
PROW Intersection	1591	Intersection of Stonecrop Trl and Loblobby Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stonecrop Trl and Loblobby Ln	\$ 11,900	N/A **	N/A **		
PROW Intersection	1592	Intersection of Hidden Meadows Trl and Stonecrop Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hidden Meadows Trl and Stonecrop Trl	\$ 14,600	N/A **	N/A **		
PROW Intersection	1593	Intersection of Pockrus Page Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pockrus Page Rd and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	1594	Intersection of Dolores Place and Arroyo Trail	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dolores Place and Arroyo Trail	\$ 14,700	N/A **	N/A **		
PROW Intersection	1595	Intersection of I35E and Pockrus Page Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of I35E and Pockrus Page Rd	\$ 1,000	N/A **	N/A **		
PROW Intersection	1596	Intersection of Burr Oak Dr and Castle Pines Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Burr Oak Dr and Castle Pines Ln	\$ 12,000	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1597	Intersection of Dolores Place and Fox Sedge Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dolores Place and Fox Sedge Ln	\$ 8,800	N/A **	N/A **		
PROW Intersection	1598	Intersection of Clubhouse Dr and Mustang Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clubhouse Dr and Mustang Dr	\$ 14,300	N/A **	N/A **		
PROW Intersection	1599	Intersection of Pockrus Page Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pockrus Page Rd and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	1600	Intersection of Dolores Place and Harbour Mist Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dolores Place and Harbour Mist Trl	\$ 8,800	N/A **	N/A **		
PROW Intersection	1601	Intersection of Monte Verde Way and Dolores Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Monte Verde Way and Dolores Pl	\$ 12,600	N/A **	N/A **		
PROW Intersection	1602	Intersection of Dolores Place and Juniperio St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dolores Place and Juniperio St	\$ 4,400	N/A **	N/A **		
PROW Intersection	1603	Intersection of Pinot Dr and Rhone Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pinot Dr and Rhone Dr	\$ 19,500	N/A **	N/A **		
PROW Intersection	1604	Intersection of Unicorn Lake Blvd and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Unicorn Lake Blvd and Midblock Crossing	\$ 9,800	N/A **	N/A **		
PROW Intersection	1605	Intersection of Vinyard Way and Loire Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vinyard Way and Loire Ct	\$ 9,300	N/A **	N/A **		
PROW Intersection	1606	Intersection of Lake Country Dr and Spur Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lake Country Dr and Spur Ct	\$ 9,300	N/A **	N/A **		
PROW Intersection	1607	Intersection of Sundown Blvd and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sundown Blvd and Midblock Crossing	\$ 5,300	N/A **	N/A **		
PROW Intersection	1608	Intersection of Clubhouse Dr and Sombrero Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clubhouse Dr and Sombrero Dr	\$ 13,100	N/A **	N/A **		
PROW Intersection	1609	Intersection of Clubhouse Dr and Paint Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clubhouse Dr and Paint Dr	\$ 6,600	N/A **	N/A **		
PROW Intersection	1610	Intersection of Alsace Dr and Tuscany Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alsace Dr and Tuscany Ct	\$ 6,000	N/A **	N/A **		
PROW Intersection	1611	Intersection of Pebble Beach Trl and Surf St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pebble Beach Trl and Surf St	\$ 14,300	N/A **	N/A **		
PROW Intersection	1612	Intersection of Pebble Beach Trl and Cliffside Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pebble Beach Trl and Cliffside Dr	\$ 14,100	N/A **	N/A **		
PROW Intersection	1613	Intersection of Echo Hill Ln and Falcon Ridge Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Echo Hill Ln and Falcon Ridge Rd	\$ 12,800	N/A **	N/A **		
PROW Intersection	1614	Intersection of Clubhouse Dr and Tuscan Hills Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clubhouse Dr and Tuscan Hills Cir	\$ 7,500	N/A **	N/A **		
PROW Intersection	1615	Intersection of Unicorn Lake Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Unicorn Lake Blvd and Driveway	\$ 8,200	N/A **	N/A **		
PROW Intersection	1616	Intersection of Castle Pines Ln and Echo Hill Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Castle Pines Ln and Echo Hill Ln	\$ 6,000	N/A **	N/A **		
PROW Intersection	1617	Intersection of Vinyard Way and Piedmonte Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vinyard Way and Piedmonte Ct	\$ 9,300	N/A **	N/A **		
PROW Intersection	1618	Intersection of Nora Ln and Pecan Tree Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nora Ln and Pecan Tree Dr	\$ 9,200	N/A **	N/A **		
PROW Intersection	1619	Intersection of Hornbeam St and Lacewood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hornbeam St and Lacewood Dr	\$ 19,500	N/A **	N/A **		
PROW Intersection	1620	Intersection of Hornbeam St and Shagbark Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hornbeam St and Shagbark Dr	\$ 19,100	N/A **	N/A **		
PROW Intersection	1621	Intersection of Sundown Blvd and Lake Country Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sundown Blvd and Lake Country Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	1622	Intersection of Hornbeam St and Tucker St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hornbeam St and Tucker St	\$ 24,000	N/A **	N/A **		
PROW Intersection	1623	Intersection of Hornbeam St and Loblobby Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hornbeam St and Loblobby Ln	\$ 16,400	N/A **	N/A **		
PROW Intersection	1624	Intersection of Soledad Dr and Monte Verde Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Soledad Dr and Monte Verde Way	\$ 10,500	N/A **	N/A **		
PROW Intersection	1625	Intersection of Bent Oaks Ct and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bent Oaks Ct and Driveway	\$ 6,900	N/A **	N/A **		
PROW Intersection	1626	Intersection of Hornbeam St and Hidden Meadows Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hornbeam St and Hidden Meadows Trl	\$ 9,700	N/A **	N/A **		
PROW Intersection	1627	Intersection of San Lucas Lane and Soledad Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of San Lucas Lane and Soledad Dr	\$ 16,200	N/A **	N/A **		
PROW Intersection	1628	Intersection of Clubhouse Dr and Frontier Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Clubhouse Dr and Frontier Dr	\$ 16,900	N/A **	N/A **		
PROW Intersection	1629	Intersection of Camino Real Trail and Soledad Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Camino Real Trail and Soledad Dr	\$ 18,400	N/A **	N/A **		
PROW Intersection	1630	Intersection of Soledad Dr and Oceanview Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Soledad Dr and Oceanview Dr	\$ 18,800	N/A **	N/A **		
PROW Intersection	1631	Intersection of Bent Oaks Ct and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bent Oaks Ct and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	1632	Intersection of Vinyard Way and Provence Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vinyard Way and Provence Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1633	Intersection of Mark Ln and Regency Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mark Ln and Regency Ct	\$ 12,800	N/A **	N/A **		
PROW Intersection	1634	Intersection of Unicorn Lake Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Unicorn Lake Blvd and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1635	Intersection of Fm 1830 and Regency Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 1830 and Regency Ct	\$ 6,000	N/A **	N/A **		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1636	Intersection of Alsace Dr and Pomerol Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alsace Dr and Pomerol Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	1637	Intersection of Pomerol Dr and Napa Valley Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pomerol Dr and Napa Valley Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1638	Intersection of Bent Oaks Ct and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bent Oaks Ct and Driveway	\$ 6,300	N/A **	N/A **		
PROW Intersection	1639	Intersection of Boxwood Dr and Stonegate Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Boxwood Dr and Stonegate Dr	\$ 8,300	N/A **	N/A **		
PROW Intersection	1640	Intersection of Frontier Dr and Sombrero Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Frontier Dr and Sombrero Dr	\$ 19,100	N/A **	N/A **		
PROW Intersection	1641	Intersection of Frontier Dr and Estacado Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Frontier Dr and Estacado Dr	\$ 14,600	N/A **	N/A **		
PROW Intersection	1642	Intersection of Lakeview Blvd and Burr Oak Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Burr Oak Dr	\$ 8,600	N/A **	N/A **		
PROW Intersection	1643	Intersection of Fm 2181 and Bent Oaks Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 2181 and Bent Oaks Ct	\$ 6,000	N/A **	N/A **		
PROW Intersection	1644	Intersection of Pecan Tree Dr and Central Village Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pecan Tree Dr and Central Village Dr	\$ 15,000	N/A **	N/A **		
PROW Intersection	1645	Intersection of Bent Oaks Ct and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bent Oaks Ct and Driveway	\$ 12,600	N/A **	N/A **		
PROW Intersection	1646	Intersection of Mustang Dr and Ranch House Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mustang Dr and Ranch House Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	1647	Intersection of Central Village Dr and Nora Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Central Village Dr and Nora Ln	\$ 12,600	N/A **	N/A **		
PROW Intersection	1649	Intersection of Monte Verde Way and Galante Lane	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Monte Verde Way and Galante Lane	\$ 5,200	N/A **	N/A **		
PROW Intersection	1650	Intersection of Vinyard Way and Claret Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vinyard Way and Claret Ct	\$ 12,000	N/A **	N/A **		
PROW Intersection	1651	Intersection of Oceanview Dr and Spyglass Hill Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oceanview Dr and Spyglass Hill Ln	\$ 9,100	N/A **	N/A **		
PROW Intersection	1652	Intersection of Spyglass Hill Lane and Surf St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Spyglass Hill Lane and Surf St	\$ 15,300	N/A **	N/A **		
PROW Intersection	1653	Intersection of San Lucas Lane and Galante Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of San Lucas Lane and Galante Ln	\$ 17,300	N/A **	N/A **		
PROW Intersection	1654	Intersection of Spyglass Hill Lane and Cliffside Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Spyglass Hill Lane and Cliffside Dr	\$ 11,900	N/A **	N/A **		
PROW Intersection	1655	Intersection of Boxwood Dr and Burr Oak Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Boxwood Dr and Burr Oak Dr	\$ 8,500	N/A **	N/A **		
PROW Intersection	1656	Intersection of Central Village Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Central Village Dr and Driveway	\$ 12,500	N/A **	N/A **		
PROW Intersection	1657	Intersection of Casa Grande Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Casa Grande Dr and Driveway	\$ 9,000	N/A **	N/A **		
PROW Intersection	1658	Intersection of Shoreline Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shoreline Dr and Driveway	\$ 5,700	N/A **	N/A **		
PROW Intersection	1659	Intersection of Shoreline Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shoreline Dr and Driveway	\$ 5,700	N/A **	N/A **		
PROW Intersection	1660	Intersection of Shoreline Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shoreline Dr and Driveway	\$ 4,200	N/A **	N/A **		
PROW Intersection	1661	Intersection of Ridgecrest Cir and Lantana Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ridgecrest Cir and Lantana Dr	\$ 5,000	N/A **	N/A **		
PROW Intersection	1662	Intersection of Regal Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Regal Dr and Driveway	\$ 13,100	N/A **	N/A **		
PROW Intersection	1663	Intersection of Lantana Dr and Sweetgum Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lantana Dr and Sweetgum Dr	\$ 8,000	N/A **	N/A **		
PROW Intersection	1664	Intersection of Unicorn Lake Blvd and Shoreline	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Unicorn Lake Blvd and Shoreline	\$ 22,500	N/A **	N/A **		
PROW Intersection	1665	Intersection of Claret Ct and Shiraz Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Claret Ct and Shiraz Dr	\$ 6,600	N/A **	N/A **		
PROW Intersection	1666	Intersection of Harbour Mist Trl and Del Rey Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harbour Mist Trl and Del Rey Dr	\$ 3,300	N/A **	N/A **		
PROW Intersection	1667	Intersection of Del Rey Dr and Juniperio St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Del Rey Dr and Juniperio St	\$ 3,300	N/A **	N/A **		
PROW Intersection	1668	Intersection of Us Hwy 377 and Central Village Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Us Hwy 377 and Central Village Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1669	Intersection of Pecan Tree Dr and Matt Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pecan Tree Dr and Matt Dr	\$ 15,800	N/A **	N/A **		
PROW Intersection	1670	Intersection of Vinyard Way and Alsace Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vinyard Way and Alsace Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1671	Intersection of Monte Verde Way and Del Rey Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Monte Verde Way and Del Rey Dr	\$ 10,700	N/A **	N/A **		
PROW Intersection	1672	Intersection of Napa Valley Dr and Riesling Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Napa Valley Dr and Riesling Dr	\$ 19,900	N/A **	N/A **		
PROW Intersection	1673	Intersection of San Lucas Lane and Del Rey Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of San Lucas Lane and Del Rey Dr	\$ 16,000	N/A **	N/A **		
PROW Intersection	1674	Intersection of Mustang Dr and Palomino Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mustang Dr and Palomino Ct	\$ 9,600	N/A **	N/A **		
PROW Intersection	1675	Intersection of Camino Real Trail and Del Rey Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Camino Real Trail and Del Rey Dr	\$ 14,100	N/A **	N/A **		
PROW Intersection	1676	Intersection of Shoreline Dr and Clubhouse Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shoreline Dr and Clubhouse Dr	\$ 23,900	N/A **	N/A **		
PROW Intersection	1677	Intersection of Aster Ct and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Aster Ct and Corridor End	\$ 6,800	N/A **	N/A **		
PROW Intersection	1678	Intersection of Sundown Blvd and Mustang Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sundown Blvd and Mustang Dr	\$ 7,600	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1679	Intersection of Oceanview Dr and Del Rey Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oceanview Dr and Del Rey Cir	\$ 6,400	N/A **	N/A **		
PROW Intersection	1680	Intersection of Ridgecrest Cir and Aster Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ridgecrest Cir and Aster Ct	\$ 11,100	N/A **	N/A **		
PROW Intersection	1681	Intersection of Riesling Dr and Rhone Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Riesling Dr and Rhone Dr	\$ 19,500	N/A **	N/A **		
PROW Intersection	1682	Intersection of Pioneer Dr and Sombrero Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pioneer Dr and Sombrero Dr	\$ 19,500	N/A **	N/A **		
PROW Intersection	1683	Intersection of Pioneer Dr and El Dorado Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pioneer Dr and El Dorado Dr	\$ 20,300	N/A **	N/A **		
PROW Intersection	1685	Intersection of Unicorn Lake Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Unicorn Lake Blvd and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	1686	Intersection of Carmel Hills Dr and Rio Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Carmel Hills Dr and Rio Rd	\$ 24,000	N/A **	N/A **		
PROW Intersection	1687	Intersection of Arroyo Trail and Rio Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Arroyo Trail and Rio Rd	\$ 1,300	N/A **	N/A **		
PROW Intersection	1688	Intersection of Sundown Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sundown Blvd and Driveway	\$ 4,100	N/A **	N/A **		
PROW Intersection	1689	Intersection of Lakeview Blvd and Smoketree Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Smoketree Trl	\$ 8,500	N/A **	N/A **		
PROW Intersection	1690	Intersection of Harbour Mist Trl and Rio Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harbour Mist Trl and Rio Rd	\$ 8,800	N/A **	N/A **		
PROW Intersection	1692	Intersection of Napa Valley Dr and Vinyard Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Napa Valley Dr and Vinyard Way	\$ 9,300	N/A **	N/A **		
PROW Intersection	1693	Intersection of Shoreline Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shoreline Dr and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	1695	Intersection of I 35 E and Regal Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of I 35 E and Regal Dr	\$ 1,900	N/A **	N/A **		
PROW Intersection	1696	Intersection of Boxwood Dr and Smoketree Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Boxwood Dr and Smoketree Trl	\$ 20,300	N/A **	N/A **		
PROW Intersection	1698	Intersection of Camino Real Trail and Seaside Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Camino Real Trail and Seaside Dr	\$ 15,800	N/A **	N/A **		
PROW Intersection	1699	Intersection of Daisy Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Daisy Dr and Corridor End	\$ 5,300	N/A **	N/A **		
PROW Intersection	1700	Intersection of Oceanview Dr and Pelican Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oceanview Dr and Pelican Ct	\$ 10,000	N/A **	N/A **		
PROW Intersection	1701	Intersection of Loon Lake Rd and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loon Lake Rd and Midblock Crossing	\$ 4,200	N/A **	N/A **		
PROW Intersection	1702	Intersection of Shiraz Dr and Napa Valley Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shiraz Dr and Napa Valley Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1703	Intersection of Carmel Hills Dr and Portola Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Carmel Hills Dr and Portola Ln	\$ 6,700	N/A **	N/A **		
PROW Intersection	1704	Intersection of Loon Lake Rd and Drainage	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Loon Lake Rd and Drainage	\$ 6,600	N/A **	N/A **		
PROW Intersection	1705	Intersection of Shoreline Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shoreline Dr and Driveway	\$ 12,200	N/A **	N/A **		
PROW Intersection	1706	Intersection of San Lucas Lane and Monte Verde Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of San Lucas Lane and Monte Verde Way	\$ 18,300	N/A **	N/A **		
PROW Intersection	1707	Intersection of Saint Claire Dr and Loon Lake Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Saint Claire Dr and Loon Lake Rd	\$ 7,600	N/A **	N/A **		
PROW Intersection	1709	Intersection of S Mayhill Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Mayhill Rd and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	1710	Intersection of Harbour Mist Trl and Portola Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harbour Mist Trl and Portola Ln	\$ 1,300	N/A **	N/A **		
PROW Intersection	1711	Intersection of Unicorn Lake Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Unicorn Lake Blvd and Driveway	\$ 14,500	N/A **	N/A **		
PROW Intersection	1712	Intersection of Camino Real Trail and Wavecrest Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Camino Real Trail and Wavecrest Ln	\$ 17,300	N/A **	N/A **		
PROW Intersection	1713	Intersection of Shoreline Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shoreline Dr and Driveway	\$ 7,800	N/A **	N/A **		
PROW Intersection	1714	Intersection of Lakeview Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Driveway	\$ 9,000	N/A **	N/A **		
PROW Intersection	1715	Intersection of Unicorn Lake Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Unicorn Lake Blvd and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1716	Intersection of Shoreline Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shoreline Dr and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1717	Intersection of Desert Willow Dr and Chittamwood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Desert Willow Dr and Chittamwood Dr	\$ 13,100	N/A **	N/A **		
PROW Intersection	1718	Intersection of Boxwood Dr and Chittamwood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Boxwood Dr and Chittamwood Dr	\$ 13,700	N/A **	N/A **		
PROW Intersection	1719	Intersection of Camino Real Trail and Monte Verde Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Camino Real Trail and Monte Verde Way	\$ 10,100	N/A **	N/A **		
PROW Intersection	1720	Intersection of Carmel Hills Dr and Las Lomas Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Carmel Hills Dr and Las Lomas Ln	\$ 7,700	N/A **	N/A **		
PROW Intersection	1721	Intersection of Pennsylvania Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pennsylvania Dr and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	1722	Intersection of Seaside Dr and Bayshore Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Seaside Dr and Bayshore Dr	\$ 8,900	N/A **	N/A **		
PROW Intersection	1723	Intersection of Las Lomas Ln and Cabrillo Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Las Lomas Ln and Cabrillo Dr	\$ 7,500	N/A **	N/A **		
PROW Intersection	1724	Intersection of Oceanview Dr and Bayshore Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oceanview Dr and Bayshore Dr	\$ 14,000	N/A **	N/A **		
PROW Intersection	1725	Intersection of Harbour Mist Trl and Las Lomas Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harbour Mist Trl and Las Lomas Ln	\$ 10,500	N/A **	N/A **		
PROW Intersection	1726	Intersection of Wind River Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Driveway	\$ 4,600	N/A **	N/A **		
PROW Intersection	1727	Intersection of Wind River Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Driveway	\$ 15,500	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1728	Intersection of Wind River Ln and Unicorn Lake Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Unicorn Lake Blvd	\$ 20,700	N/A **	N/A **		
PROW Intersection	1729	Intersection of Wind River Ln and Shoreline Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Shoreline Dr	\$ 20,200	N/A **	N/A **		
PROW Intersection	1730	Intersection of San Lucas Lane and Las Lomas Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of San Lucas Lane and Las Lomas Ln	\$ 9,800	N/A **	N/A **		
PROW Intersection	1731	Intersection of Boxwood Ct and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Boxwood Ct and Corridor End	\$ 4,500	N/A **	N/A **		
PROW Intersection	1732	Intersection of Saint Claire Dr and Lamprey Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Saint Claire Dr and Lamprey Cir	\$ 12,300	N/A **	N/A **		
PROW Intersection	1733	Intersection of Meredith Ln and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meredith Ln and Corridor End	\$ 6,600	N/A **	N/A **		
PROW Intersection	1734	Intersection of Wind River Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	1735	Intersection of Champlain Ln and Champlain Ln S	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Champlain Ln and Champlain Ln S	\$ 6,500	N/A **	N/A **		
PROW Intersection	1736	Intersection of Juniper Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Juniper Dr and Corridor End	\$ 6,000	N/A **	N/A **		
PROW Intersection	1737	Intersection of Wind River Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1738	Intersection of Wind River Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1739	Intersection of Wavecrest Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wavecrest Ln and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	1740	Intersection of Wind River Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Driveway	\$ 12,500	N/A **	N/A **		
PROW Intersection	1741	Intersection of Wind River Ln and Osage Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Osage Ln	\$ 10,600	N/A **	N/A **		
PROW Intersection	1742	Intersection of S Mayhill Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Mayhill Rd and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	1743	Intersection of E Hobson Ln and Montecito Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Hobson Ln and Montecito Rd	\$ 6,500	N/A **	N/A **		
PROW Intersection	1744	Intersection of Teasley Ln and Pennsylvania Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Pennsylvania Dr	\$ 3,600	N/A **	N/A **		
PROW Intersection	1745	Intersection of Teasley Ln and Indian Ridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Indian Ridge Dr	\$ 3,300	N/A **	N/A **		
PROW Intersection	1746	Intersection of Wind River Ln and St Claire Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and St Claire Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	1748	Intersection of Wind River Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Driveway	\$ 9,400	N/A **	N/A **		
PROW Intersection	1749	Intersection of E Hobson Ln and Carmel St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Hobson Ln and Carmel St	\$ 6,500	N/A **	N/A **		
PROW Intersection	1751	Intersection of Carmel Hills Dr and Marina Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Carmel Hills Dr and Marina Dr	\$ 3,500	N/A **	N/A **		
PROW Intersection	1752	Intersection of Marina Dr and Cabrillo Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marina Dr and Cabrillo Dr	\$ 12,400	N/A **	N/A **		
PROW Intersection	1753	Intersection of Como Lake Rd and Crater Lake Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Como Lake Rd and Crater Lake Ln	\$ 9,600	N/A **	N/A **		
PROW Intersection	1754	Intersection of San Lucas Lane and San Lucas Lane	N/A	See facility report and GIS data for detailed evaluation findings at intersection of San Lucas Lane and San Lucas Lane	\$ 3,900	N/A **	N/A **		
PROW Intersection	1755	Intersection of Wind River Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1756	Intersection of Wind River Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Midblock Crossing	\$ 6,600	N/A **	N/A **		
PROW Intersection	1757	Intersection of Camino Real Trail and Marina Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Camino Real Trail and Marina Dr	\$ 16,900	N/A **	N/A **		
PROW Intersection	1758	Intersection of Wind River Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Driveway	\$ 15,000	N/A **	N/A **		
PROW Intersection	1759	Intersection of Desert Willow Dr and Red Cedar Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Desert Willow Dr and Red Cedar Ct	\$ 15,200	N/A **	N/A **		
PROW Intersection	1760	Intersection of Marina Dr and Peninsula Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marina Dr and Peninsula Dr	\$ 8,500	N/A **	N/A **		
PROW Intersection	1761	Intersection of Marina Dr and Wavecrest Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marina Dr and Wavecrest Ln	\$ 2,600	N/A **	N/A **		
PROW Intersection	1762	Intersection of Champlain Ln and Caddo Cr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Champlain Ln and Caddo Cr	\$ 13,400	N/A **	N/A **		
PROW Intersection	1763	Intersection of Crater Lake Ln and Herring Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crater Lake Ln and Herring Ct	\$ 9,300	N/A **	N/A **		
PROW Intersection	1764	Intersection of Osage Ln and Huron Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Osage Ln and Huron Cir	\$ 13,400	N/A **	N/A **		
PROW Intersection	1765	Intersection of Marina Dr and Seaside Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marina Dr and Seaside Dr	\$ 2,500	N/A **	N/A **		
PROW Intersection	1766	Intersection of Meredith Ln and Kariba Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meredith Ln and Kariba Ln	\$ 9,000	N/A **	N/A **		
PROW Intersection	1767	Intersection of Oceanview Dr and Marina Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oceanview Dr and Marina Dr	\$ 8,700	N/A **	N/A **		
PROW Intersection	1768	Intersection of Potterstone St and Barrymore Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Potterstone St and Barrymore Rd	\$ 12,800	N/A **	N/A **		
PROW Intersection	1769	Intersection of Wind River Ln and Ottawa Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Ottawa Ln	\$ 10,600	N/A **	N/A **		
PROW Intersection	1770	Intersection of Red Cedar Ct and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Red Cedar Ct and Corridor End	\$ 6,000	N/A **	N/A **		
PROW Intersection	1771	Intersection of Lillian B Miller Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lillian B Miller Pkwy and Driveway	\$ 12,000	N/A **	N/A **		
PROW Intersection	1772	Intersection of Pennsylvania Dr and Abbot's Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pennsylvania Dr and Abbot's Ln	\$ 7,600	N/A **	N/A **		
PROW Intersection	1773	Intersection of Abbot's Ln and Hope St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Abbot's Ln and Hope St	\$ 10,100	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1774	Intersection of Wind River Ln and Como Lake Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Como Lake Rd	\$ 10,000	N/A **	N/A **		
PROW Intersection	1775	Intersection of Wind River Ln and Union Lake Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Union Lake Rd	\$ 9,800	N/A **	N/A **		
PROW Intersection	1776	Intersection of Carmel Hills Dr and Wharfside Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Carmel Hills Dr and Wharfside Pl	\$ 3,300	N/A **	N/A **		
PROW Intersection	1777	Intersection of Wind River Ln and Champlain Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Champlain Ln	\$ 9,300	N/A **	N/A **		
PROW Intersection	1778	Intersection of Wharfside Pl and Cabrillo Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wharfside Pl and Cabrillo Dr	\$ 18,000	N/A **	N/A **		
PROW Intersection	1779	Intersection of Wind River Ln and Meredith Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Meredith Ln	\$ 6,600	N/A **	N/A **		
PROW Intersection	1780	Intersection of Ih35E and Wind River Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ih35E and Wind River Ln	\$ 7,500	N/A **	N/A **		
PROW Intersection	1781	Intersection of Wind River Ln and Shoshone Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Shoshone Ln	\$ 10,800	N/A **	N/A **		
PROW Intersection	1782	Intersection of Wind River Ln and Widgeon Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wind River Ln and Widgeon Ln	\$ 6,600	N/A **	N/A **		
PROW Intersection	1783	Intersection of Ottawa Ln and Tahoe Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ottawa Ln and Tahoe Ln	\$ 9,000	N/A **	N/A **		
PROW Intersection	1784	Intersection of Camino Real Trail and Wharfside Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Camino Real Trail and Wharfside Pl	\$ 12,400	N/A **	N/A **		
PROW Intersection	1785	Intersection of Abbot's Ln and Providence St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Abbot's Ln and Providence St	\$ 10,200	N/A **	N/A **		
PROW Intersection	1786	Intersection of Desert Willow Dr and Silktree Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Desert Willow Dr and Silktree Ct	\$ 19,500	N/A **	N/A **		
PROW Intersection	1787	Intersection of Jackpine Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Jackpine Dr and Corridor End	\$ 7,500	N/A **	N/A **		
PROW Intersection	1788	Intersection of Potterstone St and Jackpine Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Potterstone St and Jackpine Dr	\$ 11,400	N/A **	N/A **		
PROW Intersection	1789	Intersection of Lillian B Miller Pkwy and Hunters Ridge Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lillian B Miller Pkwy and Hunters Ridge Cir	\$ 6,000	N/A **	N/A **		
PROW Intersection	1790	Intersection of Shoshone Ln and Tahoe Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shoshone Ln and Tahoe Ln	\$ 10,100	N/A **	N/A **		
PROW Intersection	1791	Intersection of Osage Ln and Whitefish Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Osage Ln and Whitefish Ct	\$ 9,600	N/A **	N/A **		
PROW Intersection	1792	Intersection of S Mayhill Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Mayhill Rd and Driveway	\$ 6,700	N/A **	N/A **		
PROW Intersection	1793	Intersection of Silktree Ct and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Silktree Ct and Corridor End	\$ 4,400	N/A **	N/A **		
PROW Intersection	1794	Intersection of Hope St and Providence St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hope St and Providence St	\$ 15,000	N/A **	N/A **		
PROW Intersection	1795	Intersection of Hunters Ridge Cir and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hunters Ridge Cir and Corridor End	\$ 7,300	N/A **	N/A **		
PROW Intersection	1796	Intersection of Sea Cove Ln and Cabrillo Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sea Cove Ln and Cabrillo Dr	\$ 12,400	N/A **	N/A **		
PROW Intersection	1797	Intersection of Tahoe Ln and Saranac Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Tahoe Ln and Saranac Cir	\$ 9,800	N/A **	N/A **		
PROW Intersection	1798	Intersection of Hinkley Oak Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkley Oak Dr and Corridor End	\$ 5,900	N/A **	N/A **		
PROW Intersection	1799	Intersection of Hinkley Oak Dr and Barrydale Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkley Oak Dr and Barrydale Dr	\$ 16,800	N/A **	N/A **		
PROW Intersection	1800	Intersection of Edwards Rd and Desert Willow Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Desert Willow Dr	\$ 18,300	N/A **	N/A **		
PROW Intersection	1801	Intersection of Camino Real Trail and Sea Cove Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Camino Real Trail and Sea Cove Ln	\$ 20,100	N/A **	N/A **		
PROW Intersection	1802	Intersection of Valencia Ln and Widgeon Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Valencia Ln and Widgeon Ln	\$ 9,300	N/A **	N/A **		
PROW Intersection	1803	Intersection of Valencia Ln and Union Lake Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Valencia Ln and Union Lake Rd	\$ 6,500	N/A **	N/A **		
PROW Intersection	1804	Intersection of Valencia Ln and Waterton Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Valencia Ln and Waterton Cir	\$ 9,000	N/A **	N/A **		
PROW Intersection	1805	Intersection of Edwards Rd and Swisher Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Swisher Rd	\$ 3,100	N/A **	N/A **		
PROW Intersection	1806	Intersection of Edwards Rd and Swisher Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Swisher Rd	\$ 3,000	N/A **	N/A **		
PROW Intersection	1807	Intersection of I 35 E and Medpark Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of I 35 E and Medpark Dr	\$ 4,500	N/A **	N/A **		
PROW Intersection	1808	Intersection of Lakeview Blvd and Edwards Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Edwards Rd	\$ 9,700	N/A **	N/A **		
PROW Intersection	1809	Intersection of Ottawa Ln and Geneva Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ottawa Ln and Geneva Cir	\$ 9,500	N/A **	N/A **		
PROW Intersection	1810	Intersection of Edwards Rd and Capetown Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Capetown Dr	\$ 19,500	N/A **	N/A **		
PROW Intersection	1811	Intersection of Edwards Rd and Cabrillo Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Cabrillo Dr	\$ 5,800	N/A **	N/A **		
PROW Intersection	1812	Intersection of Abbot's Ln and Chapel Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Abbot's Ln and Chapel Dr	\$ 10,500	N/A **	N/A **		
PROW Intersection	1813	Intersection of Edwards Rd and Forrest Willow Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Forrest Willow Rd	\$ 6,700	N/A **	N/A **		
PROW Intersection	1814	Intersection of Edwards Rd and Camino Real Trail	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Camino Real Trail	\$ 13,000	N/A **	N/A **		
PROW Intersection	1815	Intersection of Chapel Dr and Hope St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chapel Dr and Hope St	\$ 15,800	N/A **	N/A **		
PROW Intersection	1816	Intersection of Hinkley Oak Dr and Sweetgate Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkley Oak Dr and Sweetgate Ln	\$ 11,100	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1817	Intersection of Pennsylvania Dr and Chapel Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pennsylvania Dr and Chapel Dr	\$ 7,100	N/A **	N/A **		
PROW Intersection	1818	Intersection of Barrydale Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Barrydale Dr and Corridor End	\$ 7,500	N/A **	N/A **		
PROW Intersection	1819	Intersection of Edwards Rd and Birdie Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Birdie Dr	\$ 12,700	N/A **	N/A **		
PROW Intersection	1820	Intersection of Lillian B Miller Pkwy and Hunters Ridge Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lillian B Miller Pkwy and Hunters Ridge Cir	\$ 6,500	N/A **	N/A **		
PROW Intersection	1821	Intersection of Edwards Rd and Par Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Par Dr	\$ 13,400	N/A **	N/A **		
PROW Intersection	1822	Intersection of Desert Willow Dr and Evening Wind Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Desert Willow Dr and Evening Wind Rd	\$ 11,700	N/A **	N/A **		
PROW Intersection	1823	Intersection of Sweetgate Ln and Caribou Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sweetgate Ln and Caribou Ct	\$ 12,000	N/A **	N/A **		
PROW Intersection	1824	Intersection of Edwards Rd and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Edwards Rd and Corridor End	\$ 2,500	N/A **	N/A **		
PROW Intersection	1825	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 1,200	N/A **	N/A **		
PROW Intersection	1826	Intersection of Lakeview Blvd and Desert Willow Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Desert Willow Dr	\$ 13,800	N/A **	N/A **		
PROW Intersection	1827	Intersection of Potterstone St and Valley Stream Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Potterstone St and Valley Stream Rd	\$ 13,600	N/A **	N/A **		
PROW Intersection	1829	Intersection of Great Bear Ln and Kootenay Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Great Bear Ln and Kootenay Cir	\$ 9,000	N/A **	N/A **		
PROW Intersection	1830	Intersection of Desert Willow Dr and Capetown Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Desert Willow Dr and Capetown Dr	\$ 14,800	N/A **	N/A **		
PROW Intersection	1831	Intersection of Great Bear Ln and Ottawa Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Great Bear Ln and Ottawa Ln	\$ 9,600	N/A **	N/A **		
PROW Intersection	1832	Intersection of Great Bear Ln and Donner Lk	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Great Bear Ln and Donner Lk	\$ 9,000	N/A **	N/A **		
PROW Intersection	1833	Intersection of Hinkley Oak Dr and Red Wolfe Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkley Oak Dr and Red Wolfe Rd	\$ 11,200	N/A **	N/A **		
PROW Intersection	1834	Intersection of Desert Willow Dr and Knoll Pines Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Desert Willow Dr and Knoll Pines Rd	\$ 14,700	N/A **	N/A **		
PROW Intersection	1835	Intersection of Desert Willow Dr and Glen Crest Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Desert Willow Dr and Glen Crest Ln	\$ 10,600	N/A **	N/A **		
PROW Intersection	1836	Intersection of Lakeview Blvd and Valley Stream Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Valley Stream Rd	\$ 14,100	N/A **	N/A **		
PROW Intersection	1837	Intersection of Sweetgate Ln and Autumn Path Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sweetgate Ln and Autumn Path Rd	\$ 9,800	N/A **	N/A **		
PROW Intersection	1838	Intersection of Par Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Par Dr and Driveway	\$ 11,800	N/A **	N/A **		
PROW Intersection	1839	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1840	Intersection of Abbot's Ln and Sandpiper Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Abbot's Ln and Sandpiper Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1843	Intersection of Teasley Ln and Sandpiper Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Sandpiper Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	1844	Intersection of Hinkley Oak Dr and Bishop Pine Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkley Oak Dr and Bishop Pine Rd	\$ 5,900	N/A **	N/A **		
PROW Intersection	1845	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1846	Intersection of Birdie Dr and Par Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Birdie Dr and Par Dr	\$ 17,400	N/A **	N/A **		
PROW Intersection	1847	Intersection of Norfolk Ct and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Norfolk Ct and Cul-De-Sac	\$ 4,500	N/A **	N/A **		
PROW Intersection	1848	Intersection of Colorado Blvd and Mayhill Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Colorado Blvd and Mayhill Rd	\$ 2,500	N/A **	N/A **		
PROW Intersection	1849	Intersection of Lakeview Blvd and Sweetgate Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Sweetgate Ln	\$ 21,000	N/A **	N/A **		
PROW Intersection	1850	Intersection of Par Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Par Dr and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	1851	Intersection of Shenandoah Trail and Shiloh Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shenandoah Trail and Shiloh Rd	\$ 9,000	N/A **	N/A **		
PROW Intersection	1852	Intersection of Shenandoah Trail and Charleston Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shenandoah Trail and Charleston Ct	\$ 10,800	N/A **	N/A **		
PROW Intersection	1853	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	1854	Intersection of Shenandoah Trail and Southridge Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shenandoah Trail and Southridge Dr	\$ 16,900	N/A **	N/A **		
PROW Intersection	1855	Intersection of Shenandoah Trail and Cape Hatteras Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shenandoah Trail and Cape Hatteras Ct	\$ 10,500	N/A **	N/A **		
PROW Intersection	1856	Intersection of Evening Wind Rd and Rolling Green Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Evening Wind Rd and Rolling Green Rd	\$ 13,500	N/A **	N/A **		
PROW Intersection	1857	Intersection of Shenandoah Trail and Cumberland Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shenandoah Trail and Cumberland Ct	\$ 16,800	N/A **	N/A **		
PROW Intersection	1858	Intersection of Par Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Par Dr and Midblock Crossing	\$ 2,100	N/A **	N/A **		
PROW Intersection	1859	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 3,300	N/A **	N/A **		
PROW Intersection	1860	Intersection of Lillian B Miller Pkwy and Shenandoah Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lillian B Miller Pkwy and Shenandoah Trl	\$ 6,500	N/A **	N/A **		
PROW Intersection	1861	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 1,500	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	1862	Intersection of Lakeview Blvd and Apple Valley Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Apple Valley Ct	\$ 15,000	N/A **	N/A **		
PROW Intersection	1863	Intersection of Potomac Pkwy and Shiloh Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Potomac Pkwy and Shiloh Rd	\$ 12,300	N/A **	N/A **		
PROW Intersection	1864	Intersection of Potomac Pkwy and Stone Mountain Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Potomac Pkwy and Stone Mountain Dr	\$ 18,400	N/A **	N/A **		
PROW Intersection	1865	Intersection of Bishop Pine Rd and Red Wolfe Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bishop Pine Rd and Red Wolfe Rd	\$ 7,200	N/A **	N/A **		
PROW Intersection	1866	Intersection of Southridge Dr and Natchez Trce	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Southridge Dr and Natchez Trce	\$ 9,800	N/A **	N/A **		
PROW Intersection	1867	Intersection of Potomac Pkwy and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Potomac Pkwy and Cul-De-Sac	\$ 6,800	N/A **	N/A **		
PROW Intersection	1868	Intersection of Shiloh Rd and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shiloh Rd and Cul-De-Sac	\$ 12,000	N/A **	N/A **		
PROW Intersection	1869	Intersection of Lynhurst Ln and Jefferson Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lynhurst Ln and Jefferson Trl	\$ 11,200	N/A **	N/A **		
PROW Intersection	1871	Intersection of Lakeview Blvd and Autumn Path Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Autumn Path Rd	\$ 13,000	N/A **	N/A **		
PROW Intersection	1872	Intersection of Colorado Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Colorado Blvd and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	1873	Intersection of S Mayhill Rd and S Mayhill Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Mayhill Rd and S Mayhill Rd	\$ 2,300	N/A **	N/A **		
PROW Intersection	1874	Intersection of Southridge Dr and Richmond Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Southridge Dr and Richmond Ct	\$ 15,500	N/A **	N/A **		
PROW Intersection	1875	Intersection of Bishop Pine Rd and Barnhill Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bishop Pine Rd and Barnhill Ct	\$ 8,300	N/A **	N/A **		
PROW Intersection	1876	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	1877	Intersection of Bishop Pine Rd and Hawks View Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bishop Pine Rd and Hawks View Ln	\$ 4,000	N/A **	N/A **		
PROW Intersection	1878	Intersection of Bishop Pine Rd and Knoll Pines Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bishop Pine Rd and Knoll Pines Rd	\$ 21,300	N/A **	N/A **		
PROW Intersection	1879	Intersection of Bishop Pine Rd and Key Largo Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bishop Pine Rd and Key Largo Ct	\$ 22,000	N/A **	N/A **		
PROW Intersection	1880	Intersection of Bishop Pine Rd and Glen Crest Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bishop Pine Rd and Glen Crest Ln	\$ 10,400	N/A **	N/A **		
PROW Intersection	1881	Intersection of Bishop Pine Rd and Evening Wind Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bishop Pine Rd and Evening Wind Rd	\$ 9,300	N/A **	N/A **		
PROW Intersection	1882	Intersection of Bishop Pine Rd and Capetown Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bishop Pine Rd and Capetown Dr	\$ 16,600	N/A **	N/A **		
PROW Intersection	1883	Intersection of Natchez Trace and Stone Mountain Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Natchez Trace and Stone Mountain Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	1884	Intersection of Natchez Trace and Shiloh Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Natchez Trace and Shiloh Rd	\$ 9,600	N/A **	N/A **		
PROW Intersection	1885	Intersection of Natchez Trace and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Natchez Trace and Cul-De-Sac	\$ 13,400	N/A **	N/A **		
PROW Intersection	1886	Intersection of I 35 E and Brinker Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of I 35 E and Brinker Rd	\$ 4,000	N/A **	N/A **		
PROW Intersection	1887	Intersection of Lakeview Blvd and Bishop Pine Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Bishop Pine Rd	\$ 16,000	N/A **	N/A **		
PROW Intersection	1888	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 4,700	N/A **	N/A **		
PROW Intersection	1889	Intersection of Southridge Dr and Lynhurst Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Southridge Dr and Lynhurst Ln	\$ 16,600	N/A **	N/A **		
PROW Intersection	1890	Intersection of Colorado Blvd and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Colorado Blvd and Corridor End	\$ 2,300	N/A **	N/A **		
PROW Intersection	1892	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 700	N/A **	N/A **		
PROW Intersection	1893	Intersection of S Mayhill Rd and Leafy Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Mayhill Rd and Leafy Rd	\$ 1,600	N/A **	N/A **		
PROW Intersection	1894	Intersection of Colorado Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Colorado Blvd and Driveway	\$ 1,500	N/A **	N/A **		
PROW Intersection	1895	Intersection of Brinker Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brinker Rd and Driveway	\$ 5,500	N/A **	N/A **		
PROW Intersection	1896	Intersection of Medpark Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Medpark Dr and Driveway	\$ 3,300	N/A **	N/A **		
PROW Intersection	1897	Intersection of Southridge Dr and Hollyhill Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Southridge Dr and Hollyhill Ln	\$ 7,000	N/A **	N/A **		
PROW Intersection	1898	Intersection of Lillian B Miller Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lillian B Miller Pkwy and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	1899	Intersection of Lakeview Blvd and Hudson Bay Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakeview Blvd and Hudson Bay Ln	\$ 13,800	N/A **	N/A **		
PROW Intersection	1900	Intersection of Colorado Blvd and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Colorado Blvd and Midblock Crossing	\$ 2,300	N/A **	N/A **		
PROW Intersection	1901	Intersection of Longridge Dr and Fairfax Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Longridge Dr and Fairfax Rd	\$ 8,200	N/A **	N/A **		
PROW Intersection	1902	Intersection of Longridge Dr and Jefferson Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Longridge Dr and Jefferson Trl	\$ 6,000	N/A **	N/A **		
PROW Intersection	1903	Intersection of Teasley Ln and Longridge	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Teasley Ln and Longridge	\$ 6,300	N/A **	N/A **		
PROW Intersection	1905	Intersection of Longridge Dr and Savannah	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Longridge Dr and Savannah	\$ 6,500	N/A **	N/A **		











Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2127	Intersection of Cole Ave and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cole Ave and Midblock Crossing	\$ 5,500	N/A **	N/A **		
PROW Intersection	2128	Intersection of W Collins St and Cleveland St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Collins St and Cleveland St	\$ 800	N/A **	N/A **		
PROW Intersection	2129	Intersection of Simmons St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Simmons St and Us Hwy 77	\$ 3,600	N/A **	N/A **		
PROW Intersection	2131	Intersection of Shady Oaks Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shady Oaks Dr and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	2132	Intersection of Cook St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cook St and Midblock Crossing	\$ 2,500	N/A **	N/A **		
PROW Intersection	2133	Intersection of Duncan St and Kerley St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duncan St and Kerley St	\$ 9,800	N/A **	N/A **		
PROW Intersection	2134	Intersection of Cleveland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cleveland St and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	2135	Intersection of Morse St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Driveway	\$ 500	N/A **	N/A **		
PROW Intersection	2136	Intersection of Morse St and Kimberly Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Kimberly Dr	\$ 7,000	N/A **	N/A **		
PROW Intersection	2137	Intersection of S Carroll Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Carroll Blvd and Driveway	\$ 3,400	N/A **	N/A **		
PROW Intersection	2138	Intersection of Morse St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2139	Intersection of S Mayhill Rd and Morse St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Mayhill Rd and Morse St	\$ 7,400	N/A **	N/A **		
PROW Intersection	2140	Intersection of Morse St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	2141	Intersection of Morse St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Driveway	\$ -	N/A **	N/A **		
PROW Intersection	2142	Intersection of Morse St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2143	Intersection of Morse St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2144	Intersection of Glengary Way and Paulie Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glengary Way and Paulie Dr	\$ 8,900	N/A **	N/A **		
PROW Intersection	2145	Intersection of Myrtle St and Us Hwy 377	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Myrtle St and Us Hwy 377	\$ 600	N/A **	N/A **		
PROW Intersection	2146	Intersection of Collier St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Collier St and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	2147	Intersection of Paulie Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paulie Dr and Midblock Crossing	\$ 5,800	N/A **	N/A **		
PROW Intersection	2148	Intersection of Cook St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cook St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2149	Intersection of S Woodrow Ln and Morse St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Woodrow Ln and Morse St	\$ 14,400	N/A **	N/A **		
PROW Intersection	2150	Intersection of Myrtle St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Myrtle St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2151	Intersection of North Texas Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of North Texas Blvd and Driveway	\$ 600	N/A **	N/A **		
PROW Intersection	2152	Intersection of Bernard St and Fannin St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bernard St and Fannin St	\$ 600	N/A **	N/A **		
PROW Intersection	2153	Intersection of Fannin St and Beatty St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fannin St and Beatty St	\$ 3,600	N/A **	N/A **		
PROW Intersection	2154	Intersection of S Welch St and Fannin St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Welch St and Fannin St	\$ 8,300	N/A **	N/A **		
PROW Intersection	2155	Intersection of Ave A and Fannin St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ave A and Fannin St	\$ 13,200	N/A **	N/A **		
PROW Intersection	2156	Intersection of Fannin St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fannin St and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2157	Intersection of North Texas Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of North Texas Blvd and Driveway	\$ 1,200	N/A **	N/A **		
PROW Intersection	2158	Intersection of S Carroll Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Carroll Blvd and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2159	Intersection of Glengary Way and Whiting Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glengary Way and Whiting Way	\$ 10,300	N/A **	N/A **		
PROW Intersection	2160	Intersection of Whiting Way and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Whiting Way and Midblock Crossing	\$ 5,300	N/A **	N/A **		
PROW Intersection	2161	Intersection of North Texas Blvd and Wilshire St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of North Texas Blvd and Wilshire St	\$ 2,900	N/A **	N/A **		
PROW Intersection	2162	Intersection of Wilshire St and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wilshire St and Corridor End	\$ 3,800	N/A **	N/A **		
PROW Intersection	2163	Intersection of Wilshire St and Kendolph Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wilshire St and Kendolph Dr	\$ 8,300	N/A **	N/A **		
PROW Intersection	2164	Intersection of Ave A and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ave A and Driveway	\$ 2,200	N/A **	N/A **		
PROW Intersection	2165	Intersection of Bernard St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bernard St and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	2166	Intersection of S Welch St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Welch St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2167	Intersection of Myrtle St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Myrtle St and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	2168	Intersection of Cleveland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cleveland St and Driveway	\$ 1,000	N/A **	N/A **		
PROW Intersection	2169	Intersection of Glengary Way and Tartan Cr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glengary Way and Tartan Cr	\$ 5,200	N/A **	N/A **		
PROW Intersection	2170	Intersection of Morse St and Bushey St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Bushey St	\$ 4,800	N/A **	N/A **		
PROW Intersection	2171	Intersection of Morse St and Newton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Newton St	\$ 1,600	N/A **	N/A **		
PROW Intersection	2172	Intersection of Morse St and Duncan St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Duncan St	\$ 7,300	N/A **	N/A **		
PROW Intersection	2173	Intersection of Morse St and Robertson St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Robertson St	\$ 3,800	N/A **	N/A **		
PROW Intersection	2174	Intersection of Robertson St and Mill St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robertson St and Mill St	\$ 5,800	N/A **	N/A **		
PROW Intersection	2175	Intersection of Mill St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mill St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2176	Intersection of Cross Timber St and Mill St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cross Timber St and Mill St	\$ 2,800	N/A **	N/A **		
PROW Intersection	2177	Intersection of Eagle Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Eagle Dr and Driveway	\$ 2,000	N/A **	N/A **		
PROW Intersection	2178	Intersection of W Eagle Dr and Cleveland St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Eagle Dr and Cleveland St	\$ 800	N/A **	N/A **		
PROW Intersection	2179	Intersection of W Eagle Dr and Beatty St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Eagle Dr and Beatty St	\$ 1,500	N/A **	N/A **		
PROW Intersection	2180	Intersection of W Eagle Dr and McCormick St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Eagle Dr and McCormick St	\$ 3,300	N/A **	N/A **		
PROW Intersection	2181	Intersection of Eagle Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Eagle Dr and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	2182	Intersection of W Eagle Dr and S Ave B	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Eagle Dr and S Ave B	\$ 1,200	N/A **	N/A **		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2239	Intersection of W Highland St and Carroll Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Carroll Blvd	\$ 10,800	N/A **	N/A **		
PROW Intersection	2240	Intersection of W Highland St and Pierce St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Pierce St	\$ 5,200	N/A **	N/A **		
PROW Intersection	2241	Intersection of W Highland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Driveway	\$ 1,700	N/A **	N/A **		
PROW Intersection	2242	Intersection of W Highland St and Pierce St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Pierce St	\$ 2,500	N/A **	N/A **		
PROW Intersection	2243	Intersection of W Highland St and loof St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and loof St	\$ 5,900	N/A **	N/A **		
PROW Intersection	2244	Intersection of W Highland St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Us Hwy 77	\$ 4,000	N/A **	N/A **		
PROW Intersection	2245	Intersection of W Highland St and Bernard St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Bernard St	\$ 17,100	N/A **	N/A **		
PROW Intersection	2246	Intersection of W Highland St and Ave A	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Ave A	\$ 10,800	N/A **	N/A **		
PROW Intersection	2247	Intersection of Central Ave and W Highland St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Central Ave and W Highland St	\$ 10,500	N/A **	N/A **		
PROW Intersection	2248	Intersection of Ave S and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ave S and Midblock Crossing	\$ 2,800	N/A **	N/A **		
PROW Intersection	2249	Intersection of Lakey St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakey St and Driveway	\$ 6,500	N/A **	N/A **		
PROW Intersection	2250	Intersection of W Highland St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Midblock Crossing	\$ 2,500	N/A **	N/A **		
PROW Intersection	2251	Intersection of W Highland St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Midblock Crossing	\$ 5,800	N/A **	N/A **		
PROW Intersection	2252	Intersection of W Highland St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Midblock Crossing	\$ 6,500	N/A **	N/A **		
PROW Intersection	2253	Intersection of W Highland St and S Ave C	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and S Ave C	\$ 19,300	N/A **	N/A **		
PROW Intersection	2254	Intersection of W Highland St and Ave D	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Ave D	\$ 9,600	N/A **	N/A **		
PROW Intersection	2255	Intersection of W Highland St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and Midblock Crossing	\$ 4,800	N/A **	N/A **		
PROW Intersection	2256	Intersection of W Highland St and North Texas Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Highland St and North Texas Blvd	\$ 11,300	N/A **	N/A **		
PROW Intersection	2257	Intersection of S Bonnie Brae St and I-35 E Frontage Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bonnie Brae St and I-35 E Frontage Rd	\$ 3,000	N/A **	N/A **		
PROW Intersection	2258	Intersection of Duchess Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duchess Dr and Driveway	\$ 5,500	N/A **	N/A **		
PROW Intersection	2259	Intersection of Duchess Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duchess Dr and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	2260	Intersection of Duchess Dr and Wrangler Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duchess Dr and Wrangler Ln	\$ 5,100	N/A **	N/A **		
PROW Intersection	2261	Intersection of Duchess Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duchess Dr and Driveway	\$ 1,500	N/A **	N/A **		
PROW Intersection	2262	Intersection of Duchess Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duchess Dr and Driveway	\$ 4,900	N/A **	N/A **		
PROW Intersection	2263	Intersection of Ave S and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ave S and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	2264	Intersection of Duchess Dr and S Mockingbird Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duchess Dr and S Mockingbird Ln	\$ 12,000	N/A **	N/A **		
PROW Intersection	2265	Intersection of Duchess Dr and Stockade Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duchess Dr and Stockade Ln	\$ 4,400	N/A **	N/A **		
PROW Intersection	2266	Intersection of Duchess Dr and Trailhead Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duchess Dr and Trailhead Ln	\$ 6,200	N/A **	N/A **		
PROW Intersection	2267	Intersection of Lakey St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lakey St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2268	Intersection of S Bradshaw St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bradshaw St and Midblock Crossing	\$ 1,100	N/A **	N/A **		
PROW Intersection	2269	Intersection of Warren Ct and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Warren Ct and Us Hwy 77	\$ 6,000	N/A **	N/A **		
PROW Intersection	2270	Intersection of S Ruddell St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Ruddell St and Driveway	\$ 4,200	N/A **	N/A **		
PROW Intersection	2271	Intersection of S Bradshaw St and E Prairie St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bradshaw St and E Prairie St	\$ 3,000	N/A **	N/A **		
PROW Intersection	2272	Intersection of North Texas Blvd and Allen Saxe Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of North Texas Blvd and Allen Saxe Dr	\$ 5,300	N/A **	N/A **		
PROW Intersection	2274	Intersection of W Prairie St and Bernard St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Prairie St and Bernard St	\$ 2,500	N/A **	N/A **		
PROW Intersection	2275	Intersection of W Prairie St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Prairie St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2276	Intersection of Union Cir and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Union Cir and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	2277	Intersection of Union Cir and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Union Cir and Driveway	\$ 7,000	N/A **	N/A **		
PROW Intersection	2278	Intersection of S Ave C and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Ave C and Midblock Crossing	\$ 3,800	N/A **	N/A **		
PROW Intersection	2279	Intersection of S Bradshaw St and E Prairie St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bradshaw St and E Prairie St	\$ 6,800	N/A **	N/A **		
PROW Intersection	2280	Intersection of E Prairie St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Prairie St and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	2281	Intersection of Wagon Trail Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wagon Trail Dr and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	2282	Intersection of Wagon Trail Dr and Stockade Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wagon Trail Dr and Stockade Ln	\$ 10,400	N/A **	N/A **		
PROW Intersection	2283	Intersection of Wagon Trail Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wagon Trail Dr and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	2284	Intersection of E Prairie St and Ave S	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Prairie St and Ave S	\$ 3,000	N/A **	N/A **		
PROW Intersection	2285	Intersection of Wagon Trail Dr and Wrangler Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wagon Trail Dr and Wrangler Ln	\$ 8,700	N/A **	N/A **		
PROW Intersection	2286	Intersection of Wagon Trail Dr and S Mockingbird Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wagon Trail Dr and S Mockingbird Ln	\$ 9,700	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2287	Intersection of Wagon Trail Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wagon Trail Dr and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	2288	Intersection of Wagon Trail Dr and Trailhead Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wagon Trail Dr and Trailhead Ln	\$ 8,700	N/A **	N/A **		
PROW Intersection	2289	Intersection of W Prairie St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Prairie St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2290	Intersection of E Prairie St and Wainwright St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Prairie St and Wainwright St	\$ 3,400	N/A **	N/A **		
PROW Intersection	2291	Intersection of E Prairie St and Wainwright St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Prairie St and Wainwright St	\$ 2,900	N/A **	N/A **		
PROW Intersection	2292	Intersection of W Prairie St and Pierce St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Prairie St and Pierce St	\$ 5,300	N/A **	N/A **		
PROW Intersection	2293	Intersection of E Prairie St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Prairie St and Us Hwy 77	\$ 3,800	N/A **	N/A **		
PROW Intersection	2294	Intersection of W Prairie St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Prairie St and Us Hwy 77	\$ 8,300	N/A **	N/A **		
PROW Intersection	2295	Intersection of Western Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Western Blvd and Driveway	\$ 3,300	N/A **	N/A **		
PROW Intersection	2296	Intersection of W Prairie St and S Carroll Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Prairie St and S Carroll Blvd	\$ 11,700	N/A **	N/A **		
PROW Intersection	2297	Intersection of S Ruddell St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Ruddell St and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	2298	Intersection of North Texas Blvd and W Prairie St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of North Texas Blvd and W Prairie St	\$ 6,000	N/A **	N/A **		
PROW Intersection	2299	Intersection of S Bonnie Brae St and W Pairie St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bonnie Brae St and W Pairie St	\$ 9,000	N/A **	N/A **		
PROW Intersection	2300	Intersection of Ave H and W Prairie St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ave H and W Prairie St	\$ 3,300	N/A **	N/A **		
PROW Intersection	2301	Intersection of S Ave C and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Ave C and Midblock Crossing	\$ 6,300	N/A **	N/A **		
PROW Intersection	2302	Intersection of Duchess Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Duchess Dr and Corridor End	\$ 1,900	N/A **	N/A **		
PROW Intersection	2303	Intersection of S Welch St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Welch St and Driveway	\$ 1,800	N/A **	N/A **		
PROW Intersection	2305	Intersection of W Prairie St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Prairie St and Driveway	\$ 5,500	N/A **	N/A **		
PROW Intersection	2306	Intersection of S Woodrow Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Woodrow Ln and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2307	Intersection of S Bell Ave and Industrial St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bell Ave and Industrial St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2308	Intersection of Bernard St and Chestnut St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bernard St and Chestnut St	\$ 5,500	N/A **	N/A **		
PROW Intersection	2309	Intersection of Ave H and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ave H and Driveway	\$ 4,000	N/A **	N/A **		
PROW Intersection	2310	Intersection of North Texas Blvd and Chestnut St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of North Texas Blvd and Chestnut St	\$ 14,500	N/A **	N/A **		
PROW Intersection	2311	Intersection of Union Cir and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Union Cir and Midblock Crossing	\$ 7,300	N/A **	N/A **		
PROW Intersection	2312	Intersection of Chestnut St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chestnut St and Driveway	\$ 3,600	N/A **	N/A **		
PROW Intersection	2313	Intersection of Union Cir and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Union Cir and Midblock Crossing	\$ 3,500	N/A **	N/A **		
PROW Intersection	2314	Intersection of Chestnut St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chestnut St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2315	Intersection of Union Cir and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Union Cir and Driveway	\$ 3,500	N/A **	N/A **		
PROW Intersection	2316	Intersection of Stroud St and Us Hwy 377	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stroud St and Us Hwy 377	\$ 600	N/A **	N/A **		
PROW Intersection	2317	Intersection of Chestnut St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chestnut St and Driveway	\$ 1,500	N/A **	N/A **		
PROW Intersection	2318	Intersection of Chestnut St and Ave D	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chestnut St and Ave D	\$ 17,700	N/A **	N/A **		
PROW Intersection	2319	Intersection of S Ave C and Chestnut St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Ave C and Chestnut St	\$ 19,400	N/A **	N/A **		
PROW Intersection	2320	Intersection of Stroud St and Pierce St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stroud St and Pierce St	\$ 4,800	N/A **	N/A **		
PROW Intersection	2321	Intersection of Chestnut St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chestnut St and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	2322	Intersection of Chestnut St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chestnut St and Driveway	\$ 2,800	N/A **	N/A **		
PROW Intersection	2323	Intersection of S Carroll Blvd and Stroud St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Carroll Blvd and Stroud St	\$ 5,300	N/A **	N/A **		
PROW Intersection	2324	Intersection of Chestnut St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chestnut St and Driveway	\$ 3,300	N/A **	N/A **		
PROW Intersection	2325	Intersection of Louise St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Louise St and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	2326	Intersection of Louise St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Louise St and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	2327	Intersection of Louise St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Louise St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2328	Intersection of S Bonnie Brae St and Louise St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bonnie Brae St and Louise St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2329	Intersection of S Woodrow Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Woodrow Ln and Driveway	\$ 5,500	N/A **	N/A **		
PROW Intersection	2330	Intersection of S Wood St and E Sycamore St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Wood St and E Sycamore St	\$ 300	N/A **	N/A **		
PROW Intersection	2331	Intersection of E Sycamore St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Sycamore St and Midblock Crossing	\$ 2,300	N/A **	N/A **		
PROW Intersection	2332	Intersection of North Texas Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of North Texas Blvd and Driveway	\$ 3,700	N/A **	N/A **		
PROW Intersection	2333	Intersection of E Sycamore St and S Crawford St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Sycamore St and S Crawford St	\$ 1,100	N/A **	N/A **		
PROW Intersection	2334	Intersection of S Bradshaw St and E Sycamore St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bradshaw St and E Sycamore St	\$ 3,500	N/A **	N/A **		
PROW Intersection	2335	Intersection of E Sycamore St and S Exposition St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Sycamore St and S Exposition St	\$ 2,300	N/A **	N/A **		











Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2560	Intersection of Market St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Market St and Driveway	\$ 3,300	N/A **	N/A **		
PROW Intersection	2561	Intersection of Springtree St and Silver Sage Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Springtree St and Silver Sage Dr	\$ 7,700	N/A **	N/A **		
PROW Intersection	2562	Intersection of Silver Sage Dr and Water Oak Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Silver Sage Dr and Water Oak Rd	\$ 12,800	N/A **	N/A **		
PROW Intersection	2563	Intersection of S Bonnie Brae St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bonnie Brae St and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	2564	Intersection of Silver Sage Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Silver Sage Dr and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2565	Intersection of Bellaire Dr and Bob O Link Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bellaire Dr and Bob O Link Ln	\$ 11,000	N/A **	N/A **		
PROW Intersection	2566	Intersection of Blake St and Market St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Blake St and Market St	\$ 8,200	N/A **	N/A **		
PROW Intersection	2567	Intersection of Audra Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	2568	Intersection of Mounts Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mounts Ave and Driveway	\$ 7,800	N/A **	N/A **		
PROW Intersection	2569	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	2570	Intersection of Bradley St and Houston Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bradley St and Houston Pl	\$ 2,900	N/A **	N/A **		
PROW Intersection	2571	Intersection of Uland St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Uland St and Midblock Crossing	\$ 2,500	N/A **	N/A **		
PROW Intersection	2572	Intersection of Frame St and Uland	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Frame St and Uland	\$ 6,000	N/A **	N/A **		
PROW Intersection	2573	Intersection of Railroad Ave and Uland St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Railroad Ave and Uland St	\$ 2,800	N/A **	N/A **		
PROW Intersection	2574	Intersection of Anderson St and Amarillo St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anderson St and Amarillo St	\$ 9,300	N/A **	N/A **		
PROW Intersection	2575	Intersection of Mounts Ave and Anderson St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mounts Ave and Anderson St	\$ 9,400	N/A **	N/A **		
PROW Intersection	2576	Intersection of N Ruddell St and Davis St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Ruddell St and Davis St	\$ 5,600	N/A **	N/A **		
PROW Intersection	2577	Intersection of Blake St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Blake St and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2578	Intersection of Davis St and Corridor Start	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Davis St and Corridor Start	\$ 3,000	N/A **	N/A **		
PROW Intersection	2579	Intersection of N Wood St and Davis St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Wood St and Davis St	\$ 12,200	N/A **	N/A **		
PROW Intersection	2580	Intersection of Davis St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Davis St and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	2581	Intersection of Davis St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Davis St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2583	Intersection of Bolivar St and W Parkway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and W Parkway St	\$ 9,100	N/A **	N/A **		
PROW Intersection	2584	Intersection of Oriole Ln and Cardinal Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oriole Ln and Cardinal Dr	\$ 3,300	N/A **	N/A **		
PROW Intersection	2585	Intersection of Longmeadow St and Eagle Nest Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Longmeadow St and Eagle Nest Ct	\$ 5,700	N/A **	N/A **		
PROW Intersection	2586	Intersection of Oriole Ln and Kingfisher Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oriole Ln and Kingfisher Ln	\$ 3,100	N/A **	N/A **		
PROW Intersection	2587	Intersection of Oriole Ln and Mockingbird Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oriole Ln and Mockingbird Ln	\$ 2,500	N/A **	N/A **		
PROW Intersection	2588	Intersection of W Parkway St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Parkway St and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2589	Intersection of E Parkway St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Parkway St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2590	Intersection of W Parkway St and Denton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Parkway St and Denton St	\$ 8,000	N/A **	N/A **		
PROW Intersection	2591	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2592	Intersection of S Bonnie Brae St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bonnie Brae St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2593	Intersection of Blake St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Blake St and Driveway	\$ 3,300	N/A **	N/A **		
PROW Intersection	2594	Intersection of Ponder Ave and Scripture St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ponder Ave and Scripture St	\$ 13,800	N/A **	N/A **		
PROW Intersection	2595	Intersection of Scripture St and Fry St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Fry St	\$ 18,800	N/A **	N/A **		
PROW Intersection	2596	Intersection of Bryan St and Scripture St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bryan St and Scripture St	\$ 17,800	N/A **	N/A **		
PROW Intersection	2597	Intersection of Scripture St and Normal St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Normal St	\$ 3,400	N/A **	N/A **		
PROW Intersection	2598	Intersection of Scripture St and Lovell St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Lovell St	\$ 7,800	N/A **	N/A **		
PROW Intersection	2599	Intersection of Scripture St and Jagoe St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Jagoe St	\$ 9,300	N/A **	N/A **		
PROW Intersection	2600	Intersection of Scripture St and Gober St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Gober St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2601	Intersection of Marietta St and Scripture St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Marietta St and Scripture St	\$ 6,000	N/A **	N/A **		
PROW Intersection	2602	Intersection of Oakland St and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Corridor End	\$ 1,100	N/A **	N/A **		
PROW Intersection	2603	Intersection of Denton St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Denton St and Driveway	\$ 2,800	N/A **	N/A **		
PROW Intersection	2604	Intersection of Bradley St and Scripture St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bradley St and Scripture St	\$ 5,500	N/A **	N/A **		
PROW Intersection	2605	Intersection of Mack Dr and Doubleoak St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mack Dr and Doubleoak St	\$ 10,500	N/A **	N/A **		
PROW Intersection	2606	Intersection of Joshua St and Springtree St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Joshua St and Springtree St	\$ 13,700	N/A **	N/A **		
PROW Intersection	2607	Intersection of Water Oak Rd and Joshua St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Water Oak Rd and Joshua St	\$ 11,300	N/A **	N/A **		
PROW Intersection	2608	Intersection of S Bonnie Brae St and Scripture St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of S Bonnie Brae St and Scripture St	\$ 9,700	N/A **	N/A **		
PROW Intersection	2609	Intersection of Scripture St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2610	Intersection of Scripture St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	2611	Intersection of Longmeadow St and Doubleoak St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Longmeadow St and Doubleoak St	\$ 11,500	N/A **	N/A **		
PROW Intersection	2612	Intersection of Scripture St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Driveway	\$ 9,000	N/A **	N/A **		
PROW Intersection	2613	Intersection of Scripture St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2614	Intersection of Scripture St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Driveway	\$ 11,300	N/A **	N/A **		
PROW Intersection	2615	Intersection of Scripture St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Driveway	\$ 600	N/A **	N/A **		
PROW Intersection	2616	Intersection of Scripture St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	2617	Intersection of Doubleoak St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Doubleoak St and Driveway	\$ 7,500	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2618	Intersection of Scripture St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	2619	Intersection of Scripture St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Midblock Crossing	\$ 4,500	N/A **	N/A **		
PROW Intersection	2620	Intersection of Scripture St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	2621	Intersection of Scripture St and I-35 E Frontage Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Scripture St and I-35 E Frontage Rd	\$ 2,500	N/A **	N/A **		
PROW Intersection	2622	Intersection of Audra Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Driveway	\$ 1,400	N/A **	N/A **		
PROW Intersection	2623	Intersection of Doubleoak St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Doubleoak St and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	2624	Intersection of W Congress St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Us Hwy 77	\$ 12,000	N/A **	N/A **		
PROW Intersection	2625	Intersection of Jim Crystal Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Jim Crystal Rd and Driveway	\$ -	N/A **	N/A **		
PROW Intersection	2628	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	2629	Intersection of Oakland St and E Congress St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and E Congress St	\$ 7,000	N/A **	N/A **		
PROW Intersection	2630	Intersection of W Congress St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2631	Intersection of N Austin St and E Congress St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Austin St and E Congress St	\$ 15,700	N/A **	N/A **		
PROW Intersection	2632	Intersection of W Congress St and Bolivar St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Bolivar St	\$ 16,500	N/A **	N/A **		
PROW Intersection	2633	Intersection of E Congress St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Congress St and Us Hwy 77	\$ 8,300	N/A **	N/A **		
PROW Intersection	2634	Intersection of W Congress St and Coit St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Coit St	\$ 2,300	N/A **	N/A **		
PROW Intersection	2635	Intersection of W Congress St and Denton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Denton St	\$ 8,800	N/A **	N/A **		
PROW Intersection	2636	Intersection of W Congress St and Alice St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Alice St	\$ 2,300	N/A **	N/A **		
PROW Intersection	2637	Intersection of W Congress St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Midblock Crossing	\$ 900	N/A **	N/A **		
PROW Intersection	2638	Intersection of W Congress St and Mounts Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Mounts Ave	\$ 7,500	N/A **	N/A **		
PROW Intersection	2639	Intersection of W Congress St and Amarillo St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Amarillo St	\$ 12,000	N/A **	N/A **		
PROW Intersection	2640	Intersection of Ponder Ave and W Congress St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ponder Ave and W Congress St	\$ 4,200	N/A **	N/A **		
PROW Intersection	2641	Intersection of W Congress St and Fulton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Congress St and Fulton St	\$ 15,200	N/A **	N/A **		
PROW Intersection	2642	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	2643	Intersection of Russell Newman Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Russell Newman Blvd and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	2644	Intersection of Russell Newman Blvd and Blake St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Russell Newman Blvd and Blake St	\$ 13,300	N/A **	N/A **		
PROW Intersection	2645	Intersection of Russell Newman Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Russell Newman Blvd and Driveway	\$ 500	N/A **	N/A **		
PROW Intersection	2646	Intersection of Russell Newman Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Russell Newman Blvd and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	2647	Intersection of Russell Newman Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Russell Newman Blvd and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	2648	Intersection of Russell Newman Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Russell Newman Blvd and Driveway	\$ 300	N/A **	N/A **		
PROW Intersection	2649	Intersection of Russell Newman Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Russell Newman Blvd and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	2650	Intersection of Russell Newman Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Russell Newman Blvd and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2651	Intersection of Mack Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mack Dr and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	2652	Intersection of Bryan St and W Congress St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bryan St and W Congress St	\$ 4,300	N/A **	N/A **		
PROW Intersection	2653	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 600	N/A **	N/A **		
PROW Intersection	2654	Intersection of Malone St and W Congress St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and W Congress St	\$ 3,500	N/A **	N/A **		
PROW Intersection	2655	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 7,100	N/A **	N/A **		
PROW Intersection	2656	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 1,500	N/A **	N/A **		
PROW Intersection	2657	Intersection of Malone St and Sena St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Sena St	\$ 4,800	N/A **	N/A **		
PROW Intersection	2658	Intersection of Pauline St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pauline St and Us Hwy 77	\$ 1,000	N/A **	N/A **		
PROW Intersection	2659	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	2660	Intersection of Egan St and Carroll Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Egan St and Carroll Blvd	\$ 3,400	N/A **	N/A **		
PROW Intersection	2661	Intersection of Egan St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Egan St and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	2662	Intersection of Bolivar St and Egan St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Egan St	\$ 8,100	N/A **	N/A **		
PROW Intersection	2663	Intersection of Coit St and Egan St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Coit St and Egan St	\$ 4,400	N/A **	N/A **		
PROW Intersection	2664	Intersection of Alice St and Egan St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alice St and Egan St	\$ 1,200	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2665	Intersection of Paisley St and Hettie St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Hettie St	\$ 6,000	N/A **	N/A **		
PROW Intersection	2666	Intersection of Paisley St and Jannie St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Jannie St	\$ 5,000	N/A **	N/A **		
PROW Intersection	2667	Intersection of Paisley St and Woodford Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Woodford Ln	\$ 6,800	N/A **	N/A **		
PROW Intersection	2668	Intersection of N Austin St and Marshall St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Austin St and Marshall St	\$ 7,700	N/A **	N/A **		
PROW Intersection	2669	Intersection of Paisley St and Pinckney Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Pinckney Dr	\$ 2,300	N/A **	N/A **		
PROW Intersection	2670	Intersection of Egan St and Amarillo St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Egan St and Amarillo St	\$ 14,000	N/A **	N/A **		
PROW Intersection	2671	Intersection of Paisley St and Campbell Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Campbell Ln	\$ 8,300	N/A **	N/A **		
PROW Intersection	2672	Intersection of Paisley St and Mulkey Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Mulkey Ln	\$ 2,500	N/A **	N/A **		
PROW Intersection	2673	Intersection of Egan St and Ponder Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Egan St and Ponder Ave	\$ 12,500	N/A **	N/A **		
PROW Intersection	2674	Intersection of Fulton St and Egan St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fulton St and Egan St	\$ 14,900	N/A **	N/A **		
PROW Intersection	2675	Intersection of Paisley St and N Ruddell St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and N Ruddell St	\$ 5,500	N/A **	N/A **		
PROW Intersection	2676	Intersection of Paisley St and Rose St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Rose St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2677	Intersection of Mack Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mack Dr and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	2678	Intersection of Paisley St and N Wood St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and N Wood St	\$ 8,500	N/A **	N/A **		
PROW Intersection	2679	Intersection of Paisley St and Mid-Block Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Mid-Block Crossing	\$ 5,000	N/A **	N/A **		
PROW Intersection	2680	Intersection of Paisley St and Frame St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Frame St	\$ 3,000	N/A **	N/A **		
PROW Intersection	2681	Intersection of Egan St and Bryan St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Egan St and Bryan St	\$ 11,800	N/A **	N/A **		
PROW Intersection	2682	Intersection of Malone St and Egan St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Egan St	\$ 9,800	N/A **	N/A **		
PROW Intersection	2683	Intersection of Hallum Dr and Mid-Block Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hallum Dr and Mid-Block Crossing	\$ 5,000	N/A **	N/A **		
PROW Intersection	2684	Intersection of Paisley St and Longmeadow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Longmeadow St	\$ 9,000	N/A **	N/A **		
PROW Intersection	2685	Intersection of Paisley St and Mockingbird Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Mockingbird Ln	\$ 4,900	N/A **	N/A **		
PROW Intersection	2686	Intersection of Paisley St and Summer Oaks Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Summer Oaks Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	2687	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	2688	Intersection of Paisley St and Fall Leaf Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Fall Leaf Ct	\$ 6,000	N/A **	N/A **		
PROW Intersection	2689	Intersection of Paisley St and Fallen Leaf Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Fallen Leaf Ct	\$ 9,800	N/A **	N/A **		
PROW Intersection	2690	Intersection of Paisley St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	2691	Intersection of Paisley St and Mockingbird Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Mockingbird Ct	\$ 7,800	N/A **	N/A **		
PROW Intersection	2692	Intersection of Paisley St and Mack Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Mack Dr	\$ 14,400	N/A **	N/A **		
PROW Intersection	2693	Intersection of Paisley St and Pace Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Pace Dr	\$ 7,100	N/A **	N/A **		
PROW Intersection	2694	Intersection of Paisley St and Water Oak Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Water Oak Rd	\$ 7,000	N/A **	N/A **		
PROW Intersection	2695	Intersection of Paisley St and Oak Valley	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paisley St and Oak Valley	\$ 6,800	N/A **	N/A **		
PROW Intersection	2696	Intersection of Audra Ln and Paisley St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Paisley St	\$ 5,200	N/A **	N/A **		
PROW Intersection	2697	Intersection of Oakland St and Withers St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Withers St	\$ 11,100	N/A **	N/A **		
PROW Intersection	2698	Intersection of Withers St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Withers St and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2699	Intersection of Bell Ave and Withers St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Withers St	\$ 14,400	N/A **	N/A **		
PROW Intersection	2700	Intersection of Malone St and Crow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Crow St	\$ 2,900	N/A **	N/A **		
PROW Intersection	2701	Intersection of Panhandle St and Alice St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Panhandle St and Alice St	\$ 8,300	N/A **	N/A **		
PROW Intersection	2702	Intersection of Bolivar St and Panhandle St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Panhandle St	\$ 8,600	N/A **	N/A **		
PROW Intersection	2703	Intersection of N Carroll Blvd and Panhandle St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Panhandle St	\$ 5,700	N/A **	N/A **		
PROW Intersection	2704	Intersection of Panhandle St and Anna St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Panhandle St and Anna St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2705	Intersection of Panhandle St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Panhandle St and Driveway	\$ 9,000	N/A **	N/A **		
PROW Intersection	2706	Intersection of Panhandle St and Anna St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Panhandle St and Anna St	\$ 6,400	N/A **	N/A **		
PROW Intersection	2707	Intersection of Panhandle St and Amarillo St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Panhandle St and Amarillo St	\$ 20,300	N/A **	N/A **		
PROW Intersection	2708	Intersection of Panhandle St and Fulton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Panhandle St and Fulton St	\$ 15,900	N/A **	N/A **		
PROW Intersection	2709	Intersection of Dana Lane and Mockingbird Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dana Lane and Mockingbird Ct	\$ 5,100	N/A **	N/A **		
PROW Intersection	2710	Intersection of Panhandle St and Ponder Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Panhandle St and Ponder Ave	\$ 12,100	N/A **	N/A **		
PROW Intersection	2711	Intersection of Dana Lane and Pace Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Dana Lane and Pace Dr	\$ 10,900	N/A **	N/A **		
PROW Intersection	2712	Intersection of Panhandle St and Bryan St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Panhandle St and Bryan St	\$ 5,300	N/A **	N/A **		
PROW Intersection	2713	Intersection of Malone St and Panhandle St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Panhandle St	\$ 9,800	N/A **	N/A **		
PROW Intersection	2714	Intersection of Oakland St and Hann St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Hann St	\$ 15,000	N/A **	N/A **		
PROW Intersection	2715	Intersection of Hann St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hann St and Us Hwy 77	\$ 4,500	N/A **	N/A **		
PROW Intersection	2716	Intersection of N Austin St and Hann St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Austin St and Hann St	\$ 17,600	N/A **	N/A **		
PROW Intersection	2717	Intersection of Audra Ln and Lee Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Lee Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	2718	Intersection of Panhandle St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Panhandle St and Driveway	\$ 1,900	N/A **	N/A **		
PROW Intersection	2719	Intersection of N Bonnie Brae St and Panhandle St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Panhandle St	\$ 4,000	N/A **	N/A **		
PROW Intersection	2720	Intersection of Vine St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vine St and Driveway	\$ 3,400	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2721	Intersection of Oak Valley and Spring Meadows Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oak Valley and Spring Meadows Dr	\$ 7,200	N/A **	N/A **		
PROW Intersection	2722	Intersection of Masch Branch Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Masch Branch Rd and Driveway	\$ 4,600	N/A **	N/A **		
PROW Intersection	2723	Intersection of Summer Oaks Dr and Spring Meadows Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Summer Oaks Dr and Spring Meadows Dr	\$ 7,800	N/A **	N/A **		
PROW Intersection	2724	Intersection of Ferguson St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ferguson St and Us Hwy 77	\$ 6,300	N/A **	N/A **		
PROW Intersection	2725	Intersection of Paco Trail and Leon Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Paco Trail and Leon Way	\$ 9,800	N/A **	N/A **		
PROW Intersection	2726	Intersection of N Ruddell St and Paco Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Ruddell St and Paco Trl	\$ 4,500	N/A **	N/A **		
PROW Intersection	2727	Intersection of Texas St and Frame St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Texas St and Frame St	\$ 14,800	N/A **	N/A **		
PROW Intersection	2728	Intersection of Vine St and Texas St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vine St and Texas St	\$ 12,000	N/A **	N/A **		
PROW Intersection	2729	Intersection of Bell Ave and Texas St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Texas St	\$ 20,100	N/A **	N/A **		
PROW Intersection	2730	Intersection of Texas St and Old Main Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Texas St and Old Main Cir	\$ 6,400	N/A **	N/A **		
PROW Intersection	2731	Intersection of Texas St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Texas St and Driveway	\$ 5,500	N/A **	N/A **		
PROW Intersection	2732	Intersection of Oakland St and Texas St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Texas St	\$ 8,100	N/A **	N/A **		
PROW Intersection	2733	Intersection of Fulton St and Broadway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fulton St and Broadway St	\$ 3,100	N/A **	N/A **		
PROW Intersection	2734	Intersection of Broadway St and Ponder Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Broadway St and Ponder Ave	\$ 2,300	N/A **	N/A **		
PROW Intersection	2735	Intersection of Malone St and Broadway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Broadway St	\$ 6,700	N/A **	N/A **		
PROW Intersection	2736	Intersection of Masch Branch Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Masch Branch Rd and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	2737	Intersection of Frame St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Frame St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2738	Intersection of Oak Valley and Summer Trail Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oak Valley and Summer Trail Dr	\$ 3,700	N/A **	N/A **		
PROW Intersection	2739	Intersection of Audra Ln and Mack Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Mack Pl	\$ 9,300	N/A **	N/A **		
PROW Intersection	2740	Intersection of First St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of First St and Us Hwy 77	\$ 1,500	N/A **	N/A **		
PROW Intersection	2741	Intersection of Bolivar St and First St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and First St	\$ 5,900	N/A **	N/A **		
PROW Intersection	2742	Intersection of First St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of First St and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2743	Intersection of Schmitz Ave and Frame St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Schmitz Ave and Frame St	\$ 10,400	N/A **	N/A **		
PROW Intersection	2744	Intersection of Bell Ave and Schmitz Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Schmitz Ave	\$ 11,300	N/A **	N/A **		
PROW Intersection	2745	Intersection of Vine St and Schmitz Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vine St and Schmitz Ave	\$ 13,000	N/A **	N/A **		
PROW Intersection	2746	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	2747	Intersection of Fulton St and Linden Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fulton St and Linden Dr	\$ 10,200	N/A **	N/A **		
PROW Intersection	2748	Intersection of Linden Dr and Ponder Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Linden Dr and Ponder Ave	\$ 6,800	N/A **	N/A **		
PROW Intersection	2749	Intersection of Oak Valley and Timber Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oak Valley and Timber Trl	\$ 6,300	N/A **	N/A **		
PROW Intersection	2750	Intersection of Timber Trail and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Timber Trail and Midblock Crossing	\$ 3,500	N/A **	N/A **		
PROW Intersection	2751	Intersection of Oakland St and Sawyer Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Sawyer Ave	\$ 13,300	N/A **	N/A **		
PROW Intersection	2752	Intersection of N Austin St and Sawyer Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Austin St and Sawyer Ave	\$ 19,000	N/A **	N/A **		
PROW Intersection	2753	Intersection of Sawyer Ave and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sawyer Ave and Us Hwy 77	\$ 4,500	N/A **	N/A **		
PROW Intersection	2754	Intersection of Malone St and Linden Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Linden Dr	\$ 10,000	N/A **	N/A **		
PROW Intersection	2755	Intersection of Audra Ln and Oaktree Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Oaktree Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	2756	Intersection of N Bonnie Brae St and Lilnden Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Lilnden Dr	\$ 5,700	N/A **	N/A **		
PROW Intersection	2757	Intersection of Mockingbird Ln and Penniman Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mockingbird Ln and Penniman Rd	\$ 5,800	N/A **	N/A **		
PROW Intersection	2758	Intersection of Pirtle St and Frame St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pirtle St and Frame St	\$ 6,100	N/A **	N/A **		
PROW Intersection	2759	Intersection of Vine St and Pirtle St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vine St and Pirtle St	\$ 8,000	N/A **	N/A **		
PROW Intersection	2760	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 3,600	N/A **	N/A **		
PROW Intersection	2761	Intersection of Oak Valley and Oak Park Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oak Valley and Oak Park Dr	\$ 8,500	N/A **	N/A **		
PROW Intersection	2762	Intersection of Mulkey Ln and Post Oak Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mulkey Ln and Post Oak Ct	\$ 8,800	N/A **	N/A **		
PROW Intersection	2763	Intersection of Oak Park Dr and Timber Trail	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oak Park Dr and Timber Trail	\$ 10,300	N/A **	N/A **		
PROW Intersection	2764	Intersection of Oak Park Dr and Whispering Oaks	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oak Park Dr and Whispering Oaks	\$ 4,600	N/A **	N/A **		
PROW Intersection	2765	Intersection of Malone St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2766	Intersection of Masch Branch Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Masch Branch Rd and Driveway	\$ 4,700	N/A **	N/A **		
PROW Intersection	2767	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 5,700	N/A **	N/A **		
PROW Intersection	2768	Intersection of Fulton St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fulton St and Midblock Crossing	\$ 4,700	N/A **	N/A **		
PROW Intersection	2769	Intersection of Second St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Second St and Us Hwy 77	\$ 10,500	N/A **	N/A **		
PROW Intersection	2770	Intersection of Second St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Second St and Us Hwy 77	\$ 6,500	N/A **	N/A **		
PROW Intersection	2771	Intersection of Second St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Second St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2772	Intersection of Bolivar St and Second St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Second St	\$ 12,000	N/A **	N/A **		
PROW Intersection	2773	Intersection of E College St and Frame St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E College St and Frame St	\$ 600	N/A **	N/A **		
PROW Intersection	2774	Intersection of Vine St and E College St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vine St and E College St	\$ 12,700	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2775	Intersection of Bell Ave and E College St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and E College St	\$ 9,500	N/A **	N/A **		
PROW Intersection	2777	Intersection of Mockingbird Ln and Newport Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mockingbird Ln and Newport Ave	\$ 12,800	N/A **	N/A **		
PROW Intersection	2778	Intersection of Newport Ave and Indigo Terrace St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Newport Ave and Indigo Terrace St	\$ 6,300	N/A **	N/A **		
PROW Intersection	2779	Intersection of Lance Ln and Newport Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lance Ln and Newport Ave	\$ 11,300	N/A **	N/A **		
PROW Intersection	2780	Intersection of Pace Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pace Dr and Midblock Crossing	\$ 5,300	N/A **	N/A **		
PROW Intersection	2781	Intersection of Malone St and Carlton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Carlton St	\$ 3,400	N/A **	N/A **		
PROW Intersection	2782	Intersection of Vine St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vine St and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	2783	Intersection of Oak Valley and Whispering Oaks	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oak Valley and Whispering Oaks	\$ 9,000	N/A **	N/A **		
PROW Intersection	2784	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	2785	Intersection of Mulkey Ln and Red Oak Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mulkey Ln and Red Oak Ct	\$ 10,300	N/A **	N/A **		
PROW Intersection	2786	Intersection of Fulton St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fulton St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2787	Intersection of Lance Ln and Chase Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lance Ln and Chase Ln	\$ 10,900	N/A **	N/A **		
PROW Intersection	2788	Intersection of N Austin St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Austin St and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	2789	Intersection of Vine St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vine St and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	2790	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2791	Intersection of Us Hwy 77 and Gary St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Us Hwy 77 and Gary St	\$ 3,000	N/A **	N/A **		
PROW Intersection	2792	Intersection of Bell Ave and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Midblock Crossing	\$ 1,900	N/A **	N/A **		
PROW Intersection	2793	Intersection of Vine St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Vine St and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	2794	Intersection of Us Hwy 77 and Gary St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Us Hwy 77 and Gary St	\$ 800	N/A **	N/A **		
PROW Intersection	2795	Intersection of Us Hwy 77 and Gary St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Us Hwy 77 and Gary St	\$ 3,400	N/A **	N/A **		
PROW Intersection	2796	Intersection of Hillcrest St and Crescent St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hillcrest St and Crescent St	\$ 6,000	N/A **	N/A **		
PROW Intersection	2797	Intersection of N Bonnie Brae St and Crescent St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Crescent St	\$ 5,800	N/A **	N/A **		
PROW Intersection	2798	Intersection of Atlanta Dr and Springfield St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Atlanta Dr and Springfield St	\$ 10,400	N/A **	N/A **		
PROW Intersection	2799	Intersection of Mulkey Ln and Lattimore St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mulkey Ln and Lattimore St	\$ 3,500	N/A **	N/A **		
PROW Intersection	2800	Intersection of Bolivar St and Crescent St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Crescent St	\$ 7,500	N/A **	N/A **		
PROW Intersection	2801	Intersection of Raleigh Path and Springfield St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Raleigh Path and Springfield St	\$ 12,000	N/A **	N/A **		
PROW Intersection	2802	Intersection of Springfield St and Tallahassee Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Springfield St and Tallahassee Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	2803	Intersection of Crescent St and Coit St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crescent St and Coit St	\$ 2,900	N/A **	N/A **		
PROW Intersection	2804	Intersection of Crescent St and Denton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crescent St and Denton St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2805	Intersection of Crescent St and Alice St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crescent St and Alice St	\$ 3,100	N/A **	N/A **		
PROW Intersection	2806	Intersection of Mockingbird Ln and Howard Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mockingbird Ln and Howard Ct	\$ 4,500	N/A **	N/A **		
PROW Intersection	2807	Intersection of Crescent St and Fulton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crescent St and Fulton St	\$ 7,500	N/A **	N/A **		
PROW Intersection	2808	Intersection of Frame St and Grove St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Frame St and Grove St	\$ 2,500	N/A **	N/A **		
PROW Intersection	2809	Intersection of E Third St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Third St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2810	Intersection of E Third St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Third St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2811	Intersection of E Third St and Oakland St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Third St and Oakland St	\$ 11,300	N/A **	N/A **		
PROW Intersection	2812	Intersection of E Third St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Third St and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	2813	Intersection of N Austin St and E Third St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Austin St and E Third St	\$ 8,900	N/A **	N/A **		
PROW Intersection	2814	Intersection of Grove St and Vine St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grove St and Vine St	\$ 5,000	N/A **	N/A **		
PROW Intersection	2815	Intersection of E Third St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Third St and Driveway	\$ 800	N/A **	N/A **		
PROW Intersection	2816	Intersection of Crescent St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crescent St and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2817	Intersection of Bolivar St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2818	Intersection of Madison Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Madison Ln and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2819	Intersection of Malone St and Crescent St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Crescent St	\$ 9,400	N/A **	N/A **		
PROW Intersection	2820	Intersection of Crescent St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crescent St and Driveway	\$ 4,100	N/A **	N/A **		
PROW Intersection	2821	Intersection of Atlanta Dr and Madison Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Atlanta Dr and Madison Ln	\$ 6,000	N/A **	N/A **		
PROW Intersection	2822	Intersection of Crescent St and Gober St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crescent St and Gober St	\$ 2,300	N/A **	N/A **		
PROW Intersection	2823	Intersection of Crescent St and Bryan St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crescent St and Bryan St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2824	Intersection of Audra Ln and Lattimore St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Lattimore St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2825	Intersection of Chase Ln and Pres Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chase Ln and Pres Ct	\$ 10,800	N/A **	N/A **		
PROW Intersection	2826	Intersection of W Third St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Third St and Us Hwy 77	\$ 9,800	N/A **	N/A **		
PROW Intersection	2827	Intersection of Bolivar St and W Third St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and W Third St	\$ 7,100	N/A **	N/A **		
PROW Intersection	2828	Intersection of E Third St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Third St and Us Hwy 77	\$ 3,400	N/A **	N/A **		
PROW Intersection	2829	Intersection of E Third St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Third St and Driveway	\$ 3,400	N/A **	N/A **		
PROW Intersection	2830	Intersection of E Third St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Third St and Driveway	\$ 4,800	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2831	Intersection of Anysa Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anysa Ln and Midblock Crossing	\$ 6,800	N/A **	N/A **		
PROW Intersection	2832	Intersection of Cordell St and Crescent St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cordell St and Crescent St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2833	Intersection of Mockingbird Ln and Anysa Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mockingbird Ln and Anysa Ln	\$ 9,000	N/A **	N/A **		
PROW Intersection	2834	Intersection of Oakland St and Administration Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Administration Dr	\$ 10,700	N/A **	N/A **		
PROW Intersection	2835	Intersection of Cordell St and Crescent St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cordell St and Crescent St	\$ 4,500	N/A **	N/A **		
PROW Intersection	2836	Intersection of Atlanta Dr and Trenton Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Atlanta Dr and Trenton Pl	\$ 8,300	N/A **	N/A **		
PROW Intersection	2837	Intersection of Cordell St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cordell St and Driveway	\$ 6,100	N/A **	N/A **		
PROW Intersection	2838	Intersection of Fulton St and Cordell	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fulton St and Cordell	\$ 2,900	N/A **	N/A **		
PROW Intersection	2839	Intersection of Cordell St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cordell St and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	2840	Intersection of Cordell St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cordell St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2841	Intersection of Hillcrest St and Cordell St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hillcrest St and Cordell St	\$ 7,800	N/A **	N/A **		
PROW Intersection	2842	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 1,400	N/A **	N/A **		
PROW Intersection	2843	Intersection of Anysa Ln and Chase Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anysa Ln and Chase Ln	\$ 11,500	N/A **	N/A **		
PROW Intersection	2844	Intersection of Malone St and Cordell St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Cordell St	\$ 15,600	N/A **	N/A **		
PROW Intersection	2845	Intersection of Anysa Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anysa Ln and Midblock Crossing	\$ 8,500	N/A **	N/A **		
PROW Intersection	2846	Intersection of Mockingbird Ln and Beverly Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mockingbird Ln and Beverly Dr	\$ 2,600	N/A **	N/A **		
PROW Intersection	2847	Intersection of Malone St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2848	Intersection of Beverly Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Beverly Dr and Midblock Crossing	\$ 7,500	N/A **	N/A **		
PROW Intersection	2849	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	2850	Intersection of Malone St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2851	Intersection of Oakland St and N Austin St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and N Austin St	\$ 11,300	N/A **	N/A **		
PROW Intersection	2852	Intersection of Raleigh Path and Tallahassee Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Raleigh Path and Tallahassee Dr	\$ 8,700	N/A **	N/A **		
PROW Intersection	2853	Intersection of Atlanta Dr and Raleigh Path	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Atlanta Dr and Raleigh Path	\$ 14,300	N/A **	N/A **		
PROW Intersection	2854	Intersection of Oakland St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	2855	Intersection of Oakland St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakland St and Us Hwy 77	\$ 6,400	N/A **	N/A **		
PROW Intersection	2856	Intersection of Malone St and Westchester Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Westchester Dr	\$ 12,900	N/A **	N/A **		
PROW Intersection	2857	Intersection of Emery St and Coit St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Coit St	\$ 3,800	N/A **	N/A **		
PROW Intersection	2858	Intersection of Emery St and Alice St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Alice St	\$ 3,800	N/A **	N/A **		
PROW Intersection	2859	Intersection of Bell Ave and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Midblock Crossing	\$ 1,000	N/A **	N/A **		
PROW Intersection	2860	Intersection of Mingo Rd and Pertain St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mingo Rd and Pertain St	\$ 6,000	N/A **	N/A **		
PROW Intersection	2861	Intersection of Westchester St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Westchester St and Midblock Crossing	\$ 900	N/A **	N/A **		
PROW Intersection	2862	Intersection of Mockingbird Ln and Terry Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mockingbird Ln and Terry Ct	\$ 4,500	N/A **	N/A **		
PROW Intersection	2863	Intersection of Prominence Pkwy and Atlanta Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Prominence Pkwy and Atlanta Dr	\$ 11,300	N/A **	N/A **		
PROW Intersection	2864	Intersection of W College St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W College St and Us Hwy 77	\$ 10,200	N/A **	N/A **		
PROW Intersection	2865	Intersection of W College St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W College St and Us Hwy 77	\$ 4,000	N/A **	N/A **		
PROW Intersection	2866	Intersection of Bolivar St and W College St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and W College St	\$ 8,900	N/A **	N/A **		
PROW Intersection	2867	Intersection of Emery St and Bellemead Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Bellemead Dr	\$ 6,700	N/A **	N/A **		
PROW Intersection	2868	Intersection of Emery St and Ector St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Ector St	\$ 800	N/A **	N/A **		
PROW Intersection	2869	Intersection of Emery St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Midblock Crossing	\$ 3,000	N/A **	N/A **		
PROW Intersection	2870	Intersection of Emery St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2871	Intersection of Emery St and Emery St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Emery St	\$ 4,700	N/A **	N/A **		
PROW Intersection	2872	Intersection of Emery St and Hillcrest St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Hillcrest St	\$ 6,800	N/A **	N/A **		
PROW Intersection	2873	Intersection of Malone St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Driveway	\$ 3,400	N/A **	N/A **		
PROW Intersection	2874	Intersection of Emery St and Thomas St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Thomas St	\$ 4,800	N/A **	N/A **		
PROW Intersection	2875	Intersection of Emery St and Stanley St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Emery St and Stanley St	\$ 7,500	N/A **	N/A **		
PROW Intersection	2876	Intersection of N Bonnie Brae St and Emery St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Emery St	\$ 3,800	N/A **	N/A **		
PROW Intersection	2877	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	2878	Intersection of Audra Ln and Brittany Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Brittany Dr	\$ 5,800	N/A **	N/A **		
PROW Intersection	2879	Intersection of Audra Ln and Bayfield St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Bayfield St	\$ 9,900	N/A **	N/A **		
PROW Intersection	2880	Intersection of Audra Ln and Mockingbird Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Mockingbird Ln	\$ 3,000	N/A **	N/A **		
PROW Intersection	2881	Intersection of Audra Ln and Barbara St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Barbara St	\$ 3,300	N/A **	N/A **		
PROW Intersection	2882	Intersection of Audra Ln and Mockingbird Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Mockingbird Ln	\$ 6,300	N/A **	N/A **		
PROW Intersection	2883	Intersection of Malone St and Emery St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Emery St	\$ 5,300	N/A **	N/A **		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2884	Intersection of Audra Ln and Stockton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Audra Ln and Stockton St	\$ 9,500	N/A **	N/A **		
PROW Intersection	2885	Intersection of Bolivar St and Westway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Westway St	\$ 3,100	N/A **	N/A **		
PROW Intersection	2886	Intersection of Anna St and Westway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anna St and Westway St	\$ 4,700	N/A **	N/A **		
PROW Intersection	2887	Intersection of N Carroll Blvd and Westway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Westway St	\$ 5,900	N/A **	N/A **		
PROW Intersection	2888	Intersection of Nottingham Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nottingham Dr and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	2889	Intersection of Westway St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Westway St and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	2890	Intersection of Coit St and Westway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Coit St and Westway St	\$ 2,500	N/A **	N/A **		
PROW Intersection	2891	Intersection of Ector St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ector St and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2892	Intersection of Fulton St and Westway St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fulton St and Westway St	\$ 2,800	N/A **	N/A **		
PROW Intersection	2893	Intersection of N Bonnie Brae St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	2894	Intersection of Anna St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anna St and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	2895	Intersection of Western Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Western Blvd and Driveway	\$ 600	N/A **	N/A **		
PROW Intersection	2896	Intersection of Primrose Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Primrose Ln and Driveway	\$ 5,700	N/A **	N/A **		
PROW Intersection	2897	Intersection of Wicker Way and Telese Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wicker Way and Telese Ct	\$ 12,500	N/A **	N/A **		
PROW Intersection	2898	Intersection of Wicker Way and Allen Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wicker Way and Allen Ct	\$ 12,400	N/A **	N/A **		
PROW Intersection	2899	Intersection of Wicker Way and Ramsey Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wicker Way and Ramsey Ct	\$ 12,800	N/A **	N/A **		
PROW Intersection	2900	Intersection of Wicker Way and Stacy Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wicker Way and Stacy Ct	\$ 12,800	N/A **	N/A **		
PROW Intersection	2901	Intersection of Stockton St and Malli Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stockton St and Malli Ct	\$ 11,400	N/A **	N/A **		
PROW Intersection	2902	Intersection of Cornell Ln and Us Hwy 380	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cornell Ln and Us Hwy 380	\$ 6,000	N/A **	N/A **		
PROW Intersection	2904	Intersection of Primrose Ln and Us Hwy 380	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Primrose Ln and Us Hwy 380	\$ 6,000	N/A **	N/A **		
PROW Intersection	2905	Intersection of Ector St and Us Hwy 380	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Ector St and Us Hwy 380	\$ 3,000	N/A **	N/A **		
PROW Intersection	2906	Intersection of Georgetown Dr and Us Hwy 380	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Georgetown Dr and Us Hwy 380	\$ 4,800	N/A **	N/A **		
PROW Intersection	2907	Intersection of Nottingham Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nottingham Dr and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	2908	Intersection of Blackford Oakes and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Blackford Oakes and Corridor End	\$ 2,500	N/A **	N/A **		
PROW Intersection	2909	Intersection of Sunset St and Anna St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sunset St and Anna St	\$ 6,000	N/A **	N/A **		
PROW Intersection	2911	Intersection of Bolivar St and Sunset St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Sunset St	\$ 7,500	N/A **	N/A **		
PROW Intersection	2912	Intersection of N Carroll Blvd and Sunset St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Sunset St	\$ 4,900	N/A **	N/A **		
PROW Intersection	2913	Intersection of Sunset St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sunset St and Driveway	\$ 7,100	N/A **	N/A **		
PROW Intersection	2914	Intersection of Wicker Way and Stockton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Wicker Way and Stockton St	\$ 12,500	N/A **	N/A **		
PROW Intersection	2915	Intersection of Sunset St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sunset St and Driveway	\$ 1,000	N/A **	N/A **		
PROW Intersection	2916	Intersection of Sunset St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sunset St and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	2917	Intersection of Alice St and Sunset St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Alice St and Sunset St	\$ 3,000	N/A **	N/A **		
PROW Intersection	2919	Intersection of Malone St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	2920	Intersection of Mockingbird Ln and Oakshire St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mockingbird Ln and Oakshire St	\$ 13,800	N/A **	N/A **		
PROW Intersection	2921	Intersection of Oakshire St and Allen Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakshire St and Allen Ct	\$ 14,000	N/A **	N/A **		
PROW Intersection	2923	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2924	Intersection of Cornell Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cornell Ln and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	2925	Intersection of Oakshire St and Stockton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Oakshire St and Stockton St	\$ 13,000	N/A **	N/A **		
PROW Intersection	2926	Intersection of Gay Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gay Dr and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2927	Intersection of Anna St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anna St and Driveway	\$ 1,100	N/A **	N/A **		
PROW Intersection	2928	Intersection of Hinkle Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkle Dr and Corridor End	\$ 3,800	N/A **	N/A **		
PROW Intersection	2931	Intersection of Cornell Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cornell Ln and Driveway	\$ 2,900	N/A **	N/A **		
PROW Intersection	2932	Intersection of Redwood Pl and Seminole Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redwood Pl and Seminole Ave	\$ 7,500	N/A **	N/A **		
PROW Intersection	2933	Intersection of Gay Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gay Dr and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2934	Intersection of Boyd St and Seminole Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Boyd St and Seminole Ave	\$ 10,700	N/A **	N/A **		
PROW Intersection	2936	Intersection of Malone St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2937	Intersection of Mockingbird Ln and Stockton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mockingbird Ln and Stockton St	\$ 9,000	N/A **	N/A **		
PROW Intersection	2938	Intersection of Hinkle Dr and Corridor Start	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkle Dr and Corridor Start	\$ 7,500	N/A **	N/A **		
PROW Intersection	2939	Intersection of Malone St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	2941	Intersection of Bolivar St and Us Hwy 380	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Us Hwy 380	\$ 8,200	N/A **	N/A **		
PROW Intersection	2942	Intersection of Anna St and Us Hwy 380	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Anna St and Us Hwy 380	\$ 3,800	N/A **	N/A **		
PROW Intersection	2943	Intersection of N Bonnie Brae St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Driveway	\$ 9,000	N/A **	N/A **		
PROW Intersection	2947	Intersection of Mockingbird Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mockingbird Ln and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2948	Intersection of Hinkle Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkle Dr and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2949	Intersection of N Carroll Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	2950	Intersection of Denison St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Denison St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2951	Intersection of Mesa Dr and Bandera St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mesa Dr and Bandera St	\$ 3,600	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	2953	Intersection of Bandera St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bandera St and Midblock Crossing	\$ 3,300	N/A **	N/A **		
PROW Intersection	2954	Intersection of Malone St and Amherst Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Amherst Dr	\$ 3,100	N/A **	N/A **		
PROW Intersection	2955	Intersection of Amherst Dr and Fordham Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Amherst Dr and Fordham Ln	\$ 6,300	N/A **	N/A **		
PROW Intersection	2956	Intersection of Amherst Dr and Georgetown Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Amherst Dr and Georgetown Dr	\$ 3,000	N/A **	N/A **		
PROW Intersection	2957	Intersection of Bandera St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bandera St and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	2958	Intersection of Bandera St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bandera St and Midblock Crossing	\$ 3,000	N/A **	N/A **		
PROW Intersection	2959	Intersection of Bolivar St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Driveway	\$ 3,300	N/A **	N/A **		
PROW Intersection	2960	Intersection of Boyd St and Choctaw Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Boyd St and Choctaw Ave	\$ 11,000	N/A **	N/A **		
PROW Intersection	2961	Intersection of Denison St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Denison St and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	2962	Intersection of Redwood Pl and Choctaw Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redwood Pl and Choctaw Ave	\$ 8,800	N/A **	N/A **		
PROW Intersection	2963	Intersection of N Carroll Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	2964	Intersection of Hinkle Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkle Dr and Driveway	\$ 6,500	N/A **	N/A **		
PROW Intersection	2965	Intersection of N Ruddell St and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Ruddell St and Corridor End	\$ 2,300	N/A **	N/A **		
PROW Intersection	2966	Intersection of Bolivar St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2967	Intersection of Mesa Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mesa Dr and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	2968	Intersection of N Bonnie Brae St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Driveway	\$ 4,700	N/A **	N/A **		
PROW Intersection	2969	Intersection of Bell Ave and Woodland St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Woodland St	\$ 8,400	N/A **	N/A **		
PROW Intersection	2971	Intersection of Bolivar St and W Sherman Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bolivar St and W Sherman Dr	\$ 5,500	N/A **	N/A **		
PROW Intersection	2972	Intersection of W Sherman Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Sherman Dr and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	2973	Intersection of W Sherman Dr and Denison St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Sherman Dr and Denison St	\$ 9,000	N/A **	N/A **		
PROW Intersection	2974	Intersection of Woodland St and Fm 428	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Woodland St and Fm 428	\$ 3,000	N/A **	N/A **		
PROW Intersection	2977	Intersection of Mesa Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mesa Dr and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2978	Intersection of Shawnee St and Creek Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shawnee St and Creek Ave	\$ 11,200	N/A **	N/A **		
PROW Intersection	2979	Intersection of Nottingham Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nottingham Dr and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	2980	Intersection of Redwood Pl and Creek Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redwood Pl and Creek Ave	\$ 9,500	N/A **	N/A **		
PROW Intersection	2981	Intersection of Boyd St and Creek Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Boyd St and Creek Ave	\$ 9,000	N/A **	N/A **		
PROW Intersection	2982	Intersection of N Bonnie Brae St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	2983	Intersection of Nolen Cir and Roundabout	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nolen Cir and Roundabout	\$ 12,000	N/A **	N/A **		
PROW Intersection	2985	Intersection of Us Hwy 380 and Virginia Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Us Hwy 380 and Virginia Cir	\$ 6,300	N/A **	N/A **		
PROW Intersection	2986	Intersection of Us Hwy 380 and Glenwood Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Us Hwy 380 and Glenwood Ln	\$ 3,000	N/A **	N/A **		
PROW Intersection	2987	Intersection of Bell Ave and Roberts St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Roberts St	\$ 5,300	N/A **	N/A **		
PROW Intersection	2988	Intersection of Roberts St and Cherrywood Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Roberts St and Cherrywood Ln	\$ 3,000	N/A **	N/A **		
PROW Intersection	2989	Intersection of E Sherman Dr and Fm 428	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E Sherman Dr and Fm 428	\$ 6,500	N/A **	N/A **		
PROW Intersection	2990	Intersection of Sauls Ln and Roberts St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sauls Ln and Roberts St	\$ 2,500	N/A **	N/A **		
PROW Intersection	2991	Intersection of N Mayhill Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Mayhill Rd and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	2992	Intersection of Shawnee St and Cherokee Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shawnee St and Cherokee Ave	\$ 2,500	N/A **	N/A **		
PROW Intersection	2993	Intersection of Redwood Pl and Cherokee Ave	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redwood Pl and Cherokee Ave	\$ 7,500	N/A **	N/A **		
PROW Intersection	2994	Intersection of Boyd St and Redwood Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Boyd St and Redwood Pl	\$ 2,500	N/A **	N/A **		
PROW Intersection	2995	Intersection of N Carroll Blvd and Ross St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Ross St	\$ 4,800	N/A **	N/A **		
PROW Intersection	2996	Intersection of Glenwood Ln and Palmwood Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glenwood Ln and Palmwood Pl	\$ 2,800	N/A **	N/A **		
PROW Intersection	2999	Intersection of Nottingham Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nottingham Dr and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3000	Intersection of Forest St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Forest St and Us Hwy 77	\$ 6,300	N/A **	N/A **		
PROW Intersection	3001	Intersection of Spring Valley Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Spring Valley Dr and Driveway	\$ 4,200	N/A **	N/A **		
PROW Intersection	3003	Intersection of Augusta Dr and Colonial St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Augusta Dr and Colonial St	\$ 3,300	N/A **	N/A **		
PROW Intersection	3004	Intersection of Mesa Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mesa Dr and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	3005	Intersection of Greenway Dr and Augusta Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Greenway Dr and Augusta Dr	\$ 2,300	N/A **	N/A **		
PROW Intersection	3007	Intersection of Nottingham Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nottingham Dr and Driveway	\$ 9,000	N/A **	N/A **		
PROW Intersection	3008	Intersection of N Carroll Blvd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	3009	Intersection of Taliaferro St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Taliaferro St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3010	Intersection of Taliaferro St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Taliaferro St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3011	Intersection of Taliaferro St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Taliaferro St and Us Hwy 77	\$ 5,300	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	3012	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3013	Intersection of Cooper Creek Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cooper Creek Rd and Driveway	\$ 9,300	N/A **	N/A **		
PROW Intersection	3014	Intersection of Barcelona St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Barcelona St and Driveway	\$ 4,200	N/A **	N/A **		
PROW Intersection	3015	Intersection of Glenwood Ln and Greenwood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glenwood Ln and Greenwood Dr	\$ 5,300	N/A **	N/A **		
PROW Intersection	3016	Intersection of Us Hwy 380 and Geesling Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Us Hwy 380 and Geesling Rd	\$ 3,800	N/A **	N/A **		
PROW Intersection	3017	Intersection of N Carroll Blvd and Fain St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Fain St	\$ 7,500	N/A **	N/A **		
PROW Intersection	3018	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 5,800	N/A **	N/A **		
PROW Intersection	3019	Intersection of Worthington Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Worthington Dr and Midblock Crossing	\$ 3,000	N/A **	N/A **		
PROW Intersection	3022	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3023	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	3025	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	3026	Intersection of Cooper Creek Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cooper Creek Rd and Driveway	\$ 5,500	N/A **	N/A **		
PROW Intersection	3028	Intersection of Peach St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Peach St and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	3029	Intersection of Peach St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Peach St and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3030	Intersection of Bell Ave and Peach St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Peach St	\$ 2,500	N/A **	N/A **		
PROW Intersection	3031	Intersection of Bowling Green St and Auburn Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bowling Green St and Auburn Dr	\$ 1,400	N/A **	N/A **		
PROW Intersection	3032	Intersection of Peach St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Peach St and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3033	Intersection of Glenwood Ln and Kayewood Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glenwood Ln and Kayewood Dr	\$ 8,500	N/A **	N/A **		
PROW Intersection	3034	Intersection of Old North Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Old North Rd and Driveway	\$ 5,800	N/A **	N/A **		
PROW Intersection	3035	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	3036	Intersection of Geesling Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Geesling Rd and Driveway	\$ 8,300	N/A **	N/A **		
PROW Intersection	3037	Intersection of Malone St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Malone St and Midblock Crossing	\$ 3,800	N/A **	N/A **		
PROW Intersection	3038	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3039	Intersection of Worthington Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Worthington Dr and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	3040	Intersection of N Carroll Blvd and Strata Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Strata Dr	\$ 2,800	N/A **	N/A **		
PROW Intersection	3042	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	3043	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	3044	Intersection of N Bonnie Brae St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Driveway	\$ 11,300	N/A **	N/A **		
PROW Intersection	3045	Intersection of Old North Rd and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Old North Rd and Midblock Crossing	\$ 3,800	N/A **	N/A **		
PROW Intersection	3046	Intersection of Westward Dr and Northway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Westward Dr and Northway	\$ 6,300	N/A **	N/A **		
PROW Intersection	3047	Intersection of Westward Dr and Southway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Westward Dr and Southway	\$ 6,600	N/A **	N/A **		
PROW Intersection	3048	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3049	Intersection of Westward Dr and Overlook Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Westward Dr and Overlook Ln	\$ 12,000	N/A **	N/A **		
PROW Intersection	3050	Intersection of Westward Dr and Lookout Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Westward Dr and Lookout Ln	\$ 6,300	N/A **	N/A **		
PROW Intersection	3052	Intersection of Worthington Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Worthington Dr and Driveway	\$ 4,700	N/A **	N/A **		
PROW Intersection	3053	Intersection of Glenwood Ln and Mistywood Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glenwood Ln and Mistywood Ln	\$ 8,300	N/A **	N/A **		
PROW Intersection	3054	Intersection of Old North Rd and Mistywood Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Old North Rd and Mistywood Ln	\$ 3,100	N/A **	N/A **		
PROW Intersection	3055	Intersection of Geesling Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Geesling Rd and Driveway	\$ 12,700	N/A **	N/A **		
PROW Intersection	3057	Intersection of Royal Ln and Mistywood Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Royal Ln and Mistywood Ln	\$ 1,200	N/A **	N/A **		
PROW Intersection	3060	Intersection of Cooper Creek Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cooper Creek Rd and Driveway	\$ 5,500	N/A **	N/A **		
PROW Intersection	3062	Intersection of Hinkle Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkle Dr and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3063	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 5,800	N/A **	N/A **		
PROW Intersection	3064	Intersection of N Carroll Blvd and Oakhill Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Oakhill Dr	\$ 2,600	N/A **	N/A **		
PROW Intersection	3065	Intersection of Windsor Farms Dr and Glen Garden Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Farms Dr and Glen Garden Dr	\$ 11,800	N/A **	N/A **		
PROW Intersection	3066	Intersection of Rugby Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Rugby Ln and Midblock Crossing	\$ 6,000	N/A **	N/A **		
PROW Intersection	3067	Intersection of Rugby Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Rugby Ln and Midblock Crossing	\$ 3,300	N/A **	N/A **		
PROW Intersection	3069	Intersection of Bell Ave and Sunrise Cv	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Sunrise Cv	\$ 7,500	N/A **	N/A **		
PROW Intersection	3070	Intersection of Windsor Farms Dr and Greenway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Farms Dr and Greenway Dr	\$ 14,300	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	3071	Intersection of Glenwood Ln and Mistywood Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Glenwood Ln and Mistywood Ln	\$ 3,800	N/A **	N/A **		
PROW Intersection	3072	Intersection of Hinkle Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hinkle Dr and Corridor End	\$ 4,500	N/A **	N/A **		
PROW Intersection	3073	Intersection of Old North Rd and Chebi Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Old North Rd and Chebi Ln	\$ 8,800	N/A **	N/A **		
PROW Intersection	3074	Intersection of Cooper Creek Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cooper Creek Rd and Driveway	\$ 6,300	N/A **	N/A **		
PROW Intersection	3075	Intersection of Heritage Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Heritage Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3077	Intersection of Heritage Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Heritage Ln and Driveway	\$ 5,500	N/A **	N/A **		
PROW Intersection	3078	Intersection of Chebi Ln and Carson Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chebi Ln and Carson Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	3079	Intersection of Worthington Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Worthington Dr and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3081	Intersection of Chebi Ln and Mercer Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chebi Ln and Mercer Way	\$ 6,300	N/A **	N/A **		
PROW Intersection	3082	Intersection of Chebi Ln and Paxton Way	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chebi Ln and Paxton Way	\$ 4,000	N/A **	N/A **		
PROW Intersection	3083	Intersection of Chebi Ln and Northcrest Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Chebi Ln and Northcrest Rd	\$ 3,600	N/A **	N/A **		
PROW Intersection	3084	Intersection of Sirius Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sirius Dr and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3085	Intersection of Royal Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Royal Ln and Midblock Crossing	\$ 3,800	N/A **	N/A **		
PROW Intersection	3086	Intersection of Savill Garden Dr and Eton Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Savill Garden Dr and Eton Pl	\$ 12,000	N/A **	N/A **		
PROW Intersection	3087	Intersection of N Carroll Blvd and Headlee St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Carroll Blvd and Headlee St	\$ 3,000	N/A **	N/A **		
PROW Intersection	3088	Intersection of Windsor Farms Dr and Savill Garden Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Farms Dr and Savill Garden Dr	\$ 16,500	N/A **	N/A **		
PROW Intersection	3089	Intersection of Schuyler St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Schuyler St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3090	Intersection of Bell Ave and Chateau Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Chateau Ct	\$ 7,500	N/A **	N/A **		
PROW Intersection	3091	Intersection of Schuyler St and I-35 Frontage Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Schuyler St and I-35 Frontage Rd	\$ 5,300	N/A **	N/A **		
PROW Intersection	3092	Intersection of Schuyler St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Schuyler St and Driveway	\$ 9,700	N/A **	N/A **		
PROW Intersection	3093	Intersection of Schuyler St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Schuyler St and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	3094	Intersection of Schuyler St and Worthington Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Schuyler St and Worthington Dr	\$ 8,300	N/A **	N/A **		
PROW Intersection	3095	Intersection of Old North Rd and Foxcroft Cr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Old North Rd and Foxcroft Cr	\$ 2,500	N/A **	N/A **		
PROW Intersection	3096	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	3097	Intersection of Royal Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Royal Ln and Midblock Crossing	\$ 3,300	N/A **	N/A **		
PROW Intersection	3098	Intersection of Woodhaven St and Brookfield Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Woodhaven St and Brookfield Ln	\$ 3,300	N/A **	N/A **		
PROW Intersection	3099	Intersection of Brookfield Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brookfield Ln and Midblock Crossing	\$ 4,200	N/A **	N/A **		
PROW Intersection	3100	Intersection of Windsor Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Dr and Driveway	\$ 5,200	N/A **	N/A **		
PROW Intersection	3101	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3102	Intersection of Stuart Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Driveway	\$ 7,000	N/A **	N/A **		
PROW Intersection	3103	Intersection of Windsor Farms Dr and Englefield Green Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Farms Dr and Englefield Green Dr	\$ 24,300	N/A **	N/A **		
PROW Intersection	3104	Intersection of Bowling Green St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bowling Green St and Midblock Crossing	\$ 4,300	N/A **	N/A **		
PROW Intersection	3105	Intersection of Fm 428 and Stuart Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Stuart Rd	\$ 6,300	N/A **	N/A **		
PROW Intersection	3106	Intersection of Bell Ave and Coronado Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Coronado Dr	\$ 4,800	N/A **	N/A **		
PROW Intersection	3107	Intersection of Windsor Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Dr and Driveway	\$ 18,000	N/A **	N/A **		
PROW Intersection	3108	Intersection of Geesling Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Geesling Rd and Driveway	\$ 6,500	N/A **	N/A **		
PROW Intersection	3109	Intersection of Stuart Rd and Coronado Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Coronado Dr	\$ 3,500	N/A **	N/A **		
PROW Intersection	3110	Intersection of N Bonnie Brae St and W Windsor Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and W Windsor Dr	\$ 8,900	N/A **	N/A **		
PROW Intersection	3111	Intersection of W Windsor Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Windsor Dr and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3112	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3113	Intersection of W Windsor Dr and Northway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Windsor Dr and Northway	\$ 7,900	N/A **	N/A **		
PROW Intersection	3114	Intersection of W Windsor Dr and Southway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Windsor Dr and Southway	\$ 7,500	N/A **	N/A **		
PROW Intersection	3115	Intersection of W Windsor Dr and Cariage Hill	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Windsor Dr and Cariage Hill	\$ 3,300	N/A **	N/A **		
PROW Intersection	3116	Intersection of W Windsor Dr and Overlook Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Windsor Dr and Overlook Ln	\$ 7,300	N/A **	N/A **		
PROW Intersection	3117	Intersection of W Windsor Dr and Lookout Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Windsor Dr and Lookout Ln	\$ 7,500	N/A **	N/A **		
PROW Intersection	3118	Intersection of W Windsor Dr and Crestmeadow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Windsor Dr and Crestmeadow St	\$ 4,500	N/A **	N/A **		
PROW Intersection	3119	Intersection of W Windsor Dr and Windsor Farms Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Windsor Dr and Windsor Farms Dr	\$ 10,500	N/A **	N/A **		





Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	3239	Intersection of Windsor Dr and Windy Hill St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Dr and Windy Hill St	\$ 5,500	N/A **	N/A **		
PROW Intersection	3240	Intersection of N Bonnie Brae St and North Lakes Park	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and North Lakes Park	\$ 4,500	N/A **	N/A **		
PROW Intersection	3241	Intersection of Windsor Dr and Bluebonnet Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Dr and Bluebonnet Pl	\$ 6,300	N/A **	N/A **		
PROW Intersection	3242	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3243	Intersection of Fallmeadow St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fallmeadow St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3245	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3246	Intersection of Brooke St and Casie Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brooke St and Casie Ct	\$ 5,800	N/A **	N/A **		
PROW Intersection	3247	Intersection of Foxwood Cir and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Foxwood Cir and Cul De Sac	\$ 3,500	N/A **	N/A **		
PROW Intersection	3248	Intersection of Fm 428 and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3249	Intersection of Fallmeadow St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fallmeadow St and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	3250	Intersection of Old Orchard Ln and Broken Arrow Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Old Orchard Ln and Broken Arrow Rd	\$ 12,500	N/A **	N/A **		
PROW Intersection	3252	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3253	Intersection of Casie Ct and Evers Pkwy	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Casie Ct and Evers Pkwy	\$ 5,300	N/A **	N/A **		
PROW Intersection	3254	Intersection of Benjiman St and Brooke St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Benjiman St and Brooke St	\$ 5,500	N/A **	N/A **		
PROW Intersection	3255	Intersection of Fallmeadow St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fallmeadow St and Driveway	\$ 6,100	N/A **	N/A **		
PROW Intersection	3256	Intersection of Hollycreek St and Foxwood Cr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hollycreek St and Foxwood Cr	\$ 5,500	N/A **	N/A **		
PROW Intersection	3257	Intersection of Fm 428 and Edinburg Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Edinburg Ln	\$ 3,400	N/A **	N/A **		
PROW Intersection	3258	Intersection of Windsor Dr and Broken Bow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Dr and Broken Bow St	\$ 5,700	N/A **	N/A **		
PROW Intersection	3259	Intersection of Fallmeadow St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fallmeadow St and Driveway	\$ 500	N/A **	N/A **		
PROW Intersection	3260	Intersection of Windsor Dr and Old Orchard Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Dr and Old Orchard Ln	\$ 9,500	N/A **	N/A **		
PROW Intersection	3261	Intersection of Bell Ave and Foxwood Cr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Foxwood Cr	\$ 11,000	N/A **	N/A **		
PROW Intersection	3262	Intersection of Yellowstone Pl and Monterey Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Yellowstone Pl and Monterey Dr	\$ 6,800	N/A **	N/A **		
PROW Intersection	3263	Intersection of Windsor Dr and Dunes St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windsor Dr and Dunes St	\$ 13,400	N/A **	N/A **		
PROW Intersection	3264	Intersection of Fm 428 and Monterey Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Monterey Dr	\$ 4,500	N/A **	N/A **		
PROW Intersection	3266	Intersection of Stuart Rd and Wolftrap Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Wolftrap Dr	\$ 4,500	N/A **	N/A **		
PROW Intersection	3267	Intersection of Meadow View Ct and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadow View Ct and Cul De Sac	\$ 8,100	N/A **	N/A **		
PROW Intersection	3268	Intersection of Lido Way and Balboa Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Lido Way and Balboa Ct	\$ 9,500	N/A **	N/A **		
PROW Intersection	3269	Intersection of Gardenview St and Brooke St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gardenview St and Brooke St	\$ 9,000	N/A **	N/A **		
PROW Intersection	3270	Intersection of Evers Pkwy and Gardenview St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Evers Pkwy and Gardenview St	\$ 3,200	N/A **	N/A **		
PROW Intersection	3271	Intersection of Fallmeadow St and Gardenview St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fallmeadow St and Gardenview St	\$ 7,300	N/A **	N/A **		
PROW Intersection	3272	Intersection of Gardenview St and Joyce Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Gardenview St and Joyce Ln	\$ 2,800	N/A **	N/A **		
PROW Intersection	3273	Intersection of Evers Pkwy and Gardenview St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Evers Pkwy and Gardenview St	\$ 400	N/A **	N/A **		
PROW Intersection	3274	Intersection of Fallmeadow St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fallmeadow St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3275	Intersection of Fm 428 and Manhattan Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Manhattan Dr	\$ 2,500	N/A **	N/A **		
PROW Intersection	3277	Intersection of N Bell Ave and Hollycreek St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bell Ave and Hollycreek St	\$ 12,400	N/A **	N/A **		
PROW Intersection	3278	Intersection of Yellowstone Pl and Manhattan Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Yellowstone Pl and Manhattan Dr	\$ 3,300	N/A **	N/A **		
PROW Intersection	3279	Intersection of Stuart Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Driveway	\$ 6,300	N/A **	N/A **		
PROW Intersection	3280	Intersection of Evers Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Evers Pkwy and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	3281	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 10,400	N/A **	N/A **		
PROW Intersection	3282	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3283	Intersection of Brooke St and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brooke St and Cul De Sac	\$ 5,500	N/A **	N/A **		
PROW Intersection	3284	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3285	Intersection of Yellowstone Pl and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Yellowstone Pl and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3286	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3287	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 3,300	N/A **	N/A **		
PROW Intersection	3288	Intersection of Bell Ave and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Bell Ave and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3289	Intersection of N Bell Ave and Ashley Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bell Ave and Ashley Cir	\$ 15,300	N/A **	N/A **		
PROW Intersection	3290	Intersection of N Bell Ave and Fm 2164	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bell Ave and Fm 2164	\$ 600	N/A **	N/A **		
PROW Intersection	3291	Intersection of Fm 428 and Sierra Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Sierra Dr	\$ 1,000	N/A **	N/A **		
PROW Intersection	3292	Intersection of Yellowstone Pl and Sierra Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Yellowstone Pl and Sierra Dr	\$ 6,000	N/A **	N/A **		
PROW Intersection	3293	Intersection of Evers Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Evers Pkwy and Driveway	\$ 800	N/A **	N/A **		
PROW Intersection	3295	Intersection of Kings Row and Farris Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Farris Rd	\$ 800	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	3296	Intersection of Evers Pkwy and Cobblestone Row	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Evers Pkwy and Cobblestone Row	\$ 3,900	N/A **	N/A **		
PROW Intersection	3297	Intersection of Cobblestone Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cobblestone Row and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3298	Intersection of Kings Row and Deerwood Pkwy	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Deerwood Pkwy	\$ 3,000	N/A **	N/A **		
PROW Intersection	3299	Intersection of Nicosia St and Us Hwy 77	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nicosia St and Us Hwy 77	\$ 500	N/A **	N/A **		
PROW Intersection	3300	Intersection of Cobblestone Rw and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cobblestone Rw and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	3301	Intersection of Fm 428 and Laguna Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Laguna Dr	\$ 5,000	N/A **	N/A **		
PROW Intersection	3302	Intersection of Cobblestone Rw and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cobblestone Rw and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3303	Intersection of Cobblestone Rw and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cobblestone Rw and Driveway	\$ 3,400	N/A **	N/A **		
PROW Intersection	3304	Intersection of N Locust St and Cobblestone Rw	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Locust St and Cobblestone Rw	\$ 3,000	N/A **	N/A **		
PROW Intersection	3305	Intersection of Yellowstone Pl and Laguna Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Yellowstone Pl and Laguna Dr	\$ 300	N/A **	N/A **		
PROW Intersection	3306	Intersection of Evers Pkwy and Robbie O St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Evers Pkwy and Robbie O St	\$ 4,800	N/A **	N/A **		
PROW Intersection	3307	Intersection of Robbie-O St and Brooke St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Robbie-O St and Brooke St	\$ 2,500	N/A **	N/A **		
PROW Intersection	3308	Intersection of Deerwood Pkwy and Staghorn Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Deerwood Pkwy and Staghorn Cir	\$ 6,500	N/A **	N/A **		
PROW Intersection	3309	Intersection of Kings Row and Calvert Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Calvert Ln	\$ 14,100	N/A **	N/A **		
PROW Intersection	3310	Intersection of Kings Row and Kings Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Kings Ct	\$ 3,900	N/A **	N/A **		
PROW Intersection	3311	Intersection of Shadow Trl and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shadow Trl and Corridor End	\$ 800	N/A **	N/A **		
PROW Intersection	3312	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 7,500	N/A **	N/A **		
PROW Intersection	3313	Intersection of Windbrook St and Shadow Trail	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windbrook St and Shadow Trail	\$ 5,300	N/A **	N/A **		
PROW Intersection	3314	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	3315	Intersection of Kings Row and Nottingham Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Nottingham Dr	\$ 5,600	N/A **	N/A **		
PROW Intersection	3316	Intersection of Kings Row and Forest Bend Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Forest Bend Rd	\$ -	N/A **	N/A **		
PROW Intersection	3317	Intersection of Kings Row and Yorkshire St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Yorkshire St	\$ 7,300	N/A **	N/A **		
PROW Intersection	3318	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	3319	Intersection of Kings Row and Waldorf Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Waldorf Dr	\$ 4,000	N/A **	N/A **		
PROW Intersection	3320	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3321	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3322	Intersection of Deerwood Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Deerwood Pkwy and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	3323	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 5,800	N/A **	N/A **		
PROW Intersection	3324	Intersection of Deer Forest Dr and White Tail Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Deer Forest Dr and White Tail Dr	\$ 8,500	N/A **	N/A **		
PROW Intersection	3325	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3326	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3327	Intersection of N Bonnie Brae St and Riney Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Bonnie Brae St and Riney Rd	\$ 2,300	N/A **	N/A **		
PROW Intersection	3328	Intersection of Constantina Dr and Beatriz Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Constantina Dr and Beatriz Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	3329	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3330	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 5,800	N/A **	N/A **		
PROW Intersection	3331	Intersection of Constantina Dr and Chon Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Constantina Dr and Chon Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	3332	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3333	Intersection of Kings Row and Wellington Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Wellington Dr	\$ 7,100	N/A **	N/A **		
PROW Intersection	3334	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3335	Intersection of Kings Row and Dunes St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Dunes St	\$ 6,600	N/A **	N/A **		
PROW Intersection	3336	Intersection of Fm 428 and Kings Row	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Kings Row	\$ 6,000	N/A **	N/A **		
PROW Intersection	3337	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 300	N/A **	N/A **		
PROW Intersection	3338	Intersection of Farris Rd and White Tail Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Farris Rd and White Tail Dr	\$ 6,800	N/A **	N/A **		
PROW Intersection	3339	Intersection of Windbrook St and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windbrook St and Midblock Crossing	\$ 2,500	N/A **	N/A **		
PROW Intersection	3340	Intersection of Windbrook St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Windbrook St and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3341	Intersection of Yellowstone Pl and Kings Row	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Yellowstone Pl and Kings Row	\$ 3,300	N/A **	N/A **		
PROW Intersection	3342	Intersection of Canonngate Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Canonngate Dr and Midblock Crossing	\$ 300	N/A **	N/A **		



Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	3343	Intersection of Canonngate Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Canonngate Dr and Midblock Crossing	\$ -	N/A **	N/A **		
PROW Intersection	3344	Intersection of Canonngate Dr and Hardaway Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Canonngate Dr and Hardaway Dr	\$ 2,300	N/A **	N/A **		
PROW Intersection	3345	Intersection of Canonngate Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Canonngate Dr and Midblock Crossing	\$ 300	N/A **	N/A **		
PROW Intersection	3346	Intersection of Deerwood Pkwy and Deerfield Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Deerwood Pkwy and Deerfield Dr	\$ 12,500	N/A **	N/A **		
PROW Intersection	3347	Intersection of Kings Row and Stuart Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Stuart Rd	\$ 500	N/A **	N/A **		
PROW Intersection	3348	Intersection of Kings Row and Sunnydale Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Sunnydale Ln	\$ 12,300	N/A **	N/A **		
PROW Intersection	3350	Intersection of High Meadow Dr and Dunes St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of High Meadow Dr and Dunes St	\$ 10,100	N/A **	N/A **		
PROW Intersection	3351	Intersection of High Meadow Dr and Harvest Glen Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of High Meadow Dr and Harvest Glen Dr	\$ 5,800	N/A **	N/A **		
PROW Intersection	3352	Intersection of Tripp Trail and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Tripp Trail and Midblock Crossing	\$ 3,300	N/A **	N/A **		
PROW Intersection	3353	Intersection of Beatriz Dr and Santos Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Beatriz Dr and Santos Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	3354	Intersection of Santos Dr and Chon Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Santos Dr and Chon Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	3355	Intersection of Yellowstone Pl and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Yellowstone Pl and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3357	Intersection of Becker Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Becker Dr and Midblock Crossing	\$ 2,300	N/A **	N/A **		
PROW Intersection	3358	Intersection of Calvert Ln and La Vista Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Calvert Ln and La Vista Ct	\$ 9,300	N/A **	N/A **		
PROW Intersection	3359	Intersection of Fm 428 and Buckingham Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Buckingham Dr	\$ 5,900	N/A **	N/A **		
PROW Intersection	3360	Intersection of Deerwood Pkwy and Grant Pkwy	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Deerwood Pkwy and Grant Pkwy	\$ 5,800	N/A **	N/A **		
PROW Intersection	3361	Intersection of Cricket Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cricket Dr and Driveway	\$ -	N/A **	N/A **		
PROW Intersection	3362	Intersection of Nicosia St and Santos Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nicosia St and Santos Dr	\$ 7,500	N/A **	N/A **		
PROW Intersection	3363	Intersection of Hermalinda Dr and Santos Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hermalinda Dr and Santos Dr	\$ 6,600	N/A **	N/A **		
PROW Intersection	3364	Intersection of Santos Dr and Crisoforo Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Santos Dr and Crisoforo Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	3365	Intersection of Becker Dr and Davenport Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Becker Dr and Davenport Dr	\$ 400	N/A **	N/A **		
PROW Intersection	3366	Intersection of Shadow Trl and Pear Tree Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shadow Trl and Pear Tree Pl	\$ 1,500	N/A **	N/A **		
PROW Intersection	3367	Intersection of Davenport Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Davenport Dr and Driveway	\$ -	N/A **	N/A **		
PROW Intersection	3368	Intersection of Yellowstone Pl and Imperial Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Yellowstone Pl and Imperial Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	3369	Intersection of Cricket Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cricket Dr and Driveway	\$ 3,800	N/A **	N/A **		
PROW Intersection	3370	Intersection of Sagewood St and Pear Tree Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sagewood St and Pear Tree Pl	\$ 7,100	N/A **	N/A **		
PROW Intersection	3371	Intersection of Pear Tree Pl and Pheasant Hollow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pear Tree Pl and Pheasant Hollow St	\$ 6,800	N/A **	N/A **		
PROW Intersection	3372	Intersection of Grant Pkwy and Deer Forest Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grant Pkwy and Deer Forest Dr	\$ 6,300	N/A **	N/A **		
PROW Intersection	3373	Intersection of Mckamy Blvd and Doris Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mckamy Blvd and Doris Dr	\$ 10,500	N/A **	N/A **		
PROW Intersection	3374	Intersection of Harvest Glen Dr and Harvest Hill Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Harvest Glen Dr and Harvest Hill Dr	\$ 9,500	N/A **	N/A **		
PROW Intersection	3375	Intersection of Cricket Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cricket Dr and Driveway	\$ -	N/A **	N/A **		
PROW Intersection	3376	Intersection of Mckamy Blvd and Skelton St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mckamy Blvd and Skelton St	\$ 17,100	N/A **	N/A **		
PROW Intersection	3377	Intersection of Becker Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Becker Dr and Midblock Crossing	\$ -	N/A **	N/A **		
PROW Intersection	3378	Intersection of Mckamy Blvd and Fm 2164	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mckamy Blvd and Fm 2164	\$ 7,800	N/A **	N/A **		
PROW Intersection	3379	Intersection of Beatriz Dr and Eufemia Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Beatriz Dr and Eufemia Dr	\$ 9,600	N/A **	N/A **		
PROW Intersection	3380	Intersection of Morin Dr and Eufemia Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morin Dr and Eufemia Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	3381	Intersection of Brentwood Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Brentwood Dr and Driveway	\$ -	N/A **	N/A **		
PROW Intersection	3382	Intersection of Grant Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grant Pkwy and Driveway	\$ 5,800	N/A **	N/A **		
PROW Intersection	3383	Intersection of Hermalinda Dr and Eufemia Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hermalinda Dr and Eufemia Dr	\$ 9,300	N/A **	N/A **		
PROW Intersection	3385	Intersection of Fm 428 and Royal Acres Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Royal Acres Dr	\$ 5,500	N/A **	N/A **		
PROW Intersection	3386	Intersection of Manten Blvd and Calvert Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Manten Blvd and Calvert Ln	\$ 9,900	N/A **	N/A **		
PROW Intersection	3387	Intersection of Manten Blvd and Inwood Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Manten Blvd and Inwood Ct	\$ 10,900	N/A **	N/A **		
PROW Intersection	3388	Intersection of Manten Blvd and Lockhurst Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Manten Blvd and Lockhurst Ln	\$ 10,900	N/A **	N/A **		
PROW Intersection	3389	Intersection of Shadow Trl and Tanglewood St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shadow Trl and Tanglewood St	\$ 6,600	N/A **	N/A **		
PROW Intersection	3390	Intersection of Tanglewood St and Sagewood St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Tanglewood St and Sagewood St	\$ 6,800	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	3391	Intersection of Grant Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grant Pkwy and Driveway	\$ 2,300	N/A **	N/A **		
PROW Intersection	3392	Intersection of Greystone Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Greystone Dr and Midblock Crossing	\$ 2,300	N/A **	N/A **		
PROW Intersection	3393	Intersection of Pheasant Hollow St and Tanglewood St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pheasant Hollow St and Tanglewood St	\$ 7,500	N/A **	N/A **		
PROW Intersection	3394	Intersection of Greystone Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Greystone Dr and Midblock Crossing	\$ -	N/A **	N/A **		
PROW Intersection	3395	Intersection of Meadowedge Ln and Northpointe Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadowedge Ln and Northpointe Dr	\$ 11,900	N/A **	N/A **		
PROW Intersection	3396	Intersection of Meadowedge Ln and Meadowtrail Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadowedge Ln and Meadowtrail Ln	\$ 9,800	N/A **	N/A **		
PROW Intersection	3397	Intersection of Morin Dr and Carrigan Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morin Dr and Carrigan Ln	\$ 20,700	N/A **	N/A **		
PROW Intersection	3398	Intersection of Stuart Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Driveway	\$ 8,800	N/A **	N/A **		
PROW Intersection	3399	Intersection of Fallmeadow St and Meadowedge Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fallmeadow St and Meadowedge Ln	\$ 14,900	N/A **	N/A **		
PROW Intersection	3400	Intersection of Meadowedge Ln and Ann Arbor Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadowedge Ln and Ann Arbor Ln	\$ 16,800	N/A **	N/A **		
PROW Intersection	3401	Intersection of Meadowedge Ln and Chapel Hill Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadowedge Ln and Chapel Hill Ln	\$ 17,400	N/A **	N/A **		
PROW Intersection	3402	Intersection of Fm 428 and Wellington Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Wellington Dr	\$ 1,000	N/A **	N/A **		
PROW Intersection	3403	Intersection of Hermalinda Dr and Carrigan Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hermalinda Dr and Carrigan Ln	\$ 15,300	N/A **	N/A **		
PROW Intersection	3405	Intersection of Beatriz Dr and Carrigan Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Beatriz Dr and Carrigan Ln	\$ 10,800	N/A **	N/A **		
PROW Intersection	3407	Intersection of Greystone Dr and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Greystone Dr and Midblock Crossing	\$ 4,500	N/A **	N/A **		
PROW Intersection	3408	Intersection of Westgate Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Westgate Dr and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	3410	Intersection of La Fonta and Manten Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of La Fonta and Manten Blvd	\$ 10,500	N/A **	N/A **		
PROW Intersection	3412	Intersection of Shadow Trl and Willow Stone St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shadow Trl and Willow Stone St	\$ 4,600	N/A **	N/A **		
PROW Intersection	3413	Intersection of Sagewood St and Willow Stone St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sagewood St and Willow Stone St	\$ 10,800	N/A **	N/A **		
PROW Intersection	3414	Intersection of Willow Stone St and Pheasant Hollow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Willow Stone St and Pheasant Hollow St	\$ 7,100	N/A **	N/A **		
PROW Intersection	3415	Intersection of Grant Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grant Pkwy and Driveway	\$ 6,800	N/A **	N/A **		
PROW Intersection	3416	Intersection of Greystone Dr and Corridor End	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Greystone Dr and Corridor End	\$ 500	N/A **	N/A **		
PROW Intersection	3417	Intersection of Stuart Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Driveway	\$ 8,300	N/A **	N/A **		
PROW Intersection	3418	Intersection of Grant Pkwy and Farris Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grant Pkwy and Farris Rd	\$ 3,600	N/A **	N/A **		
PROW Intersection	3419	Intersection of Grant Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grant Pkwy and Driveway	\$ 6,300	N/A **	N/A **		
PROW Intersection	3421	Intersection of Grant Pkwy and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grant Pkwy and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3422	Intersection of Fallmeadow St and Cotten Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fallmeadow St and Cotten Dr	\$ 14,900	N/A **	N/A **		
PROW Intersection	3423	Intersection of Fm 428 and Picadilly Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Picadilly Ln	\$ 1,000	N/A **	N/A **		
PROW Intersection	3424	Intersection of Hermalinda Dr and Evan Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hermalinda Dr and Evan Dr	\$ 12,400	N/A **	N/A **		
PROW Intersection	3426	Intersection of Sunnydale Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sunnydale Ln and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3428	Intersection of Morin Dr and Evan Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morin Dr and Evan Dr	\$ 12,200	N/A **	N/A **		
PROW Intersection	3429	Intersection of Fawn Dr and Antler Cir	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fawn Dr and Antler Cir	\$ 6,800	N/A **	N/A **		
PROW Intersection	3430	Intersection of Shadow Trl and Plum Hollow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shadow Trl and Plum Hollow St	\$ 1,700	N/A **	N/A **		
PROW Intersection	3431	Intersection of Plum Hollow St and Sagewood St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Plum Hollow St and Sagewood St	\$ 6,500	N/A **	N/A **		
PROW Intersection	3432	Intersection of Cyrus Way and Canton Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cyrus Way and Canton Ct	\$ 9,800	N/A **	N/A **		
PROW Intersection	3433	Intersection of Cyrus Way and Brian Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cyrus Way and Brian Dr	\$ 7,500	N/A **	N/A **		
PROW Intersection	3434	Intersection of Sun Valley Dr and Yellowstone Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Yellowstone Pl	\$ 8,300	N/A **	N/A **		
PROW Intersection	3435	Intersection of Sun Valley Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3436	Intersection of Sun Valley Dr and Sheraton Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Sheraton Rd	\$ 5,500	N/A **	N/A **		
PROW Intersection	3437	Intersection of Sun Valley Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	3438	Intersection of Stuart Rd and Sun Valley Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Sun Valley Dr	\$ 11,800	N/A **	N/A **		
PROW Intersection	3439	Intersection of Pheasant Hollow St and Plum Hollow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Pheasant Hollow St and Plum Hollow St	\$ 7,300	N/A **	N/A **		
PROW Intersection	3440	Intersection of Cyrus Way and Tristan Ct	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cyrus Way and Tristan Ct	\$ 8,500	N/A **	N/A **		
PROW Intersection	3441	Intersection of Sun Valley Dr and Sunnydale Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Sunnydale Ln	\$ 12,300	N/A **	N/A **		
PROW Intersection	3442	Intersection of Cyrus Way and Teal Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Cyrus Way and Teal Dr	\$ 6,000	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	3443	Intersection of Sun Valley Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Driveway	\$ 6,300	N/A **	N/A **		
PROW Intersection	3444	Intersection of Sun Valley Dr and Valley View Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Valley View Rd	\$ 9,800	N/A **	N/A **		
PROW Intersection	3445	Intersection of Sun Valley Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3446	Intersection of Manten Blvd and La Mirada	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Manten Blvd and La Mirada	\$ 10,100	N/A **	N/A **		
PROW Intersection	3447	Intersection of Sun Valley Dr and Huntington Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Huntington Dr	\$ 4,500	N/A **	N/A **		
PROW Intersection	3448	Intersection of Sun Valley Dr and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3449	Intersection of Sun Valley Dr and Atlas Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Atlas Dr	\$ 8,500	N/A **	N/A **		
PROW Intersection	3450	Intersection of Sun Valley Dr and Buckingham Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Sun Valley Dr and Buckingham Dr	\$ 3,000	N/A **	N/A **		
PROW Intersection	3451	Intersection of Morin Dr and Crisoforo Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morin Dr and Crisoforo Dr	\$ 11,600	N/A **	N/A **		
PROW Intersection	3452	Intersection of Hermalinda Dr and Morin Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hermalinda Dr and Morin Dr	\$ 16,100	N/A **	N/A **		
PROW Intersection	3453	Intersection of Nicosia St and Morin Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Nicosia St and Morin Dr	\$ 11,000	N/A **	N/A **		
PROW Intersection	3454	Intersection of Stuart Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3455	Intersection of Canton Ct and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Canton Ct and Cul De Sac	\$ 3,800	N/A **	N/A **		
PROW Intersection	3456	Intersection of Tristan Ct and Cul De Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Tristan Ct and Cul De Sac	\$ 3,800	N/A **	N/A **		
PROW Intersection	3457	Intersection of Shadow Trl and Cul-De-Sac	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Shadow Trl and Cul-De-Sac	\$ 4,200	N/A **	N/A **		
PROW Intersection	3458	Intersection of Meadow Ln and Pheasant Hollow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadow Ln and Pheasant Hollow St	\$ 6,600	N/A **	N/A **		
PROW Intersection	3459	Intersection of Meadow Ln and Sagewood St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Meadow Ln and Sagewood St	\$ 7,600	N/A **	N/A **		
PROW Intersection	3460	Intersection of Fm 428 and Hercules Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Hercules Ln	\$ 4,000	N/A **	N/A **		
PROW Intersection	3461	Intersection of Hercules Ln and Wellington Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Wellington Dr	\$ 3,300	N/A **	N/A **		
PROW Intersection	3462	Intersection of Hercules Ln and Picadilly Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Picadilly Ln	\$ 3,000	N/A **	N/A **		
PROW Intersection	3463	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3464	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3465	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,300	N/A **	N/A **		
PROW Intersection	3466	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3467	Intersection of Hercules Ln and Buckingham Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Buckingham Dr	\$ 5,000	N/A **	N/A **		
PROW Intersection	3468	Intersection of Hercules Ln and Royal Acres Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Royal Acres Dr	\$ 5,800	N/A **	N/A **		
PROW Intersection	3469	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3470	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 4,500	N/A **	N/A **		
PROW Intersection	3471	Intersection of Hercules Ln and Huntington Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Huntington Dr	\$ 6,500	N/A **	N/A **		
PROW Intersection	3472	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3473	Intersection of W Hercules Ln and Northpointe Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Northpointe Dr	\$ 15,100	N/A **	N/A **		
PROW Intersection	3474	Intersection of Hercules Ln and Sheraton Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Sheraton Rd	\$ 7,000	N/A **	N/A **		
PROW Intersection	3475	Intersection of W Hercules Ln and Chapel Hill Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Chapel Hill Ln	\$ 16,900	N/A **	N/A **		
PROW Intersection	3476	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3477	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3478	Intersection of W Hercules Ln and Cotten Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Cotten Dr	\$ 16,900	N/A **	N/A **		
PROW Intersection	3479	Intersection of W Hercules Ln and Fallmeadow St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Fallmeadow St	\$ 17,000	N/A **	N/A **		
PROW Intersection	3480	Intersection of W Hercules Ln and Ann Arbor Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Ann Arbor Ln	\$ 14,100	N/A **	N/A **		
PROW Intersection	3481	Intersection of W Hercules Ln and Midblock Crossing	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Midblock Crossing	\$ 3,800	N/A **	N/A **		
PROW Intersection	3482	Intersection of W Hercules Ln and Allison Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Allison Dr	\$ 10,800	N/A **	N/A **		
PROW Intersection	3483	Intersection of Hermalinda Dr and W Hercules Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hermalinda Dr and W Hercules Ln	\$ 25,300	N/A **	N/A **		
PROW Intersection	3484	Intersection of W Hercules Ln and Beatriz Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Beatriz Dr	\$ 21,500	N/A **	N/A **		
PROW Intersection	3485	Intersection of Hercules Ln and Stuart Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Stuart Rd	\$ 12,800	N/A **	N/A **		
PROW Intersection	3486	Intersection of W Hercules Ln and Nicosia St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Nicosia St	\$ 9,900	N/A **	N/A **		
PROW Intersection	3487	Intersection of W Hercules Ln and Logan Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Logan Dr	\$ 10,800	N/A **	N/A **		
PROW Intersection	3488	Intersection of Hercules Ln and Camelot St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Camelot St	\$ 7,300	N/A **	N/A **		
PROW Intersection	3489	Intersection of Hercules Ln and Atlas Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Atlas Dr	\$ 6,800	N/A **	N/A **		
PROW Intersection	3490	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,500	N/A **	N/A **		

Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	3491	Intersection of Hercules Ln and Titan Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Titan Trl	\$ 7,600	N/A **	N/A **		
PROW Intersection	3492	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3493	Intersection of Hercules Ln and Redstone Rd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Redstone Rd	\$ 9,600	N/A **	N/A **		
PROW Intersection	3494	Intersection of Hercules Ln and Meadow Lane PI	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Meadow Lane PI	\$ 4,100	N/A **	N/A **		
PROW Intersection	3495	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3496	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 6,300	N/A **	N/A **		
PROW Intersection	3497	Intersection of Hercules Ln and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hercules Ln and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3498	Intersection of W Hercules Ln and Meadowtrail Ln	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Hercules Ln and Meadowtrail Ln	\$ 19,500	N/A **	N/A **		
PROW Intersection	3499	Intersection of Poinsettia Blvd and Diamond Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Poinsettia Blvd and Diamond Dr	\$ 11,800	N/A **	N/A **		
PROW Intersection	3501	Intersection of Poinsettia Blvd and Teal Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Poinsettia Blvd and Teal Dr	\$ 9,000	N/A **	N/A **		
PROW Intersection	3503	Intersection of Poinsettia Blvd and Manten Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Poinsettia Blvd and Manten Blvd	\$ 6,600	N/A **	N/A **		
PROW Intersection	3505	Intersection of Stuart Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Driveway	\$ 2,500	N/A **	N/A **		
PROW Intersection	3506	Intersection of Fm 428 and Poinsettia Blvd	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fm 428 and Poinsettia Blvd	\$ 600	N/A **	N/A **		
PROW Intersection	3507	Intersection of Stuart Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Driveway	\$ 4,800	N/A **	N/A **		
PROW Intersection	3509	Intersection of Stuart Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Driveway	\$ 5,000	N/A **	N/A **		
PROW Intersection	3510	Intersection of Hermalinda Dr and Beall St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Hermalinda Dr and Beall St	\$ 9,000	N/A **	N/A **		





Facility Type	GPS ID	Project Name	Finding #	Self-Evaluation Finding	Cost Projection	Priority Value	Priority Rank	Funding Year	Year Completed
PROW Intersection	3646	Intersection of Kings Row and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Kings Row and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3647	Intersection of W Sycamore St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Sycamore St and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3648	Intersection of W Sycamore St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Sycamore St and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3649	Intersection of W Sycamore St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of W Sycamore St and Driveway	\$ 3,000	N/A **	N/A **		
PROW Intersection	3650	Intersection of Parvin St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Parvin St and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3651	Intersection of Stuart Rd and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Stuart Rd and Driveway	\$ 6,000	N/A **	N/A **		
PROW Intersection	3652	Intersection of Redstone Dr and Titan Trl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redstone Dr and Titan Trl	\$ 9,000	N/A **	N/A **		
PROW Intersection	3653	Intersection of Redstone Rd and Atlas Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Redstone Rd and Atlas Dr	\$ 12,000	N/A **	N/A **		
PROW Intersection	3654	Intersection of Crescent St and Thomas St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Crescent St and Thomas St	\$ 6,000	N/A **	N/A **		
PROW Intersection	3655	Intersection of Fulton St and Emery St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Fulton St and Emery St	\$ 6,000	N/A **	N/A **		
PROW Intersection	3656	Intersection of N Locust St and E 3Rd St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Locust St and E 3Rd St	\$ 3,000	N/A **	N/A **		
PROW Intersection	3657	Intersection of N Elm St and Ferguson St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of N Elm St and Ferguson St	\$ 3,000	N/A **	N/A **		
PROW Intersection	3658	Intersection of Grant Pkwy and Fawn Dr	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Grant Pkwy and Fawn Dr	\$ 3,000	N/A **	N/A **		
PROW Intersection	3659	Intersection of E University Dr and Shawnee St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of E University Dr and Shawnee St	\$ 3,000	N/A **	N/A **		
PROW Intersection	3660	Intersection of Mingo Rd and Boyd St	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mingo Rd and Boyd St	\$ 3,000	N/A **	N/A **		
PROW Intersection	3661	Intersection of Mingo Rd and Redwood Pl	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Mingo Rd and Redwood Pl	\$ 3,000	N/A **	N/A **		
PROW Intersection	3662	Intersection of Morse St and Driveway	N/A	See facility report and GIS data for detailed evaluation findings at intersection of Morse St and Driveway	\$ 3,000	N/A **	N/A **		
<b>TOTAL</b>					<b>\$ 43,770,910</b>	<b>** See individual intersection reports and gis data for ramp priorities.</b>			