

Weekly Vehicle Inspection

Name *	
Please enter your first and last name	
reade enter your mot and tast name	
Date *	
31	
Unit Number *	
PM GARYTRUCK	X *
Mileage *	
Please enter the current odometer reading	
Oil Level *	
Oil is at correct level	
Transmission Fluid *	
Transmission Fluid is at correct level	
Tire Pressure *	

PM Vehicle Inspections

smartsheet

Name I Kristi Cooper								
, Ariasi Looper	Date 12/03/21	Unit Number PM 1175	Mileage Oil Lev	Tire Pres	ure Transmis	sion Fluid Lights	Cleanlin	Physical Damage
2 Bryan	12/03/21	PM 1175 PC 0891	67746 37356.5	✓	☑	∨	▽	▼ ▼
3 Janson Bewley	01/18/22	PC 1475	51103			<u> </u>		Damage to driver side front quarter panel and doors and rear bumper on north driver and passenger side bumper. Numerous dents, dings and scratches on vehicle in numerous spots, which were older. The truck does need
4 Brian Noles	01/24/22	PM 1517	48927	<u> </u>				
5 Janson Bewley	01/24/22	PC 1475	51197	☑	☑	V	☑	Same as list weeks notes and pictures. Light bar switches need to be replaced at some point. The switch works some and not other times.
6 Janson Bewley	01/24/22	PC 0891	37388	✓	✓	☑	☑	Bed clearance lights on sides are not working all other lights work. Same notes as last week, no new damage noted.
7 Jordan Settlemyre	01/25/22	PL 1329	36986					
8 Kristi Cooper 9 Philip King	01/25/22	PM 1175 PL 1330	68404 46640	✓	☑	✓	✓	☑ Niu
10 Charles Strada	01/26/22	PL 0842	53873		<u> </u>		▽	✓ Left license plate light out
Bryan kirby	01/31/22	PC 0891	37419.5			<u> </u>		All lights work except flat bed clearance lights.
12 Janson Bewley	01/31/22	PC 1475	51283	<u> </u>				Same as last weeks. It does appear the batteries are getting weaker and might be a small Freon leak on top hose, above afternator.
13 Robert Pitt	01/31/22	PC 0929	73994.8	☑	☑	☑		
14 Charles Strada	62/01/22	PL 0842	54000	☑	☑	2	☑	Orivers License plate light out
15 Jordan Settlemyre	02/01/22	PL 1329	37087	☑		☑		
16 kevin jackson 17 Kristi Cooper	62/01/22 62/01/22	PL 1331 pm1175	38494 88541	<u> </u>		✓	✓	
15 Philip King	02/01/22	PL 1330	46683	▽	▽	✓	☑	▼ Nia
10 Ryan Moyer	02/01/22	PC 1326	50845			<u> </u>		
20 Bryan kirby	02/07/22	PC 0891	37471.5	2				Running lights on flat bed not working
21 Janson Bewley	02/07/22	PC 1475	51573	✓	<u> </u>	☑	☑	Same as last week. The power steering fluid is at middle of add line. The truck is ditty inside and out from recent winter storm. All else tooks good.
22 Robert Pitt	62/07/22	PC 0929	74046	☑	☑	2	☑	
23 Ryan Moyer	02/07/22	PC 1328	50875	☑				
24 Charles Strada 25 Kevin Jackson	02/08/22 02/08/22	PL 0842 PL 1331	54017 38519	<u> </u>		✓	▽	Orivers said license plate light out
Kristi Cooper	02/08/22	pm1175	88578	☑	▽	✓	☑	♥
7 Philip King	02/08/22	PL 1330	46694			<u> </u>		▼ Nu
S Jordan Settlemyre	02/11/22	PL 1329	37309	2				
Janson Bewley	62/14/22	PC 0891	37495	<u> </u>	<u> </u>	<u> </u>		Truck needs to be cleaned. The power steering fluid and coolars is slightly low. The side bed clearance lights are still not working. At else is the same from previous weeks.
D Janson Bewley	02/14/22	PC 1475	51742	☑		☑	☑	Same as previous weaks. Slightly low on power steering fluid and switch needs to be replaced for light bar.
Robert Pitt	02/14/22	PC 0288	15,929.00	☑		☑		
2 Ryan Moyer	02/14/22 02/15/22	PC 1328	50966	<u> </u>				
Charles Strada Jordan Settlemyre	02/15/22	PL 0842 PL 1329	54060 37339	☑	▽	✓	✓	Chivers license plate light out ✓
Kristi Cooper	02/15/22	PM 1175	8826	☑		<u> </u>		
36 Philip King	02/15/22	PL 1330	46742	<u> </u>		<u> </u>		▼ Nu
Robert Pitt	02/15/22	PC 0929	74,060.00	☑	☑	<u> </u>	☑	
38 Brian Notes	02/16/22	PM 1517	49137	✓	☑	☑	☑	
Robert Pitt	69/20/22	PC 0929	74107	<u> </u>		<u> </u>		
Brian Notes	69/21/22 69/21/22	PM 1517 PC 1475	49185			☑		Same as previous reports and inspections and check engine light is on and shows 02 sensor. All else the same as previous inspections.
Janson Bewley Janson Bewley	69/21/22 69/21/22	PC 1475 PC 0891	51859 37530	☑	▽	✓	✓	Same as previous reports and inspections and chack engine light is on and shows 02 sensor. All else the same as previous inspections. A very small amount of residual brake fluid was noted under carister on top of booster pump, but it does not appear to be actively leaking. All else the same as previous weeks impections.
(2 Jarson beway (3 Charles Strada	69/22/22	PL 0842	54123	☑		<u> </u>		A very small amount or reacular crasse tudo was noted union carriage on top or occoser pump, out it does not appear to be actively reasong. As ease this same as previous weeks inspections.
14 Jordan Settlemyre	69/22/22	PL 1329	37491			<u> </u>		
15 Kevin jackson	69/22/22	PL 1331	38913	☑	☑	<u> </u>	☑	
16 Kristi Cooper	69/22/22	PM 1175	68746	☑	☑	☑	☑	
47 Philip King	69/22/22	PL 1330	46775	<u> </u>		<u> </u>		Nh
48 Janson Bewley 49 Ryan Moyer	02/28/22 02/28/22	PC 1475 PC 1326	At shop 51088		☑	✓	▽	Truck is at shop for fleet to make repairs needed, as noted on previous inspection sheets.
40 Ryan Moyer	03/01/22	PC 1526 PC 0891	37595.3	☑	☑	✓	☑	Running lights on filet bed not working
Charles Strada	09/01/22	PL 0842	54154	<u> </u>		<u> </u>		Drivens side (icones plate light broke
32 Janson Bewley	03/01/22	PM 1517	49205	<u> </u>				Oil has a fixel smell on dip stick. A few small dents and scratches noted but no major damage. Frost burroper has some minor diemage but doesn't appear new. All elies locks good.
3 Kevin Jackson	03/01/22	PL 1331	38946	<u> </u>	<u> </u>	<u> </u>		
4 Kristi Cooper	03/01/22	PM 1175	68810	☑	☑	☑	☑	
5 Philip King	09/01/22	PL 1330	46783	✓	✓	☑		Nia Nia
Janson bewley Janson bewley	09/07/22 09/07/22	PC 0891 PC 1475	37713	<u> </u>				Side clearance bed lights not working but all other lights work good. Coolant and power steering levels slightly low. Needs to be washed and vacuumed. All else same as previous weeks.
57 Janson bewley 58 Brian Notes	03/07/22	PC 1475 PM 1517	Unknown at shop 49287	☑	☑	✓	✓	▼ Truck is at fleet getting serviced.
50 Charles Strada	03/08/22	PL 0842	54165	<u> </u>		<u> </u>		
SO Jordan Settlemyre	03/08/22	PL 1329	37699					
81 Kristi Cooper	03/08/22	PM 1175	68947	<u> </u>	<u> </u>	<u> </u>		
82 Philip King	03/08/22	PL 1330	46897	☑	☑	☑	☑	No damage. One headlight out, turning into fleet this afternoon
83 Robert Pitt	09/09/22	PC 0288	15978	✓	✓	☑		
84 Robert Pitt	03/09/22 03/14/22	PC 0929 PC 0991	74244					
85 Janson bewley Janson bewley	03/14/22	PC 0891 PC 1475	37878 Unknown at fleet getting repairs	☑	☑	✓	✓	Same as previous weeks. No new damage same slightly low fluids and no bed clearance lights are working, which appears to be a fuse issue. Unknown, truck is at firet getting repaired and has been there several weeks.
87 Ryan Moyer	03/14/22	PC 1328	51377	<u> </u>		<u> </u>		VARIOUS, SUCCESS AND SERVING SPACES AND LINES ARE SHOULD AND LINES AND LINES ARE SHOULD AND LINES ARE SHOULD AND LINES ARE SHOULD AND LINES AND LINES ARE SHOULD AND LINES ARE SHOULD AND LINES ARE SHOULD AND LINES ARE SHOULD AND LINES AND LINES AND LINES ARE SHO
38 Jordan Settlemyre	03/15/22	PL 1329	37861					
10 Kristi Cooper	03/15/22							
70 Kristi Cooper		PM 1175	69070	✓	✓	✓	~	
Philip King	03/15/22	PL 1331	39005		✓		☑	Driver side rear fender, back of failigate
	09/15/22	PL 1331 PL 1330	39005 46943	▽	✓✓	☑	☑	Chicar sole near fender, back of larigulas No
Charles Strada	09/15/22 03/16/22	PL 1331 PL 1330 PL 0842	30005 46943 54213	▽	✓✓✓	✓✓✓	✓✓✓	Driver side near funder, bank of hallpate Na
Charles Strada Robert Pitt	03/15/22 03/16/22 03/16/22	PL 1331 PL 1330 PL 0842 PC 0929	39005 48943 54213 74531	✓✓✓		✓✓✓	✓✓✓✓	Chicar side was funder, bask of failigeas 100
Charles Strada Charles Strada Robert Pitt Janson bewley	09/15/22 03/16/22	PL 1331 PL 1330 PL 0842	39005 48943 54213 74331 38032	✓ ✓ ✓ ✓			✓✓✓✓	Driver side near feacher, back of fairbyste The State of
72 Charles Strada 73 Robert Pitt	6915/22 6918/22 6918/22 6912/22 6912/22 6912/22	PL 1331 PL 1330 PL 0842 PC 0629 PC 0629 PC 1475 PC 0629	3005 46943 54213 74331 38032 Unknown at fleet for repair. 74,375.00	✓✓✓		✓✓✓	♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥ ♥	Choice sole now founds, back of ballgate 100
72 Charles Stradu 73 Robert Pitt 74 Jierson bewley 75 Jarson Bewley 76 Robert Pitt 77 Ryen Moyer	691502 691602 691602 691602 692102 692102 692102 692102	PL 1331 PL 1330 PL 1330 PL 6842 PC 6629 PC 6691 PC 1475 PC 6629 PC 1328	39005 48943 54213 74331 38032 Unknown at fleet for repair. 74,375.00 51515					Other sale new feeder, based of teleplate No Series as provious reports. No new destrage noted but grows cleaning fluid and coolent on all slightly how and bed lights are not exching and appears to be bloom face. The webler also needs serviced on bard. The truck means that for reports his rever as weaks. Underwood velocits has been at flead for reports for several weeks.
72 Charles Strada 73 Robert Pitt 74 Janson besley 75 Janson Besley 76 Robert Pitt 77 Ryan Moyer 76 Charles Strada	6915/22 6916/22 6916/22 6921/22 6921/22 6921/22 6921/22 6922/22	PL 1331 PL 1330 PL 0842 PC 0829 PC 0829 PC 0829 PC 0829 PC 1475 PC 0829 PC 1526 PL 1542	39005 446413 54213 74331 74331 38032 Unknown at fixed for repair. 74,375.00 515155 54423					Other side new forcits, basis of ballyste No State of ballyste U U U U U U U U U U U U U
72 Charles Strada 73 Robert Pitt 74 Janson beeley 75 Janson Beeley 76 Robert Pitt 77 Roam Moyer 78 Charles Strada 79 Kristi Cooper	6015/22 6018/22 6018/22 6021/22 6021/22 6021/22 6021/22 6022/22 6022/22	PL 1331 PL 1330 PL 1350 PL 10812 PC 0629 PC 0629 PC 0629 PC 1075 PC 1026 PC 1326 PL 1082 PH 1175	38005 48943 54213 54213 74331 38032 Unbrown at feast for repair. 74,375.00 51515 54233 60125					Once side new feedor, best of telepas No. No. No. No. No. No. No. No
Charles Strada Robert Pitt Janson Bendey Robert Pitt Aurson Bendey Robert Pitt Roym Moyer Charles Strada Charles Strada Krist Cooper Philip King	69/15/22 69/16/22 69/16/22 69/21/22 69/21/22 69/21/22 69/21/22 69/21/22 69/21/22 69/21/22	PL 1331 PL 1330 PL 0842 PC 0829 PC 0829 PC 0829 PC 1425 PC 1228 PC 1328 PL 0842 PAI 1175 PL 1330	30005 48043 54213 74331 38032 Unknown at fleat for repair. 74,37300 51515 5423 69125					Chicar side new forche; bett of beingste Chicar side new forche; bett of beingste No No No Chicar side new forche; bett of beingste No Chicar side new forche; bett of beingste No No No Chicar side new forche; bett of beingste No Chicar side new forche; bett of beingste No No No No Chicar side new forche; bett of beingste No Chicar side new forche; bett of beingste No No No No Chicar side new forche; bett of beingste No Chicar side new forche; bett of beingste No Chicar side new forche; bett of beingste No No No Chicar side new forche; bett of beingste No Chicar side new forche; bett of being forche; bett of beindependent of being forche; bett of being forche; being forche; b
72 Charles Strada 73 Robert Pitt 74 Janson beeley 75 Janson Beeley 76 Robert Pitt 77 Roam Moyer 78 Charles Strada 79 Kristi Cooper	6015/22 6018/22 6018/22 6021/22 6021/22 6021/22 6021/22 6022/22 6022/22	PL 1331 PL 1330 PL 1350 PL 10812 PC 0629 PC 0629 PC 0629 PC 1075 PC 1026 PC 1326 PL 1082 PH 1175	38005 48943 54213 54213 74331 38032 Unbrown at feast for repair. 74,375.00 51515 54233 60125					Once side new feedor, beard shapes No No No No No No No No No N
Charles Strada Robert Pitt Aussich benfey Janisch benfey Robert Pitt Robert Pitt Ryan Möyer Ryan Möyer Kriat Cooper Kriat Cooper Pillip King Jordan Settlernyne	60/15/22 60/16/22 60/16/22 60/21/22 60/21/22 60/21/22 60/21/22 60/21/22 60/22/22 60/22/22 60/22/22 60/22/22	PL 1331 PL 1330 PL 0842 PC 0629 PC 0629 PC 0629 PC 1475 PC 1328 PL 0842 PR 1175 PL 1330 PL 1320	30005 48043 54213 54213 74331 36002 Utrizone at fees for repair. 74,375 00 51515 54223 69125 47000 37900					Once side new feeder, best of inelpse No. No. No. No. No. Starte as provious regords. This new destrape noted but grows clearing field and coolent an affi slightly how and but light as not working and appears to be bloom have. The welder also results serviced on bed. The buck needs Distriction velocis has been af feed for regords for asserted weeks. Distriction velocis has been af feed for regords for asserted weeks.
Charles Strade Pathers Fit Robert Fit Robert Fit Service Strade Pathers Fit Service Strade Pathers Strade	691602 691602 691602 692102 692102 692102 692102 692102 692202 692202 692002 692002 692002 692002 692002 692002 692002	PL 1331 PL 1330 PL 0842 PC 06091 PC 16091 PC 1675 PC 06099 PC 1336 PL 0842 PL 1336 PL 1336 PL 1336 PL 1337 PL 1330 PL 1339 PC 1475 PC 06091	30005 46843 55113 75431 36525 Whitesam of fixed for reputs 51115 51115 51115 51115 41100 31100 31100 51115 5115 51					Other side may fender, beat of beligne Other side may fender, beat of beligne No Other side may fender be beligned as not sorting and appears to be blown fear. The wester also needs serviced or bed. The fender needs Other side may be fender for regards for several wester. Other side fender for regards for several wester. Other side fender for regards for several wester. No No No No No No No No No N
Charles Disease Patient Pitt Pa	691502 691602 691002 692102 692102 692102 692102 692102 69220 69220 6920 69	P. 1331 P. 1310 P. 1082 P. 0842 P. 0842 P. 0849 P. 0869 P. 0859 P. 0852 P. 0842 P. 1310 P. 1310 P. 1475 P. 1489 P. 1475 P. 1499 P. 1475 P. 1500 P. 1697 P. 1697 P. 1697 P. 1697 P. 1697 P. 1697	30005 46943 5613 74231 2001 2001 2001 2001 2001 2001 2001 2					Once rade new feedure, bear of inalgate No. No. Once and new feedure, bear of inalgate No. No. Once and new feedure of inalgate No. Once and new individual in the second of inalgate of inalg
Charles Streeks Parkham Pill American Beerley American Beerley Figure Mayer Figure Mayer Figure Mayer Charles Streeks Figure Mayer Figure Ma	6915622 691622 691622 692102 693102 693102	F. 1331 F. 1042 F. 1043 F. 1030	30005 46843 55113 75431 38032 Walveson of fixed for requirements 51010 51010 51010 51010 51010 51010 51010 5202 4700 53050 53050 740542 33156 33156					Other solar new function, based of lawlyses No No No No Same as previous reports. No race damage noted but power stearing field and colour are old slightly low and bed light are not evolving and appears to be bloom face. The webler also needs serviced on bad. The fluct needs Distriction vehicle has been at face for reports for several weeks. Distriction vehicle has been at face for reports for several weeks. No No No Trust to back from shop but off has starting and before yourse in monthly it appears to meeting and species for the starting after date of the starting after date of the starting and before yourse in the starting and starting and the sta
Charles Streda Charles Streda Amenon bearley	641562 641562 641562 641562 641562 641562 641562 641562 641562 6405620 6405620 6405620 6405620 6405620 6405620 6405620 6405620	F. 1331 F. 1330 F. 1982 F. 1982 F. 1982 F. 1983 F. 1983 F. 1983 F. 1983 F. 1983 F. 1330	30005 46843 46843 5673 74037 2007 2007 2007 2007 2007 2007 2007 2					Cooler and peaks to provide any provide and peaks are founder, beard analysis. Once and near founder, beard analysis. No. Once and near founder, beard analysis. No. Cooler and power desired to Jones a family of the peaks and the peaks
20 Chefe Stelde 21 Chefe Stelde 22 Chefe Stelde 23 January Stelde 24 January Stelde 25 January Stelde 26 Stelde 26 Stelde 27 Span Moye 20 Chefe Stelde 20 Chefe Stelde 20 Chefe Stelde 20 Chefe Stelde 20 January Stelde 21 January Stelde 22 January Stelde 23 January Stelde 23 January Stelde 24 January Stelde 25 January Stelde 26 January Stelde 26 January Stelde 27 January Stelde 27 January Stelde 28 January Stelde 29 January Stelde 20 January Stelde 21 January Stelde 21 January Stelde 21 January Stelde 22 January Stelde 23 January Stelde 24 January Stelde 25 January Stelde 26 January Stelde 26 January Stelde 27 January Stelde 28 January	6915622 691622 691622 692102 693102 693102	F. 1331 F. 1330 F. 1342 F. 1350 F. 135	30005 46843 56113 7613 7613 3002 3002 3002 3002 5105 5105 5423 60725 4700 3706 5254 53150 5453 3016 5254 52576 5277					Once ratio new fends, these of below. No No No Same as provious reports. No new damage noted but power stearing field and cooled are off skiptify four and bed lights are not exciting and appears to its bloom hase. The webter abor needs serviced on hard. The field needs have been a field for reports for several weeks. Ustransvers vehicle has been at field for reports for several weeks. No No No No No No Cooled when shop but did has skirting and before yourse in morning. It appears be not severing the short field and field weeker has been all field for the skirting and the field weeker to be weeked. All date But also and sear clearance lights are not variety it appears be not because in the same affect of the sear skirting by the All white same as previous reportions. No Cooled and power descript four and faight from and fairs in bloom for fairs. In bloom the last, the same and onlying of the same as previous reportions. Cooled and power descript fluid slightly for and fairs in bloom for fairs. The declarances lights are not existing fluid and so good. Track was stabled and counted. Power stearing fairs a slightly tow and better sever deal again budge, Minister readers are in the sholes gift or a fight of the did not stable gift or 5 fight o
Charles Streda Charles Streda Charles Streda Charles Te Amount headey Amount headey Charles Te Charles Te Charles Streda Charl	69/1962 69/1962	F. 1331 F. 1330 F. 1982 F. 1982 F. 1982 F. 1983 F. 1983 F. 1983 F. 1983 F. 1983 F. 1330	30005 46843 46843 5673 74037 2007 2007 2007 2007 2007 2007 2007 2					Once side rear fender, best of talgate No No Service any provision reports. No rear demands reducted by power sharing facility and content as self refuging to an extract legislation are describing and opposes to be blown face. The webbr abino reads serviced or bed. The bush head Unknown vehicle has been at fixed for regards for several weeks. Unknown vehicle has been at fixed for regards for several weeks. No Though its back from whop that delt has starting and bettery issues in morning it appears something in deserting from believies after trook is farmed off and inventer has been off. Trook is did yet reads to be assumed. All date Though its back from whop that delt has starting and bettery issues in morning it appears something in deserting from believies after trook is farmed off and inventer has been off. Trook is did yet reads to be assumed. All date Though its back from whop that delt has starting and bettery issues in morning it appears something in deserting from believies after trook in started off and inventer has been off. Trook is did yet or reads to be assumed. All date No Cooler and power starting facility deploy to use of face in blow to note legistic somewhere. The back deserves legist one not exclude, plus of a face in blow to note legistic somewhere. The back deserves legist one not exclude, plus of a face in blow to note legistic somewhere. The back deserves legist one not exclude, plus of a face in the blow to note legistic somewhere. The back deserves legist one not exclude, plus of a face in the blow to note legistic somewhere. The back deserves legist one not exclude, plus of a face in the blow to note legistic somewhere. The back deserves legist one not exclude, plus of a face in the blow to note legistic somewhere. The back deserves legist one not exclude plus to a face in the blow to note legistic somewhere. The back deserves legist one not exclude plus to a face in the blow to note legistic somewhere. The back deserves legist one not exclude plus to a face in the blow to n
20 Owder Daniel 21 Owder Daniel 22 Owder Daniel 23 January Beedy 24 January Beedy 25 January Beedy 26 Januar	64 1562 1 64 156	P. 1331 P. 1330 P. 1340 P. 1350 P. 135	30005 46443 46443 5473 7433 3032 Unincess at fleet for repair. 5155 5473 69729 47000 37096 47000 37096 47000 37096 57096					Once radio near funder, bear of inalgate No No Service and provide radio funder of the service of the servic
Control State Control State Control State Control State Control State Control State Control Control State Control Cont	69/15/22 69/15/62	R. 1331 R. 1330 R. 1380	30006 40043 5013 7031 7031 7031 3002 3002 3002 5015 5013 6013 6013 6013 7000 3000 3000 3000 3000 3000 3000 3					Once rath rear feeder, best of beligne No. No. No. Starte as provious reports. To now damage noted bud power desiring fault and cooled an ellid slightly how and bud lights are not exching and appears to be bloom how. The walter also reads serviced on hear. The hands need to be the same of service and service. Distressor values has been at fault for repairs for several weeks. Distressor values has been at fault for repairs for several weeks. No. No. Though a basic form shop but at the sateting and before several memory. It appears something in desemp from hadiness after took in format of and member has been off. Took is diffy and reads to be washed. At older the basic forms of the sateting and before several memory. It appears to be a fault took and the sateting and before several memory. It appears to be a fault took and the sateting and before several memory. It appears to be a fault took and the sateting and before several memory. It appears to be format took and the sateting and before several memory. It appears to be format took and the sateting and interest has been off. Took is diffy and reads to be washed. At older the sate forms and provide and provide memory and the sates to sate took. No. Coalest and power attenting fluid slightly has and fault in Start for the lighth somewhere. The best distances light are not working. At day and several may replicate. That was weaked and dissert Power altering fluid slightly be and belief to simplify be and belief took and approved tooks. More than the provide and price and light is dist. At oline is pound. No.
27 Onder Stands 28 Onder Stands 29 Onder Stands 20 Onder Stand	64 1562 1 64 156	P. 1331 P. 1330 P. 1340 P. 1350 P. 135	30005 46843 5473 7473 34032 Usknown if faut for repair 5473 6473 64730 6					Cooker side near funder, based of inalgate No. No. Cooker side near funder, based of inalgate No. Cooker side near funder, based of inalgate No. Cooker side near funder, based of inalgate No. Cooker side near funder f
To Charle State The Cha	691962 691962	F. 1331 F. 1330 F. 1382 F. 1382 F. 1382 F. 1382 F. 1383	30005 4043 5013 5013 7431 3032 7431 3032 044000 of feet or regular 5033 6013 5033 6013 5033 6013 5000 5030 5030 5030 5030 5030 5030 5					Down rate new feeds, bear of beigne. No. No. The same as provious reports. This new damage noted but proser clearing field and colorist an elli slightly how and but large in an end southing and appears to be blown how. The wolder abin needs serviced or best. The buck need to report for several weeks. Districtions vehicle has been at feed for reports for several weeks. No. No. Thus it is based from shop but all has abstring and before several morning. It appears and report in proceedings in the same of an order in the beautiful field in the same of an order in the same
27 Onter Street 28 Onter Street 29 Onter Street 20 American Street 20 American Street 20 American Street 20 American Street 20 Onter Street 20 American Street 20 American Street 21 American Street 21 American Street 22 American Street 23 American Street 24 American Street 25 American Street 26 American Street 26 American Street 26 American Street 27 American Street 27 American Street 28 American Street 29 American Street 20 American Street 20 American Street 20 American Street 20 American Street 21 American Street 22 American Street 23 American Street 24 American Street 25 American Street 26 American Street 27 American Street 28 American Street 29 American Street 20 American Street 20 American Street 21 American Street 21 American Street 22 American Street 23 American Street 24 American Street 25 American Street 26 American Street 26 American Street 27 American Street 28 American Street 28 American Street 28 American Street 29 American Street 29 American Street 20 American Street 21 American Street 21 American Street 22 American Street 23 American Street 24 American Street 24 American Street 24 American Street 25 American Street 26 American Street 26 American Street 26 American Street 27 American Street 27 American Street 27 American Street 28 Ame	64 1562 1 64 156	R. 1331 R. 1330 R. 1340 R. 1350 R. 135	30005 46843 5613 7633 3632 10303 10303 10303 10303 10303 10303 10303 10303 10303 10303 10303 10303 10303 10303 10303 10303 10303 10303					Choice side near feedorb, bear of inalgets No. No. States as previous reports. No new derange reduct for given from the feed of the special
To Charle State The Cha	691962 691962	F. 1331 F. 1330 F. 1382 F. 1382 F. 1382 F. 1382 F. 1383	30005 4043 5013 5013 7431 3032 7431 3032 044000 of feet or regular 5033 6013 5033 6013 5033 6013 5000 5030 5030 5030 5030 5030 5030 5					Once sold new feedor, bear of inelgate No. No. No. States as provious reports. No rew demaps noted but power desiring fault and colour on and slightly to work but light as not working and appears to be bloom face. The worker also seads serviced on bed. The back need Delevenier vehicle has been at fault for reports for assent weeds. No. No. Trock is back from shop but all has addring and backery seasos in morning. It appears as beautifing in diseasing from buffering selfer trock in turneed of and monetor has been all fault in diffy and needs to be washed. All older Bed sold and new clearance light are not working in a please to be for less facility and needs to be washed. All older Bed sold and new clearance light are not working in a please to be facility and needs for front in the season in processing in the facilities after trock in turneed of and monetor has been all front is diffy and needs to be washed. All older Bed sold and new clearance light are not working it appears to be facilities and the facilities and season and process in reportion. No. No. No. No. No. No. No.
20 Owler Street 21 Owler Street 22 Owler Street 23 Assert New York 24 Assert New York 25 Assert New York 26 Assert New York 26 Owler Street 26 Owler Street 26 Assert New York 26 Owler Street 26 Assert New York 27 Assert New York 28 Assert New York 28 Assert New York 29 Assert New York 29 Assert New York 20 Assert New York 20 Assert Street 20 New York 20 Assert Street 20 New York 20 Assert 21 York 22 Assert 23 Assert 24 Assert 25 Assert 26 Owler Street 26 Owle	641562 65162	F. 1331 F. 1330 F. 1382 F. 1382 F. 1382 F. 1382 F. 1383	30005 40404 5013 5013 7031 7031 3032 10400an of feet for regular 5033 6013 5033 6013 5033 6013 5033 6013 5033 6013 5033 6013 5033 6013 5034 5035 6013 5014 5017 5017 5013 5016 6005 6005 6005 6005 6005 6005 6005					Choice side near feedorb, bear of inalgets No. No. States as previous reports. No new derange reduct for given from the feed of the special
27 Onter Brain 28 Onter Brain 29 Onter Brain 20 Annua Freig 20 Annua Freig 20 Annua Freig 20 Annua Freig 20 Onter Brain 20 Onter Brain 20 Onter Brain 20 Annua Freig 21 Annua Freig 21 Annua Freig 22 Annua Freig 23 Annua Freig 24 Annua Freig 25 Annua Freig 26 Freig 26 Annua Freig 26 Annua Freig 27 Annua Freig 28 Annua Freig 28 Annua Freig 28 Annua Freig 29 Annua Freig 20 Annua Freig 20 Annua Freig 20 Annua Freig 20 Annua Freig 21 Annua Freig 22 Annua Freig 23 Annua Freig 24 Annua Freig 25 Annua Freig 26 Freig 26 Annua Freig 27 Annua Freig 28 Annua Freig 28 Brain Freig 29 Annua Freig 29 Annua Freig 20 Onter Brain 20	64 1562 1 64 156	P. 1331 P. 1330 P. 1582 P. 1582 P. 1582 P. 1582 P. 1582 P. 1582 P. 1583	30005 46843 55413 55413 3553 Whosan if faul for repair. 1,1275,00 55113 5513 60125 4700 37006 53106					Chose side near feedor, beat of insights No. No. Starts as previous reports. No non derange collect for govern feedor and slightly has writted sights an not seeting and appears to be bloom fasts. The webbr abin reads serviced on lead. The buch needs Chickness vehicle has been at feet for reports for several reads. No. No. No. Truck to basic from other body but off has similing and believy taxons in moving. It appears controlling to dening then believes after bods in basic feet on off-truck in day and reads to be asserted. All date But and and earl character sights are not earling to a great several reads. No. Truck to basic from other bods that similing and believy towns in moving. It appears to be a feat into Prover allowing their and other for these leads of movember has been off. Truck is diffy and reads to be asserted. All date But and order character sights are not earling. All date same as provious impections. To closed and power advanting fault deploys to an ellowing the believes were designed upon today. Movine reads and several great stages of the sight of the distance regists are not exceeding. All dates are as provious impections. To closed and power advanting fault deploys to a sightly low and believes twent dealing in today. Movine reads rate for the other gift as district first off also as good. No. Plant land distances sights not excharge.
Control State Control State Control State Control State Control State Control State Control Co	641462 651462	R 1331 R 1330 R 15812 R 15812 R 15815	30005 40404 5013 5013 7030 7030 1000 1000 1000 1000 1000 1					Once rate new feedor, bear of inelgate No No No Same as previous regords. No rew derange noted but power sharing fault and conter are self-slightly to end bed light as not working and appears to be bloom face. The worker ability seeds needs serviced or bed. The buck needs Dishorous vehicle has been as fault to require for areas of works. No No No Touch a basic from shop but all has selenting and battery assess in morrory. It appears assembling on the believe self-short in but to the latest and of more for more for the latest and of the works. All date Bed sole and nor clearance lights are not working it appears to be not assess. Power descript floor of content has been off. Tout is diffy and reads to be warded. All date Bed sole and nor clearance light are not working it appears to be not assess. Power descript floor of content has a soleting and in diffy and reads to be warded. All date See a second of the clearance light are not working it appears to be not been descript from the latest and point from the latest and point for a second and point for the light on an of working. All date seems as previous requestions. Took as leads and one clearance light and not faunt a lightly to and batterian seem dead again today. Morabes marks rear find a short grid at the register and in a date is good. No No Fail bed disseases light not working. Fair bed disseases light not working. Seems as lead and procedure from the low meanures. Seems as a previous registerior from No row and sample or toward process.
Control States Charles States American	64 1562 64 1562 65 156 156 156 156 156 156 156 156 156 1	P. 1331 P. 1330 P. 1342 P. 1350 P. 135	3000 1604 1604 1604 1604 1604 1604 1604 1					Chose side near fundar, bear of inalgate No. No. Same as previous reports. No row durange collect for given for fundary flow and for lightly to an offer lightly no and for lightly no and lightly no and for lightly no and lightly no and for lightly no and lightly no a
Control States Control Con	641562 641562 651562	R 1330 R 1581 R 1582 R	30005 4014 5013 5013 7013 3002 1040000 of feet for repair. 5013 5013 5013 5013 5013 5013 5013 5013					Once rate new feedor, bear of inelgate No No No Same as previous regords. No rew derange noted but power sharing facility and content are self-alight as not excellenged agrees to be bloom face. The walder abin needs serviced on bed. The buck needs Dishorous vehics has been as facility or market legit as no reliability or any time of any agrees to be bloom face. The walder abin needs serviced on bed. The buck needs No No No Thick is basic from shop but all has selenting and buttery assess in morrory. It agrees assembling not bedown select from the time of any control has been off. Thick is diffy and reads to be warded. All date Bed sole and nor clearance lights are not exoting: It agrees to be facilities after track in home off any clearing has diffy and reads to be warded. All date Bed sole and nor clearance light are not exoting: It agrees to be facilities. No Bed sole and nor clearance light are not exoting: It agrees to be facilities. No No Coolers and power steering fluid alignity low and face is bloom for the lights committee. The lock clearance light are not working. All date serve as provious regorders. That has discussed regit and clearance. Prevent deterring fluid is slightly to and betteries were desirable light as not working. All date are not provided and cleared. Prevent deterring fluid is slightly to and betteries were desirable light as not working. All date are not an advanced in the label light and in all dates is good. No Fall had discussed light not working. No Serve as agreedow interpretion from No low one waters fluid as services as provided. Services are provided interpretion from No low one waters fluid as services as provided as registers. No new demands noted the sightly low. All dates as an as provided as registers. No new demands noted. The new lightly as an all not outstay and a power to be date to before the action. The power desires, fluid and content are slightly low. All dates as an as provided as registers.
20 Outer Street 21 Outer Street 22 Outer Street 23 Americ Need 24 Americ Need 25 Americ Need 26 Americ Need 26 Americ Need 27 Outer Street 27 Outer Street 28 Americ Need 28 Americ Need 29 Americ Need 29 Americ Need 20 Americ Need 20 Americ Need 20 Americ Need 21 Americ Need 21 Americ Need 22 Americ Need 23 Americ Need 24 Americ Need 25 Americ Need 26 Americ Need 26 Americ Need 27 Americ Need 26 Americ Need 27 Americ Need 28 Americ Need 29 Americ Need 29 Americ Need 20 Americ Need 21 Americ Need 22 Americ Need 23 Americ Need 24 Americ Need 25 Americ Need 26 Americ Need 27 Americ Need 28 Americ Need 28 Americ Need 29 Americ Need 20 Americ Need 21 Americ Need 21 Americ Need 22 Americ Need 23 Americ Need 24 Americ Need 25 Americ Need 26 Americ Need 26 Americ Need 27 Americ Need 27 Americ Need 28 Americ Need 2	64 1502 64 1502 65 150 150 150 150 150 150 150 150 150 15	F. 1331 F. 1330 F. 1342 F. 1350 F. 135	3000 1604 1604 1604 1604 1604 1604 1604 1					Once sole new feedor, bear of talgate No No Same as previous reports. No row damage colled ful power sharing full and collect an all rightly to sent full rights as not working and appears to be bloom fuse. The webbr akin results serviced on block. The funds head Unknown vehicle has been at fact for reports for several results. No No No Truck to bead from one pot off the skeleting and before; beam of working it appears committing a searing from bediene after from its human off end weeter this beam of Truck as day and results to be anothed. All days Bed asks and man of human step but off the skeleting and before; beam on morning it appears mornings a searing from beddens after from its human off end weeter this beam off. Truck as days and results to be anothed. All days Bed asks and man off human step but off the skeleting and before; beam on the vehicle it is a beam of the skeleting and beam of the same an previous reportions. No Control and power absently float digitify to and fact is blown for heal being the amountain. The but channess rights are to such right of the same as previous respections. No No No First head deseasons lights not earling the same of specific for earling the same of earling the same o
Control States Charles States Amena States	641562 641562 651562	R 1330 R 1581 R 1582 R	30005 4014 5013 5013 7013 3002 1040000 of feet for repair. 5013 5013 5013 5013 5013 5013 5013 5013					Does side nor include, these of inalges No No No Same as previous region. No new derange noded but power sharing facility and content as self sightly on well-but legisla am not receiving and appears to be bloom face. The welder also needs serviced on heal. The but need Dishows vehicle has been at fleat for regions for anexest weeds. No No Thomas is load from shop but still has scaring and bettery assess in morroring it appears assembling in desarry from shallours after trood in strong off employers has been self-faced from great to be searched. All other fleat from shall from which that been at fleat for regions for anexest weeds. No Best sole and non-clearance lights are not working. It appears has been fleat assess. Please identifyed that and content level are slightly from All other search as previous respections. No See sole and non-clearance lights are not working. It appears has been fleat assess. Please identifyed that an slightly from All other search assess as previous respections. No No No No No No No No No N
20 Outer Street 21 Outer Street 22 Outer Street 23 Industries 24 Industries 25 Industries 26 Industries 26 Industries 26 Industries 26 Industries 27 Outer Store 27 Outer Store 28 Industries 28 Indus	641562 641562 641562 641562 641562 641562 641562 641562 641562 641562 641562 641562 641562 641562 641562 641562 641562	F. 1331 F. 1330 F. 1342 F. 1350 F. 135	3000 30					Once sols not funds to the ord displace No. State we provides regards. No new demage related had power sharing fluid and colored are off old play to weel final glipts are not southing and appears to letters fast. The weblar date meads serviced or held. The book need Lidenous relation has been at final for regards for several expense to letters fast. The weblar date meads serviced or held. The book need Lidenous relation has been at final for regards for several expense. No. No. Tray is a basis from shap had still has serving and basiny insues in morning. It appears in the set has insue. However, the final play is not related by the service in several expenses. No. But risks and our desarrows glipts are off southing. It appears in the set has insue. However, the final play is not working. At data some as previous respections. No. Cooler and power steering fluid shighly how and had as a little for best lights somewhere. The set channes lights are not working. At data some as greatering mendions. Truck was welled and dozend. Prever severny fluid is adjuly to and had selected again below, Missister works are left stricks light and fluid in districts. And well as a pure several play in a service in separation in the second again below. Truck was welled and dozend. Prever severny fluid is adjuly to and belief several again below, Missister works are left stricks light and fluid in an approximate prevention in the second again below. Full bed disseases lights not working. And General had belief to see as previous inspection. No row damage reside. The best lights are as previous inspection from home was been provided and display from A data same as previous inspections. Mississes in row damage residence fluid in slightly line. Defines have been belief other performer to be the residual play. Mississes in row damage residence fluid in slightly line. Defines have been belief other performer to be to expend play in district. No row damage reside. The best light as well for country and again to the as ti
Control State Control State American Ameri	64 1502 64 1502 65 150 150 150 150 150 150 150 150 150 15	F. 1331 F. 1330 F. 1342 F. 1350 F. 135	3000 1 5011 1 50					Once sols not funds to the ord displace No. State we provides regards. No new demage related had power sharing fluid and colored are off old play to weel final glipts are not southing and appears to letters fast. The weblar date meads serviced or held. The book need Lidenous relation has been at final for regards for several expense to letters fast. The weblar date meads serviced or held. The book need Lidenous relation has been at final for regards for several expense. No. No. Tray is a basis from shap had still has serving and basiny insues in morning. It appears in the set has insue. However, the final play is not related by the service in several expenses. No. But risks and our desarrows glipts are off southing. It appears in the set has insue. However, the final play is not working. At data some as previous respections. No. Cooler and power steering fluid shighly how and had as a little for best lights somewhere. The set channes lights are not working. At data some as greatering mendions. Truck was welled and dozend. Prever severny fluid is adjuly to and had selected again below, Missister works are left stricks light and fluid in districts. And well as a pure several play in a service in separation in the second again below. Truck was welled and dozend. Prever severny fluid is adjuly to and belief several again below, Missister works are left stricks light and fluid in an approximate prevention in the second again below. Full bed disseases lights not working. And General had belief to see as previous inspection. No row damage reside. The best lights are as previous inspection from home was been provided and display from A data same as previous inspections. Mississes in row damage residence fluid in slightly line. Defines have been belief other performer to be the residual play. Mississes in row damage residence fluid in slightly line. Defines have been belief other performer to be to expend play in district. No row damage reside. The best light as well for country and again to the as ti
Control States Charles States Amena States	64 1502 65 150 150 150 150 150 150 150 150 150 15	R 1330 R 1581 R 1582 R	30005 16101					Other side near broader, but of uniquies No States as previous reports. No new damage rotated but power sharing fluid and consists are self-slightly law and feed for require for several require. States as previous reports. No new damage rotated but power sharing fluid and consists are self-slightly law and resulting and appears to be likewise fluid. The webber also neads serviced on beld. The broad need Dictions needlink has been at fleet for require for several require. No No Track is basic thorn should be all has starting and latterly issues in mouring. It operans something in distance that the track is but but and off and inventor has been self. Track is a day and reach to be weathed. All other fluids are self-slightly in the self-slight are required in the self-slightly into previous reportions. No Read colored and are cleanous lights as mell controlling it appears something in distance that the solid part of control treal are slightly law. All also same as previous respectives. No Read colored. Controlline and power desempt fluid adjuly to send than as Store for law fluids incomes. Self-slight are not excelling a fluid in distance layers are not excellent playing and an appears an expension. Track was seathed and cleaned. Power desempt fluid in slightly low and butteres seen clead applies being a being the spirit in dirt. All date in good. No Palled cleanesce light and on whiting No Seate as the simple fluid in the seathing fluid and controlling. No new desempt model. The best lights are self not excelling and departs to be day to be dainy to be self-slight and controlling. No Seate as the simple fluid in a self-or outside good appears to be dain to a filter fluid. In appear desiring fluid and control are slightly low. All dates are as previous impactions. Mounters in our demands indicate light to did working just director. Power steaming fluid and control are slightly low. All dates are as a previous impactions. No Seate as the size of fluid in the size of fluid and control lower fl
Control Stocks Control Stocks American Ameri	64 1502 64 1502 65 150 150 150 150 150 150 150 150 150 15	R. 1331 R. 1330 R. 1340 R. 134	3606 3607 5613 7631 3603 3603 3603 3603 3603 3603 3603 3706 3707 3706 3706 3706 3707 3706 3706 3707 3706 3707 3706 3707 3706 3707 3706 3707 3706 3707 3706 3707 3706 3707 3707 3708					One wish may fonds, but of largues No. The same as provious reports. No new demage rotate had power sharing find and colored are off oliging his worst find fight are not southing and appears to laboration. The weblar date meads survived on bed. The book need Lidenous verbich has been of find for regards for several expens. Lidenous verbich has been of find for regards for several expens. No. No. Things he lacks from sharing had placed like as earling and buttery insues in morting. It oppores constroys a research fine that insue and find of or mortine has been off. That is, did yet of reach to be assubed. All dates But club and near reaching find and power sharing had all spling his own of south part and part to south off and colored touril and spling has not an expension. The butter find and output find an expension fining had all spling and part of south fine of the colored touril and spling had all south fine. The south final and spling had all south fining had all south
Charle State Charle State Amen Teal Amen	64 1562 65 156 156 156 156 156 156 156 156 156 1	R 1330 R 1581 R 1582 R	30005 16101					One wish may be sold the self-rate blood in the self-rate proble for joint or self-rate problems in the self-rate problems in part of the self-rate problems in part of the self-rate problems in the self-rate problems in part of the self-rate problems in part of the self-rate problems in the self-rate pr
Control States Description American Teach American Teach American Teach American Teach Figure Moyer Countrol States Figure Moyer Countrol States Figure Moyer Countrol States Figure Moyer American Teach American Figure Moyer Figure Moy Figure Moyer	64 1502 64 1502 65 150 150 150 150 150 150 150 150 150 15	R. 1331 R. 1330 R. 1340 R. 134	3000 1 5010 1 50					Other wish may broduce has of singles. No. Start we approximate reports. No new derivage models had power sharing fluid and colored are self-shiply to see of held sights are not suching and appears to in bitter face. The weblar also reach survived on held. The took need to the start for regards for second expenses. Unknown reports for second expenses in bitter face. The weblar also reach survived on held. The took need to the start for regards for second expenses. No. No. Tracks in basic from high had still has earling and basiny insues an morning. It oppores consisting a desarring from the face for regards for second expenses with the start for the start for the start for the start for the start of the start for t
Charles States Charles States Amena Teacle Amena Teacle	64 1562 64 1562 65 156	R 1330 R 1982 R 1983 R	3000 30					Other side was broaded and services of the service design region to the service design are not excited part of power to be blown facilities. The webbr also reads serviced on bod. The bod need Dahmon relative has been of fined for regions for service results. Contract to the service of th
Charles States Annua File James Beeley Babari File James Beeley Babari File Sanan Beeley Babari File Sanan Beeley Charles States James Beeley Ked Corper Filip Rigg Right File Sayan Kidy Charles States James Beeley Ked Corper Ked Corper	64 1502 64 1502 65 150 150 150 150 150 150 150 150 150 15	R. 1331 R. 1330 R. 1340 R. 1350 R. 1360 R. 136	3000 1 5010 1 50					Other side new broats, beard religion. No. Start was previous reports. No new derange noted but power sheeting fluid and collect are sell objet by the set but fights are not seeking and appears to be below fluids. The violet also neeks perclaid on bull. The touch new fluid of collect are sell objets for an extend extent. Unknown velocids has been of fluid for impairs for account or extends an extend extends. Unknown velocids has been of fluid for impairs for account or extends extends. No. No. This has been for fluid and place and beauty impairs are not working. It regions something is desired, but the sell of the collect found and spility for any fluid collection. But do do not not character light as not working. It regions something is desired, but the fluid and found review has been off. This is display and residue to be sealed, did display for the sealed and collection. No. No. No. No. No. No. This has been for found and place and pl
Charles States British File James Review British File James Review British File James British British File James British Ja	64 1562 64 1562 65 156	R 1330 R 1982 R 1983 R	3000 30					Diver side may broad to be and milegine No Seams as provious reports. No new densing model but power shearing fluid and coalent are sell objects, we all but lights are not excellent and excellent and the sellent share sellent for reports for seame of equates to be bloom fluid. The webbr date needs serviced on bad. The back needs Alaborators which has been at fleaf for reports for seame of equates. No No Thank is black from should be all has sharing and betterly takes in moving it appears correcting to all excellent plants about the sellent sellent sellent fluid and better fluid as delay and reach to be washed. All other fluids and sellent s
Control States Charles States Amena Teacle Amena Teacle	64 1562 65 156 156 156 156 156 156 156 156 156 1	R 1331 R 1330 R	30005 40104 5013 7023 3022 Unbrown of four for regular 5023 6023					One with read broads. Note of the properties request to the state of the properties request to the state of t
Count States Amen Teel Amen Teel Amen Teel Amen Teel Amen Teel Figar Moyer Counts Strein Figar Moyer Counts Strein Fings Moyer Counts Strein Fings Fings Amen Teel Fings Kog Strein Fings Kog Amen Teel	64 1502 64 1502 65 150 150 150 150 150 150 150 150 150 15	R. 1331 R. 1330 R. 1340 R. 1350 R. 1360 R. 136	3000 1 5010 1 50					One with read broads. Note of the properties request to the state of the properties request to the state of t
Control States Charles States Amen Teach Amen Teach	64 1562 64 1562 65 156 156 156 156 156 156 156 156 156 1	R. 1331 R. 1330 R. 1340 R. 1350 R. 135	30005 16404					Other side has blood been side and broad in the side of the side o
Control States Amena Teach Amena Teach Amena Teach Amena Teach Amena Teach Amena Teach Figure Moyer Control States Finge Moyer Control States Finge Moyer Amena Teach Amena Te	64 1502 64 1502 65 150 150 150 150 150 150 150 150 150 15	R. 1331 R. 1330 R. 1340 R. 1350 R. 1360 R. 136	3000 5010 50					Other wide new bloods: Note of reliquies Note Allers are provious reports. No new derenge related but gover sharing fluid and contrive are self-shiply for any fluid grows on according and agreement in bibliom fluids. The weblar also reach serviced on bed. The book reach Unknown vehicle has been of fluid for register for second equals. Unknown vehicle has been of fluid for register for second equals. Unknown vehicle has been of fluid for register for second equals. Note No. Thing is built from while but self has needing and buttery insues an reversing it agreemes according in the second grows the butter fluid for the review has been off. Thou is did you're reach to be assessed. All sizes But olds and man of second rear characters (gift on on the society, it opposes to be in fluid incomes by the fluid and contrive fluid and order has been off. Thou is did you're reach to be assessed. All sizes But olds and man of second rear characters (gift on on the society, it opposes to be in fluid incomes fluid in the butter fluid and order there is subject, to an according of the second read of characters (gift on on society). It opposes to be fluid incomes fluid incomes fluid and order there is subject, for an according of the second read of characters (gift on the society). No. Pall bed discussions by the on while you will not contribute on the society of the second read order on subject to the society. No. Serves as to be in proposition from you have also provided an according on the society of the second read of the society. No. Serves as to be in proposition from you have also provided an according on the society of the second read of the society. No. Serves as to be in bed and on evening. No rew demany model. The bed flyths are all order ordering put do not be burning models as a previous impendion reports. Part bed right on districtly and districtly and districtly and districtly on districtly and districtly o
Control States Charles States Amena Meeting Amen	64 1562 64 1562 65 156 156 156 156 156 156 156 156 156 1	R. 1331 R. 1330 R. 1340 R. 1350 R. 135	30005 40104 5011 7021 3022 Unbrown of four for regule. 5023 5023 6025					Other side has broad began to be blown face in the season and the season of the season and the s
Counts Stocks Charles Stocks American Stocky American Stocky Stocks Stocks Charles Stocks American Stocks Philip Stock American Stocks American Stocks American Stocks American Stocks American Stocks American Amer	64 1502 64 1502 65 150 150 150 150 150 150 150 150 150 15	R. 1331 R. 1330 R. 1340 R. 1350 R. 1360 R. 136	3000 30					Other side was broder, but of foligings No. But was provious reports. No new demage rotate but gauser starting fluid and control are self sidily for low and fast for regards for second angular gausers to be bloom face. The weblar also reach serviced on bed. The book reach Licenson reports for second means. No. No. Those is based from showing but self less confined and present second means. No. Those is based from showing but self less confined and for means an operation in precisions. No. Those is based from showing but self less confined and for former second means. In the second for the second means an operation respective. No. Those is based from showing but self less confined from former second for the second former second from former second former second from former second from former second former second former second from former second from former second former second from former sec
Control States Charles States Amena Meeting Amen	64 1562 64 1562 65 156 156 156 156 156 156 156 156 156 1	R. 1331 R. 1330 R. 1340 R. 1350 R. 135	30005 40104 5011 7021 3022 Unbrown of four for regule. 5023 5023 6025					Other side has broad began to be blown face in the season and the season of the season and the s
20 Onder States 21 Onder States 22 Onder States 23 Amount Needy 24 Amount Needy 25 Amount Needy 26 Amount Needy 27 Amount Needy 27 Amount Needy 28 Amount Needy 28 Amount Needy 29 Amount Needy 20 Amount Needy 21 Amount Needy 22 Amount Needy 23 Amount Needy 24 Amount Needy 25 Amount Needy 26 Amount Needy 27 Amount Needy 28 Amount Needy 29 Amount Needy 20 Amount Needy 21 Amount Needy 21 Amount Needy 22 Amount Needy 23 Amount Needy 24 Amount Needy 25 Amount Needy 26 Amount Needy 27 Amount Needy 28 Amount Needy 29 Amount Needy 20 Amount Needy 20 Amount Needy 21 Amount Needy 22 Amount Needy 29 Amount Needy 20 Amount Needy 20 Amount Needy 21 Amount Needy 22 Amount Needy 22 Amount Needy 23 Amount Needy 24 Amount Needy 25 Amount Needy 26 Amount Needy 27 Amount Needy 28 Amount Needy 28 Amount Needy 29 Amount Needy 20 Amount Needy 21 Amount Needy 22 Amount Needy 23 Amount Needy 24 Amount Needy 25 Amount Needy 26 Amount Needy 26 Amount Needy 27 Amount Needy 28 Amount Need	64 1562 65 156 2 6	R. 1331 R. 1330 R. 1340 R. 1351 R. 1350 R. 1350 R. 1351 R. 1350 R. 135	36005 46143 5613 7623 3622 3622 Unbrown at faul for regule. 5523 6425 6425 6425 6425 6425 6425 6425 6426					Cheer wild near funder, but of failights No. One was previous reports. No new dermaps roded but govern whereing flad and content an self singlify his well but light are not working and oppose to be bloom fusion. The welder also reachs serviced or band. The but needs Delences refricis has been at fined for regions for several weeds. No. No. Thou is has been shipped of either scheding and butlery issues in morning. It appears sourcining is desired from butleries after book is brand off and owner has been off. Truck is dily and meads to be asselled. All also Best size and man clearrows lights are not entering it appears but has been as freed for regions for several weeks. No. Though has been shipped of either scheding and butlery issues in morning. It appears to be fast instead Power desiring but and colored to were slightly to an off and the services. No. No. Cooled and power alsering fluid nightly for and fast in the term for the light scores/burn. The base clearrows lights are not entering. At date serve as previous inspections. Truck were seathed and cleared. Power desarray fluid is slightly for and better issues are desartage in things. Motivate reside rear light and right is dirt. All dates as a good. No. No. No. First lated desearces lights not working. Same as such reports from The new desartage or causes model. Same as such reports from The new desartage or causes model. Same as such reports from The new desartage or causes model. Same as such reports from previous man, No trans instead or desartage. No. No. Same as such reports from The new desartage or causes model. Same as a previous inspection from previous man, No trans instead or desartage. No. No. Counted desartage previous inspection from previous man, No trans instead or desartage. No. No. No. Counted desartage previous inspection from previous man, No trans instead or desartage and in reserving the same as previous inspection report. No. No. Counted desartage previous from previous man, No trans instead or desa
27 Onder Street 28 Onder Street 29 Onder Street 20 America Street 21 Onder Street 22 America Street 23 America Street 24 America Street 25 America Street 25 America Street 26 America Street 26 America Street 26 America Street 26 America Street 27 America Street 27 America Street 28 America Street 29 America Street 20 America Street 21 America Street 22 America Street 23 America Street 24 America Street 25 America Street 26 America Street 26 America Street 26 America Street 27 America Street 27 America Street 28 America Street 29 America Street 29 America Street 20 America Street 20 America Street 20 America Street 21 America Street 21 America Street 22 Birton Nober 23 America Street 24 America Street 25 America Street 26 America Street 27 America Street 27 America Street 27 America Street 28 America Street 29 America Street 20 America Street 20 America Street 21 America Street 21 America Street 22 Birton Nober 23 America Street 24 America Street 25 America Street 26 America Street 27 America Street 28 America Street 28 America Street 28 America Street 29 America Street 20 America Street 21 America Street 21 America Street 21 America Street 22 America Street 21 Ame	64 1502 64 1502 65 150 150 150 150 150 150 150 150 150 15	R 1330 R 15000	3000 1 5010 1 50					Choice side near fundar, beard disaples No. No. State on any provious reports. No rear desarge rother but power sharing fluid and contact an self eighty, the self but lights are not seeting and appears to be bloom face. The webler abor reachs serviced on bed. The beat head Unknown vehicle has been at fluid for spars for several weaks. No. No. No. No. No. No. No. N

Name	Date	Unit Number PC 1475	Mileage Oi	Level	Tire	Pressure	В	Transmissio	on Fluid	Lights	Clea	nlines	Ph	hysical Damage
27 Bryan kirby 28 Bryan kirby	05/16/22 05/16/22	PC 1475 PC 0891	53188 38603.8	·		_	✓		✓		_			Power steering fluid low Fluit bed light not working
29 Brian Notes	06/17/22	PM 1517	50295				✓		✓				_	i michala agus laci michalag
Robert Pitt	05/18/22	PC 0929	75079	V			✓		✓	· ·	2	V		
Ryan Moyer Charles J Strada	05/23/22 05/24/22	PC 1326 PL 1331	52481 39256	<u>.</u>			✓ ✓		√ ✓					
33 Janson bewley	05/24/22	PM 1784	37576				<u>v</u>		✓			Ī		Inside is dirty but outside is clean. Change engine oil light is on. Engine oil is dirty. Coolant slightly low and windshield wiper fluid is close to empty. All alse looks good. Latches on driver side upper box are not working
Janson bewley	06/24/22	PC 0891	38642	V	1		<u> </u>		✓		2	V		Registration sticker is out, bed clearance lights are not working. Coclant and power steering fluid are slightly low. Inside and out are pretty diny. All else books good.
Jordan Settlemyre Robert Pitt	05/24/22 05/24/22	PL 1329 PC 0929	39035 75141	V			✓		✓			_		
7 Bryan kirby	06/31/22	PC 1475	53252	V			<u>v</u>		<u>✓</u>				-	
Charles J Strada	06/31/22	PL 1331	39294	v			<u>~</u>		<u>~</u>		2	V		
10 Kristi Cooper	06/31/22 06/31/22	PM 1175 PL 1330	70165 47395				~		<u> </u>			V		No.
Delip King Jordan Settlemyre	05/31/22 06/02/22	PL 1330 PL 1329	47395 39208	· ·			✓		✓					Na Na
2 Robert Pitt	06/02/22	PC 0929	75256	V			<u> </u>		<u>√</u>			Ī		
Charles J Strada	06/07/22	PL 1331	39347	V			✓		✓	· ·		V		
14 Janson Bewley 15 Janson Bewley	06/08/22 06/08/22	PC 1475 PC 0891	53396 Unknown	v v			✓		✓					Check engine light is back on, moisture is in back passenger side led light but it still works. Water cooler is off truck on rear bumper. No new damage noted. Truck needs to be cleaned inside and out. Seat is form on drive Truck is at fleet and miles and above information is unknown until picked back up from fleet services.
15 Robert Pitt	06/09/22	PC 0929	75348				<u>v</u>		✓			·		THAN IN IN THE BILL THEE BILL BACKS FRANCISCO IN A DECIDENT WITE PLANTAGE ABOVE AND REPORTED.
7 Brian Notes	06/13/22	PM 1517	50740	V			✓		✓	· ·	2	V		
Charles J Strada Janson Bewley	06/14/22 06/14/22	PL 1331 PC 1475	39397 53566	V			✓		✓			_		Chack engine light is back on: Truck is dirty inside and out. Coolant level is lightly low. Back light on driver side lad is dim due to moisture in lenses.
50 Janson bewley	06/14/22	PC 1475	38856	V			<u>✓</u>		<u>✓</u>					Collant and power steering slightly low. Bed light not working on clearance lights. Truck is dirty inside and out. New window registration sticker needs to be placed on truck. New floor mats were placed in truck today.
Jordan Settlemyre	06/14/22	PL 0842	54705	V			<u> </u>		~			v		
S2 Robert Pitt	06/17/22	PC 0929	75488	V			✓		✓	C		V		Needs cleaning
53 Charles J Strada 54 Janson Bewley	06/21/22 06/21/22	PL 1331 PC 1475	39428 53664	·			✓		✓			V	-	Check engine light is on again. Rear driver side led light works but has moisture in lenses. Several dents and drigs but nothing new. All else looks good.
55 Janson Bewley	06/21/22	PC 0891	38908	Ū			<u> </u>		✓			Ĭ		Truck was washed on Friday. Coolant and power steering fluid are slightly low. Bed clearance lights are now working on sides or back. Truck has dents and dings but nothing new. All else looks good.
58 Robert Pitt	06/22/22	PC 0929	75514	V			<u>~</u>		<u>~</u>			V		
57 Janson bewley	06/29/22 06/29/22	PC 0891 PC 1475	38958	V			✓		<u> </u>			_		Power steering fluid and coclant are slightly low. Bed lights were working and no other issues were noted.
SS Janson bewley RobertbPitt	06/29/22	PC 1475 PC 0929	53829 75568				✓ ✓		☑ ☑					Truck has several dents and scratches but nothing new. Check engine light is still on. Nothing else new is noted.
30 Kristi Cooper	07/05/22	PM 1175	70787	V			<u>~</u>		<u>~</u>			Ū		
S1 Jordan Settlemyre	07/08/22	PL 1329	39521	V	1		✓		✓	· ·		V		
Robert Pitt Charles J Strada	07/08/22 07/12/22	PC 0929 PL 1331	75726 39485	v v			✓		✓					
34 Jordan Settlemyre	07/12/22	PL 1329	39572				✓		✓					
Robert Pitt	07/14/22	PC 0929	73978	V			✓		✓	· ·	2	V		
GS Janson Bewley Janson Bewley	07/18/22 07/18/22	PC 1475 PC 0891	54087 39117	V			✓		✓			V		Same dents and scratches as before. Power steering fluid slightly low. Driver side back led light had moisture inside lenses but still works. Truck needs to be washed but sprayer nozzie has been broken at fleet. Bud clearance lights have been working. Same dents and scratches as before. Coolent is slightly low. Welder has 9.7 hours and appears good.
67 Janson Bewley Charles J Strada	07/18/22	PC 0891	39117	V			✓		✓					bled clearance lights have been working. Same dents and scritiches as before. Coolent is slightly low. Welder has 9.7 hours and appears good.
Gg Jordan Settlemyre	07/19/22	PL 1329	39655	V			<u>~</u>		<u>~</u>			·		
70 Kristi Cooper	07/19/22	PM 1175	71051	V			✓		✓			V		
71 Philip King Philip King	07/19/22 07/26/22	PL 1330 PL 1330	47584 47501	V			✓		✓					
73 Robert Pitt	07/29/22	PC 0929	75953				<u>~</u>		<u>~</u>					
74 Charles J Strada	08/09/22	PL 1331	39755	V			<u> </u>		~			v		
75 Philip King	08/09/22	PL 1330	47665	V			✓		✓			V		
76 Charles J Strada 77 Charles J Strada	08/16/22 08/23/22	PL 1331 PL 1331	39965 39996	V			✓ ✓		✓					
78 Brian Notes	08/29/22	PM 1517	51768	Ū			<u>~</u>		<u>✓</u>			Ĭ		
79 Alex Holland	08/30/22	pm1175	71451	V			<u>~</u>		<u>~</u>	· ·	2	V		Rear bumper dented
80 Bryan kirby 91 Jenson bewley	08/30/22 08/30/22	PC 1475 PC 1475	54652 39625	V			<u>~</u>		<u>~</u>			V		Power steering fluid is slightly low. No new damage is noted. All alse looks good.
81 Janson bewley 82 Philip King	08/30/22	PC 1475 PL 1330	39525 47835	· ·			✓		✓					Power steering fluid is slightly low. No new damage is noted. All else looks good.
83 Charles J Strada	09/06/22	PL 1331	40137	Ū			<u> </u>		✓			V		
84 Janson Bewley	09/06/22	PC 1475	39593	V			✓		✓	· ·		V		Coolent and power steering fluid are slightly low. There is still a glitch in the 6 way trailer plug from time to time, when pulling a trailer it turns off. Driver side cab clearance light has to be tapped on before it starts working
85 Ryan Moyer 86 Janson Bewley	09/06/22	pc1475 PC 1475	54798 54967	v v			✓		✓					Headlight is out and needs replaced. All else is same as last week.
87 Janson Bewley	09/12/22	PC 0891	39665				<u>v</u>		✓					Coolant and power stearing fluid are slightly low. A loose wire is somewhere in the trailer wiring 6 way plug.
88 Ryen Moyer	09/12/22	PC 0929	76093	V			<u>~</u>		✓		2	V		
39 Janson Bewley 90 Janson Bewley	09/19/22 09/19/22	PC 1475 PC 0891	55120 39765	V			✓		<u> </u>			V		Will fauld levels are good. Power steering is at top of lowest level of add and coolant is at level of highest minimum level. Check engine light is on and the particular filter display will go on and off when difning. We drive till light filter than a second of the se
90 Jarson Bewley 91 Ryen Moyer	09/19/22	PC 0829	76234	<u>.</u>			✓ ✓		✓ ✓					The trainer is way will florier on running lights when hooked to trainer. The issue was sent to freet and repaired plug but still have problems with plug from time to time. Coolant level is lightly low. The waster has 24.7 hours of
92 Janson Bewley	09/26/22	PC 1475	55258				<u> </u>		<u>-</u>			ē	Th	The check engine light is still on and diesel partic filter light comes on and stays every time we start the truck. The truck needs to be washed and cleaned and driver side near lenses is fogged over but light still works. Cools
93 Janson bewley	09/26/22	PC 0891	39798	V			✓		✓	C		V		Trailer plug wiring harmess needs to be repaired at some point. It flickers when trailer is hooked up. Coolant level is slightly low and truck needs to be washed. Welder has 34.0 hours on it. All else is good.
94 Ryen Moyer 95 Jorden Settlemyre	09/26/22 09/27/22	PC 0929 PL 1329	76353 40630				✓		✓					
96 Philip King	09/27/22	PL 1330	47968				<u>~</u>		<u>~</u>					
97 Jordan Settlemyre	10/04/22	PL 1329	40955	V			<u>~</u>		<u>_</u>		2	V		
98 Philip King	10/04/22	PL 1330	48011				~		<u> </u>			V		Engine coner reduced will max out at 15mph
99 Bryan kirby 90 Bryan kirby	10/10/22	PC 1475 PC 0891	55514 39835.5	V			✓ ✓		✓ ✓					Engine gower reduced will max out at 15mph
01 Bryan kirby	10/17/22	PC 0891	39956	V			<u>~</u>		<u> </u>			V		
02 Janson Bewley	10/17/22	PC 1475	Unknown	V			✓		<u> </u>	·		V		Truck has been at fleet so unknown above information until it is returned.
103 Robert Pitt 104 Janson Bewley	10/18/22 10/25/22	PC 0929 PC 1475	76659 55655	<u> </u>			✓		✓					Went to fleet, they looked up vehicle, got ATF red for power steering. Cot 4 * round ballight, blinker, brake light and installed. Truck needs to be washed. The check engine light has been on since we got it out of the shop and the diseal partic filter light came back on today too. Nothing else noted that needed attention.
105 Janson Bewley	10/25/22	PC 0891	40036				7		<u> </u>				_	Coolant level is slightly low. Generator welder hours are 44.4. The wrench light did come on this week but then went off.
06 Robert Pitt	10/25/22	PC 0929	76,749.00	V			✓		✓			V		
Janson bewley Janson bewley	11/02/22	PC 1475 PC 0891	Unknown 40219	·			✓		✓			V		Truck is still at field being repaired. Unknown above information due to being gone. All bed clearance lights are not working due to trailer plug which is plugged in due to pulling trailer. Cociant is slightly low. Mice and not tracks noted on top of motor. All else looks good.
Janson bewley Bryan kirby	11/02/22	PC 0891	40219 40322.3	v v			✓ ✓		✓ ✓					All bed clearance lights are not working due to trailer plug which is plugged in due to pulling trailer. Cocilent is slightly low. Mice and nat tracks noted on top of motor. All else looks good. Clearance lights on bed not working
10 Janson Bewley	11/07/22	PC 1475	Unknown	V			<u>~</u>		<u>_</u>		2	V		Truck has been at fleet for a few weeks now so above Information is unknown.
11 Janson Bewley	11/14/22	PC 0891	40435	V			<u> </u>		<u> </u>			V		The bed clearance lights are not working. Coolant is slightly low and air filter is showing majority yellow And is close to needed replaced or cleaned. Nothing else obvious was noted.
Janson Bewley Janson Bewley	11/14/22	PC 1475 PC 0891	Unknown 40484	V			✓		✓			V		The above information is unknown due to being in fixed for the last few weeks. Bed side and rear clearance lights are not working. Appears a fisse is blown. Coolant is slightly low. Driver side top clearance light is also not working.
13 Janson Bewley	11/21/22	PC 1475	56083				<u>✓</u>		<u>✓</u>					Bolt holding AC charging port to top radiator hose loose and came out. Placed bolt in door panel till it cools off and will place back. Topped off DEF today as well.
15 Robert Pitt	11/29/22	PC 0929	77135	V	1		<u> </u>		<u>~</u>		2	V		
Bryan kirby Janson Bewley	11/28/22 11/28/22	PC 0891 PC 1475	40484 56142	·			☑		✓					Lights on bad. Coolant Little low No issues noted recently. Doesn't need to be cleaned outside and vacuumed inside. Nothing new noted that needs attention.
17 Jarson Bewley	11/28/22	PC 1475 PC 0929	56142 77194	V			✓ ✓		✓ ✓					No issues noted recently. Doesn't need to be cleaned outside and vacuumed made. Nothing new noted that needs attention.
Janson Bewley	12/05/22	PC 1475	56271	V			<u>v</u>		<u> </u>		2	V		Large screw in front passenger side line. Moisture in rear driver side light but it's still working. The part filter light is still on.
20 Janson Bewley 21 Robert Pitt	12/05/22 12/08/22	PC 0891 PC 0929	Unknown 77307	V			<u> </u>		<u>~</u>	· ·	2	V		Truck has been at fleet for a week or so for lighting and fuse problems.
21 Robert Pitt 22 Janson Bewley	12/08/22	PC 0929 PC 1475	77307 56356	v V			✓		✓					Driver side front tire is low. Check engine light is back on and particulate filter display is back on again. Truck needs to be washed and cleaned.
23 Janson Bewley	12/13/22	PC 0891	Unknown	<u> </u>			<u>v</u>		<u>~</u>			·		Truck is waiting on parts from fleet. Above information is unknown.
24 Janson Bewley	12/21/22	PC 1475	56519	V			✓		✓	· ·		V		Front driver side tire was repaired today at Briscoe. The check engine light and part filter display is back on. All elise seems good as of now.
25 Janson Bewley 26 Robert Pitt	12/21/22 12/28/22	PC 0991 PC 0929	40600 77494	v v			✓		✓				_	Coolant level is slightly low. The truck is waiting on brake controller for trailers from fixet. The bed clearance lights are working today. No other issues are noticed at this time.
25 Jarson Bewley	01/03/23	PC 1475	56756				<u>~</u>		<u>✓</u>					assenger side inside dual line slightly low. Moisture in lenses on driver side rear flashing light but still works. Windshield wiper fluid and power steering fluid are slightly low. All else looks good. Truck needs to be cleaned
28 Kevin Burkman	01/05/23	PB 1478	49436	V			<u>~</u>		<u>~</u>		2	V		
29 Steve Bender	01/05/23	PM 1516	129972	V			✓		✓			V		Produce and described Productions on Male of hand
30 Javier Secundino 31 Robert Pitt	01/06/23 01/06/23	PM 1919 PC 0929	16518 77626				✓		✓					Dents on driver side: Florer bumper Side of bed
31 Baylor tomlinson	01/09/23	PM 1509	72516	V			<u>~</u>		<u>~</u>			·	-	
33 Daniel Mccaig	01/09/23	PM 1112	80229	V			✓		✓	· ·	2	V		
34 Javier Secundino 35 Kevin Burkman	01/09/23	PM 1919 PB 1478	18552 49477	·			✓		✓					Front bumper Side of the bad-driver side
35 Never Bunder	01/09/23	PM 1516	130136	V			✓		✓ ✓					
37 Teddy Reynolds	01/09/23	PM 0744	75224	V			<u>~</u>		<u>~</u>		2	V		
38 Alejandro Mora	01/12/23	PC 1475	56887	V			✓		✓			V		
Alejandro Mora Baylor tomlinson	01/12/23	PC 0691 PM 1509	40679 72985	v V			✓		✓					
41 Bryan Kirby	01/17/23	PC 0891	40705.2	V			<u>v</u>		<u>✓</u>			V		
12 Daniel McCaig	01/17/23	PM 1112	80299	V			<u> </u>		<u> </u>		2	V		
43 Janson Bewley 43 Javier Secundino	01/17/23	PC 1475 pm1919	56988 16614	V			V		~					Buttery was dead this morning. Power steering fluid is slightly low and moisture noted in near driver side flashing light but still working. Air was slightly low in back inside dual fire.
Javier Secundino Samuel Ballesteros	01/17/23	pm1919 Pm 0893	16614				✓		✓					Front bumper and driver side bed have dents
46 Gary Green	01/18/23	PM GARYTRUCK	2390	V			<u>v</u>		<u>~</u>			·	-	
Robert Pitt	01/18/23	PC 0929	77763	V			✓		✓	U	2	V		
Adrian Luna Baylor tominson	01/23/23 01/23/23	PL 1327 PM 1509	61914 72786	v v			✓		✓					None
So Felipe Lira	01/23/23	PM 1909 PL 1327	30754				<u>✓</u>		<u>✓</u>					NONE
51 Frank Pierson	01/23/23	PM 1414	74599	V			<u>~</u>		<u></u>		2	V		
52 Gary Patrick Green	01/29/23 01/29/23	PM GARYTRUCK pm1919	24041 16671	·			✓		✓			V		excellent condition
Samuel Ballesteros	01/23/23	pm1919 pm 0803	16671	▽			✓		✓					
	Withday	pm www3	09/49				4		4		•	~		

Name E 255 Steve Bender	Date 01/23/23	Unit Number PM 1516	Mileage Oil Level	✓ Tire Pressur	e Transmissi	on Fluid Lights	Clear	iness	Physical Damage
256 Teddy Reynolds	01/23/23	pm0744				2		V	Needs to be cleaned out and washed
257 Alejandro mora	01/24/23	PC 1475					✓	✓	Back driver side work light has moisture still works but will need replacing soon. Engine light is on Diesel particulate filter is full
258 Alejandro Mora 250 Bill Smith	01/24/23 01/25/23	PC 0891 PM 1332					☑	▽	Driver top clearance light burst out Power steering and coolant low. Air filter will need change soon No new.
250 Bill Smith 260 Gene Trinklein	01/26/23	PM 1332 PM 1201			_		✓	✓	TAL DEBT.
261 Bryan Kirby	02/06/23	PC 0891	40724	2	☑	☑	✓	<u> </u>	One clearance light out on top of cab
262 Janson Bewley	02/06/23 02/06/23	PC 1475						☑	All fluid levels were good. Back flashing light is working but has moisture in it. The check engine light is still on and part filter full display is still on. There is a screw in back driver fire but not low on air. Truck needs to be
263 Javier Secundino 264 Javier Secundino	02/06/23 02/06/23	PM 1919 PM 1509				☑ ☑	▽	▽	Front bumper and driver side dent on the bed
285 Jamison Bourgeois	02/10/23	PC 1326			V	<u>∨</u>	<u> </u>	<u> </u>	
266 Robert Pitt	02/10/23	PC 0929		<u> </u>	☑	☑	<u> </u>	2	
267 Alejandro mora	02/13/23	PC 1475					☑	<u> </u>	Back left strobe light has condessrion inside housing. Engine light on Diesel partic. Filter full
268 Gene Trinklein 269 Janson Bewley	02/13/23 02/13/23	PM 1201 PC 0891				2		2	Coclent level is slightly low, small amount of corrosion around battery ferminals. Air filter needs to be changed it is in the yellow on visual factory display. We did change out clearance light bulb and added power sheering fluid
200 Jaroun Bewey 270 Alejandro Mora	02/20/23	PC 0891					▽	▽	Coolan level is signey ow, small amount or corollon around belong seminals. At their needs to be changed it is in the yeard on violal factory display, we do change out change out change out obtained agric cut and about power swelling tube.
271 Javier Secundino	02/20/23	PM 1919				2		Ž.	Front bumper and drivers side of the bed has a dent.
272 Janson Bewley	02/21/23	PC 1475	Unknown	2	☑		<u> </u>	<u> </u>	Truck is at fleet and above information is unknown.
273 Robert Pitt	09/23/23 09/27/23	PC 0929 PM 1919			_		✓	✓	
274 Javier Secundino 275 Alejandro Mora	02/27/23	PM 1919 PC 1475				☑	✓	▽	
276 Janson Bewley	09/01/23	PC 0891					<u> </u>	<u> </u>	Truck has been at fleet waiting on repair, so above information is unknown.
277 Janson Bewley	09/06/23	PC 0891			☑	☑	<u> </u>	<u> </u>	Above information is unknown due to being in fleet services.
278 Janson Bewley	03/06/23	PC 1475					✓	✓	Cover for windshield fluid is broken off and missing under hood. Lenses cover is leaking water on driver side near fleshing light. It is still working some but has moisture inside it. All else appears good.
279 Javier Secundino 280 Alejandro Mora	03/06/23 03/13/23	PM 1919 PC 1475					☑	☑	Dents: Front bumper and bed of the truck Check engine light is on: Rear driver side strobe has water inside it
281 Alejandro Mora	03/13/23	PC 0891					<u> </u>	V	Vehicle is at fleet right now. All above information is NIA
282 Javier Secundino	03/13/23	PM 1919	17263	2		☑	✓	✓	
283 Jamison Bourgois 204 Robert Pitt	09/14/23 03/14/23	PC 1326					<u> </u>	<u> </u>	
284 Hobert Hill	03/14/23	PC 0929 PC 1475					☑	☑	Back driver side strobe light has condensation in it
286 Janson Bewley	09/20/23	PC 0891							Above information is unknown. The truck is still at fleet and has been for a few weeks now.
287 Robert Pitt	09/20/23	PC 0288	16,306.00	2	☑	☑	☑	<u> </u>	Hours 4514x24+106,336 miles Truck worked good at termis.
288 Jamison Bourgeois	03/23/23	PC 1326			✓	✓	<u> </u>	<u> </u>	
289 Robert Pitt 290 Alejandro Mora	09/23/23 09/27/23	PC 0929 PC 0991		2 2	☑ ☑	☑ ☑	☑	▽	Vehicle is at feet right new. Information unknown
291 Janson Bewley	03/27/23	PC 1475					☑	<u> </u>	Ventous is at take tright now, instrument introduct. The windshield wiper fluid cap is missing. There is moisture in near flashing light lenses on driver side. The check engine light is off for now.
292 Javier Secundino	09/27/23	PM 1919	17447	2	☑	☑	✓	✓	
293 Alejandro Mora	04/03/23 04/03/23	PC 0891 PC 1475					<u> </u>	<u> </u>	Vehicle is still at fleet information unknown.
294 Janson Bewley 295 Robert Pitt	04/03/23 04/03/23	PC 1475 PC 1326		2 2		✓	✓	▽	Cap is broken on windshield wiper fluid. Lenses has moisture in near flashing light on driver side light. Truck needs to be washed and cleaned. The check engine light has not been on in a few weeks now. It did come on three
295 Robert Pill 296 Jamison Bourgeois	04/10/23	PC 1326					☑	<u> </u>	
297 Robert Pitt	04/10/23	PC 0929	78,787.00	2	☑	☑	✓	<u> </u>	
298 Samuel Ballesteros	04/10/23	pm 0893					<u> </u>	<u> </u>	NA
299 Alejandro Mora 300 Alejandro Mora	04/11/23 04/11/23	PC 1475 PC 0891			☑ ☑		✓	✓	Windshield wiper fluid reservoir lid cracked. Black driver side strobe has condensation
300 Alejandro Mora 301 Bryan Marriott	04/11/23	PC 0891 PM 1175		_			✓	☑	back bumper falling off
302 Janice Heidberger	04/11/23	PL 1331	41,198.00	2		2	2	<u> </u>	Nothing new. See photos of previous damage noticed. This is not a detail of all damage.
303 Jordan Settlemyre	04/11/23	PL 1329	43,762.00	2	☑	☑	✓	~	
304 Philip King 305 Robert Pitt	04/11/23 04/11/23	PL 1330 PC 0929					∠	☑	Picked up 0029 yeatherday. They did not fix the flashers, they were written up, when I turned it in.
305 Robert Hill 308 Jamison Bourgeois	04/17/23	PC 0029			✓	✓	∠	✓	Pricked up 0229 yealenday. They dut not fix the flashers, they were written up, when I turned it in.
307 Janson Bewley	04/17/23	PC 1475				2		V	Cap is broken on wiper fluid fill and lenses has moisture on driver side rear light. Nothing else new is noted
338 Janson Bewley	04/17/23	PC 0891		2	☑	☑	☑	<u> </u>	Waiting on brake controller from fiset. Coolant is slightly low. New radiator and top hose is noted. Nothing else new noted.
309 Robert Pitt	04/17/23	PC 0929				☑	☑	<u> </u>	
310 Bryan Marriott 311 Janice Heidberger	04/18/23 04/18/23	PM 1175 PL 1331					▽	☑	Not new damage. Antenna is messed up. Old damage.
312 Russell	04/20/23	PA 8103					☑	<u> </u>	полня чинада. Алення и певево ор. Он чинада.
313 Gene Trinklein	04/21/23	PM 1201					<u> </u>	V	
314 Janice Heidlberger	04/24/23	PL 1331					✓	✓	Oil a little fow. Added one quart.
315 Janson Bewley 316 Janson Bewley	04/24/23 04/24/23	PC 1475 PC 0891					<u> </u>	<u> </u>	Coclard level is slightly low, windshield wiper fill cap is missing. Moisture in lenses on driver side rear light. Truck is dirty and needs washed. Nothing else new noted. Truck battery was dead and had to be jumped off. Coclard level is slightly low. Air filter indicator shows it needs to be cleared or replaced scon and is on yellow. We see waiting on a brake controller for trailer towing from fleet
316 Jarson Dewey 317 Robert Pitt	04/24/23	PC 0929				☑ ☑	☑	▽	Tricks basiney was called and raid to be jumped on. Column level in signify low. Art men indicates shows it needs to be clearled or replaced soon and it on yeardw. Eve any watering on a characteristic relates howing mon need.
318 Jamison Bourgeois	04/25/23	PC 1326		_			<u> </u>	V	
319 Daniel McCaig	04/27/23	PB 1509	76,574.00		☑	☑	<u> </u>	<u> </u>	
320 Gary Green	04/27/23 05/01/23	PM GARYTRUCK					<u> </u>	<u> </u>	
321 Bryan Kirby	05/01/23	PC 0891 PM 1201					▽	☑	
323 Janson Bewley	05/01/23	PC 1475				2		<u> </u>	Front light bar lights are not working. Windshield wiper fluid cap is missing. Coolent is slightly low. Moisture is noted in rear driver side lenses on flashing yellow light, but light is still working. Truck is drifty and needs washed.
324 Javier Secundino	05/01/23	PM 1919	18023	2			✓	~	
325 Robert Pitt	06/01/23	PC 0929					✓	✓	
326 Bryan Marriott 327 Jamison Bourgeois	05/02/23 05/02/23	PM 1175 PC 1326					✓	☑	
328 Janice Heidlberger	06/02/23	PL 1331						V	
329 Daniel McCaig	05/08/23	PM 0744					✓	✓	
330 Gene Trinklein 331 Janson Bewley	05/08/23 05/08/23	PM 1175 PC 1475					2	☑	Coolant is slightly low, missing cap on windshield wiper fluid fill, micristure in near lenses but flashing light is working, front light bar spot light in not working. Truck needs fuel and def and needs to be washed.
331 Janson Bewley 332 Janson Bewley	05/08/23 05/08/23	PC 1475 PC 0891					☑	☑	Coolant is slightly low, missing cap on windsheld where fluid fill, moisture in near lenses but flashing light is working, front light bar spot light is not working. Truck needs feel and del and needs to be washed. Fuel is low on one tank. The batteries are weak and need replaced. The air filter indicator shows it is close to needing replaced. Coolant level is slightly low. Front tires are close to weeds mark line. Welder has 49.7 hours
333 Javier Secundino	05/08/23	PM 1919	18106	2	<u> </u>	2	<u> </u>	V	
334 Samuel Ballesteros	05/08/23	pm 0893					☑	v ·	
335 Jamison Bourgeois	05/09/23	PC 0929					<u> </u>	V	
338 Jamison Bourgeois 337 Janice Heidberger	05/09/23 05/09/23	PC 1326 PL 1331				☑ ☑	▽	▽	
338 Daniel McCaig	05/12/23	PB 1509					☑	<u> </u>	
339 Adam Stantz	05/15/23	PC 1325	52664	2			☑	2	
340 Alejandro Mona 341 Bryan Kirby	05/15/23 05/15/23	PC 1475 PM1517					<u> </u>	<u> </u>	Check-engine light on Windshield washer fluid reservoir needs cap
341 Bryan Kirby 342 Dustin Bryant	06/15/23	PM1517 PC 1643					▽	▽	None
343 Janson Bewley	06/15/23	PC 0891					<u> </u>	<u> </u>	The batteries were dead and needed jumped off again. The welder has 49.7 hours on it. The coolent is slightly low. Air filter is close to needing replaced.
344 Javier Secundino	05/15/23	pm1919	18226	2	☑	☑	✓	~	
345 Joel Westerland Bryan Marriott	05/15/23 05/16/23	PM 1784 PM 1175					∠	▽	
348 Bryan Marnott 347 Jamison Bourgeois	05/16/23 05/16/23	PK 1175 PC 1326					∠	✓	
348 Janice Heidberger	05/16/23	PL 1331	41637	2	☑	☑	☑	<u> </u>	
349 Philip King	05/16/23	PL 1330					<u> </u>	2	
350 Robert Pitt 351 Daniel McCaig	05/16/23 05/17/23	PC 0929 PB 1642					☑	▽	Windshield washer pump not functioning. Drivers Side Marker Light not working/Repaired 5/17
352 Robert Pitt	06/21/23	PC 0929					☑	<u> </u>	The second secon
353 Adam Stantz	05/22/23	PC 1325	52832	2	☑	☑	☑	<u></u>	
354 Alejandro Mora	05/22/23 05/22/23	pc1475 PM 1517					2	<u> </u>	Windshield fluid reservoir cap broken Check engine light on
355 Bryan kirby 356 Dustin Bryant	05/22/23 05/22/23	PM 1517 PC 1643					☑	☑	
357 Janson Bewley	05/22/23	PC 0891	41020	2		<u> </u>	<u> </u>	V	Truck is dirty and needs washed. The batteries need replaced and are dated 2018. The coclarat level is slightly low and air filter needs replaced or cleaned. The truck still needs trailer basks controller installed from fleet. The
358 Javier Secundino	06/22/23	PM 1919	18337	/	☑	☑	V	~	
359 Joel Westerlund Bryan Marriott	05/23/23 05/23/23	PM 1784 PM 1175					2	V	
360 Bryan Marriott 361 Janice Heidberger	06/23/23 06/23/23	PM 1175 PL 1331					☑	▽	
362 Kevin Burkman	05/23/23	PB 1478	52771				<u> </u>	<u> </u>	
363 Philip King	06/23/23	PL 1330					2	2	
364 Samuel Ballesteros	05/23/23	PM 0893					☑	<u> </u>	Chook agains fall on 15th projection of the control
365 Alejandro Mora 366 Bryan Marriott	05/30/23 05/30/23	PC 1475 PM 1175					☑	☑	Check engine light on Lid for windshield washer reservoir broken. Black left drivers side strobe light not working properly has condensation
367 Daniel McCaig	05/30/23	PM 1112					☑	<u> </u>	
368 Janice Heidberger	05/30/23	PL 1331	41700	2	☑		☑	~	
369 Janson Bewley	06/30/23	PC 0891					<u> </u>	<u> </u>	Truck just had batteries replaced. Wedder has 49.8 hours. Coolant is slightly low and air filter is close to needing cleaned or replaced. It appears a new trailer brake controller was installed. Truck needs to be washed and
370 Javier Secundino 371 Joel Westerlund	05/30/23 05/30/23	PM 1919 PM 1784					▽	▽	
371 John Westerfund 372 Kevin Burkman	05/30/23	PB 1478					☑	<u> </u>	
373 Philip King	06/30/23	PL 1330	50375	2	☑	☑	☑	2	
374 Robert Pitt	05/31/23 06/01/23	PC 0929 PC 1326						2	
375 Jamison Bourgeois 376 Gene Trinklein	06/01/23 06/05/23	PC 1326 PM 1201					▽	▽	
376 Gene Innoen 377 Jamison bourgeois	06/05/23	PC 1326				⊻	☑	<u> </u>	
377 Jamison courgeors		PC 0929		2	☑	☑	✓	<u> </u>	
378 Robert Pitt	06/05/23								
378 Robert Pitt 379 Samuel ballesteros	06/05/23	PM0893 PL1331						✓	
378 Robert Pitt		PM0893 PL 1331 PC 1325	41820	2	☑	☑	☑	<u> </u>	
378 Robert Pitt 379 Samuel ballesteros 380 Janice Heidtberger	06/05/23 06/06/23	PL 1331	41820 53902	Z	✓ ✓	✓ ✓			

Name	Date	Unit Number	Mileage Oil Level	Tire Pressure	Transmission	Fluid Linhts	Cleanti	ness	Physical Damage
383 Joel Westerlund	06/12/23	Unit Number PM 1784	43813	Tire Pressure	V	Fluid Lights	✓	~	T 11/3/Gail Distringe
384 Samuel Ballesteros	06/12/23 06/13/23	PM 0893			· ·		☑	✓	
385 Janice Heidberger 386 Javier Secundino	06/13/23	PL 1331 PM 1919					☑	☑	
387 Janson bewley	06/14/23	PC 0891					2	V	Coolant is slightly low. Air filter needs cleaned, welder has 49.9 hours and truck needs to be washed and cleaned and fuel in welder.
388 Janson Bewley	06/14/23	PC 1475	60356	2	· ·		<u> </u>	<u> </u>	Truck needs new oil dip stick. It has loose cable that will pose you. Windshield wiper fluid cap is missing. Truck is dirty and needs waarhed. Moisture in rear flashing light lenses on driver side rear. Check engine light is on and
389 Robert Pitt	06/15/23	PC0929					2	<u> </u>	
Sg0 Bryan Marriott Sg1 Janice Heidtberger	06/20/23 06/20/23	PM 1175 PL 1331						☑	
392 Joel Westerlund	06/20/23	PM 1784						V	
393 Samuel Ballesteros	06/20/23	PM 0893	72185	2			✓	<u> </u>	
394 Adam Stantz	06/26/23	PC 1325		2	C		☑	✓	
395 Joel Westerlund	06/26/23 06/26/23	PM 1784 PM0893					2	<u> </u>	
396 Samuel Ballesteros 397 Bryan Marriott	06/26/23	PM0893					☑	☑	AC fan turns on and off intermittently
398 Jamison Bourgeois	06/27/23	PC 0929					✓	<u> </u>	PACIENT SAND AND REAL OF TREATMENT OF
339 Jamison Bourgeois	06/27/23	PC 1326					<u> </u>	v ·	
400 Janice Heidberger	06/27/23	PL 1331		2	· ·		2	~	Rear tail light passenger side on trailer PL0280 flickers or doesn't work. Electric wiring loose near light.
401 Janson Bewley	06/27/23 06/27/23	PC 1475 PC 0891					2	<u> </u>	Oil dip stick needs to be replaced and will poke you checking it due to fray in cable. Cap is missing on windshield wiper fluid. Front driver side fine has gash in sidewall. Moisture noted in rear driver side flashing light but it is
402 Jarson Bewley	06/27/23	PC 0891					☑	✓✓	Coolant is slightly low and air filter needs to be replaced. Generator has 49.9 hours and needs fuel. Truck needs to be washed and cleaned.
404 Adam Stantz	07/03/23	PC 1325					☑	V	
405 Joel Westerlund	07/03/23	PM 1784	44027				<u> </u>	v ·	
408 Janice Heidberger	07/05/23	PL 1331	42323	2			☑	<u> </u>	
407 Jamison Bourgeois	07/07/23	PC 0929		2	· ·		☑	✓	
408 Janson Bewley 409 Jenson bewley	07/07/23 07/07/23	PC 0891 PC 1475			· ·			<u>~</u>	Coolant is slightly low and air filter display shows it needs cleaned or replaced. Welder has 50 hours and needs faul. Truck needs to be washed and cleaned. Oil dip slick needs replaced. Moisture in tenses on driver side but still working. Truck needs to be washed and cleaned. Check engine light is still on.
410 SAMUEL BALLESTEROS	07/09/23	PM 1919					☑	✓✓	Оп ор эвох пенов перводо, можеше из менам от отмет экон оох эли можету. Поск пенам из оне местно эко онемес. Спеск изден издел и эли ст.
411 Daniel McCaig	07/10/23	PB 1509					<u> </u>	v v	Page Side Mirror cracked but still usable. Rear Bumber damaged and already turned in.
412 Jamison Bourgeois	07/10/23	PC 0929		2	· ·		☑	✓	
413 Janson Bewley	07/10/23	PC 0891		2	· ·		☑	✓	Coolant is slightly low and air filter shows it needs cleaned or replaced. Welder has 50 hours on it. Truck needs to be washed and cleaned.
414 Janson Bewley 415 Adam Stantz	07/10/23 07/11/23	PC 1475 PC 1325						<u>~</u>	Windshield fluid cap is broken and missing. Oil dip stick has cable that needs to be replaced. The check engine light is on and moisture is noted in driver side rear light lenses but it is still working. The truck needs to be
415 Adam Stantz 416 Janice Heidberger	07/12/23	PC 1325					☑	▽	
417 Alejandro Mora	07/17/23	PC 1475	60923				☑	<u> </u>	Check engine light on. Windshield washer fluid reservoir lid broke: Driver rear strobe has condensation inside
418 Jamison Bourgeois	07/17/23	PC 0929	80548	2	· ·		☑	<u>~</u>	
419 Janson Bewley	07/17/23	PC 0891			· ·			<u> </u>	Truck needs to be washed and cleaned. The welder has 50 hours on it. The coolent is slightly low and air filter shows it needs replaced. Truck needs windshield wiper fluid.
420 Joel Westerlund 421 Bryan Marriott	07/17/23 07/18/23	PM 1784 PM 1175					☑	▽	
421 Bryan Marnott 422 Janice Heidiberger	07/18/23 07/18/23	PM 11/5					✓	▽	
423 Jamison Bourgeois	07/19/23	PC 1326						<u> </u>	
424 Adam Stantz	07/24/23	PC 1325	54282	2	· ·	1	2	~	
425 Janice Heidberger	07/25/23	PL 1331			· ·		<u> </u>	<u> </u>	
428 Janson Bewley 427 Janson Bewley	07/25/23 07/25/23	PC 1475 PC 0891					✓	✓✓	Truck is dirty and needs to be washed. Moisture is noted in driver side lenses of near flashing light but it is working. Windshield wiper fluid cap is missing. Check engine light is on. Truck is driv. Coolent is slicitify low and air filter shows it needs cleared or realized. Welder has 50.2 hours on it.
427 Järson Bewiey 428 Jordan Settlemyre	07/25/23 07/25/23	PL 1329					☑	✓	THOSE MEMORY, COLUMN IN MIGHTY OF MICH. ME HOME IT THROUGH CHAPPED OF HYDROG. THROUGH THE DULL SIGHTS OF IS,
429 Robert Pitt	07/25/23	PC 0929					✓	<u> </u>	
430 Robert Pitt	07/26/23	BI 0822	16358		· ·		☑	~	4598 hours Air pressures: Front 130psi, rear 120 psi Added air to right front Added air to the left, front outside rear tine
431 Alejandro Mora	07/31/23	PC 1475		2	C		☑	✓	Check engine light on
432 Jamison Bourgeois 433 Janson Bewley	07/31/23 07/31/23	PC 0929 PC 0991					2	<u> </u>	Replaced right near blinker butb Truck is dirty and needs to be weahed. The coolant is slightly low and air filter shows it needs to be cleaned or replaced. Welder has 50.8 hours on it. Truck bed needs to be cleaned out.
433 Janson Bewley 434 Joel Westerlund	07/31/23	PC 0891					☑	✓	Inuck is drifty and needs to be weathed. The coolant is slightly low and air filter shows it needs to be cleaned or replaced. Weater has 50.8 hours on it. I nuck bed needs to be cleaned out.
435 Janice Heidberger	08/02/23	PL 1331					<u> </u>	<u> </u>	
438 Jamison Bourgeois	08/07/23	PC 0929					☑	<u> </u>	
437 Joel Westerlund	08/07/23	PM 1784		2	C		☑	✓	
438 Janice Heidberger	08/09/23 08/14/23	PL 1331 PC 0891			<u> </u>		☑	<u> </u>	Oil is a little low. Needs regular maintenance and an oil change. Royal Purple synthetic oil.
439 Janson Bewley Joel Westerlund	08/14/23	PC 0891 PM 1784					☑	✓	Truck needs to be washed and cleaned. The coolant is slightly low and air filter shows it needs to be cleaned. Welder has \$2.4 hours on it.
441 Samuel Ballesteros	08/14/23	PM 0893					☑	☑	
442 Robert Pitt	08/15/23	PC 0929					✓	v ·	
443 Janice Heidberger	08/16/23	PL 1331		2	· ·		✓	✓	
444 Janson Bewley	08/21/23	PC 1475		2	C		☑	✓	Windshield wiper fluid is low and cap is missing. Moisture is noted in rear flashing light but it's partially working. Truck needs to be washed and cleaned. The check engine light is still on.
445 Janson Bewley 446 Javier Secundino	08/21/23 08/21/23	PC 0891 PM 1919					☑	<u> </u>	Truck is dirty and needs washed and cleaned. Air filter needs cleaned or replaced. Coolant is slightly low. Welder has 56.2 hours and needs faet.
446 Javer Securiono	08/21/23	PG 0929					☑	▽	
448 Samuel Ballesteros	08/21/23	Pm 0893						<u> </u>	
449 Bryan Marriott	08/22/23	PL 1330					☑	<u> </u>	
450 Janice Heidberger	08/22/23	PL 1331		2	· ·		2	✓	
451 Daniel McCaig Gene Trinklein	08/28/23	PB 1509 PM 1201					✓	<u> </u>	Passenger side mirror is cracked.
452 Gene Trinklein 453 Javier Secundino	08/28/23 08/28/23	PM 1201 PM 1919					☑	✓	
453 Jeff hall	08/28/23	PL 0842					☑	<u> </u>	Head ache rack and tool box damaged
455 Joel Westerlund	08/28/23	PM 1784					<u> </u>	<u> </u>	
458 Kevin Burkman	08/28/23	PB 1478		2	· ·		✓	✓	
457 Robert Pitt	08/28/23 08/28/23	PC0929 PM 0893					☑	<u> </u>	
458 Samuel Ballesteros 459 William Smith	08/28/23	PM 0893						☑	No new damage
460 Alejandro Mora	08/29/23	PC 0891						<u> </u>	
461 Bryan Marriott	08/29/23	PL 1330					☑	<u> </u>	
462 Felipe Lira	08/29/23	PB 1877		2	· ·		✓	✓	Has a dent in the front bumper
463 Frank Pierson	08/29/23 08/29/23	PL 1327 PC 1475			· ·		2	☑	Passenour side headfold is out. Check ennine light is on and confocure filter full disclay is on. The driver side year lenses has moisture and is only certifully working.
464 Janson Bewley 465 Samuel T Huggenberger	08/29/23 08/29/23	PC 1475 PM1515					☑	✓	* meaninger and immension or one, common region in an a participant inter sur display as on. I no criver seer (64) Artists has module and it only pathlety working.
466 samuel huggenberger@cityofde	08/29/23	PB1876					☑	<u> </u>	
467 Daniel McCaig	08/30/23	PM 0744	76815				2	✓	Battery box is dented.
468 Janice Heidberger	08/30/23	PL 1331	43632		V		<u> </u>	✓	
469 Janice Heidberger 470 Luis Muro	08/30/23 08/31/23	PM 1787 pb1641					▽	✓	Tallights not working. Using hazards during headlight hours. Needs repair.
470 Luis Muro 471 Luis Muro	08/31/23	pb1481					☑	▽	
472 Juan Cruz	09/01/23	PB 1642	17117					<u> </u>	
473 ADRIAN LUNA	09/05/23	PM1414		2	· ·		<u> </u>	<u> </u>	
474 ADRIAN LUNA 475 Bryan Marriott	09/05/23 09/05/23	PM1414 PL 1330					▽	☑	
475 Bryan Marriott 476 Felipe Lira	09/05/23 09/05/23	PL 1330 PB1876					✓	☑	Dent in front of the bumper truck
477 Frank Pierson	09/05/23	PL 1327					☑	<u> </u>	
478 Gene Trinklein	09/05/23	PM 1201	72355		· ·	1	2	✓	
479 Janice Heidberger	09/05/23	PL 1331			C	1	<u> </u>	<u> </u>	
480 Janson Bewley	09/05/23 09/05/23	PC 1475 PM 1784					▽	✓	Windshield wiper fluid cap is missing and fluid is low. Check engine light is on. Moisture in driver side rear flashing light. Truck needs to be washed and cleaned.
481 Joel Westerlund 482 Josph balli	09/05/23 09/05/23	PM 1784 PL 0842					☑	▽	Bed rack tore up
483 William Smith	09/05/23	PM 1332						<u> </u>	No new damage
484 Janson Bewley	09/06/23	PC 0891	41321	2			2	<u> </u>	Air filter shows it needs to be cleaned or replaced. Coolant is slightly low. Welder needs fuel and has 56.3 hours on it. Truck is dirty and needs to be washed and cleaned.
485 Luís Muro	09/06/23	PB 1641			V		<u> </u>	<u> </u>	
488 Luis Muro 497 PM1515	09/06/23 09/06/23	pb1481 PM1515						✓	
487 PM1515 488 Robert Pitt	09/06/23	PM1515 PC0929					☑	✓	
489 Daniel McCaig	09/11/23	PB 1509						<u> </u>	Trans fluid low. Added trans fluid to bring back to proper level.
490 Felipe Lira	09/11/23	pb1876	34758	2	· ·		✓	~	
491 Frank Pierson	09/11/23	PL 1327		2	· ·		☑	✓	
492 General Dyke-Barela	09/11/23	PM 1784			· ·		2	☑	Post Production and advantable has date
493 Javier Secundino 494 Kevin Burkman	09/11/23 09/11/23	PM 1919 PB 1478						☑	Front, Rear bumper and enhants pipe have dents.
494 Kevin Burkman 495 Samuel Ballesteros	09/11/23 09/11/23	PB 1478 PM 0893					☑	✓	
406 Samuel T Huggenberger	09/11/23	PM1515					✓	☑	
497 William Smith	09/11/23	PM 1332	77596				2	<u> </u>	No new damage
roo Bryan Marriott	09/12/23	PL 1330	51411		V		<u> </u>	<u> </u>	
430	09/12/23	PL 1331			· ·		2	<u> </u>	
499 Janice Heidberger		pb1641 pb1481						✓	
500 Luis Muro	09/12/23						✓	☑	
	09/12/23 09/12/23 09/15/23	PC 0929	81572	_ 🐸			☑	▽	
500 Luis Muro 501 Luis Muro	09/12/23							V	
100 Luis Muro	09/15/23 09/15/23 09/18/23 09/18/23	PC 0929 pl1327 PM 1784	65275 45436	2			2	<u> </u>	
500 Luis Muro 501 Luis Muro 502 Jamison Bourgeois 503 Felipe Lina 504 Generey Dyke-Barella 505 Javier Secundino	09/12/23 09/15/23 09/18/23 09/18/23 09/18/23	PC 0929 pl 1327 PM 1784 PM 1919	65275 45436 20421				✓✓	▽	Fort and mail bumper
500 Luis Muro 501 Lisis Muro 502 Jamison Bourgeris 503 Felipe Lira 504 Genemy Dyke-Banela 505 Javier Secundino 506 Kevin Burkman	0011223 0011523 0011823 0011823 0011823	PC 0929 pl 1327 PM 1784 PM 1919 PB 1478	65275 45436 20421 55570				✓✓✓	✓ ✓	Ford and naw bumper
Luis Muro	09/12/23 09/15/23 09/18/23 09/18/23 09/18/23	PC 0929 pl 1327 PM 1784 PM 1919	65275 45436 20421 55570 51461		V				Front and nan bumper
500 Lisi Muro 501 Lisi Muro 502 Jamison Bourgeois 503 Felipe Lisi 504 Centerly Dyka-Barella 505 Jalvier Secundero 505 Kevin Bustman 507 Lisi Muro	60°1223 60°1523 60°1523 60°1523 60°1523 60°1523 60°1523	PC 0029 pf1327 PM 1784 PM 1919 PB 1478 pb1641	65275 45436 20421 55570 51461 62217				✓✓✓		First and new bumper
Luis Muro	00/15/23 00/15/23 00/15/23 00/15/23 00/15/23 00/15/23 00/15/23	PC 0029 pi 1327 PM 1784 PM 1919 PB 1478 ph 1641 PC 1475	65275 45438 20421 55570 51461 62217 73576		V				Foret and teat bumper

Maria		11.28	101	T. 0		. 6	lov. r		C 1.10
Name Trey Scott	Date 09/18/23	Unit Number PB 1877	Mileage Oil Level 34833	Tire Pressur	e Transmissio	on Fluid Lights	Cleanlin	ess ✓	Physical Damage N/A
512 William Smith	09/18/23	PM 1332						v v	No new damage
513 Luis Muro	09/19/23	pb1481						<u> </u>	
514 Robert Pitt	09/20/23	PC 0929					<u> </u>	v .	
515 Janice Heidlberger	09/21/23	PL 1331						<u> </u>	
516 Frank Pierson	09/25/23	PL 1327	65353	2	☑	✓	✓	✓	
517 Javier Secundino	09/25/23	pm1919	20505	2	☑ [✓	☑	✓	Firent and rear bumpar dents
518 Kevin Burkman	09/25/23	PB 1478	55774	2	☑	✓	☑	✓	
519 Luis Muro	09/25/23	pb1641	51667	2	<u> </u>	✓	~	✓	
520 Samuel T Huggenberger	09/25/23	PM1515	50,147.00	2	☑	✓	~	✓	
521 Trey Scott	09/25/23	PB 1877		2	☑	✓	✓	✓	
522 William Smith	09/25/23	PM 1332	78207	2	☑	✓	☑	✓	No new damage
523 Bryan Marriott	09/26/23	PL 1330	51586	2	☑ [✓	✓	✓	
524 Janice Heidlberger	09/26/23	PL 1331	44205	2	☑ [✓	☑	~	Oil seems a little low, drifty. New damage: normal west and rear of an existing hole in drivers seat, new paint chip, front passenger side light not working on Corner light har setting (while bulb on photo).
525 Robert Pitt	09/26/23	PC 0929			☑ [✓	☑	~	
528 Samuel ballesteros	09/26/23	PM 23062	240	2	☑	✓	~	✓	
527 Daniel McCaig	10/02/23	PB 1509	79471	2	✓	✓	✓	✓	Darrage to the rear bumper that's already been turned in.
528 Javier Secundino	10/02/23	pm1919						<u> </u>	Damage to ford and rear bumper
529 Joel Westerlund	10/02/23	PM 1784	45654					<u> </u>	
530 Kevin Burkman	10/02/23	PB 1478						v ·	
531 Samuel Ballesteros	10/02/23	PM 23062						v ·	
532 Trey Scott	10/02/23	PB 1877						v .	
533 William Smith	10/02/23	PM 1332						ŭ	No new damage
COA Adrian Luna	10/03/23	PM 1414						Ž.	
535 Jamison Bourgeois	10/03/23	PC 0929						v v	
535 Janice Heidberger	10/03/23	PL 1331						Ž.	
537 Bryan Marriott	10/03/23	PL 1330						v v	
538 samuel huggenberger	10/03/23	PM1515						Ž	
539 Luis Muro	10/03/23	pb1641						v .	
CO Luis Muro	10/03/23	pb1481						Ž	
540 Gene Trinklein	10/04/23	PM 1201						Ž.	
542 Luis Muro	10/09/23	PB 1481						v v	
543 Luis Muro	10/09/23	PB 1641						v v	
CAA Luis Muro	10/09/23	PB 1478						Ž	
545 Christopher lelonek	10/09/23	pm23060						<u> </u>	
545 Crinstopher sections 546 Javier Secundino	10/09/23	PM 1919						☑	Front and rear bumper Amber light on side mirror(left) cracked Dents on bad of the truck, driver side
546 Samuel Ballesteros	10/09/23	PM 23082						<u> </u>	And A common ages are some consequency announce access on the SE STAN, MITTEL STAN
547 SAMULE Damesters 548 Gary Patrick Green	10/09/23	PM GARYTRUCK						<u> </u>	nia cleantiness truck in the Beet
548 Gary Parnox Green 549 Samuel T Huggenberger	10/09/23	PM GARYTRUCK PM1515						<u>~</u>	THE CHEMISTRAN FLOAT II AND STREET
549 Samuel I Huggenberger 550 Jamison Bourgeois	10/09/23	PM1515 PC 0929						✓	
550 Jamson Bourgeois 551 Bryan Marriott	10/09/23	PC 0629						✓	
551 Bryan Marnott 552 Janson Bewley	10/11/23	PL 1330 PC 0891							Generator has 58.4 hours and final is full. The coolant is slightly low on truck -land air filter shows it needs cleaned or replaced. Truck is drifty and needs wished and cleaned.
553 Alejandro Mona	10/11/23	PC 1475						☑	Back left exterior tire wall has small shallow gash
554 Janice Heidberger 555 Samuel Ballesteros	10/13/23 10/16/23	PL 1331 PM 23062						<u> </u>	
333							☑	✓	
558 William Smith	10/16/23	PM 1332						<u> </u>	No new damage
557 Javier Secundino	10/16/23	PM 1919						☑	Front bumper, near bumper have dents Amber light is cracked passenger side mirror. Dent on top conner of passenger driver side
558 Joel Westerlund	10/16/23	PM 1784						<u> </u>	
550 Samuel T Huggenberger	10/16/23	PM1515						✓	
590 Luís Muro	10/17/23	pb1641						~	passinger side wheel hub with some damage
581 Luis Muro	10/17/23	pb1481						✓	
582 adrian luna	10/17/23	pb1414				✓		✓	
583 Luis Muro	10/17/23	pb1478		2	☑ [✓	✓	✓	front hood damage
564 Trey Scott	10/17/23	PB 1877	35360	2	☑ [✓	☑	✓	N/A
585 Janice Heidberger	10/17/23	PL 1331	44632	2	<u> </u>	✓	☑	✓	
566 janson bewley	10/09/23	PC 0891	41894	2	<u> </u>	✓	✓	✓	Coolant is slightly tow and wiper fluid is low. Air fifter shows it needs to be cleaned or replaced. Truck needs to be washed and cleaned.
567 janson bewley	10/09/23	PC 1475						✓	The check engine light is on. The driver side rear fleshing light is barely working and needs to be replaced.
588 Trey Scott	10/23/23	PB 1877	35474	2	☑	✓	✓	✓	
599 William Smith	10/23/23	PM 1332						✓	
570 Frank Pierson	10/23/23	PL 1327	65665	4	v	~	V	~	
571 Jeff hall	10/23/23	pm0744	77202	2	☑ [7	2	~	Battery box is all derited up
572 Luis Muro	10/23/23	PB1478						<u></u>	
573 Luís Muro	10/23/23	PB1641						<u> </u>	
574 Luis Muro	10/23/23	PB1481						v .	
575 Javier Secundino	10/23/23	PM 1919						Ž.	Dents on front and back bumper Dents above driver passenger side Dents on the bad of the truck, driver side Small crack on amber light passenger side mirror
576 Samuel T Huggenberger	10/23/23	PM1515						v v	
577 Gene Trinklein	10/23/23	PM 1201						Ž.	
577 Samuel Ballesteros	10/24/23	PM 23062						<u> </u>	
579 Joel Westerlund	10/24/23	PM 1784						Ž	
580 Janson Bewley	10/24/23	PC 0891						<u> </u>	Truck need to be washed and cleaned. Air filter shows it needs to be replaced and coolent is slightly low. Welder has 56.6 hours on it.
581 Janice Heidberger	10/24/23	PL 1331							TOOL THE COLOR TENSION OF THE PROPERTY OF THE
581 Janice Heldberger Trey Scott	10/24/23	PE 1331 PB 1877						✓	
583 Luis Muro	10/30/23	pb1478						<u> </u>	
SSA Luis Muro	10/30/23	pb1481						<u> </u>	
Samuel Ballesteros	10/30/23	PM 23062							
Sas Luis Muro	10/30/23	pb1641						✓	
587 Samuel T Huggenberger	10/30/23	PM1515						<u> </u>	
See Janson Bewley	10/30/23	PC 0891							Air filter shows it is dirty and needs replaced. Coolant is slightly low and truck needs to be washed and cleaned. The welder has 59.7 hours on in and the fuel if full.
588 Jartion beway 589 Ryan Moyer	10/30/23	PC 1475						<u> </u>	Art title should it is only and needs replaced. Column is signify low and stock needs to be washed and capanial. The weight rise 592 models in and the total it iss.
	10/30/23	PC 1475 PM1414					2	<u> </u>	
500 Adrian Luna 501 Frankie Pierson	10/30/23	PM1414 PL 1327						☑	
591 Frankie Pierson William Smith	10/30/23	PL 1327 PM 1332						☑	
502 William Smith 503 Daniel McCaig	10/30/23	PM 1332 PB 1641						☑	All damage has already been recorded.
593 Daniel McCaig 594 Javier Secundino	10/30/23	PB 1641 PM 1919						▽	All demage has already been reported. Front and near bumper have dents Bed of the truck has dents Above Driver passenger door has dent Passages side mirror amber light has a crack.
	10/30/23	PM 1919 PL 1331							Train and their duringer make derival and on the static rises demonstrate passeringer door rise dern Massages side mitter arriver light has a crack
595 Janice Heidiberger	11/01/23							▽	Front and rear burnoers have dents Truck bed had small dents Passencer side minor amber light has a crack
598 Javier Secundino	11/06/23	PM 1919 PB 1877						☑	Front and near bumpers have dents Truck bed had small dents Passenger side mirror amber light has a crack None
507 Felipe Lira 508 Joel Westerlund	11/06/23	PB 1877 PM 1784						☑	NONE
598 Joel Westerlund 598 Baylor Tomlinson	11/06/23	PM 1784 PC 1326						☑	
500 Baylor Tominson Frank Pierson	11/06/23	PC 1328 PL 1327						☑	
								<u> </u>	
601 Samuel Ballesteros 602 Samuel T Huggenberger	11/06/23	PM 23062 PM1515							
								☑	No.
603 Ramiro Renovato 604 ADRIAN LUNA	11/06/23	PB 1641 PB 1642						☑	N/A
	11/06/23	PB 1642 PM 1332						☑	
605 William Smith								<u> </u>	
606 Jason Wilson	11/06/23	PB 1481						<u> </u>	
607 Gary Patrick Green 608 Bryen Marriott	11/06/23 11/07/23	PM GARYTRUCK PM 1175						<u> </u>	Excellent condition. Placeanger headlight is out.
608 Bryan Marriott	11/07/23	PM 1175 PC 1475						<u> </u>	1 1
0.02								☑	Truck needs to be washed and cleaned. Windshield wiper fluid needs to be filled. Rear driver side fire has a gook in sidewall and needs to be replaced soon. Rear driver side light needs to be replaced. It has moisture and
610 Janice Heidberger	11/07/23	PL 1331				_		<u> </u>	Paint coming off. Front, passenger "Conner" flast-blink light not working.
611 Luis Muro	11/07/23	PB 1478						<u> </u>	
612 William Jackson Smith III	11/13/23	PM 1332						<u> </u>	
613 Samuel Ballesteros	11/13/23	PM 23062						<u> </u>	
614 Frankie Pierson	11/13/23	PL 1327						☑	
615 Jeffrey hall	11/13/23	PB 1509						☑	Dents on the front bumper
616 Joel Westerlund	11/13/23	PM 1784						<u> </u>	
617 Ramiro Renovato	11/13/23	PB 1641						<u> </u>	None
618 Samuel T Huggenberger	11/13/23	PM1515						<u> </u>	
619 Janson Bewley	11/14/23	PC 0891						<u> </u>	Air filter shows it needs replaced or cleaned. Front driver side tire needs to be replaced. Coolant is slightly low and needs topped off. The front end bounces when driving and hitting a dip.
620 Bryan Marriott	11/14/23	PM 1175						✓	
621 Javier Secundino	11/14/23	PM 1919						<u> </u>	Dents on front and rear bumper Cracks on passenger side mirror ember light Crack on rear driver turn signal
622 ADRIAN LUNA	11/14/23	PM1414						<u>~</u>	
623 Luis Muro	11/14/23	PB 1478	57003				☑	<u> </u>	
624 Janice Heidberger	11/15/23	PL 1331	45164					v ·	Front passenger flast-blink "Corner" light doesn't blink.
625 William Smith	11/20/23	PM 1332						v .	
626 Trey Scott	11/20/23	pm1414						Ž.	NA NA
627 Janson Bewley	11/20/23	PC 0891						Ž.	Truck is dirty and needs to be washed and cleaned. The coclant is slightly low and air filter shows it needs to be cleaned or replaced. The welder has 50.6 hours and fuel is full. The front driver side fire needs to be replaced
628 Trey Scott	11/20/23	PB 1877						v ·	
629 Alejandro Mora	11/20/23	PC 1475						<u> </u>	
630 Samuel Ballesteros	11/20/23	PM 23062						v v	
631 Javier secundino	11/20/23	pm1919						<u> </u>	Front and rear bumper have dents Bed of the truck has small dents Driver rear turn light has a crack,
632 Ramiro Renovato	11/20/23	PB 1641						v v	None
632 ADRIAN LUNA	11/20/23	PM 1175						v v	
633 Samuel T Huggenberger	11/20/23	PM1515						Ž.	
635 Luis Muro	10/30/23	PB 1478						Ž.	
636 Janice Heidberger	11/22/23	PL 1331						v v	Front passenger "corner" fast-blink light doesn't work.
637 Trey Scott	11/27/23	PL 1327						Ž	
638 Samuel Ballesteros	11/27/23	PM 23062						Ž.	
E3E Danies Danessinos									

Name	Date	Unit Number	Mileage Oil Level	Tire Pressure	Transmissio	n Fluid Lights	Cleanlin	ess	Physical Damage
639 William Smith 640 Ramino Renovato	11/27/23 11/27/23	Unit Number Pm1332 PB 1641	80400		Transmissio		☑	~	Right front bumper dent where Kenny hit a stump in tall grass
641 Javier Secundino	11/27/23	PM 1919		2			☑	☑	Front and rear bumpers have dants Truck but have dants driver side break light is cracked
842 Samuel T Huggenberger	11/27/23 11/27/23	PM1515 PB 1478	51201	2	2	2	☑	✓	
843 Luis Muro 844 Bryan Marriott	11/27/23	PB 1478 PM 1175		2			✓	☑	Both of the headlights are out.
645 ADRIAN LUNA	11/28/23	PM 1414	79620	2	2		<u> </u>	✓	
646 Janice Heidfberger 647 Samuel Ballesteros	11/29/23	PL 1331 PM 23062		Z (2		☑	☑	Front passenger Control fast-blink light not blinking.
648 Frank Pierson	12/04/23	PL 1327		2			<u>✓</u>	✓	
649 William Smith	12/04/23	PM 1332	80695	2			☑	✓	No new damage
650 Ramino Renovato 651 Samuel T Huggenberger	12/04/23 12/04/23	PB 1641 PM1515		2	2		☑	☑	None
652 Javier Secundino	12/05/23	pm1919	21473		2		✓	<u> </u>	Frontinear bumper dents Break light on driver side has crack
653 Gene Trinklein	12/05/23 12/06/23	PM 1201 PB 1478			2		☑	<u>~</u>	
654 Luis Muro 655 Luis Muro	12/08/23	PB 14/8 PB 1481		2			✓	☑	
656 ADRIAN LUNA	12/06/23	PM 1414	79634				2	<u> </u>	
657 Janice Heidberger	12/08/23 12/11/23	PL 1331 PB 1641		2			☑	<u>~</u>	Front passanger "Corner" fast-Birk light not working.
658 Hamino Hanovato 659 Trey Scott	12/11/23	PB 1641 PB 1877		2	2		☑	☑	None
660 Janson Bewley	12/11/23	PC 0891	42658	2			✓	<u></u>	Truck is dirty and needs to be washed and cleaned. Air filter shows it needs to be cleaned or replaced. Welder is full on fuel and has 50 hours on it.
661 Frank Pierson William Smith	12/11/23	PL 1327 PM 1332		2			✓	☑	No new damage
662 William Smith	12/11/23	PM 23062		2			☑ ☑	☑	NO TWY CHINAP
664 Javier Secundino	12/11/23	pm1919	21520	2	2	2	☑	✓	Dents on front and rear bumper Driver break light has crack Passanger side mirror amber blinker crack
665 Samuel T Huggenberger 666 Ryan Moyer	12/11/23 12/11/23	PM 1515 PC 1475		2 2	2		☑ ☑	☑	
667 ADRIAN LUNA	12/12/23	PM 1414					<u>v</u>	<u> </u>	
668 Bryan Marriott	12/12/23	PM 1175		2	2		2	✓	
669 Janice Heidlberger 670 Jason Wilson	12/14/23	PL 1331 PB 1481		2			☑	☑	Added a quart of oil because it was low. Purple royal from napa.
670 Jacon Wiston 671 Alejandro Mora	12/14/23	PC 1475		2 2			2	<u>✓</u>	Real left tire has gash on sidewall
672 Luis Muro	12/14/23	PB 1478	57585	2	2	2	2	<u></u>	
673 William Smith 674 Frank Pierson	12/18/23 12/18/23	PM 1332 PL 1327		V	2		✓	☑	No new damage
674 Hrank Pierson 675 Jason Wilson	12/18/23	PE 1481			2		☑	✓	
676 Ramiro Renovato	12/18/23	PB 1641	53113	2	2	2	☑	✓	None
677 Alejandro mora 678 Janson Bewley	12/18/23 12/18/23	PC 1475 PC 0891			2		☑ ☑	☑	Gaish on near driver side fire wall Trock is dirly and needs to be weathed and cleaned. Welder has 50 hours on it. Fuel is full in truck and welder.
679 ADRIAN LUNA	12/18/23	PM1414	80046		2		<u> </u>	☑	, and the second
680 Jamison Bourgeois	12/18/23	PC 0929	83285	2	2	2	☑	✓	
681 Javier Secundino 682 Samuel T Huggenberger	12/18/23 12/18/23	PM 1919 PM1515		2			☑	☑	Front and rear bumper have dents Break light on driver side has a crack
683 Luís Muro	12/18/23	PB 1478	57670	Z			<u> </u>	✓	
684 Trey Scott	12/19/23	PB 1877 PM 23082	36343	2	2	2	☑	✓	
685 Samuel Ballesteros 585 Janice Heidberger	12/19/23	PM 23062 PL 1331		2	2		☑	☑	Front passanger "Control" light doesn't blink fisst or work like it should.
687 Ramiro Renovato	12/27/23	PB 1641					<u> </u>	<u> </u>	None
688 Samuel T Huggenberger	12/27/23	PM 1515		2			☑	✓	
689 Alejandro mora 690 Ryan Moyer	12/28/23	PC 1475 PC 0891		2			☑ ☑	☑	Gash on rear driver side: tire
691 Ramiro Renovato	01/02/24	PB 1641					2	<u></u>	None
692 Javier Secundino	01/02/24	PM 1919			2		☑	✓	Front and near bumpers have dents Driver side brake light has crack Passenger side mirror amber light has small crack
693 Bryan Marriott 694 Samuel T Huggenberger	01/02/24 01/02/24	PL 1330 PM 1515			2		☑ ☑	☑	
695 Janice Heidberger	01/02/24	PL 1331					2	<u>~</u>	Oil is low and very black. Front passenger "control" light not fast-blinking like it should be.
696 Trey Scott	01/03/24	PB 1877		2			✓	✓	
697 Frank Pierson 698 Jason Wilson	01/03/24 01/03/24	PL 1327 PB 1641		Z			☑ ☑	☑	
699 ADRIAN LUNA	01/03/24	PM1414					2	<u> </u>	
700 Jason Wilson 701 Jarson Bewley	01/03/24 01/05/24	PB 1481 PC 0891		2			☑	✓	
701 Janson Bewley 702 Alejandro Mona	01/05/24	PC 0891 PC 1475		2 2			☑ ☑	☑	Weider has 50 hours on it and is full on fuel. Truck is diffy and needs to be washed and cleaned. Air filter shows it needs to be replaced or cleaned. Coolent is at bottom level of minimum. The geach near driver side
703 William Smith	01/08/24	pm1332					2	<u> </u>	No new damage
704 Samuel Ballesteros	01/08/24	PM 23082			2		☑	<u> </u>	
705 Ramino Renovato 706 Javier Secundino	01/08/24 01/08/24	PB 1641 PM 1919			2		☑	☑	None Firont and rear bumper have dents Driver side break light has crack Passenger side mirror amber light cracked Driver door decals coming off
707 Jason Wilson	01/08/24	PB 1481	34332	2	2		2	✓	
708 Trey Scott	01/08/24 01/08/24	PB 1877 PM 1515		2			✓	<u> </u>	
709 Samuel T Huggenberger 700 Frank Pierson	01/08/24	PM 1515 PL 1327		2	2		☑	☑	
711 Ryan Moyer	01/08/24	PC 1475	64475	2	2	2	2	✓	
712 ADRIAN LUNA	01/08/24 01/08/24	PM1414 PB 1478		2			☑ ☑	☑	
714 Janice Heidberger	01/10/24	PL 1331					<u> </u>	<u> </u>	
715 Janson Bewley	01/11/24	PC 0891			2		☑	▽	Truck is dirty and needs to be cleaned. Air filter shows it needs to be cleaned. Welder has 59.0 hours on it.
716 Samuel T Huggenbgerger 717 Jason Wilson	01/16/24	PM 1515 PB 1641			2		☑	☑	
718 Jason Wilson	01/16/24	PB 1481					2	<u>~</u>	
719 Ramiro Renovato	01/16/24	PB 1641	52966	2	2	2	✓	✓	None
720 Trey Scott 721 Trey Scott	01/16/24 01/16/24	PB 1877 PM1414			2		☑ ☑	☑	
722 Luis Muro	01/16/24	PB 1478	57976	2		2	2	✓	
723 Janice Heidberger 724 Janson Bewley	01/18/24 01/19/24	PL 1331 PC 0891		2			<u> </u>	<u> </u>	The truck is diffy and needs to be cleaned. There appears to be a leak at the broke booster pump and or hose. The air filter shows it needs to be cleaned and or replaced.
724 Janson Bewley 725 Ryan Moyer	01/19/24	PC 1475		2 2			☑ ☑	☑	THE WARM IN VALUE AND A THE WARM AND A THE CHARGE STATE OF A MARK AS THE CHARGE SCHOOL PUTTE OF CLOSE. I THE APP TRICE STATES A THORS AS THE CHARGE STATE OF THE APP TRICE STATES AND ASSESSED TO BE CHARGED AND OF THE PUTTE
728 William Smith	01/22/24	pm1332	82649	2	2	2	2	<u> </u>	No new damage
727 Javier Secundino 728 Janson Bewley	01/22/24 01/22/24	PM23063 PC 0891			2		☑	☑	Walder is full on fuel and has 50:1 hours on it. The air filter shows it needs to be cleaned or replaced. The cocleant is slightly low and brake fluid appears to be leaking.
728 Ramiro Renovato	01/22/24	PB 1641		2			<u> </u>	☑	Weder a function seal and the day, include on it. This are time and the season to be cleared on replaced. This coolers is augmay low and prevention appears to be leaving. None
730 Samuel T Huggenberger	01/22/24	PM1515	52,012.00	2	2	2	☑	<u></u>	
731 Luís Muro 732 Samuel Ballesteros	01/22/24 01/23/24	PB 1478 PM 23062		v) (✓	☑	
732 Samuel Gallesianos 733 Frank Pierson	01/24/24	PL 1327					<u> </u>	☑	
734 Janice Heidberger	01/26/24	PL 1331	46821	2	2	2	☑	✓	Got headlight fixed. Fast-blink light on Corner light still out.
735 Samuel Ballesteros 736 Ramiro Renovato	01/29/24 01/29/24	PM 23062 PB 1641		2 2	2		☑ ☑	☑	None
737 Jason Wilson	01/29/24	PB 1481	34469	2			⊻	✓	
738 Javier Secundino	01/29/24	PM 23063	294	2	2	2	✓	✓	
730 William Smith 730 Alejandro Mora	01/29/24 01/29/24	pm1332 PC 1475		2	2		☑	☑	No new damage Gash on near driver side tire
741 ADRIAN LUNA	01/29/24	PM 1414	80460	2			<u> </u>	☑	
742 Samuel T Huggenberger 743 Janson Beviley	01/29/24 01/29/24	PM1515 PC 0891		2	2		✓	☑	Total is didu and acode to be withhold and closured. The benefit have been
743 Janson Bewley 744 Frank Pierson	01/29/24	PC 0891 PL 1327		2			☑ ☑	☑	Truck is dirty and needs to be washed and cleaned. The booster brake pump hose seems to have a slight leak and coolant seems to be slightly low. The air filter shows it needs to be cleaned or replaced. The welder has \$9.1
745 Luis Muro	01/30/24	PB 1478	58248	2	2	2	☑	✓	
746 Joel Westerlund	01/29/24 02/05/24	PM 1784 PL 1327		2			V		
747 Frank Pierson 748 Jason Wilson	02/05/24	PL 1327 PB 1481		Z	2		✓	☑	
749 Trey Scott	02/05/24	PB 1877	37121	2	2	2	✓	~	
750 Alejandro Mona	02/05/24 02/12/24	PC 1475 PB 1641			2		V	☑	Gash on rear driver side tire . None
751 Ramino Renovato 752 Javier Secundino	02/12/24	PB 1641 PM 23063		2			☑	☑	NOTH
753 Janson Bewley	02/05/24	PC 0891	43481.6	2	2	2	☑	✓	Air filter shows it needs to be cleaned or replaced. Welder is full on fuel and has 59.1 hours on it. The coolant is slightly low and brake booster hose has a very small leak. The truck is dirty and needs to be washed and
754 ADRIAN LUNA 755 Luis Moro	02/05/24 02/05/24	PM 1414 PB 1478		✓	2		✓	☑	
755 Luis Muro 756 Samuel T Huggenberger	02/05/24	PM1515		2			☑	✓	
757 Janice Heidberger	02/05/24	PL 1331	47226	2	2	2	2	<u></u>	Knobling noise on start up
758 Samuel Ballesteros 759 William Smith	02/05/24 02/05/24	PM 23062 PM 1332		· · · · · · · · · · · · · · · · · · ·			V	☑	No new damage
750 William Smith 760 Janice Heidberger	02/08/24	PM 1332 PL 1331			2		☑	☑	No new damage Knodking noise on start-up. Front CORNER fast-blink light out.
781 Javier Secundino	02/12/24	Pm 23063	536	2	2	2	2	✓	
762 Ramino Renovato 763 William Smith	02/12/24 02/12/24	PB 1641 PM 1332			2		☑	☑	None No new damage
764 Trey Scott	02/12/24	PB 1877	80719				☑	☑	TEV 1999 velicings
765 Samuel Ballesteros	02/12/24	PM 23062	2512	2	2	2	✓	✓	
788 Joel Westerlund	02/12/24	PM 1784	47700	2	2	2	✓	✓	

Name		Date	Unit Number	Mileage Oil Level		Tire Pressur	Ta.	Transmirsio	n Fluid Linhte	Classi	Date	Physical Damage
767	Genemy Dyke	02/12/24	PC 1326	58419	✓	THE THE SEC	e		n Fluid Lights	✓	ness ✓	r ryansa Garraga
	muel T Huggenberger	02/12/24	PM1515	52,424.00	✓		✓		2	✓	~	
769 J	Janice Heidberger	02/13/24 12/18/23	PL 1331 PB 1478	47426 58464	<u> </u>		☑			☑	<u>~</u>	Front passenger fast-blink light not working.
770	Luis Muro Felipe Lira	02/15/24	Pb 1876		<u> </u>		<u> </u>			☑	✓	
772 S	Samuel Ballesteros	02/19/24	PM 23062		▽		☑			<u> </u>	<u> </u>	
773	Trey Scott	02/19/24	PB 1877		<u> </u>		<u> </u>			<u> </u>	<u></u>	
	Adam Stantz	02/19/24	PC 1325	57729	▽		✓		2	☑	~	
	Ramiro Renovato	02/19/24	PB 1478		✓		☑			☑	2	None
7.10	Joel Westerlund muel T Huggenberger	02/19/24	PM 1784 PM 1515	47834 52,578.00	☑		✓			☑	<u> </u>	
	ADRIAN LUNA	02/19/24	PM 1414		▽		☑				✓	
	Jeson Wilson	02/20/24	PB 1481				☑			<u> </u>	V	
	Janice Heidberger	02/20/24	PL 1331		✓		<u> </u>			<u> </u>	v ·	OI at half.
	Janson Bewley	02/22/24	PC 0891	43696	✓		<u> </u>			✓	~	Truck is dirty and needs weished. Welder has 53.9 hours on it.
	Samuel Ballesteros	02/26/24	PM 23062		✓		✓			✓	✓	
702	Frank Pierson	02/26/24	PL 1327		<u> </u>		✓			✓	<u> </u>	
784	Janson Bewley Adam Stantz	02/26/24 02/26/24	PC 0891 PC 1325		▽		☑				✓	Truck is dirty and needs to be washed and cleaned. Air filter indicator shows it needs to be replaced or cleaned. Coolant is slightly low. Welder is full and has 59.3 hours on it. The front passenger side tire looks like it is loosing
785	Luis Muro	12/18/23	PC 1325		<u>✓</u>		☑				<u> </u>	
787	Luis Muro	12/18/23	PB1641	54149	<u> </u>		<u> </u>			<u> </u>	<u>~</u>	
788 San	nuel T Huggenberger	02/27/24	PM1515	52,740.00	<u> </u>		<u> </u>			☑	v v	
789	William Smith	03/04/24	pm1332		✓		✓			✓	✓	No new damage
790	Trey Scott	03/04/24	PM 1414		✓		✓			☑	~	
	Jason Wilson	03/04/24	PB 1481		<u> </u>		✓		4	☑	<u>~</u>	
	Javier Secundino Samuel Ballesteros	03/04/24 03/04/24	PM 23063 PM 23062		▽		▽				✓	
	amuel Huggenberger	03/04/24	PM 1515	52,863.00	<u> </u>		<u>✓</u>			☑	<u>~</u>	
	Ramiro Renovato	03/04/24	PB 1641	54224			<u> </u>			<u> </u>	V	None
	Frank Pierson	09/05/24	PL 1327		<u> </u>		<u> </u>			✓	<u></u>	
797 J	Janice Heidberger	03/06/24	PL 1331	47808	▽		✓		2	☑	~	Fleet topped off oil yesterday. "Comer" Light on front passenger still not working. New crack on dealthoard from weatherization. See photo.
	ADRIAN LUNA	03/06/24	PB 1642		☑		☑			☑	2	
	Ramiro Renovato	03/11/24	PB 1641		<u> </u>		✓				<u>~</u>	None
	Frank Pierson William Smith	03/11/24 03/11/24	PL 1327 PM 1332	67846 83882	▽		☑				✓	No new damage
802	Trey Scott	03/11/24	PM 1332 PB 1876		☑		☑				▽	TAX TRATE VALUE OF
803	ADRIAN LUNA	03/10/24	PM 1414				☑			☑	<u> </u>	
804	Joel Westerlund	03/11/24	PM 1784	48204	<u> </u>		<u> </u>			<u> </u>	<u> </u>	
	Javier Secundino	03/11/24	PM 23063	937	~		✓		2	☑	~	
	muel T Huggenberger	03/11/24	PM 1515		<u> </u>		✓		2	✓	<u> </u>	
	Janice Heidberger	03/14/24	PL 1331				☑			2	☑	
	Gene Trinklein Barnuel Ballesteros	03/14/24 03/18/24	PM 1201 PM 23062		☑		▽				▽	
	Joel Westerlund	03/18/24	PM 23062 PM 1784		<u>✓</u>		☑				<u> </u>	
811	Trey Scott	03/18/24	pb 1876	37548	<u> </u>		<u>✓</u>			☑	<u>~</u>	
812	Ramiro Renovato	03/18/24	PB 1641		<u> </u>		✓		2	<u> </u>	~	None
813	Luis Muro	03/18/24	PB 1478	59058	<u>~</u>		~		4	☑	<u></u>	
0.14	Frank Pierson	03/18/24	PL 1327		✓		✓			✓	✓	
	muel T Huggenberger	03/18/24	PM 1515		<u> </u>		☑			☑	<u> </u>	
	Gene Trinklein Javier Secundino	03/18/24 03/18/24	PM 1201 PM23063		✓✓		▽				✓	
017	Janice Heidberger	03/20/24	PL 1331				☑			☑	v v	
819	Kevin Burkman	03/25/24	PM 22037		<u> </u>		✓			<u> </u>	Ž.	
820 S	Samuel Ballesteros	09/25/24	PM 23062	3255	✓		✓			☑	~	
821	William Smith	03/25/24	PM 1332		✓		✓		4	✓	~	No niew damage
	Frank Pierson	03/25/24	PL 1327	68099	✓		☑			✓	<u>~</u>	
	Daniel McCaig Ramiro Renovato	03/25/24 03/25/24	PM 22068 PB 1641		☑		✓			☑	<u> </u>	None
824	Trey Scott	03/25/24	pb 1876		▽		☑			☑	✓	FISHER
826	Javier Secundino	09/25/24	PM 23063		<u> </u>		Z			<u> </u>	V	
	ADRIAN LUNA	03/26/24	PM 1414		<u> </u>		<u> </u>			☑	<u></u>	
828	Joel Westerlund	03/26/24	PM 1784	48412	✓		✓			✓	~	
	muel Huggenberger	03/28/24	PM 1515		✓		✓			✓	~	
830	Janson Bewley Rvan Mover	03/29/24 03/29/24	PC 0891 PC 1475		✓		✓			☑	<u> </u>	Truck is dirty and needs to be washed and cleaned. There is a small leak on brake booster line and air filter shows it needs to be cleaned or replaced.
831	Kevin Burkman	03/29/24	PC 1475 PM 22037		☑		▽		2		✓	
	Samuel Ballesteros	04/01/24	PM 23062				<u> </u>			☑	<u> </u>	
	Jason Wilson	04/01/24	PB 1481		☑		<u> </u>			☑	<u></u>	
835	Trey Scott	04/01/24	PM GARYTRUCK	37906	✓		✓			✓	✓	
836	Jeffrey hall	04/01/24	PM 22068		✓		✓			☑	~	
	Janson Bewley	04/01/24	PC 0891		<u> </u>		✓			☑	<u>~</u>	Truck is dirty and needs to be washed and cleaned. Small leak in brake booster line hose crimp. Air filter shows it needs to be cleaned or replaced. Welder has 60.4 hours on it and fuel is full.
0.00	William Smith Ramiro Renovato	04/01/24 04/01/24	pm1332 PB 1641	84872 54682	<u> </u>		<u> </u>			☑	<u>~</u>	No nie None
	Javier Secundino	04/01/24	PM 23063		☑		☑			☑	✓	PERM
	Joel Westerlund	04/01/24	PM 1784		<u> </u>		Z			<u> </u>	<u> </u>	
842	Luís muro	04/01/24	PB 1478	59319	✓		<u> </u>			☑	2	
	muel Huggenberger	04/01/24	PM 1515		✓		✓			☑	~	
	Gene Trinklein	04/01/24	PM 1201				<u> </u>			☑	<u> </u>	
	Frank Pierson ADRIAN LUNA	04/01/24 04/02/24	PL 1327 PM1414	68271 81790	✓✓		☑				✓	
846	Ryan Moyer	04/02/24	PM1414 PC 1475		<u>✓</u>		☑			☑	✓	
	Janice Heidberger	04/05/24	PL 1331		<u>✓</u>		<u>✓</u>			<u> </u>	<u> </u>	
849	Kevin Burkman	04/08/24	PM 22037		✓		_ _			✓	<u> </u>	
	Samuel Ballesteros	04/08/24	PM 23062	3510	☑		~			☑	✓	
	Janson Bewley Trey Scott	04/08/24	PC 0691		<u>~</u>		<u> </u>			<u> </u>	<u>~</u>	Truck is dirty and needs to be wished and cleaned. Air filter shows it needs to be cleaned. Coolant is slightly low and very small leak on brake booster pump hose at fitting. There is a screw in back fire but it doesn't leak air.
852 853	Trey Scott Jeffrey hall	04/08/24 04/08/24	PB 1876 PM 22068	38092 4853	✓		☑			☑	✓	None
	Jeson Wilson	04/08/24	PM 22068 PB 1481		✓		☑			☑	✓	Thore
	William Smith	04/08/24	PM 1332				☑				<u> </u>	No new damage
856	Javier Secundino	04/08/24	PM 23063	1278	☑		~		4	☑	✓	
	Joel Westerlund	04/08/24	PM 1784		<u> </u>		☑		2	✓	<u> </u>	
	muel T Huggenberger Ryan Moyer	04/08/24 04/08/24	PM 1515 PC 1475	53,411.00 65752			☑			☑	☑	
	Ryan Moyer Miles Johnson	04/08/24	PC 1475 PB 1641		✓		☑			☑	▽	
861	Luis muro	04/08/24	PB 1478				☑				<u> </u>	
UU2.	Frank Pierson	04/09/24	PL 1327	68384	<u> </u>		<u> </u>			<u> </u>	<u> </u>	
	Janice Heidberger	04/12/24	PL 1331	48753	✓		✓		2	✓	~	
	Kevin Burkman	04/15/24	PM 22037	5054	✓		✓		2	✓	<u> </u>	
000	Joel Westerlund	04/15/24	PM 1784				☑			2	☑	
	Javier Secundino Janson Bewley	04/15/24 04/15/24	PM 23063 PC 0891		▽		☑				▽	Welder has 60.7 hours on it and fuel is full. Truck is dirly and needs to be washed and cleaned. Coolant is slightly low and air filter shows it needs to be cleaned or replaced.
	Adam Stantz	04/15/24	PC 1925		☑		☑				<u> </u>	THE OWNER OF THE OWNER OW
	Ryan Moyer	04/15/24	PC 1426	65848	<u> </u>		<u>✓</u>			<u> </u>	<u>~</u>	
	Jeson Wilson	04/15/24	PB 1481				✓		2	✓	~	
	Frank Pierson	04/15/24	PL 1327	68533	<u>~</u>		~		4	✓	✓	
072	Samuel ballesteros	04/15/24	PM 23062		<u> </u>		<u>~</u>			☑	<u> </u>	
	Chris lelonek	04/15/24	PM 22068				☑		2	2	☑	No.
	Ramiro Renovato muel T Huggenberger	04/15/24 04/15/24	PB 1641 PM 1515		☑		☑				✓	None
875 Own	Trey Scott	04/15/24	pb 1876	38227	<u>✓</u>		✓				<u> </u>	
	William Smith	04/15/24	PM 1332		<u> </u>		<u> </u>			<u> </u>	<u>~</u>	No new damage
877			PM 0744	78321	☑		<u> </u>		2	☑	<u></u>	Back lower passenger side brake light and running light not working
877 878	Jeffrey hall	04/16/24		59754	☑		☑		2	☑	✓	
878 879	Luis Muro	04/15/24	PB 1478		<u> </u>		<u> </u>			<u> </u>	<u>~</u>	
878 879 890	Luis Muro Adrian Luna	04/15/24 04/17/24	PM1414		✓		☑			☑	<u>~</u>	
878 879 880 881	Luis Muro Adrian Luna Janice Heidiberger	04/15/24 04/17/24 04/17/24	PM1414 PL 1331	48863			✓				▽	
878 879 880 881 J	Luis Muro Adrian Luna	04/15/24 04/17/24	PM1414	48863 5245	▽		~				-	
878 879 880 881 J 882	Luis Muro Adrian Luna Janice Heidlberger Kevin Burkman	04/15/24 04/17/24 04/17/24 04/22/24	PM1414 PL 1331 PM 22037	48863 5245 3756	✓✓✓		☑			~	~	None
878 879 880 881 J 882	Luis Muro Adrian Lune Janice Heidberger Kevin Burkman Kevin Burkman	04/15/24 04/17/24 04/17/24 04/22/24 04/22/24	PM1414 PL 1331 PM 22037 PM 23082	48863 5245 3756 55012	☑				4		✓✓	None
878 879 880 881 J 882 883 884 I	Luis Muro Adrian Luna Janica Haidibenger Kevin Burkman Kevin Burkman Ramiro Ranovato Jeffrey hall Javier Secundino	04/15/24 04/17/24 04/17/24 04/22/24 04/22/24 04/22/24 04/22/24 04/22/24	PM1414 PL 1331 PM 22037 PM 23082 PB 1641 PM 22088 PM 23063	48863 5245 3756 55012 5134 1487	☑		▽			✓✓✓	✓✓	Ross
878 879 880 881 J 882 883 884 I 885	Luis Muro Adrian Luna Janica Haidibanger Kevin Burkman Kevin Burkman Ramino Ranovato Jeffrey hall Javier Secundino Trey Scott	641528 641724 641724 642294 642294 642294 642294 642294 642294 642294	PM1414 PL 1331 PM 22037 PM 23062 PB 1641 PM 22068 PM 23063 PB 1876	48893 5245 3756 55012 5134 1487 38377	<!--</td--><td></td><td></td><td></td><td></td><td>✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓</td><td>✓✓✓</td><td></td>					✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓	✓✓✓	
878 879 880 881 J 882 883 884 I 885 886 ·	Luís Muro Adrian Luna Jarrice Heidbenger Kevin Burleman Kevin Burleman Ramino Ranovato Jeffrey hall Javiar Secundino Trey Scott William Smith	04/15/24 04/17/24 04/17/24 04/22/24 04/22/24 04/22/24 04/22/24 04/22/24 04/22/24 04/22/24	PM1414 PL 1331 PM 22037 PM 22037 PM 22062 PB 1641 PM 22068 PM 2065 PB 1876 PM 1332	48693 5345 3756 55012 5134 1487 38377 85600							<!--</td--><td>None No ner danaga</td>	None No ner danaga
878 879 880 881 J 882 883 884 I 885 886 .	Luis Muro Adrian Luna Adrian Luna Janica Heldberger Kevin Burkman Kevin Burkman Ramino Ramovato Jeffrey hall Javier Secundino Trey Scott William Smith Jason Wilson	041924 041724 041724 041724 042224 042224 042224 042224 042224 042224 042224 042224	PM1414 PL 1331 PM 22037 PM 22062 PM 5961 PM 22068 PM 22068 PM 22068 PM 1322 PB 1481	48683 5245 3756 55612 5134 1447 38677 65600 35105							<!--</td--><td></td>	
878 879 880 881 J 882 883 884 I 885 886 .	Luis Maro Adrian Luna Jarice Holdberger Kevin Burkman Kevin Burkman Ramsino Ranovato Joshey hall Javier Secundino Trey Social William Sirah Jason Wilson muai Huggenberger	041554 041754 041754 042754 042204 042204 042204 042204 042204 042204 042204 042204 042204 042204	P81414 PF. 1331 PR 20037 PR 20037 PR 20062 PR 15641 PR 20068 PR 12068 PR 1312 PR 1411 PR 1515	48883 5245 3756 55012 5134 1447 38377 68690 35105 53714							V V V V V V V V V V V V V V V V V V V	
878 879 880 881 J 882 883 884 885 886 887 888 889 800 Saa	Luis Muro Adrian Luna Adrian Luna Janica Heldberger Kevin Burkman Kevin Burkman Ramino Ramovato Jeffrey hall Javier Secundino Trey Scott William Smith Jason Wilson	041924 041724 041724 041724 042224 042224 042224 042224 042224 042224 042224 042224	PM1414 PL 1331 PM 22037 PM 22062 PM 5961 PM 22068 PM 22068 PM 22068 PM 1322 PB 1481	46863 5245 3756 55012 5134 1407 36377 86600 9105 66077								
878 879 880 881 J 882 883 884 885 886 887 888 889 800 Saa	Luis Maro Adrian Luna Jarice Heldiberger Kovin Burkman Kavin Burkman Ramine Ranovato Jeffrey hall Jusier Steandino Trey Scott William British Jacon William Jacon William Pagenberger Ryan Moyer	04/1524 04/1724 04/1724 04/2724 04/2224 04/2224 04/2224 04/2224 04/2224 04/2224 04/2224 04/2224 04/2224 04/2224	PRI1414 PR 12027 PR 20027 PR 20092 PR 1901 PR 20093 PR 1908 PR 12093 PR 1878 PR 1878 PR 1878 PR 1878 PR 1878	46863 5245 3756 55012 5134 1407 36377 86600 9105 66077							V V V V V V V V V V V V V V V V V V V	

Name	Date 04/29/24	Unit Number	Mileage	Oil Level		Tire Pressure	2	Transmiss	ion Fluid	Lights	Cle	sanlines	is	Physical Damage
5 Jeffrey Hall	04/29/24	PM 22068	5294				✓		☑	· ·			4	
Geremy Dyke-Barela		PC 1326	57289				✓		✓	V			2	
7 Jason Wilson	04/29/24	PB 1481	35133	V			✓		✓	· ·			4	
3 Javier Secundino	04/29/24	PM 23063	1603	V			✓		✓	· ·			2	
Samuel Huggenberger	04/29/24	PM 1515	53,856.00	V			✓		✓	· ·	2		2	
PM 23062	04/29/24	PM 23062	3898	V	1		✓		✓	V	3		2	
Joel Westerlund	04/29/24	PM 1784	48926	V			✓		✓	U	2		2	
Frank Pierson	04/29/24	PL 1327	68728				✓		<u></u>				2	
Kevin Burkman	04/30/24	PM 22037	5675				7		<u> </u>					
Luis Murr	04/30/24	PR 1478	60112											
	04/20/24	PD 1476		■			✓		✓	V			2	
S Ryan Moyer			66105				✓		✓	V			4	
Janson Bewley	04/30/24	PC 0891	44543				✓		✓	V			/	Truck is dirty and needs to be washed and cleaned. Coolant shows slightly low and air filter needs to be cleaned. Welder is full on fuel.
Jeff hall	05/08/24	PM 22068	5523	V			✓		✓	· ·	3		2	
Samuel T Huggenberger	05/08/24	PM 1515	54,078.00	V	1		✓		✓	U	2		2	
Jason Wilson	05/08/24	PB 1481	35175				<u> </u>		<u> </u>				2	
Javier Secundino	05/06/24	PM 23063	1686	V			7		7				7	
Tray Scott	05/06/24	PR 1876	38616				<u> </u>	_	<u> </u>	Ĭ				
William Smith	05/06/24	PM 1332	86451											No new damage
				V			✓		☑	V			4	No new damaga
Ryan Moyer	05/08/24	PC 1475	66257				✓		✓	V			4	
Janson Bewley	05/06/24	PC 0891	44591	V	1		✓		✓	· ·			2	Truck is dirty and needs to be washed and cleaned. Welder has 3/4 fuel and has 62.9 hours on it. Coolant shows slightly low and air filter shows it needs to be cleaned.
Ramiro Renovato	05/06/24	PB 1641	55230	V			✓		✓	U	3		<u> </u>	None
Samuel Ballesteros	05/06/24	PM 23062	3995				✓		✓	U	1	Į.	4	
Joel Westerlund	05/06/24	PM 1784	49059				<u> </u>		<u>_</u>	V				
Luis Muro	05/06/24	PB 1478	60249				<u> </u>			· ·				
Adrian Luna	05/08/24	PB 1877	50917				✓		<u> </u>					
Adnan Luna Frank Pierson	05/06/24	PB 1877	68897											
				V			✓		✓	V			2	
Adam Stantz	05/08/24	PC 1325	59117				✓		✓	V			4	
2 Gene Trinklein	06/07/24	PM 1201	74902				✓		✓	V			Z	
Kevin Burkman	05/13/24	PM 22037	5977		1		✓		✓	U			/	
4 Janson Bewley	05/13/24	PC 0891	44710				✓		<u> </u>		2		2	Truck is dirty and needs to be washed and cleaned. Coolant level is lightly low and air filter shows it needs to be cleaned. Welder has 65.1 hours and fuel is 58. Cutting torch botfles are close to needing to be replaced.
C Trey Scott	05/13/24	PB 1876	38787				✓		<u> </u>				7	
Frank Pierson	05/13/24	PL 1327	69064				7		<u> </u>					
Ramiro Renovato	05/13/24	PB 1641	55375											None
				_			✓		☑	V			2	19219
S Joe Martinez	05/13/24	PC 1475	66410	_			✓		✓	V			2	
Geremy Dyke	05/13/24	PM 1784	49214				✓		✓	V			2	
O Adam Stantz	05/13/24	PC 1325	59222	V			✓		✓	· ·	2		7	
ADRIAN LUNA	05/13/24	PB 1414	82272	V	1		✓		✓	· ·	1		4	
2 Daniel McCaig	05/13/24	PM 22068	5731	V			✓		✓	U	2		2	
Samuel Ballesteros	05/13/24	PM 23062	4116				<u> </u>		<u></u>	V			2	
William Smith	05/13/24	PM 1332	86707				<u> </u>		<u> </u>					No new damage
Daniel McCaig	05/13/24	PM 1332 PM 22068	5731	_			<u>~</u>		☑				4	No contragge
				V										
Euis Muro	05/13/24	PB 1478	60391	V	•		✓		✓	V			2	
7 Gene Trinklein	05/13/24	PM 1201	74982	_	•		✓		✓	· ·			4	
Samuel T Huggenberger	05/13/24	PM 1515	54,336.00	V			✓		✓	U	3		2	
Janice Heidberger	05/14/24	PL 1331	49618	V			✓		<u> </u>	U	1		4	
Javier Secundino	05/20/24	PM 23063	1870				v		V			_		
Jason Wilson	05/20/24	PB 1481	35229		•		<u> </u>		<u> </u>					
Trey Scott	05/20/24	PB 1876	38934											
							✓		☑	V			4	
Janson Bewley	05/20/24	PC 0891	44822				✓		✓	V			2	Truck is dity and needs to be washed and cleaned. Coolant is slightly low and air filter shows it needs to be cleaned. Bed needs to be cleaned out. Welder has 66.3 hours and is 1/2 on fuel. Truck needs to be topped off w
Samuel T Huggenberger	05/20/24	PM 1515	54,472.00				✓		✓	V			2	
5 Joel Westerlund	05/20/24	PM 1784	49379				✓		✓	V	1		Z	
6 Kevin Burkman	05/20/24	PM 22037	6099	V	1		✓		✓	V	1		4	
7 Samuel Ballesteros	05/22/24	PM 23062	4263				<u> </u>		<u></u>	· ·				Scrape on front passenger wheel. Dent on top center of taligate.
Janice Heidberger	05/23/24	PL 1331	49872				✓		<u> </u>				7	
Joel Westerlund	05/28/24	PM 1784	49494				7		<u> </u>					
Samuel T Huggenberger	05/28/24	PM 1515	54,664,00											
Samuel T Huggenberger ADRIAN LUNA	05/28/24 05/28/24	PM 1515 PM 1414	54,664.00 82905				✓		☑	V			2	
				■			✓		✓	V			4	
2 Frank Pierson	05/29/24	PL 1331	49986				✓		✓	U			2	
3 Gene Trinklein	05/29/24	PM 1201	75257		1		✓		✓	· ·			4	
4 Samuel Ballesteros	05/30/24	PM 23062	4416	V	1		✓		✓	U	3		/	
5 Ryan Moyer	05/30/24	PC 1475	66808				✓		✓	U			2	
Jeson Wilson	05/31/24	PB 1481	35380				✓		<u> </u>	· ·			2	
Luis Muro	05/28/24	PB 1478	60752				<u> </u>		<u> </u>	Ĭ				
Kevin Burkman	06/03/24	PM 23082	4467					-						Scratches to the wheels.
	06/03/24		4467				✓		✓	U			4	
Janson Bewley		PC 0891					✓		✓	V			4	Truck is dirty and needs to be washed and cleaned. Air filter shows it needs to be cleaned or replaced. Coolant is slightly low and brake booster has very small leak. Welder has 66.4 hours and it 1/2 on fuel.
Jason Wilson	06/03/24	PB 1478	60762				✓		✓	· ·			2	
Trey Scott	06/03/24	PB 1876	39276	V	1		✓		✓	· ·	3		/	
2 Jason Wilson	06/02/24	PB 1481	35396	V	1		✓		✓	U	1	E	2	
Ramiro Renovato	06/03/24	PB 1641	55757				<u> </u>		<u></u>	· ·			7	None
Samuel T Huggenberger	06/03/24	PM 1515	54,807.00				<u> </u>		<u> </u>					
. Joel Westerlund	06/03/24	PM 1784	49692				7		<u> </u>					
Frank Pierson	06/03/24	Pt. 1327	49692 69147											
							✓		☑				4	
y Javier Secundino	06/03/24	PM 23063	2118	V	i		✓		✓	U	3		4	