

TEXAS DEPARTMENT OF INSURANCE

333 Guadalupe, P. O. Box 149104-Mail Code 103-9A Austin, Texas 78714-9104 (512) 322-3435 Fax (512) 305-7425

Amusement Ride Certificate of Inspection/Reinspection

Required for each ride, pursuant to Texas Occupations Code, Chapter 2151, Amusement Ride Safety Inspection and Insurance Act and 28 Texas Administrative Code §§5.9004 -- 5.9014, Amusement Ride Rules, along with a \$40 per ride filing fee and picture of the ride in an operable state taken at the time of the inspection.

	<u>Owner/Operato</u>	or information			
Owner/Operator (Insure	d) City Of Denton Water Works	City Of Denton Water Works			
Address	2400 Long Road, Denton, TX	2400 Long Road, Denton, TX 76207			
Telephone Number	(940) 349-880 <u>5</u>				
	Amusement Ric	de Information			
Amusement Ride Name	MULTI SLIDE TOWER	Serial Number <u>SEE PHOTO SHEETS</u>			
Manufacturer WHITE	WATER & SPLASHTACULAR	Date Manufactured 2003 & 2010			
Date of Last Overhaul of	or Renovation	Date of Last (previous) Inspection 5/10/19			
Amusement Ri () (X)	de Classification:A Ride designed primarily for use by children 1B Ride other than Class A	2 years of age or younger with a fixed location			
	Amusement Ride Inspector Shall C	complete the Following Statement			
Self Insured	Insurance Company and the inspection require OR: DO NOT USE STAPLES ON PICTURES.	ected in an operable state and meets the standards and requirements of ements as set forth in 28 TAC §§5.9001 5.9014 and in Chapter 2151, Texas PICTURE PAGE MUST HAVE BUSINESS NAME / RIDE NAME / SERIAL			
Name and Title of Inspector	Paul L. Zellar, President				
Inspection Company	Zellar Consulting, LLC				
Address	1801 Sumac Drive, Flower Mound, T	X 75028			
Telephone Number (972) 35	55-1967 Cell Number: (972) 74	1-9288			
	Authorization of the	Insurance Company			
Name and Title (Print)					
Signature of Authorized Insu	ırance Company Representative	Telephone Number			

TDI Inspection Sticker Number____

TDI Amusement Ride Validation Stamp



TEXAS DEPARTMENT OF INSURANCE

333 Guadalupe, P. O. Box 149104-Mail Code 103-9A Austin, Texas 78714-9104 (512) 322-3435 Fax (512) 305-7425

Amusement Ride Certificate of Inspection/Reinspection

Required for each ride, pursuant to Texas Occupations Code, Chapter 2151, Amusement Ride Safety Inspection and Insurance Act and 28 Texas Administrative Code §§5.9004 -- 5.9014, Amusement Ride Rules, along with a \$40 per ride filing fee and picture of the ride in an operable state taken at the time of the inspection.

	<u>Owner/Operator</u>	<u>Information</u>	
Owner/Operator (Insured)	City Of Denton Water Works		_
Address	2400 Long Road, Denton, TX 7	6207	
Telephone Number	<u>(940) 349-8805</u>		
	Amusement Ride	<u>Information</u>	
Amusement Ride Name_	INDOOR OPEN BODY SLIDE	Serial Number 47141	<u>E</u>
Manufacturer	WHITEWATER	Date Manufactured 2003	
Date of Last Overhaul or I	Renovation	Date of Last (previous) Inspecti	on <u>5/10/19</u>
`	Classification: Ride designed primarily for use by children 12 y Ride other than Class A	ears of age or younger with a fixed location	1
Aı	musement Ride Inspector Shall Cor	mplete the Following Statemen	nt
Self Insured In	Taulot	ents as set forth in 28 TAC §§5.9001 5.9 CTURE PAGE MUST HAVE BUSINESS N	0014 and in Chapter 2151, Texas
Inspection Company Zo			
	801 Sumac Drive, Flower Mound, TX	75028	
Telephone Number (972) 355-	.1967 Cell Number: (972) 741-9	9288	
	Authorization of the Ins	surance Company	
Name and Title (Print)			
Signature of Authorized Insura	nce Company Representative		Telephone Number
TDI Amusement Ride Validation	n Stamp	TDI Inspection Sticker Number	




TEXAS DEPARTMENT OF INSURANCE

333 Guadalupe, P. O. Box 149104-Mail Code 103-9A Austin, Texas 78714-9104 (512) 322-3435 Fax (512) 305-7425


Amusement Ride Certificate of Inspection/Reinspection

Required for each ride, pursuant to Texas Occupations Code, Chapter 2151, Amusement Ride Safety Inspection and Insurance Act and 28 Texas Administrative Code §§5.9004 -- 5.9014, Amusement Ride Rules, along with a \$40 per ride filing fee and picture of the ride in an operable state taken at the time of the inspection.


	<u>Owner/Operator</u>	<u>Information</u>	
Owner/Operator (Insured)			
Address	2400 Long Road, Denton, TX 7	76207	
Telephone Number	<u>(940) 349-8805</u>		
	Amusement Ride	<u>Information</u>	
Amusement Ride Name	OPEN FLUME BODY SLIDE	Serial Number CC-001	
Manufacturer	SPLASHTACULAR	Date Manufactured 2006	
Date of Last Overhaul or Re	enovation	Date of Last (previous) Inspection_	5/10/19
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Classification: Ride designed primarily for use by children 12 y Ride other than Class A	ears of age or younger with a fixed location	
Amı	usement Ride Inspector Shall Co	mplete the Following Statement	
Self Insured Insu	rance Company and the inspection requirem DO NOT USE STAPLES ON PICTURES. PICTURES.	ted in an operable state and meets the standards ents as set forth in 28 TAC §§5.9001 5.9014 a CTURE PAGE MUST HAVE BUSINESS NAME	and in Chapter 2151, Texas
Name and Title of Inspector Pau			
Inspection Company Zell	_		
Address 180	1 Sumac Drive, Flower Mound, TX	75028	
Telephone Number (972) 355-19	267 Cell Number: (972) 741-	9288	
	Authorization of the In	surance Company	
Name and Title (Print)			
Signature of Authorized Insurance	e Company Representative		Telephone Number
TDI Amusement Ride Validation S	Stamp	TDI Inspection Sticker Number	




MULTI SLIDE TOWER-PUKA ENCLOSED BODY SLIDE WHITEWATER 2003 SERIAL NUMBER 47141B




MULTI SLIDE TOWER-OHANA OPEN BODY SLIDE WHITEWATER 2003 SERIAL NUMBER 47141C



MULTI SLIDE TOWER-BIG KAHUNA ENCLOSED TUBE SLIDE WHITEWATER 2003 SERIAL NUMBER 47141D




MULTI SLIDE TOWER-HULA LOOP ENCLOSED BODY SLIDE SPLASHTACULAR 2010 SERIAL NUMBER WWP-001



INDOOR OPEN BODY SLIDE WHITEWATER 2003 SERIAL NUMBER 47141E

CITY OF DENTON Denton, Texas May 18, 2021 CIVIC CENTER POOL



OPEN FLUME BODY SLIDE SPLASHTACULAR 2006 SERIAL NUMBER CC-001